

Project Nos. 305776 305777 305778 305788 June 1992

Final Report

Former Raritan Arsenal Removal Action Edison, New Jersey

Prepared for: U.S. Army Corps of Engineers Huntsville Division Huntsville, Alabama DACA87-91-D-0009 Delivery Order Nos. 0001, 0002, 0003, 0006

Prepared by: IT Corporation Monroeville, Pennsylvania

RESPONSIVE TO THE NEEDS OF ENVIRONMENTAL MANAGEMENT



FINAL REPORT FORMER RARITAN ARSENAL EDISON, NEW JERSEY

CONTRACT NO. DACA87-91-D-0009
DELIVERY ORDER NO. 0001, 0002, 0003, 0006
PROJECT NOS. 305776, 305777, 305778, 305788

Prepared for

U.S. ARMY CORPS OF ENGINEERS
HUNTSVILLE DIVISION
HUNTSVILLE, ALABAMA 35807-1957

Prepared by

IT CORPORATION 2790 MOSSIDE BOULEVARD MONROEVILLE, PA 15146

MAY 1992

Table of Contents

		Page
1.0	Executive Summary	.4
	1.1 Introduction of the Project	4
	1.2 Site Description	4
	1.3 Description of the Report	5
	1.4 Summary of Work Performed	5
2.0	Discussion By Areas of Concern	8
	2.1 Area 1	8
	2.2 Area 2	8
	2.3 Area 3	9
	2.4 Area 4	10
	2.5 Area 6	11
	2.6 Area 7	11
	2.7 Area 8	12
	2.8 Area 9	13
	2.9 Area 10	14
	2.10 Area 11	15
	2.11 Area 12	16
	2.12 Area 13	16
	2.13 Area 14	17
	2.14 Area 16	17
	2.15 Area 17 and Wastepile	19
	2.16 Spoils Area	19
	2.17 Building No. 118	20
3.0	Ordnance Disposal	21
4.0	Chemical Data Discussion	23
	4.1 Area 4 Wastewater Holding Tank Sample	23
	4.2 Building No. 118 Site 112-gallon Gasoline UST Postexcavation Soil Samples	23
	4.3 Building No. 118 Site 1500-gallon No. 2 Fuel Oil UST Postexcavation Soil	
	Samples	24
	4.4 Building No. 118 Site Soil Classification For Disposal	24
5.0	"Phase-Out" Safety Report for Safety, Health and Emergency Response Review	26
6.0	Site Security Plan Review	7
7.0	Contractor Quality Control Summary	8

8.0	Problems Associated with Project Quality Control	10
9.0	Lessons Learned	11
	9.1 Delivery Order Issuance	11
	9.2 Section 3.2.4 of the Contract	
	9.3 Multiple Delivery Orders at One Location	
	9.4 Contract Work Statement Requirements	
	9.5 Security	12
	9.6 Partnering	13
App	pendices	
	Appendix A - Inorganics Technical Report	
	Appendix B - No. 2 Fuel Oil List Closure Report	
	Appendix C - Gasoline Tank Closure Report	
	Appendix D - Certificate of Analysis	
	Appendix E - Submission of UXO Removal After Action Report of EOD Technolog	ies

1.0 Executive Summary

1.1 Introduction of the Project

International Technology Corporation (IT) was retained by the U.S. Army Corps of Engineers (USACE) - Huntsville Division to perform ordnance and explosive wastes location and removal at the former Raritan Arsenal (FRA) in Edison, New Jersey under Contract Number DACA87-91-D-0009. This contract was conducted in accordance with the scope of work defined under Delivery Order Nos. 0001, 0002, 0003, and 0006. IT subcontracted to EOD Technology Inc. (EODT) to provide ordnance expertise. The objective of this project was to perform an ordnance and explosive wastes location and removal at 17 areas which were identified as suspected contaminated sites by the Letterkenny Army Depot (LEAD) in 1963, the O'Brien & Gere Report in 1989, and the Meftcalf & Eddy Inc. Report in 1991. This Final Report provides historical background of the site and summarizes the work conducted on all sites.

1.2 Site Description

The Former Raritan Arsenal Site consists of approximately 3,200 acres located in Middlesex County, New Jersey, along the banks of the Raritan River. The former arsenal is bordered to the north and northwest by Woodbridge Avenue, and to the southwest by Mill Road and the ILR Landfill.

From 1917 to 1963 the Army used the site for receipt, storage, shipment and decommissioning of ordnance arms, and machinery. During this period, waste materials, including ordnance and chemical agents were buried and burned on-site. Before the Army purchased the Raritan Arsenal site in 1917, the property consisted of farm land with several residences.

Operations at the former Raritan Arsenal were phased out between 1961 and 1963. Starting in 1964, the Army passed land to a variety of owners, including:

- General Services Administration
- Edison Township
- Middlesex County
- State of New Jersey
- U.S. Department of Health, Education and Welfare
- U.S. Environmental Protection Agency
- Army Reserve

· Private Parties.

The site is now the home of Middlesex County College, Thomas A Edison County Park, EPA offices, and Raritan Center, New Jersey's largest industrial park. The redeveloped land on the former arsenal site is concentrated in the northern half of the site, and consists mostly of light industrial facilities, warehouses, and office space. The southern half of the site has remained primarily wetlands, with limited development since the arsenal closed in 1963.

1.3 Description of the Report

This report is divided into nine (9) sections, Appendices, and Attachments.

- Section One is a general introduction of the scope of work.
- Section Two provides the detailed description of the site background and scope of work performed on each site.
- Section Three provides the description of ordnance and explosives disposal operation conducted during the project.
- Section Four discussed chemical data obtained due to waste soil/water produced during the operation.
- Section Five is a phase-out Safety Report as safety, health and emergency response review at the completion of the project.
- Section Six is a site security plan review.
- Section Seven provides a contractor quality control summary.
- · Section Eight discussed problems associated with project quality control, and
- · Section Nine is a conclusion and lessons learned from the project.

1.4 Summary of Work Performed

IT has reviewed 17 areas which were authorized by USACE to perform ordnance and explosives location and removal work. IT also prepared the Final Work Plan with Amendments No. 1 and No. 2 to state the type of field operations and the procedures of the operations. Ordnance and explosives location and removal have been completed at these following Areas:

- Area 1
- Area 4 (within IT's Scope of Work (i.e. TNT to 1/2")
- Area 16, Building 643 & 644
- Area 17
- Building 118.

The following area had work in progress when IT demobilized.

• Area 10

Due to lack of funds and the length of the contract, only minimum preparation work was performed but no field operations were conducted at these following Areas:

- Area 2
- Area 3
- Area 6
- Area 7
- Area 8
- Area 9
- Area 11
- Area 12
- Area 13
- Area 14
- Spoil Area at Middlesex County Utilities Authority

This report is an Ordnance Removal Report to describe the work performed, degree of completion at each area, ordnance and explosive recoveries and disposal, and the problems encountered during the project execution. Included within this report is a copy of EOD Technology, Inc.'s Final UXO Removal After-Action Report, and selected attachments pertaining to the Former Raritan Arsenal as Attachment F.

The daily site reports prepared for FRA have not been included with this report. A copy was issued to the USACE project officer at the site.

2.0 Discussion By Areas of Concern

There are 17 Areas at FRA which IT was authorized by USACE to perform the ordnance removal activities. In this section, these Areas are discussed separately as an individual site. The site map with the New Jersey State Plan coordinates is included in this report. In addition, blown up sections of the areas worked at are within Attachment E.

2.1 Area 1

Area 1 is located on GSA/EPA property. It is approximately 0.6 acre. This area was used as a former demolition ground after World War I and into the early 1930's for the destruction of adapter boosters, point and base detonating fuses, and 37 mm to 6-inch gun projectiles. The area is now covered with brush and is in transition to forest.

The LEAD personnel conducted a surface search as part of a decontamination operation in 1963 and UXB investigated the area in 1988. There was no record of any discovered ordnance.

Based on the Delivery Order No. 0003 from the USACE, IT proposed a cleanup plan at this area. Prior to the UXO cleanup operation, wood chippers were used to chip and spread trees and brush that would impede UXO operations at the area. IT's subcontractor EODT conducted the UXO location and recovery operation by using a GA-52B magnetometer, marking hits with red flagging, searching and using shovel and backhoe to excavate the area at early May, 1991. Only metallic scraps were found. All excavated soils were backfilled after the searching was done. No ordnance related items were found at this area. Quality Control was performed by EODT personnel.

2.2 Area 2

Area 2 is located adjacent to Area 3. This 14 acre site was a former demolition ground that was in operation between 1917 and the early 1930's and was used for the destruction of adapter boosters, point and base detonating fuses and various gun projectiles. A previous survey noted some spent brass casings and ammunition component parts found in this Area.

Area 2 is now partially developed with buildings and roadways. Since the closure of the arsenal, there has been no reported incidents involving discoveries of ordnance at this site.

IT planned to have its subcontractor EODT to search the area for ordnance location and recovery under Delivery Order No. 0003. Preparation work for the site has been conducted. The utilities mark-out has been done and right-of-entry was obtained. One fuze, PD-M52, was found from EOD Technology site walk. The actual field UXO searching and clearing work was not performed by IT Corporation due to lack of funding, and contract time constraints.

2.3 Area 3

This area is approximately 22 acres in size. It was identified as a demolition and burning grounds. It was used from WWI until 1948 for the destruction of adapter boosters, fuses, and projectiles. Various types of fuses, primer detonators, small arms, artillery primers and pyro techniques were destroyed in aboveground destruction chambers and ground pits. Surface burning of smokeless powder and loose low and high explosives were also part of the operation in this Area. The residue from these burning operations was buried in some portions of Area 3 to a depth of 5-6 feet. During the WWII period, Area 3 was also used for storage of small arms ammunitions and cartridge cases.

At previous investigation of the area, heavily corroded unexploded items, spent casings and unburned propellant grains were found. In 1963, LEAD decontamination operation fenced off a 1.9 acre parcel (which was the burn Area and demolition pits) and performed a surface search for ammunition items outside this fenced off section. Also as part of the O'Brien & Gere Contamination Evaluation, 20 ordnance related items were found, one of which was identified as explosive.

In March of 1992, there were several ordnance related items found on the surface at Area 3 during an investigation by Dames and Moore personnel. These items were 39 each MK II grenade fuzes, 3 each 3.5-inch rocket fuze, 5 each Miscellaneous fuze components, 1 each MIII projo fuze, and 1 each stokes morter. These items then were taken to the Demolition Area (part of Area 12) to be disposed of.

IT had planned the ordnance searching and removal activities based on Delivery Order No. 0003. The site walk has been completed. The underbrush was cleared and chipped in the wooded area. IT has obtained Right-of-Entry, and arranged utilities mark-out at the area. Due to lack of funding, IT was not able to have its subcontractor to perform the ordnance location and removal operation at this area.

2.4 Area 4

This area is located in Raritan Center Business area. Area 4 was identified by FRA personnel as the site of renovation operations conducted by the Columbia Salvage Company and the Delaware Steel and Ordnance Salvage Corp in the 1920's. The area was used as high explosive salvage and melt-out area for demilitarization of various calibers and types of ammunition from 75mm to 12-inch projectiles. A portion of the area approximately 2 acres was fenced and access restricted by USEPA before IT's subcontractor started performing any cleanup operations. Area 4 site map showed the fenced-in area. Bulk high explosives (TNT), explosive residues, and several projectiles were found in this area during previous surveys. The fenced part of Area 4 contains trees and shrub. The remainder of Area 4 is occupied by commercial buildings and roadways.

According to Delivery Order No. 0002, IT proposed in it's 1991 Final Work Plan to cleanup the fenced area at Area 4. The site was first inspected for surface UXO by EOD personnel. All vegetation 3-inches and less in diameter were cut and processed through a chipper and then dispersed on site. Grid search lanes were laid out and a surface/sub-surface UXO location and recovery operation was commenced. A trackhoe and a front-end loader were used to excavate the area. Hand excavation was utilized once the excavation was within 12-inches of the suspect item. A sifter was used to sort the excavated soils for raw explosives and any ordnance. The material was sifted and recovered down to 1/2" sized material.

On a daily base operation, the recovered raw explosives were weighted and placed in a plastic container and labeled, then the container was transported to the ordnance storage box pending detonation. The TNT and any ordnance items disposal will be discussed in Section 3.0. Prior to exiting Area 4 fenced area, all personnel and equipment passed through a decontamination station followed proper decontamination procedure from The Safety, Health and Emergency Response Plan (SHERP), Appendix A of Final Work Plan.

TNT and ordnance removal operation in the fenced area is fully completed. EODT Quality Control personnel conducted QC work and the result was satisfactory. Table 1 listed all ordnance items and explosives recovered at Area 4. IT has completed the authorized work at Area 4 fenced area. This area requires additional remediation of the soil and groundwater.

2.5 Area 6

Area 6 is adjacent to a closed Sulphuric Acid manufacturing plant. This plant has been closed for several years. The vegetation consists of small trees with heavy to sparse shrubs in two separate one acre plots.

This area was identified as contaminated by FRA employees in 1961 due to burning operations conducted up to the closure of the arsenal. FRA employees also indicated that no detonation was performed in this area during their tenure (1939 to Closure). In January 1988, UXB conducted spot checks with a magnetometer (an ordnance/metal locator) in conjunction with the O'Brien & Gere contamination evaluation (November, 1989) identified no ordnance related objects at this area. No geophysical surveys were conducted in the area.

According to Delivery Order No. 0006 from USACE, in IT's 1991 Final Work Plan, Amendment No. 1, IT proposed to have its subcontractor performing excavation at the area and examining the excavated soils and exposed ground surface for any munition components or any additional hazards not previously addressed. This work was not performed by IT due to lack of funds and contract expiration. However, IT initiated the site preparation such as confirmed with USACE for obtaining Right-of-Entry to the site, arranged to have related utility companies to mark-out the utilities when IT informs them to do so.

2.6 Area 7

Area 7 is located in a parking lot of a maintenance/office complex. The size of the site is approximately 35×25 feet. There are no trees or plants in the area to impede surface operation. The surface is mostly asphalt at the area.

FRA personnel identified Area 7 as a contaminated area in 1961 due to its use for ammunition renovation and salvage operations from 1929 to closure of the arsenal (information from "Decontamination Report" - LEAD, October, 1963). The facility was called the Ammunition

Renovation Plant and, unlike earlier salvage operations, was run by the arsenal. Area 7 included the location of the Breakdown Building (used to disassemble rounds prior to meltout and also housed a burn vessel), the washout tank, the drawing tank, the settling tank, and several storage buildings.

Decontamination of the Area was performed by LEAD personnel in 1963. The decontamination of the Area consisted of excavating and burning conduits from the Washout Tank to the disposal ditch. The disposal ditch was approximately 200 feet from the washout tank but its exact location is not known. The washout tank itself was not decontaminated but was fenced off with restrictions placed on further use. During the decontamination, small arms cartridges and projectiles were found adjacent to the Breakdown Building. The ordnance material was believed to be processed ammunition from the disassembly and burn operations conducted in the Breakdown Building. Approximately 7,000 cubic yards of soil was removed to clean the Area of this contamination. The material was transported to Area 3.

According to O'Brien & Gere Contamination Evaluation Report (November, 1991), UXB conducted an investigation at Area 7 and the results of magnetometer surveys were inconclusive due to many ferrous objects in the vicinity. Soil and groundwater tests did not show the presence of any explosive contamination.

There is presently a building at 350 Raritan Center Parkway which lies over a portion of Area 7. No ordnance related material was found during its construction.

In IT's 1991 Final Work Plan, Amendment No. 1, IT proposed to have its subcontractor sweep the area with magnetometer and commence clearing surface debris and any ammunition components utilizing shovels and/or Case 580 loader/backhoe. All excavated soil and the exposed ground surface would have been examined for any ammunitions, explosives or hazards not previously mentioned. No work was performed at this Area due to lack of funds and contract expiration.

2.7 Area 8

This Area was previously used for storage and loading of small arms ammunition and components. The size of the site is approximately 10 to 12 acres. The vegetation consists of

small trees, bushes, vines and friars. A small stream enters at the southeast corner and flows northerly exiting at the northeast end of the site.

During the early 1930's, fire and explosions scattered large grains of unburned 16 inch (gun) powder over this area. The area was later used during WWII for storage of overseas returned ammunitions and inert components of various types. During the 1963 LEAD cleanup operation, all propellant powder found was burned and the entire area was diced to 6" and surface searched. It was released to Federal Warehouse without restrictions.

Construction of the building at 450 Raritan Center Parkway which lies over Area 8 was completed in 1987. Soil investigations for this building site reveal that prior to 1980, this site was moderately wooded with an active drainage ditch crossing the site (Information from Converse Consultants East, May, 1987). The northeast corner of the site was a swampy Area. Between 1980 and 1987, the drainage ditch and swampy Area were filled in and the entire wooded area was cleared and stripped of its topsoil. Several feet of the underlying sandy soils were excavated and used as structural fill for other sites within Raritan Center. Subsequently, the site was then used as a spoils area for unsuitable fill from neighboring sites. In 1987 when 450 Raritan Center Parkway was to be built, the thickness of uncontrolled fill ranged from 2.5 feet to 12.0 feet. This uncontrolled fill had to be replaced by suitable fill prior to construction.

Based on the information from Report of Soils and Foundation Investigation, 450 Raritan Center Parkway (Converse Consultants East, May, 1987), IT planed to have its subcontractor EODT to lay out sweep lanes in specific sections and clear the area working in grids. Due to lack of funds and time constraints, no work was performed at Area 8.

2.8 Area 9

Area 9 was used as a magazine storage area. It is approximately nine acres in size. Due to the construction of office buildings and a main roadway, it is only possible to clear about 3/4 of an acre at the present time. The Area contains many trees and shrubs.

This Area was identified by FRA employees due to OEW contamination resulting from the explosion of magazine H-65 on November 9, 1943. While French-made 152 mm loaded cartridges were being loaded from magazine H-65 to freight car, disturbance to the cartridges

ignited one of them and started a fire in the freight car. The fire spread to magazine H-65 and to a nearby freight car loaded with 90mm complete round ammunition. The explosion resulted in the detonation of 90mm ammunition stored in the freight car and magazine. The magazine contained the following ordnance:

- Semi-fixed cartridges (152mm, 90mm, 35mm)
- 90mm full rounds
- 37mm full rounds
- Hand grenades
- Miscellaneous small arms
- Impulse charges

The investigation was conducted after the incident and the following ordnance on the surface or buried in the surrounding area were found:

- Steel and brass fragments
- Live 90mm ordnance
- 152mm cartridge cases
- 90mm cartridge cases

The LEAD decontamination operation discovered several 35mm cartridges. In 1987, UXB clearance operation showed only a total of 19 "ordnance related items" found as result of the search, none of them were potentially hazardous. After the 1987 cleanup operation, 115 Newfield Avenue was constructed.

Based on Delivery Order No. 0006 from the USACE, IT was requested to perform a thorough search for ordnance and its related items at Area 9. This Area was not started due to lack of funds and time constraints.

2.9 Area 10

This area is partially located on the campus of Middlesex County College and partially located in Thomas A. Edison Park. It was used for ammunition magazines and depriming cartridge cases. The site is approximately ten acres in size. The vegetation consists of bushes and a wooded area with a lot of trees (mostly are small sized) with small walkways and jogging trails

throughout. Currently, the area appears to be in the process of being landscaped with several new sprinkler systems installed recently.

This area was not listed in LEAD Report or Archives Search Report by Metcalf and Eddy, Inc as known contaminated area by specific type ammunitions.

With Delivery Order No. 0006 from the USACE, IT was responsible to search the area. Some small trees (diameter 3-inch or less) were cut off by a brush-hog. A portion of the area was secured by caution tapes, orange safety fence and barricades. Sweep lanes were layed out and magnetometer was used for metal/ordnance location. Shovel and/or case 580 loader/backhoe was used to excavate the area when it was necessary. Personnel discovered 13 French rifle grenades and several grenade fuzes on site. During the ordnance searching and clearing operation, Edison Park Police department coordinated with IT for the site security. During the off-work hours, weekend and holidays, Edison Park Police provided the security at the site to keep the curious park visitors out of the site.

IT was not able to complete the ordnance searching and clearing operations at the site due to lack of funding and time constraints. With USACE's instruction, IT arranged to install a chain-linked fence around the uncompleted area to protect the public. After the fence was installed, IT canceled the site security schedule with Edison Park Police under USACE safety officer's authorization. This fence will be removed in the future after the ordnance removal action is completed at the Park.

An Ultra-Sonic Ranging Device (USRADS) was also utilized at Area 10. This report has been previously submitted.

2.10 Area 11

Area 11 is located by Raritan River and is approximately 6.5 acres in area. This Area consists of dredge spoils from Raritan River channel with potential hazards and contamination of subsurface unexploded ammunition, grenades, and mortar shells. The vegetation consists of marsh type grass (6-8 feet in height) and in many areas standing water. It was identified as a suspect area due to the discovery of hand grenade components and live small arms cartridges behind one of the dock sheds in 1961.

During the 1963 LEAD cleanup of Area 11, a large quantity of buried ammunition was removed from a 0.52 acre parcel in the vicinity of the former discovery. The material was dredged with a dragline and discovered at depths of up to 15 feet. After dredging, a check with a mine detector indicated the area was still contaminated. This heavily contaminated section of Area 11 was fenced off and restricted.

Based on USACE's modification to Delivery Order No. 0006 in which Area 11 was added to the areas to be cleared, IT proposed to lay out sweep lanes and search for ordnance and its related components. In early March, Dames & Moore personnel arrived on site to do soil-gas sampling for soil remediation at the area. During their site walk and their field activity, a number of ordnance items were found which were: 54 each French rifle grenade, 9 each MK II grenade, 8 each 20mm round, and 1 each 76mm projectile. These items were immediately removed and taken to the magazine area for storage. IT was not able to start the actual field work to cleanup the ordnance on site due to lack of funding and time constraints.

2.11 Area 12

Similar to Area 11, Area 12 is the site where dredged material from the Raritan River were periodically deposited. This area consists of a UXO disposal site in a small cleared area (approximately 0.5 acres) within the eastern end of Area 12. It has hazards and contamination consisting of explosives and explosive munitions as a result of explosive testing and disposal operations authorized by the USACE.

From Delivery Order No. 0006 and its modifications, IT was authorized to use part of Area 12 to be ordnance detonation site, operating by EOD personnel. All ordnance and explosives unearthed during the cleanup operations were detonated on this site. Also, USACE requested IT to arrange and perform the ordnance searching and removal at entire Area 12. IT has proposed the cleanup plan at the area but no work was conducted due to lack of funds and time constraints. Courtesy sweeps were performed around the detonation to clean up visible "kickouts".

2.12 Area 13

Area 13 was part of the waterfront dock on the Raritan River channel. This area may have ammunition items lodged in the bottom of the river around the dock area. The dock is

approximately 2000 feet long and parallels to the river. No investigation of the area has been conducted since closure of the arsenal.

According to Middlesex County Utility Authority employees, some grenades and gun shells were recently found by the dock area while dredging the River to install an outfall structure for a wastewater treatment plant. This matter was brought to the Army's attention at that time.

In Delivery Order No. 0006 modification on September 30, 1991, Area 13 has been added on to the Areas which were to be reviewed. IT proposed the scope of the work at the area in Amendment No. 2 in Final Work Plan. Also, IT conducted several site walks, discussed safety concerns, type of equipment needed on site, etc. for the actual field operation. But the field operation did not start due to lack of funding and time constraints.

2.13 Area 14

Area 14 is approximately 150 acres in size and consists of dredge spoils from the river channel and dock area. Similar to Area 11, Area 14 was possibly contaminated by explosives and explosive munitions. This area is heavily vegetated in parts and other areas are covered with water.

In 1988 ordnance locator surveys conducted by UXB (part of the O'Brien & Gere Contamination Evaluation) did not include Area 14 as part of UXB's investigation. USACE modified the Delivery Order No. 0006 on September 30, 1991 to add Area 14 to the areas need to be surveyed and cleaned. IT proposed the work plan at the area and conducted several site walk with its subcontractor. IT also had a meeting with the owner of the property in order to get more information for the site and discuss the Right-of-Entry requirements. Due to lack of funds and time constraints to the project, the actual cleanup operation was not started.

2.14 Area 16

Area 16 is heavily vegetated with marsh grass over six feet in height. It is located undeveloped part of Raritan Center Industrial Park. There were storage buildings and magazines at this area when the former arsenal was in operation. In 1985, a grass fire destroyed building 643. During the demolition of the building, a large amount of 37mm shells were found below the ground surface and were removed by the 54th EOD Detachment Unit from Fort Monmouth around

building 643. The shells were identified as "37mm, armour piercing, anti-aircraft shells with a pressed block powder charge, probably pre WWII". These shells were still alive. A surface cleanup then was performed and access to the area restricted.

The Delivery Order No. 0001 authorized IT to perform a thorough ordnance searching and cleanup at this area. An area around building 643 then was cleared and grubbed. EOD personnel layed out 5-foot apart sweep lanes and carefully searched by magnetometer. A Cat 235 excavator and Cat 963 loader with a four-in-one bucket were used to excavate soil. During excavation a water pump was used due to the water table being closed to ground surface. All soil excavated were carefully put through a sifter with screen openings no larger than an inch in size. This ensured that all 37mm projectiles and any other UXOs were recovered from the area. After all of the UXOs were removed, the earth and fill were pushed back into the excavated area. Before the completion of ordnance removal at building 643, a site walk and surface sweep revealed some ordnance around building 644 area. IT reported the discovery to the USACE and received permission to conduct the ordnance cleanup activities around building 644 after the completion of ordnance removal at building 643 area. An additional sweep search was performed around buildings 645 and 646. No ordnance was found around these two buildings.

All unearthed UXOs then were stored in the storage boxes with triple locks and the boxes were placed in the cage on site. At the end of each working day, the cage was safety locked. These ordnance were detonated at demolition area (part of Area 12) later.

To the completion of ordnance location and removal at building 643 and building 644 area, there were 29,194 each 37mm projectiles around buildings 643 and 955 each 37mm projectiles around building 644 unearthed. Both the QA and QC inspections have been performed at both sites.

During the period of ordnance removal operations, Building Security Services was used as site safety guard 24 hours a day. Access to the area was limited to authorized personnel only. The balance of Area 16 remains to be investigated.

2.15 Area 17 and Wastepile

Area 17 is located on the Middlesex County College Campus. It was a salvage and property disposal area during the former arsenal operation. The area is approximately 10 acres, but only a small portion of the area is accessible for searching and cleanup.

In May 1991, IT received Delivery Order No. 0006 from the USACE to perform removal actions at Area 17 accessible areas. IT then proposed work plan and have its subcontractor conducted ordnance location and removal operation. A portion of Area 17 near Gym building and Student Center was searched for ordnance by using magnetometer. When excavation was required, shovel and Case 580 backhoe were used to excavate the grass covered ground. Five test pits were excavated. Scrap metal pieces were unearthed during the excavation. There was no ordnance found at these five test pits. The site restoration has been completed.

Also, there was a waste pile near ball field on the College Campus. Personnel noticed the wastepile and suspected that it might be contaminated by munitions. USACE officer authorized IT to have EOD personnel to examine the wastepile. Through the search, several cartridge cases were found from the wastepile. The discoveries were transported to the Area 16 storage cage for disposal later.

Area 17 was also used to test and set protocol for the use of USRADS in November 1991.

2.16 Spoils Area

This area is covered with river bed spoils that was dredged up during construction of the Supplemental Outfall Facilities of the Middlesex County Utilities Authority. The size of the area is approximately four acres. During dredging, French rifle grenades were recovered and deposited at the site.

Under Delivery Order No. 0006, IT was authorized to perform ordnance searching and removal actions at the Spoils Area. IT proposed the work plan for this area, conducted several site walks and also held meetings with USACE and property owner to discuss the removal and on-site disposal procedures and safety matters, etc. During these site walks, several ordnance items were seen on the surface. But no actual field operation was started due to lack of funding and time constraints.

2.17 Building No. 118

This area is located on the Middlesex County College Campus. The size of the area is approximately 10 acres. Vegetation consists of very large oak trees, maple trees and grass. The possible contaminants were grenades, 75-mm shrapnel projectiles, adapter boosters and fuses which were buried near Building No. 118.

Under Delivery Order No. 0006 from the USACE, IT was assigned to lay out sweep lanes and locate any obvious hot areas. The area of approximately 2 acres then was fenced and access to the fenced area limit to authorized personnel only. All the "hot" areas were excavated by shovel and/or Case 580 or 426 loader/backhoe. All removed soil and exposed ground surface were examined and cleared of ammunitions or any other ordnance not previously mentioned.

During the ordnance searching/excavation operation, there were two underground storage tanks (UST) uncovered. These two tanks were at the place the ordnance search had to be performed. With USACE's authorization, IT removed both tanks and followed NJDEPE tank closure requirements. Also IT had removed a concrete driveway behind the Building No. 118, and a part of concrete case with cable/power lines due to their partial ordnance contamination. At this fenced area, a total of 83,873 each adapter boosters were unearthed behind the building No. 118 within an area of approximately 10,000 square feet. During the daily base operation, all unearthed adapter boosters were transported to a safe ordnance storage cage at Area 16 and the boosters were stored in triple locked steel boxes. Each time, the Middlesex County College Police escorted the ordnance transporting vehicle through the campus to provide safety to the public. Also, security was stationed at the fenced area to prevent unauthorized personnel's access to the site during the off-work hours, weekends and holidays by both Campus Police and Building Security Services Inc.

Accompanied with satisfied QA/QC by USACE officer, ordnance searching and clearing at this area is completed. The excavated areas had been back filled with ordnance-free soils. The site restoration, such as removed tree replacement, grass reseeding, fuel storage tank reinstallation, etc., has taken place.

3.0 Ordnance Disposal

Under USACE's authorization, part of Area 12 was used as the demolition (demo) site for ordnance disposal. At the beginning of the project, Army EOD from Fort Monmouth, New Jersey performed detonation to destroy the unearthed unexploded ordnance periodically as requested. In July, 1991 IT proposed ordnance disposal plan and prepared a Standard Operating Procedure (SOP) for demilitarization of military ordnance. The plan was approved by the USACE. A crew of 3 ordnance disposal technicians were mobilized to the demo site. A safety plan was established for demilitarization of UXOs at the demo site.

All ordnance, ordnance related items and TNT explosives recovered from each site stored at Area 16 storage cage then were destroyed at the demo site on a daily base operation. Listed below are summary of ordnance, ordnance related items and explosives uncovered from the areas during the project and were detonated and destroyed at the demo site by EODT:

Area 2 1 fuse, PD-M52

Area 3 39 MK II grenade fuzes

3 3.5 inch rocket fuzes

5 miscellaneous fuze components

1 M III projectile fuze

1 Stokes mortar

Area 4 12,360 lb. TNT bulk explosives

1 each 20 lb. bomb

21 75mm projectiles

3 projectile fuzes

9 projectile adapter boosters

1 9.2 inch projectile

3 booster cups

Area 10 13 French rifle grenades

Area 11 54 French rifle grenades

Area 16 Building 643 29,194 37mm projectiles

> Building 644 955 37mm projectiles

Bldg. 118 83,873 adapter boosters 1 MK II grenade

Each day the unexploded ordnance, its related items or TNT explosives were transported to the demo site from Area 16 storage cage. They were placed into the chosen disposal pit. The ordnance or TNT then were counter charged with binary yellow stick explosives. The explosive was primed with Primadet nonelectric detonators. The nonelectric detonator then was initiated by 2 electric blasting caps. Shot was covered by hand with sand to a depth of 12", and an additional 24" of sand was placed by a loader. Five shots were set up at one time. EODT conducted tests to establish the amount of TNT and binary explosive needed and allowed them to remain within the acceptable noise level.

To the completion of the project, all ordnance and TNT recovered were destroyed, except 487 adapter boosters which were discovered at Building 118 site in Middlesex County College during the QA/QC check by the USACE officer. These 487 adapter boosters were stored at Area 16 storage cage and safely locked by triple locks.

After each detonation, the scrap metals were collected and stored in a roll-off. These scrap metals were weighed and turned in to the DRMO in Bayonne, New Jersey periodically during the project. All documents were signed by the USACE project officer, USACE New York District personnel, and EODT supervisor.

4.0 Chemical Data Discussion

4.1 Area 4 Wastewater Holding Tank Sample

At Area 4, the main operation was TNT bulk high explosives location and removal. EOD personnel worked on the site wore protective clothing. After the daily operation, they decontaminated the equipment, tools and their working outfit with tap water. The water was then collected in a 5000-gallon wastewater holding tank.

At the completion of TNT removal in Area 4, an IT field engineer sampled the wastewater from the holding tank and sent the sample to Environmental Testing and Certification Corporation (ETC) to be analyzed for TNT and Lead. The sample results showed non-detectable for TNT at detection limit of 125 ug/l (ppb) and low concentration of 170 ug/l (ppb) for Lead. See Attachment A for the sample results and QA/QC control data.

IT applied for a permit from Middlesex County Utilities Authority (MCUA) and Edison Township Health Department to discharge the wastewater to the local sewer since the wastewater is not hazardous. This action was granted and the water disposed of accordingly.

4.2 Building No. 118 Site 112-gallon Gasoline UST Postexcavation Soil Samples

During the ordnance removal operation, a 112-gallon gasoline UST was discovered which was not in use by Middlesex County College. Since the ordnance removal had to be done at the UST location, the tank was removed and postexcavation soil sampling was conducted. Three soil samples were taken along the former tank center line location. The samples were analyzed for Total Petroleum Hydrocarbons (TPHC), Base Neutrals with a forward library search (B/N + 15), Volatile Organic Compounds with a forward library search (VOC + 15), and Lead.

A UST closure report was prepared by IT and submitted to NJDEPE in order to conform the New Jersey UST closure requirements. Attachment B is the closure report with sample locations and sample results summary.

The analytical results showed either non-detectable at detection limit or below the NJDEPE action levels. There was no further excavation required. Any soils formerly excavated at the tank location were drummed in two drums and were disposed of off-site.

PT/06-92/REM_C:305778*Final_Rpt

4.3 Building No. 118 Site 1500-gallon No. 2 Fuel Oil UST Postexcavation Soil Samples

A 1500-gallon No. 2 fuel oil UST was discovered at the point where ordnance removal was required. This tank was in use by Middlesex County College to supply heating oil to Building No. 118. Overfill/leakage was suspected and the tank was removed. An IT Corporation field engineer took three postexcavation soil samples at the removed tank location. The samples then were analyzed for TPHC. The TPHC concentrations for three soil samples are non-detectable, 950 ppm, and 3900 ppm, respectively. One of the samples, with a TPHC concentration of 3900 ppm, exceeded the current BUST action level of 1000 ppm. Comparison of the individual concentrations detected in other two samples and with the results of the tank integrity test support the contention that the contamination is likely attributable to the piping connections at the North end of the tank. Therefore, the tank piping was located, removed and disposed of properly. Five soil samples were taken along each 15 feet of the piping, and analyzed for TPHC. Concentration of TPHC for all five soil samples were non-detectable at detection limit of 21 ppm to 24 ppm. According to the analysis results, piping connection were in good condition. contamination maybe resulted by over fill or slow leaking. Additional soil excavation then was conducted twice to excavate to a depth of 13 feet which is approximately 9 feet below the former 1500-gallon tank base. The excavated soil will be disposed off-site. Six additional postexcavation soil samples were taken and analyzed for TPHC. The results of analysis showed 1700 ppm and 5400 ppm at a depth of 6 feet below the ground surface and non-detectable or 21 ppb at a depth of approximately 13 feet below the ground surface.

A closure report was prepared by IT Corporation to NJDEPE to be in compliance with the State UST closure and discharge requirements which was sent to NJDEPE on January 21, 1992. See Attachment C for the closure report.

4.4 Building No. 118 Site Soil Classification For Disposal

The soils from postexcavation after the 112-gallon gasoline tank and 1500-gallon No. 2 fuel oil tank removed were sampled as a composite twice and one sample for each time. The first sample was analyzed for TPHC, Total Organic Halogen (TOX), PCB's, VOC, Lead, and Flash Point. The second sample was analyzed for TCLP-Lead. The analysis results showed non-detectable for TPHC, PCB's, VOC, and TOX, and showed non-ignitable for Flash Point. Lead had a concentration of 29 ppb which is well below NJDEPE action level of 250 ppm. The TCLP-Lead result showed 0.051 ppm (51 ppb).

Based on these analytical results, the soils are considered non-hazardous. These soils were disposed off-site as non-hazardous material. Also, after the additional postexcavation the excavated soils were left on plastic sheet and covered with it. The Soils will be disposed by Middlesex County College. These soils were sampled as one composite sample and analyzed for waste classification parameters: TPHC, TOX, PCB's, VOC-BTEX, PH, TCLP Lead and Flash Point. The sample results have been sent to Middlesex County College for their disposal information.

In Attachment D are the Analytical Certificate of Analysis documents on the soils from Building 118.



ACCIDENT PREVENTION PROGRAM FORMER RARITAN ARSENAL PROJECT SITES: 4, 10, 16, 118, DEMOLITION AREA

IT Corporation prepared the site-specific Health and Safety Plan to be strictly adhered to by IT Corporation and subcontractor personnel during field activities of the Former Raritan Arsenal project.

The following actions were conducted by IT Corporation to ensure corporate, state, and federal health and safety regulations and guidelines were compiled with by IT Corporation and subcontractor personnel.

- Prior to job start-up, a site-specific health and safety briefing was presented by the Mr. Jay Keough, project CIH. This four hour briefing concentrated on the review of the health and safety plan, which included the potential site-specific health and safety hazards present on the project, work procedures, and appropriate emergency procedures.
- An additional four hour safety briefing was conducted by Mr. Keough and Mr. Tracy
 Estes, CSP (on-site H/S person) for operations conducted at Area 4 which involved
 excavation of UXO and TNT-contaminated soil.
- Daily tailgate safety meetings were presented at each job site which emphasized the following: chemical and physical hazards that may be anticipated, personal protective equipment to be utilized, review of the previous day's operation and emergency procedures which included first aid, fire, police, and hospital information.
- Monthly safety audits were conducted at each job site for the duration of the project.
 The safety audits verified the following safety components were being implemented:
 health and safety issues were properly addressed, proper job set-up was present, daily
 tailgate safety meetings were being documented, health and safety hazards were
 communicated to the on-site personnel, and adequate personal protective equipment was
 being utilized..

The following personnel conducted monthly health and safety audits at the various job sites:

Jay Keough, CIH
Tracy Estes, CSP
Dolly Li, Site Engineer

All health and safety deficiencies were corrected immediately and follow-up inspections were conducted to verify the corrections were implemented.

1.0 Introduction

International Technology Corporation (IT) was contracted by the U.S. Army Corps. of Engineers, Huntsville, AL District to provide remedial services to remove unexploded ordnance (UXO) and bulk trinitrotoluene (TNT) from the former Raritan Arsenal, Area 4, located in the Raritan Business Center in Edison Township, New Jersey.

The project was conducted successfully, meeting all the safety, health, and emergency response requirements. No adverse incidents such as lost-time injuries were experienced by IT employees or subcontractors.

2.0 Air Monitoring Program

In accordance with the project contract specification, an air monitoring program was developed and implemented for the remediation activities conducted at Area 4. The approved air monitoring program is outlined in the Health and Safety Plan addendum of the Safety, Health, and Emergency Response Plan (SHERP). This program established requirements for both personal sampling and real time monitoring. Due to the potential for airborne TNT-contaminated dust, contractor personnel wore Level C protection during excavation and screening/separation operations which were being performed in the exclusion zone.

2.1 Personal Air Sampling

Personal air sampling was performed once a week from November 15, 1991 to March 4, 1992 to measure for total respirable particulate. The following equipment was utilized to collect the air samples: two Gillian personal sampling pumps, model HFS-513A, and 5 umPVC filters. The Gillian personal sampling pumps were calibrated before and after each use. The calibration methods were documented on the Field Activity Daily Logs (FADL) and IT calibration sheets. NIOSH analytical Method 0500 was utilized to analyze for total respirable dust.

Two IT contractors were randomly chosen to wear the personal sampling pumps during each weekly sampling session. The contractor personnel were chosen as being most likely to be exposed to potential TNT-contaminated dust during the screening/separation operations or the excavation operations.

Due to the fact that NIOSH analytical Method 0500 measured total dust and could not identify TNT particulate, all sample analysis were interpreted as total TNT particulate, as a worst-case analysis. Actual TNT concentrations varied from trace amounts to 10 percent TNT in the soil.

The decision to analyze for total dust particulate instead of total TNT particulate was due to the expense and time delay of the TNT particulate analysis.

Analytical results were reviewed as they became available and were consistently found to be below the Permissible Exposure Level (PEL) of TNT. The PEL of TNT is 0.5 mg/m3.

The results of the personal air sampling are noted in Attachment 1.

2.2 Real-Time Air Monitoring

Real-time air monitoring was conducted continuously at Area 4 and documented on a hourly basis, both in the exclusion zone and the site perimeter during all remediation activities where the exposure to potential contaminated TNT dust existed. The instrument utilized for real-time air monitoring was MIE Inc. Model PDM-3 Real Time Aerosol Monitor (mini-ram).

Two mini-rams were utilized at Area 4. One mini-ram was located in the exclusion zone, adjacent to the area which had the potential of creating airborne TNT-contaminated dust (screener/separator or excavation operations) and the other mini-ram was located in the support zone perimeter downwind from the exclusion zone.

Real-time air monitoring readings were recorded hourly in the exclusion zone and were conducted hourly around the site perimeter. The IT subcontractor would provide the real-time readings, taken from the exclusion zone, to the on-site IT Health and Safety Coordinator. The IT Health and Safety Coordinator would walk the site perimeter hourly to record the real-time air monitoring readings and evaluate potential off-site migration of TNT-contaminated dust.

All air monitoring results were recorded on Real Time Air Monitoring Logs and also recorded on the FADL's. The Real Time Air Monitoring readings were communicated to on-site personnel during the daily tailgate safety meetings. The readings obtained during project activities were below the action levels listed in the addendum to the SHERP.

3.0 Cold Stress Monitoring

Cold stress prevention and control measures were implemented for personnel at Area 4. A tent, containing electrical heat sources, was located adjacent to the decontamination line to provide a warm break area to personnel. Also, contractor personnel had an office trailer in the support zone to keep warm during extended breaks, such as lunch. Instructions were provided on the signs and symptoms of cold stress during the daily tailgate safety meetings and personnel were instructed to leave the work area if these sings/symptoms appeared. No adverse cold stress related incidents were experienced during the project.

4.0 Decontamination

4.1 Personnel Decontamination

A personnel decontamination area was established on site to ensure that all site workers maintained a high degree of personal hygiene and minimize the possibility of exposure to site contaminants.

The decontamination area was constructed immediately outside the exclusion zone in the contamination reduction zone (CRZ) to facilitate the removal of protective outer clothing. All personnel exiting the exclusion zone passed through this decontamination area to remove gross contamination and outer protective clothing prior to entering the support zone. All protective clothing was disposed in 55-gallon drums and were disposed of properly.

Also, a support trailer was located in the support zone adjacent to the contamination reduction zone where workers when decontaminated could utilize the shower and hot/cold running water. An adequate supply of towels and soap was supplied to the subcontractors.

Waste water from the trailer was collected and disposed of from the site.

4.2 Equipment Decontamination

Any equipment entering the exclusion zone was assumed to be contaminated and was decontaminated at the equipment decontamination pad in the CRZ. It was the responsibility of the on-site Health and Safety Coordinator to inspect all decontaminated equipment prior to it leaving the site. Equipment used in the decon process consisted of a high pressure washer, decon pad with a water collection sump and stiff bristle brushes for removal of heavy materials. Site workers performing equipment decontamination were dressed in Level Modified D with splash protection. A copy of all equipment decontamination certification forms are included as Attachment 2.

5.0 Medical Surveillance

All personnel entering the exclusion zone or CRZ were required to undergo medical examination within 30 days prior to participating in on-site operations and within 30 days after the conclusion of the work. The medical exam protocol met the requirements of OSHA standard 29 CRF 1910.120. The exam consisted of the following:

- Medical History
- General Physical Examination
- Pulmonary Function Testing (FEV1.0 and FVC)
- Biological Profile 20 channel
- CBC
- Urinalysis
- Methemoglobin
- Urine Heavy Metal
- · Serum Lead
- Zinc Protoporphyrin
- Chest X-ray
- Otoscopic Exam
- Visual Acuity
- Audiometric Exam

6.0 Site Security Plan Review

During the ordnance location and removal operation, security guards were required at Area 16, the Demolition Area, Building 118, and Area 10. IT coordinated with Edison Township Fire Department, Edison Park Police, Middlesex County College Campus Police, and Building Security Services Inc. to successfully provide the site security and safe environment. Basically, the security schedule was activated during the off-work time, weekends, and holidays. But at Area 16 and Demolition Area, the security was scheduled 24 hours daily to limit the unauthorized personnel closeby the demolition Area. Signs like "Blasting Area - Danger", "Turn-off Engine - Detonation Area", "Restricted Area", etc., could be seen at least 500 feet away from the Demo Site. Also, the Edison Fire Department provided a crewed fire engine each day if detonation was scheduled. There were no injuries due to access to the sites by the public. Some small incidents such as missing locks from the gate, stolen trailer steps, etc., occurred during the project.

Fire damage to the "brush-hog" equipment took place on September 11, 1991. IT contracted Rothberg Company to clear out brush in Area 10, prior to EODT's searching, excavating and removal of unexploded ordnance. The clearing procedure was being accomplished by the utilization of a "brush-hog" mechanism, which was attached in front of a bulldozer.

When the Rothberg employee was operating a bulldozer with the "brush-hog" attached to the front. The operator noticed smoke emitting from the "brush-hog" unit and turned off the "brush-hog" operation. IT field engineer was at the site and utilized fire extinguisher on the smoldering fire. Employees immediately notified the Edison Fire Department.

The probable cause of the fire was apparently by either brush getting caught in the blade making the engine overheat, or brush was caught up against the hot motor, causing the brush to catch on fire.

The fire rendered the "brushing-hog" unit inoperable. No persons were injured during the fire fighting incident. No brush fire occurred due to the quick action of personnel and procedures ensuring fire extinguisher were present at the job site. The appropriate emergency numbers were present on site to contact the fire department.

7.0 Contractor Quality Control Summary

In February 1991, the USACE placed IT under contract to perform the ordnance location and removal action at Former Raritan Arsenal in Edison, New Jersey. The contract included ordnance location, removal, and disposal at suspected Areas within the Former Raritan Arsenal. The project grew to include 17 different areas.

The first several months were utilized preparing the required submittals (i.e. work plans, equipment and material information, etc.), project scheduling, ordering materials and equipment and other activity essential prior to mobilization. The preliminary site survey was conducted by Sailor and Sailor Associates to provide the required field references to complete the project.

IT subcontracted EOD Technology Inc. (EODT) to perform the actual field ordnance searching, removal, and detonation operation. During the project, a fence was installed at Building 118 site in Middlesex County College to protect the public. Also, two IT office Trailers, a USACE office trailer, four site trailers, a shower/locker trailer, and a personnel decontamination pad complete with utilities were installed during the project. Power was supplied to the site, and regular/or portable phones and radio communication were equipped to all trailers. Building Security Services, Middlesex County College Campus Police and Edison Park Police coordinated to monitor the sites during all nonworking hours over the entire length of the project.

Work began on each area by laying out sweep lanes and locating any obvious "hot" areas. Clearing and grubbing operations were conducted to some areas with heavy vegetation. Magnetometers (metal detector) were used to detect the ordnance. The detection limit was approximately 10-12 feet. All surface munitions and munitions to one foot deep were removed by shovel. Munitions deeper than one foot were excavated utilizing loader/backhoe to within one foot of the vicinity of any suspected UXO and then proceeded by hand digging. All the areas were cleared down to the point as the groundwater permitted or to a depth of six feet unless otherwise directed by the USACE. At areas like Area 16 and Area 4, large pockets of UXO's were found. The RD-40 Screen-All was utilized. It was approved that the munitions and/or TNT bulk explosives were compatible with this type of screening operation. The entire areas were cleared of munitions and explosives in a logical sequence that was determined on-site and all excavated, examined soils were backfilled after the area was identified ordnance free.

At the completion of each site, EODT QC personnel and USACE QA officer conducted quality control examinations. To introduce a new time saving ordnance searching methods, an USRADS crew was mobilized to perform the ordnance searching at part of Area 17 and part of Area 10 by using computerized equipment combined with magnetometer. This method provided fast-speed, graphic displayed, way to do the ordnance searching and/or QA/QC.

During the QA/QC, one 37 mm projectile was found at Area 16 and 487 adapter booster were uncovered at Building 118 site in Middlesex County College.

IT maintained responsibility of overseeing subcontractor compliance with applicable quality control elements. The quality control system utilized during the project provided an organized procedure that complies with the specification to monitor the site operation through a series of health and safety tailgate checking, site auditing, daily field activities records, ordnance accountability log maintenance, and air monitoring at applicable site, i.e. - Area 4.

Results of quality assurance inspections were reported on daily Quality Control Inspection Report written by the IT field engineer and submitted to the USACE. This report also provided a day-by-day diary of project activities and included the following information:

- Weather Conditions
- Phases of Operation in Progress
- Material and/or Equipment Delivery and Demobilization
- Inspections
- Testing Information
- Verbal Instructions Received
- Changed Conditions/Delays /Conflicts Encountered
- Remarks.

8.0 Problems Associated with Project Quality Control

- Groundwater entering the excavation hole at Area 16 and Area 4 slowed down the normal operation. Water pumps were used to pump the water out from the excavation hole;
- Rain, Snow, and iced ground created poor site conditions and delayed the operation.
- Power lines were damaged during the excavation at Building 118 site in Middlesex County College due to unclear utilities information at the area provided by the College.
- Noise monitoring at Demo Site was not satisfied, and several complaints from Sayerville Residents were received through township and police department.
- Ordnance removal operation was delayed due to discovery and removal of two USTs at Building 118 site in Middlesex County College. Also telephone and power line conduit blocked the way of ordnance clearing at the area which caused slowing down the normal operation.

9.1 Delivery Order Issuance

The start of every Delivery Order was implemented by utilizing a DD 1155. There was some warning that an order was on the way. Once the order was received with the USACE's estimate, a site walk was conducted, a video taken, and work plans commenced. In the beginning, IT Corporation provided a "BIDIT" estimate of the work requested, our input was denied. The contractor needs to perform an estimate prior to initializing work activities on a Delivery Order. His presentation of the estimate should be reviewed, revised, and approved so all parties participating have a gauge to measure against.

9.2 Section 3.2.4 of the Contract

3.2.4.1.1 Requires the Contractor to provide the necessary UXO personnel and equipment to complete the work. Their qualifications were presented in later paragraphs of the section.

IT is understood that UXO specialists are necessary to handle and identify Ordnance related items, but operator and laborer work should be conducted by those types of individuals.

There is a shortage of UXO personnel. Of those that work at Raritan most were all retired Military and senior type personnel. The lower levels could not be obtained, thereby substantially increasing the cost. Operator and laborer levels were not utilized because it was believed by the parties involved that unless an individual was UXO trained, no entry was permitted into and exclusion zone where operations were ongoing. This did not have to be the case at Raritan, particularly in Area 4 where the primary work was excavating for TNT. During the removal of the concrete driveway, an experienced IT operator was brought in to operate the hoeram and this proved to work very well.

A recommendation to incorporate into a contract is that non-UXO personnel who will be entering an exclusion zone where UXO operations are being performed, be given a safety training course prior to the start of work. This course should be designed by a UXO person and should be at least 8 hours but no more than 16 hours.

9.3 Multiple Delivery Orders at One Location

At Raritan, 4 Delivery Orders were issued to perform work at 18 sites including the detonation area. Modification to the original Delivery Order would have been more appropriate to facilitate project controls. The Delivery Orders increased the volume of accounting purchasing, invoicing, and management required to report the projects.

9.4 Contract Work Statement Requirements

As with all government procurements, there are many governing regulations. The Statements of Work Clauses, or special clauses define specific requirements for the work to be performed. On the Huntsville East Contract, many of the standards were incorporated because of so many possibilities and restrictions. These items may have included the following:

- Work and Data Management Plan
- Geo Technical Sub-Plan
- Obtaining Miles National Crime Information of all employees working on site
- Environmental Report (3.2.3)
- Etc.

A Total Quality Management Plan should be developed for contracts of this nature. Start with a Quality Program Plan which incorporates, the General Contract Quality Plan, the Health & Safety Plan, the Sampling and Analysis Plan and Remediation Quality Plan. Each individual Delivery Order should build the site-specific plans based on the Quality Program Plan (QPP). A matrix of requirements should be incorporated in the QPP. For each Delivery Order, the matrix should be checked off and agreed to for site-specific reporting requirements and these actions implemented.

9.5 Security

Providing security at the former Raritan Arsenal was one of the most costly activities encountered. The different security agencies involved:

- Middlesex County Park Police
- Edison Police
- Middlesex County College Police
- Building Security Systems

During operations, security guard services seemed to paramount. In this case, too many agencies wanted to "Protect their turf", at significant cost (i.e., Police at \$25.00 per hour vs. a service at \$14.00 per hour).

For the Raritan Project, a single security service must be contracted to provide and coordinate security in a cost effective manner. The government must approach the local agencies or the local political system and work out this agreement.

9.6 Partnering

Partnering is one important factor that needs to be implemented between the Government and Contractor. By creating an atmosphere of team spirit, the desired results are toward an objective path.

TABLE 1 AREA 10 ORDNANCE RECOVERY AND DISPOSAL LOG FORMER RARITAN ARSENAL

DATE	FRENCH RIFLE GRENADE RECOVERY	TOTAL TO-DATE	FRENCH RIFLE GRENADE DESTROYED	DESTROYED TO-DATE
10/18/91	1	1	0	0
10/21/91	1	2	0	0
11/05/91	1	3	0	0
11/07/91	0	3	3	3
11/21/91	1	4	0	3
11/22/91	1	5	0	3
11/27/91	1	6	0	3
12/04/91	1	7	0	3
12/05/91	0	7	4	7
12/12/91	1	8	0	7
12/19/91	0	8	1	8
02/19/92	1	9	0	8
02/21/92	1	10	0	8
02/25/92	1	11	0	8
03/03/92	1	12	0	8
03/06/92	0	12	4	12
03/17/92	1	13	0	12
03/20/92	0	13	1	13

^{*10/17/91 - 1} MK23 3 lb. practice bomb destroyed on 11/7/91.

^{**}Several grenade fuzes were uncovered, but did not count in the log.

TABLE 2
AREA 4
ORDNANCE & EXPLOSIVES LOG - TNT
FORMER RARITAN ARSENAL

DATE	TNT RECOVERED (LB)	TNT TO-DATE (LB)	TNT DESTROYED (LB)	TNT DESTROYED TO-DATE (LB)
11/07/91	24.5	24.5	. 0	0
11/08/91				
11/09/91				
11/10/91				
11/11/91				
11/12/91	11.0	35.5	0	0
11/13/91	16.0	51.5	0	0
11/14/91	11.5	63	0	0
11/15/91	18.5	81.5	63.0	63.0
11/16/91				
11/17/91		7		
11/18/91	91	172.5	18.5	81.5
11/19/91	86.5	259.0	0	81.5
11/20/91	100.0	359.0	0	81.5
11/21/91	139.0	498.0	0	81.5
11/22/91	100.0	598.0	102.0	183.5
11/23/91				
11/24/91				
11/25/91	112.0	710.0	91.0	274.5
11/26/91	150.0	860.0	200.0	474.5
11/27/91	100.0	960.0	485.5	960.0

DATE	TNT RECOVERED (LB)	TNT TO-DATE (LB)	TNT DESTROYED (LB)	TNT DESTROYED TO-DATE (LB)
11/28/91				
11/30/91				
12/01/91				
12/02/91				
12/03/91	69.0	1029.0	0	960.0
12/04/91	100.0	1129.0	0	960.0
12/05/91	30.0	1159.0	0	960.0
12/06/91	20.0	1179.0	199.0	1159.0
12/07/91				
12/08/91				
12/09/91	77.0	1256.0	20.0	1179.0
12/10/91	90.0	1346.0	77.0	1256.0
12/11/91	70.0	1416.0	0	1256.0
12/12/91	10.0	1426.0	170.0	1426.0
12/13/91				
12/14/91				
12/15/91			,	
12/16/91	0	1426.0	0	1426.0
12/17/91	0	1426.0	0	1426.0
12/18/91	80.0	1506.0	0	1426.0

		· · · · ·	<u> </u>	,
DATE	TNT RECOVERED (LB)	TNT TO-DATE (LB)	TNT DESTROYED (LB)	TNT DESTROYED TO-DATE (LB)
12/19/91	38.0	1544.0	118	1544.0
12/20/91 - 01/06/92	Holidays			
01/07/92				
01/08/92	0	1544.0	0	1544.0
01/09/92	102.5	1646.0	0	1544.0
01/10/92	186.5	1833.0	0	1544.0
01/11/92				
01/12/92				
01/13/92				
01/14/92	302.0	2135.0	0	1544.0
01/15/92	467.0	2602.0	0	1544.0
01/16/92	0	2602.0	0	1544.0
01/17/92	125.0	2727.0	978.0	2522.0
01/18/92				
01/20/92				
01/21/92	222.0	2949.0	0	2522.0
01/22/92	385.0	3334.0	0	2522.0
01/23/92	204.0	3538.0	0	2522.0
01/24/92	220.0	3758.0	0	2522.0

DATE	TNT RECOVERED (LB)	TNT TO-DATE (LB)	TNT DESTROYED (LB)	TNT DESTROYED TO-DATE (LB)
01/25/92				
01/26/92		_		
01/27/92	175.0	3933.0	0	2522.0
01/28/92	240.0	4173.0	0	2522.0
01/29/92	240.0	4413.0	0	2522.0
01/30/92	180.0	4593.0	1145.0	3667.0
01/31/92			-	
02/01/92				
02/02/92				
02/03/92				
02/04/92	220.0	4813.0	0	3667.0
02/05/92	236.0	5049.0	0	3667.0
02/06/92	360.0	5409.0	0	3667.0
02/07/92	360.0	5769.0	1436.0	5103.0
02/08/92				
02/09/92				
02/10/92	·			
02/11/92	180.0	5949.0	0	5103.0
02/12/92	240.0	6189.0	0	5103.0
02/13/92	240.0	6429.0	0	5103.0

DATE	TNT RECOVERED (LB)	TNT TO-DATE (LB)	TNT DESTROYED (LB)	TNT DESTROYED TO-DATE (LB)
02/14/92	360.0	6789.0	0	5103.0
02/15/92				
02/16/92				
02/17/92				
02/18/92	240.0	7029.0	0	5103.0
02/19/92	300.0	7329.0	0	5103.0
02/20/92	240.0	7569.0	0	5103.0
02/21/92	160.0	7729.0	2626	7729.0
02/22/92				
02/23/92				
02/24/92	240.0	7969.0	0	7729.0
02/25/92	240.0	8209.0	0	7729.0
02/26/92	240.0	8449.0	0	7729.0
02/27/92	1282.0	9731.0	2002.0	9731.0
02/28/92				
02/29/92				
03/01/92				
03/02/92				
03/03/92	360.0	10,091.0	0	9731.0
03/04/92	360.0	10,451.0	0	9731.0

DATE	TNT RECOVERED (LB)	TNT TO-DATE (LB)	TNT DESTROYED (LB)	TNT DESTROYED TO-DATE (LB)
03/05/92	360.0	10,811.0	0	9731.0
03/06/92	480.0	11,291.0	1560.0	11,291.0
03/07/92			_	
03/08/92	· · · · · · · · · · · · · · · · · · ·			
03/09/92				
03/10/92	300.0	11591.0	0	11291.0
03/11/92	140.0	11731.0	0	11291.0
03/12/92	0	11731.0	0	11291.0
03/13/92	0	11731.0		11291.0
03/14/92				
03/15/92				
03/16/92				
03/17/92	18.0	11749.0	0	11291.0
03/18/92	360.0	12109.0	0	11291.0
03/19/92	71.0	12180.0	0	11291.0
03/20/92	180.0	12360.0	1069.0	12360.0

DATE	ITEM RECOVERED	DATE DESTROYED	TOTAL NUMBER
11/06/91	20lb bomb uncovered	11/14	1
11/14/91	1 75mm proj. uncovered	12/05	1
11/18/91	1 projectile fuze uncovered	03/06/92	1
12/10/91	1 155mm projectile	12/12	1
12/11/91	1 75 mm projectile 4 projectile adapter boosters	12/11 12/11	2 4
12/12/91	1 projectile adapter boosters	12/12	5
12/16/91	1 9.2-inch projectile	12/19	1
12/18/91	1 75mm projectile	12/19	3
01/15/92	3 75mm projectile	03/06	6
02/14/92	1 projectile adapter booster	03/06	6
02/18/92	1 projectile fuze	03/06	2
02/20/92	13 75 mm projectile 3 booster cups 1 projectile fuze	03/06 03/06 03/06	19 3 3
03/06/92	1 projectile adapter booster	03/06	7
03/17/92	2 75 mm projectile 2 projectile adapter boosters	03/20 03/20	21 9

		MK II/III BOOS	MK II/III BOOSTER ADAPTERS				
DATE	Bldg. 118		_	Total			
	Recovered	Total To-Date	Date Destroyed	Destroyed To-Date			
06/27/91	712	712	0	0			
06/28/91	0	712	0	0			
06/29/91	0	712	0	0			
06/30/91	0	712	0	0			
07/01/91	654	1366	0	0			
07/02/91	678	2044	0	0			
07/03/91	189	2233	0	0			
07/04/91	0	2233	0	0			
07/05/91	483	2716	0	0			
07/06/91	0	2716	0	0			
07/07/91	0	2716	0	0			
07/08/91	1130	3846	0	0			
07/09/91	135	3981	0	0			
07/10/91	870	4851	0	0			
07/11/91	1218	6069	0	0			
07/12/91	0	6069	0	0			
07/13/91	0	6069	0	0			
07/14/91	0	6069	0	0			
07/15/91	0	6069	0	0			
07/16/91	1220	7289	50	50			
07/17/91	432	7721	350	400			

		MK II/III BOOS	TER ADAPTERS	S
DATE	Bld	Bldg. 118		Total
	Recovered	Total To-Date	Date Destroyed	Destroyed To-Date
07/18/91	0	7721	1000	1400
07/19/91	1000	8721	479	1879
07/20/91	0	8721	0	1879
07/21/91	0	8721	0	1879
07/22/91	1578	10299	1000	2879
07/23/91	1309	11608	1750	4629
07/24/91	931	12539	1425	6054
07/25/91	1097	13636	768	6822
07/26/91	0	13636	0	6822
07/27/91	0	13636	0	6822
07/28/91	0	13636	0	6822
07/29/91	0	13636	0	6822
07/30/91	217	13853	0	6822
07/31/91	336	14189	0	6822
08/01/91	1336	15525	1712	8534
08/02/91	1162	16687	2250	10784
08/03/91	0	16687	0	10784
08/04/91	0	16687	0	10784
08/05/91	395	17082	1500	12284
08/06/91	917	17999	450	12734

		MK II/III BOOS	TER ADAPTERS	S
DATE	Bld	g. 118	Date	Total
	Recovered	Total To-Date	Destroyed	Destroyed To-Date
08/07/91	267	18266	2115	14849
08/08/91	1204	19470	2265	17114
08/09/91	0	19470	0	17114
08/10/91	0	19470	0	17114
08/11/91	0	19470	0	17114
08/12/91	0	19470	0	17114
08/13/91	632	20102	0	17114
08/14/91	148	20250	0	17114
08/15/91	582	20832	0	17114
08/16/91	1804	22636	0	17114
08/17/91	0	22636	0	17114
08/18/91	0	22636	0	17114
08/19/91	326	22962	0	17114
08/20/91	135	23097	0	17114
08/21/91	271	23368	0	17114
08/22/91	729	24097	0	17114
08/23/91	0	24097	0	17114
08/24/91	0	24097	0	17114
08/25/91	0	24097	0	17114
08/26/91	0	24097	0	17114

		MK II/III BOOS	TER ADAPTER	S
DATE	Bld	g. 118	Date	Total Destroyed
	Recovered	Total To-Date	Destroyed	To-Date
08/27/91	222	24319	0	17114
08/28/91	949	25268	0	17114
08/29/91	527	25795	949	18063
08/30/91	1082	26877	2250	20313
08/31/91	0	26877	0	20313
09/01/91	0	26877	0	20313
09/02/91	0	26877	0	20313
09/03/91	681	27558	0	20313
09/04/91	1008	28566	0	20313
09/05/91	421	28987	0	20313
09/06/91	0	28987	0	20313
09/07/91	0	28987	0	20313
09/08/91	0	28987	0	20313
09/09/91	210	29197	0	20313
09/10/91	619	29816	0	20313
09/11/91	225	30041	631	20944
09/12/91	1369	31410	0	20944
09/13/91	0	31410	0	20944
09/14/91	0	31410	0	20944
09/15/91	0	31410	0	20944

	MK II/III BOOSTER ADAPTERS					
DATE	Bldg. 118			Total		
	Recovered	Total To-Date	Date Destroyed	Destroyed To-Date		
09/16/91	0 31410		0	20944		
09/17/91	1267	32677	1391	22335		
09/18/91	1074	33751	1502	23837		
09/19/91	1369	35120	1500	25337		
09/20/91	1290	36410	1515	26852		
09/21/91	0	36410	0	26852		
09/22/91	0	36410	0	26852		
09/23/91	73	36483	1533	28385		
09/24/91	11	36494	1500	29885		
09/25/91	0	36494	707	30592		
09/26/91	8	36502	1536	32128		
09/27/91	0	36502	0	32128		
09/28/91	0	36502	0	32128		
09/29/91	0	36502	0	32128		
09/30/91	0	36502	0	32128		
10/01/91	0	36502	471	32599		
10/02/91	101	36603	0	32599		
10/03/91	0	36603	0	32599		
10/04/91	131	36734	0	32599		
10/05/91	0	36734	0	32599		

	MK II/III BOOSTER ADAPTERS				
DATE	Bld	g. 118		Total	
	Recovered	Total To-Date	Date Destroyed	Destroyed To-Date	
10/06/91	0	36734	0	32599	
10/07/91	149	36883	0	32599	
10/08/91	220	37103	0	32599	
10/09/91	609	37712	0	32599	
10/10/91	1370	39082	0	32599	
10/11/91	0	39082	0	32599	
10/12/91	0	39082	0	32599	
10/13/91	0	39082	0	32599	
10/14/91	0	39082	0	32599	
10/15/91	1140	40222	0	32599	
10/16/91	1369	41591	800	33399	
10/17/91	2001	43592	840	34239	
10/18/91	2650	46242	3000	37239	
10/19/91	0	46242	0	37239	
10/20/91	0	46242	0	37239	
10/21/91	2654	48896	3000	40239	
10/22/91	1400	50296	2030	42269	
10/23/91	1403	51699	1925	44194	
10/24/91	302	52001	2093	46287	
10/25/91	0	52001	0	46287	

	MK II/III BOOSTER ADAPTERS				
DATE	Bldg. 118		D-4-	Total	
	Recovered	Total To-Date	Date Destroyed	Destroyed To-Date	
10/26/91	0	52001	0	46287	
10/27/91	0	52001	0	46287	
10/28/91	0	52001	0	46287	
10/29/91	1597	53598	2044	48331	
10/30/91	2506	56104	1000	49331	
10/31/91	1313	57417	0	49331	
11/01/91	1278	58695	1000	50331	
11/02/91	0		0	50331	
11/03/91	0		0	50331	
11/04/91	1305	60000	1000	51331	
11/05/91	3000	63000	2055	53386	
11/06/91	3144	66144	2006	55392	
11/07/91	2856	69000	1530	56911	
11/08/91	0		0		
11/09/91	0		0		
11/10/91	0		0		
11/11/91	0		0		
11/12/91	1240	70240	1356	58278	
11/13/91	1343			60278	
11/14/91	2001	73584	1223	61501	

	MK II/III BOOSTER ADAPTERS				
DATE	Bldg. 118			Total	
	Recovered Total To-Dat		Date Destroyed	Destroyed To-Date	
11/15/91	2022	75606	0		
11/16/91	0		0		
11/17/91	0		0		
11/18/91	1011	76617	0		
11/19/91	841	77458	3010	64511	
11/20/91	555	78013	3000	67511	
11/21/91	1131	79144	2945	70456	
11/22/91	867	80011	0		
11/23/91	0		0		
11/24/91	0		0		
11/25/91	792	80803	950	71,406	
11/26/91	101	80904	0		
11/27/91	117	81021	25	71,431	
11/28/91	0		0		
11/29/91	0		0		
11/30/91	0		0		
12/01/91	0		0		
12/02/91	0		0		
12/03/91	0	81021	0		
12/04/91	0	81021	1400	72,831	

	MK II/III BOOSTER ADAPTERS					
DATE	Bldg. 118		-	Total		
	Recovered	Total To-Date	Date Destroyed	Destroyed To-Date		
12/05/91	0	81021	1000	73,831		
12/06/91	0	81021	1002	74,833		
12/07/91	0		0			
12/08/91	0		0			
12/09/91	135	81156	1000	75,833		
12/10/91	184	81340	1534	77,367		
12/11/91	99	81439	1000	78,367		
12/12/91	0	81439	555	78,922		
12/13/91	0	·	0			
12/14/91	0		0			
12/15/91	0		0			
12/16/91	0	81439	1000	79,922		
12/17/91	0	81439	1000	80,922		
12/18/91	0	81439	517	81,439		
12/19/91	23	81402	23	81,462		
12/20/91	0		0			
12/21/91	0		0			
12/22/91	0		0			
12/23/91	0		0			
12/24/91	0		0			

	MK II/III BOOSTER ADAPTERS					
DATE	Bld	g. 118		Total		
	Recovered Total To-Date		Date Destroyed	Destroyed To-Date		
12/25/91	0		0			
12/26/91	0		0			
12/27/91	0		0			
12/28/91	0		0			
12/29/91	0		0			
12/30/91	0		0			
12/31/91	0		0			
01/08/92	372	81834	0	81,462		
01/09/92	33	81867	0	81,462		
01/10/92	103	81970	0	81,462		
01/11/92				81,462		
01/12/92				81,462		
01/13/92				81,462		
01/14/92	40	82,010	0	81,462		
01/15/92	50	82,060	0	81,462		
01/16/92	0	82,060	0	81,462		
01/17/92	0	82,060	0	81,462		
01/18/92				81,462		
01/19/92				81,462		
01/20/92				81,462		

	MK II/III BOOSTER ADAPTERS				
DATE	Bld	g. 118	D.4.	Total	
	Recovered	Total To-Date	Date Destroyed	Destroyed To-Date	
01/21/92	5	82,065	0	81,462	
01/22/92	4	82,069	0	81,462	
01/23/92	12	82,081	0	81,462	
01/24/92	0	82,081	0	81,462	
01/25/92				81,462	
01/26/92				81,462	
01/27/92	5	82,086	0	81,462	
01/28/92	22	82,108	0	81,462	
01/29/92	0	82,108	0	81,462	
01/30/92	0	82,108	0	81,462	
01/31/92				81,462	
02/01/92				81,462	
02/02/92				81,462	
02/03/92				81,462	
02/04/92	29	82,137	0	81,462	
02/05/92	69	82,206	0	81,462	
02/06/92	0	82,206	0	81,462	
02/07/92	0	82,206	744	82,206	
02/08/92					
02/09/92					

	MK II/III BOOSTER ADAPTERS				
DATE	Bldg. 118			Total	
	Recovered Total To-Date		Date Destroyed	Destroyed To-Date	
02/10/92				·	
02/11/92	132	82,338	0		
02/12/92	87	82,425	0		
02/13/92	266	82,691	0		
02/14/92	18	82,709	0	82,206	
02/15/92					
02/16/92					
02/17/92					
02/18/92	112	82,831	0		
02/19/92	10	82,831	0		
02/20/92	0	82,831	0		
02/21/92	0	82,831	0		
02/22/92					
02/23/92					
02/24/92	16	82,847	0		
02/25/92	13	82,860	0		
02/26/92	0	82,860	0		
02/27/92	0	82,860	654	82,860	
02/28/92					
02/29/92					

	MK II/III BOOSTER ADAPTERS					
DATE	Bldg. 118		D	Total		
	Recovered	Total To-Date	Date Destroyed	Destroyed To-Date		
03/01/92						
03/02/92			· · · · · · · · · · · · · · · · · · ·			
03/03/92	4	82,864	0			
03/04/92	0	82,864	0			
03/05/92	8	82,872	0			
03/06/92	0	82,872	12	82,872		
03/07/92						
03/08/92						
03/09/92		·				
03/10/92	0	82,872	0			
03/11/92	13	82,885	0			
03/12/92	0	82,885	0			
03/13/92	0	82,885	0	82,872		
03/14/92						
03/15/92						
03/16/92						
03/17/92	0	82,885	0			
03/18/92	0	82,885	0			
03/19/92	231	83,116	0			
03/20/92	0	83,116	244	83,116		

	MK II/III BOOSTER ADAPTERS					
DATE	Bldg. 118			Total		
	Recovered	Total To-Date	Date Destroyed	Destroyed To-Date		
03/21/92						
03/22/92						
03/23/92						
03/24/92						
03/25/92						
03/26/92	3	83,119	0	83,116		
03/27/92						
03/28/92						
03/29/92						
03/30/92	0	83,119	0			
03/31/92	5	83,124	0			
04/01/92	18	83,124	0			
04/02/92	0	83,124	0			
04/03/92	40	83,182	0	83,116		
04/04/92						
04/05/92						
04/06/92	138	83,320	0			
04/07/92	26	83,346	0			
04/08/92	2	83,348	0			
04/09/92	2	83,350	0			

	MK II/III BOOSTER ADAPTERS					
DATE	Bld	g. 118	Date	Total		
	Recovered	Total To-Date	Destroyed	Destroyed To-Date		
04/10/92	0	83,350	0	83,116		
04/11/92						
04/12/92						
04/13/92	2	83,352	0			
04/14/92	0	83,352	0			
04/15/92	0	83,352	0	83,116		
04/16/92	0	83,352	270	83,386		
04/17/92	15	83,401	0			
04/18/92						
04/19/92						
04/20/92	235	83,636	0			
04/21/92	180	83,816	0			
04/22/92	27	83,843	0			
04/23/92	17	83,860	0			
04/24/92	10	83,870	0	83,386		
04/25/92						
04/26/92						
04/27/92	3	83,873	0	83,386		

^{*}On 3/18/92, 1 MKII grande was found at Building 118 site.

(continued)

Note: There are 487 adapter boosters in storage which were uncovered during the QA/QC from 4/17-4/27.

TABLE 5 OTHER AREAS FORMER RARITAN ARSENAL ORDNANCE LOG

Area 3

3/10/92

39 MKII grenade fuzes

1 Stokes mortar

3 3.5 inch rocket fuzes5 misc. fuze components1 MIII projectile fuze

Destroyed 3/20/92

<u>Area 11</u>

3/13/92

54 French rifle grenades

9 MKII grenades 8 20mm rounds

1 projectile (75mm RR)

Destroyed 3/20/92

Area 2

(No date available from EODT site walk)

1 fuze, PD M52 - destroyed 3/20/92

Wastepile (between Edison Park and College)

3 37mm cartridge case

1 40mm cartridge case

TABLE 6

ORDNANCE LOG FOR FORMER RARITAN ARSENAL PROJECT

			37	-MM	PROJECTILI	es es	
DATE	Bld	g. 643	Bldg	. 644	Total	Destroyed	Total destroyed
	Recovered	Total to-date	Recovered	Total to-date	Recovered	On the day	To-date
05/13/91	289	289	. 0	0	289	0	0
05/14/91	907	1196	0	0:	1196	0	0
05/15/91	602	1798	0	0	1798	0	0
05/16/91	2188	3986	0	0	3986	1200	1200
05/17/91	0	3986	0	0	3986	1000	2200
05/18/91	0	3986	0	0	3986	0	2200
05/19/91	0	3986	0	0	3986	0	2200
05/20/91	1047	5033	0	0	5033	1250	3450
05/21/91	1152	6185	0	0	6185	0	3450
05/22/91	803	6988	0	0	6988	1200	4650
05/23/91	513	7501	0	0	7501	0	4650
05/24/91	0	7501	0	0	7501	0	4650
05/25/91	0	7501	0	0	7501	0	4650
05/26/91	0	7501	0	0	7501	0	4650
05/27/91	0	7501	0	0	7501	0	4650
05/28/91	232	7733	0	0	7733	0:	4650
05/29/91	3212	10945	0	0	10945	0	4650
05/30/91	1730	12675	0	0	12675	0	4650
05/31/91	1707	14382	0	0	14382	0	4650
06/01/91	0	14382	0	0	14382	0	4650
06/02/91	0	14382	0	0	14382	0	4650
06/03/91	2226	16608	0	0	16608	0	4650
06/04/91	0	16608	-0	0	16608	0	4650
06/05/91	0	16608	0	0	16608	0	4650
06/06/91	2426	19034	0	0	19034	0	4650



ENVIRONMENTAL TESTING AND CERTIFICATION CORP.

Inorganics Technical Report

for

IT CORP P.O. BOX 5902 **RARITAN CENTER** EDISON, NJ 08837

Chain of Custody Data Required for ETC Data Management Summary Reports

CB0330-CB0331

IT CORP

ITCENJINT

ETC Sample No.

Company

Facility

Sample Point

Date

Time

Richard P. Albert Vice President, General Manager

File # 001067

This Technical Report is an INSITE service generated by LODESTAR on Data Management Software.

ETC CORP. TECHNICAL REPORT

TABLE OF CONTENTS

Introduction

Laboratory Address Analytical Methodologies Certifications

Tabulated Analytical Results

Organics Inorganics

GC/MS Quality Control Data

Instrument Performance Check Calibration Summary Laboratory Blank

GC/MS Sample Data

Total Ion Chromatogram Quantitation Report Mass Spectral Data TIC Mass Spectral Data

GC Quality Control Data

Calibration Summary Laboratory Blank

GC Sample Data

Chromatogram Quantitation Report Confirmation Data if required

Chain of Custody Documentation

INTRODUCTION

Environmental Testing and Certification Corp. 284 Raritan Center Parkway, CN 7808 Edison, New Jersey 08818-7808 (908) 225-6700

This technical report contains analytical results in tabular format. It includes comprehensive data for the analytical processes performed. Unless specified otherwise, all soil and sediment results are reported on a dry weight basis.

The report deliverables included in this technical report are based upon the level of report deliverable requested and the applicable quality assurance protocols in the methodologies performed. The sections listed in the Table of Contents represent the full, standard package for organic and inorganic analyses; the report deliverables for this package may vary according to the actual analyses performed.

The ETC/Edison laboratory utilizes a wide variety of methodologies and USEPA approved procedures. Analytical processes and quality assurance protocols are based upon the following references.

Analytical References - Methods and Procedures

Methods of Organic Chemical Analysis of Municipal and Industrial Wastewater", Federal Register Vol. 49, No. 209, October 26, 1984;

"Test Methods for Evaluating Solid Waste", SW-846 Third Edition, USEPA, September 1986;

"Standard Methods for the Examination of Water and Wastewater", 14th, 15th and 16th Edition, 1985;

"Methods for Chemical Analysis of Water and Wastes", EPA 600/4-79-020, EMSL, March 1983;

USEPA Organic Contract Laboratory Program SOW, February 1988;

USEPA Inorganic Contract Laboratory Program SOW, July 1987;

USEPA 2,3,7,8-TCDD Solicitation WA86-K357 SOW, September 1986;

"Methods for the Determination of Organic Compounds in Drinking Water", EPA-600/4-88/039, December 1988;

"Handbook for Analytical Quality Control in Water and Wastewater Laboratories", EPA-600/4-79-019, March 1979; and

"National Enforcement Investigation Center Policies and Procedures Manual", EPA-330/9/78/001-R, Revised May 1986.

The ETC Corp., Edison NJ laboratory is certified to perform environmental analyses for samples collected throughout the United States of America. The laboratory certification identification numbers are summarized below should a certification reference be required in the technical report.

Certification Summary - March 2, 1992

State Agency	<u>Certification</u> <u>Number</u>
Arizona Department of Environmental Quality	322
California Department of Health Services	I-1005
Connecticut Department of Health Services	0511
Illinois Environmental Protection Agency	100224
Kansas Department of Health and Environment	E148, E1122
Massachusetts Department of Environmental Protect	ion NJ136
New Hampshire Department of Environmental Service	es 202690-A
New Jersey Department of Environmental Protection	12941
New York Department of Public Health	10586
North Carolina Department of the Environment	326
Oklahoma Water Resources Board	8703
Pennsylvania Department of Environmental Resource	es 68-323
South Carolina Department of Health and Environmental Control	94002
Tennessee Department of Health and Environment	02915
Utah Department of Health	E-91
Virginia Department of General Services	00113
Wisconsin Department of Natural Resources	999464070

06/07/91 06/08/91	0	19034	0	0	19034	·	1650
06/08/91					19034	0	4650
00,00,71	0	19034	0	0	19034	0	4650
06/09/91	0	19034	0	0	19034	0	4650
06/10/91	741	19775	0	0	19775	0	4650
06/11/91	686	20461	0	0	20461	0	4650
06/12/91	806	21267	0	0	21267	275	4925
06/13/91	47.5	21742	0	0	21742	1600	6525
06/14/91	0	21742	0	0	21742	0	6525
06/15/91	0	21742	0	0	21742	0	6525
06/16/91	0	21742	0	0	21742	0	6525
06/17/91	0	21742	0	0	21742	0	6525
06/18/91	234	21976	0	0	21976	120	6645
06/19/91	82	22058	0	0	22058	480	7125
06/20/91	140	22198	0	0	22198	0	7125
06/21/91	209	22407	0	0	22407	960	8085
06/22/91	0	22407	0	0	22407	0	8085
06/23/91	0	22407	0	0	22407	0	8085
06/24/91	435	22842	0	0	22842	0	8085
06/25/91	468	23310	0	0	23310	0	8085
06/26/91	210	23520	0	0	23520	280	8365
06/27/91	364	23884	0	0	23884	720	9085
06/28/91	0	23884	0	0	23884	0	9085
06/29/91	0	23884	0	0	23884	0	9085
06/30/91	0	23884	0	0	23884	0	9085
07/01/91	275	24159	0	0	24159	0	9085
07/02/91	1709	25868	0	0	25868	0	9085
07/03/91	77	25945	0	0	25945	0	9085
07/04/91	0	25945	0	0	25945	0	9085
07/05/91	304	26249	0	0	26249	0	9085

	07/06/91	0	26249	0	0	26249	0	9085
	07/07/91	0	26249	0	0	26249	0	9085
	07/08/91	152	26401	0	0	26401	0	9085
	07/09/91	1679	28080	0	0	28080	0	9085
	07/10/91	299	28379	0	0	28379	0	9085
	07/11/91	599	28978	0	0	28978	0	9085
	07/12/91	0	28978	0	0	28978	0	9085
	07/13/91	0	28978	0	0	28978	0	9085
	07/14/91	0	28978	0	0	28978	0	9085
	07/15/91	0	28978	0	0	28978	0	9085
Γ	07/16/91	87	29065	0	0	29065	0	9085
	07/17/91	80	29145	0	0	29145	0	9085
	07/18/91	33	29178	0	0	29178	0	9085
	07/19/91	8	29186	0	0	29186	0	9085
	07/20/91	0	29186	0	0	29186	0	9085
	07/21/91	0	29186	0	0	29186	0	9085
* -	07/22/91	. 8	29194	0	0	29194	0	9085
^ [07/23/91	0	29194	366	366	29560	0	9085
nke	07/24/91	0	29194	76	442	29636	0	9085
	07/25/91	0	29194	17	459	29653	30	9115
, [07/26/91	0	29194	. 0	459	29653	0	9115
Ī	07/27/91	. 0	29194	0	459	29653	0	9115
	07/28/91	0	29194	0	459	29653	0	9115
	07/29/91	0	29194	0	459	29653	0	9115
	07/30/91	0	29194	8	467	29661	200	9315
	07/31/91	0	29194	20	487	29681	502	9817
	08/01/91	0	29194	49	536	29730	0	9817
	08/02/91	0	29194	62	598	29792	0	9817
	08/03/91	0	29194	0	598	29792	0	9817
_								

This is the last day worked at Bulg 643.

08/05/91 0 29194 32 630 29824 0 9817 08/06/91 0 29194 11 641 29835 0 9817 08/07/91 0 29194 16 657 29851 0 9817 08/08/91 0 29194 2 659 29853 0 9817 08/09/91 0 29194 0 659 29853 0 9817 08/10/91 0 29194 0 659 29853 0 9817 08/11/91 0 29194 0 659 29853 0 9817 08/12/91 0 29194 0 659 29853 0 9817 08/13/91 0 29194 39 698 29892 690 10507 08/14/91 0 29194 10 726 29920 877 12035 08/15/91 0 29194 0 735								
08/06/91 0 29194 11 641 29835 0 9817 08/07/91 0 29194 16 657 29851 0 9817 08/08/91 0 29194 2 659 29853 0 9817 08/10/91 0 29194 0 659 29853 0 9817 08/10/91 0 29194 0 659 29853 0 9817 08/11/91 0 29194 0 659 29853 0 9817 08/12/91 0 29194 0 659 29853 0 9817 08/13/91 0 29194 0 659 29853 0 9817 08/13/91 0 29194 39 698 29892 690 10507 08/14/91 0 29194 10 726 29920 877 12033 08/15/91 0 29194 0 735	08/04/91	0	29194	0	598	29792	0	9817
08/07/91 0 29194 16 657 29851 0 9817 08/08/91 0 29194 2 659 29853 0 9817 08/09/91 0 29194 0 659 29853 0 9817 08/10/91 0 29194 0 659 29853 0 9817 08/11/91 0 29194 0 659 29853 0 9817 08/12/91 0 29194 0 659 29853 0 9817 08/13/91 0 29194 39 698 29892 690 10507 08/14/91 0 29194 18 716 29910 651 11158 08/15/91 0 29194 10 726 29920 877 12035 08/16/91 0 29194 0 735 29929 0 13205 08/18/91 0 29194 0 735	08/05/91	0	29194	32	630	29824	0	9817
08/08/91 0 29194 2 659 29853 0 9817 08/09/91 0 29194 0 659 29853 0 9817 08/10/91 0 29194 0 659 29853 0 9817 08/11/91 0 29194 0 659 29853 0 9817 08/12/91 0 29194 0 659 29853 0 9817 08/13/91 0 29194 39 698 29892 690 10507 08/13/91 0 29194 18 716 29910 651 11158 08/15/91 0 29194 10 726 29920 877 12035 08/17/91 0 29194 0 735 29929 1170 13205 08/18/91 0 29194 0 735 29929 0 13205 08/20/91 0 29194 3 738	08/06/91	0	29194	11	641	29835	0	9817
08/09/91 0 29194 0 659 29853 0 9817 08/10/91 0 29194 0 659 29853 0 9817 08/11/91 0 29194 0 659 29853 0 9817 08/12/91 0 29194 0 659 29853 0 9817 08/13/91 0 29194 39 698 29892 690 10507 08/14/91 0 29194 18 716 29910 651 11158 08/15/91 0 29194 10 726 29920 877 12035 08/16/91 0 29194 9 735 29929 0 13205 08/17/91 0 29194 0 735 29929 0 13205 08/18/91 0 29194 0 735 29929 0 13205 08/19/91 0 29194 3 738	08/07/91	0	29194	16	657	29851	0	9817
08/10/91 0 29194 0 659 29853 0 9817 08/11/91 0 29194 0 659 29853 0 9817 08/12/91 0 29194 0 659 29853 0 9817 08/13/91 0 29194 39 698 29892 690 10507 08/14/91 0 29194 18 716 29910 651 11158 08/15/91 0 29194 10 726 29920 877 12033 08/16/91 0 29194 9 735 29929 1170 13205 08/17/91 0 29194 0 735 29929 0 13205 08/18/91 0 29194 0 735 29929 0 13205 08/19/91 0 29194 3 738 29932 375 13580 08/20/91 0 29194 3 738 </td <td>08/08/91</td> <td>0</td> <td>29194</td> <td>2</td> <td>659</td> <td>29853</td> <td>0</td> <td>9817</td>	08/08/91	0	29194	2	659	29853	0	9817
08/11/91 0 29194 0 659 29853 0 9817 08/12/91 0 29194 0 659 29853 0 9817 08/13/91 0 29194 39 698 29892 690 10507 08/14/91 0 29194 18 716 29910 651 11158 08/15/91 0 29194 10 726 29920 877 12035 08/16/91 0 29194 9 735 29929 1170 13205 08/17/91 0 29194 0 735 29929 0 13205 08/18/91 0 29194 0 735 29929 0 13205 08/19/91 0 29194 3 738 29932 375 13580 08/20/91 0 29194 35 773 29967 468 14048 08/21/91 0 29194 0 7	08/09/91	0	29194	0	659	29853	0	9817
08/12/91 0 29194 0 659 29853 0 9817 08/13/91 0 29194 39 698 29892 690 10507 08/14/91 0 29194 18 716 29910 651 11158 08/15/91 0 29194 10 726 29920 877 12035 08/16/91 0 29194 9 735 29929 1170 13205 08/17/91 0 29194 0 735 29929 0 13205 08/18/91 0 29194 0 735 29929 0 13205 08/19/91 0 29194 3 738 29932 375 13580 08/20/91 0 29194 3 73 29967 468 14048 08/21/91 0 29194 12 785 29979 1000 15048 08/22/91 0 29194 0 <t< td=""><td>08/10/91</td><td>0</td><td>29194</td><td>0</td><td>659</td><td>29853</td><td>0</td><td>9817</td></t<>	08/10/91	0	29194	0	659	29853	0	9817
08/13/91 0 29194 39 698 29892 690 10507 08/14/91 0 29194 18 716 29910 651 11158 08/15/91 0 29194 10 726 29920 877 12035 08/16/91 0 29194 9 735 29929 1170 13205 08/17/91 0 29194 0 735 29929 0 13205 08/18/91 0 29194 0 735 29929 0 13205 08/19/91 0 29194 3 738 29932 375 13580 08/20/91 0 29194 35 773 29967 468 14048 08/21/91 0 29194 12 785 29979 1000 15048 08/22/91 0 29194 0 785 29979 0 15848 08/23/91 0 29194 0	08/11/91	0	29194	0	659	29853	0:	9817
08/14/91 0 29194 18 716 29910 651 11158 08/15/91 0 29194 10 726 29920 877 12035 08/16/91 0 29194 9 735 29929 1170 13205 08/17/91 0 29194 0 735 29929 0 13205 08/18/91 0 29194 0 735 29929 0 13205 08/19/91 0 29194 3 738 29932 375 13580 08/20/91 0 29194 35 773 29967 468 14048 08/21/91 0 29194 12 785 29979 1000 15048 08/22/91 0 29194 0 785 29979 0 15848 08/23/91 0 29194 0 785 29979 0 15848 08/25/91 0 29194 0 <t< td=""><td>08/12/91</td><td>0</td><td>29194</td><td>0</td><td>659</td><td>29853</td><td>0</td><td>9817</td></t<>	08/12/91	0	29194	0	659	29853	0	9817
08/15/91 0 29194 10 726 29920 877 12035 08/16/91 0 29194 9 735 29929 1170 13205 08/17/91 0 29194 0 735 29929 0 13205 08/18/91 0 29194 0 735 29929 0 13205 08/19/91 0 29194 3 738 29932 375 13580 08/20/91 0 29194 35 773 29967 468 14048 08/21/91 0 29194 12 785 29979 1000 15048 08/22/91 0 29194 0 785 29979 0 15848 08/23/91 0 29194 0 785 29979 0 15848 08/25/91 0 29194 0 785 29979 0 15848 08/25/91 0 29194 0 7	08/13/91	0	29194	39	698	29892	690	10507
08/16/91 0 29194 9 735 29929 1170 13205 08/17/91 0 29194 0 735 29929 0 13205 08/18/91 0 29194 0 735 29929 0 13205 08/19/91 0 29194 3 738 29932 375 13580 08/20/91 0 29194 35 773 29967 468 14048 08/21/91 0 29194 12 785 29979 1000 15048 08/22/91 0 29194 0 785 29979 800 15848 08/23/91 0 29194 0 785 29979 0 15848 08/24/91 0 29194 0 785 29979 0 15848 08/25/91 0 29194 0 785 29979 0 15848 08/26/91 0 29194 0 78	08/14/91	0	29194	18	716	29910	651	11158
08/17/91 0 29194 0 735 29929 0 13205 08/18/91 0 29194 0 735 29929 0 13205 08/19/91 0 29194 3 738 29932 375 13580 08/20/91 0 29194 35 773 29967 468 14048 08/21/91 0 29194 12 785 29979 1000 15048 08/22/91 0 29194 0 785 29979 800 15848 08/23/91 0 29194 0 785 29979 0 15848 08/24/91 0 29194 0 785 29979 0 15848 08/25/91 0 29194 0 785 29979 0 15848 08/26/91 0 29194 0 785 29979 0 15848 08/27/91 0 29194 0 785 </td <td>08/15/91</td> <td>0</td> <td>29194</td> <td>10</td> <td>726</td> <td>29920</td> <td>877</td> <td>12035</td>	08/15/91	0	29194	10	726	29920	877	12035
08/18/91 0 29194 0 735 29929 0 13205 08/19/91 0 29194 3 738 29932 375 13580 08/20/91 0 29194 35 773 29967 468 14048 08/21/91 0 29194 12 785 29979 1000 15048 08/22/91 0 29194 0 785 29979 800 15848 08/23/91 0 29194 0 785 29979 0 15848 08/24/91 0 29194 0 785 29979 0 15848 08/25/91 0 29194 0 785 29979 0 15848 08/26/91 0 29194 0 785 29979 0 15848 08/27/91 0 29194 0 785 29979 0 15848 08/28/91 0 29194 2 787 </td <td>08/16/91</td> <td>0</td> <td>29194</td> <td>9</td> <td>735</td> <td>29929</td> <td>1170</td> <td>13205</td>	08/16/91	0	29194	9	735	29929	1170	13205
08/19/91 0 29194 3 738 29932 375 13580 08/20/91 0 29194 35 773 29967 468 14048 08/21/91 0 29194 12 785 29979 1000 15048 08/22/91 0 29194 0 785 29979 800 15848 08/23/91 0 29194 0 785 29979 0 15848 08/24/91 0 29194 0 785 29979 0 15848 08/25/91 0 29194 0 785 29979 0 15848 08/26/91 0 29194 0 785 29979 0 15848 08/27/91 0 29194 0 785 29979 0 15848 08/28/91 0 29194 1 785 29979 0 15848 08/29/91 0 29194 1 788 </td <td>08/17/91</td> <td>0</td> <td>29194</td> <td>0</td> <td>735</td> <td>29929</td> <td>0</td> <td>13205</td>	08/17/91	0	29194	0	735	29929	0	13205
08/20/91 0 29194 35 773 29967 468 14048 08/21/91 0 29194 12 785 29979 1000 15048 08/22/91 0 29194 0 785 29979 800 15848 08/23/91 0 29194 0 785 29979 0 15848 08/24/91 0 29194 0 785 29979 0 15848 08/25/91 0 29194 0 785 29979 0 15848 08/26/91 0 29194 0 785 29979 0 15848 08/27/91 0 29194 0 785 29979 0 15848 08/28/91 0 29194 2 787 29981 900 16748 08/29/91 0 29194 1 788 29982 569 17317 08/30/91 0 29194 0 788	08/18/91	0	29194	0	735	29929	0	13205
08/21/91 0 29194 12 785 29979 1000 15048 08/22/91 0 29194 0 785 29979 800 15848 08/23/91 0 29194 0 785 29979 0 15848 08/24/91 0 29194 0 785 29979 0 15848 08/25/91 0 29194 0 785 29979 0 15848 08/26/91 0 29194 0 785 29979 0 15848 08/27/91 0 29194 0 785 29979 0 15848 08/28/91 0 29194 2 787 29981 900 16748 08/28/91 0 29194 1 788 29982 569 17317 08/29/91 0 29194 0 788 29982 210 17527 08/30/91 0 29194 0 810<	08/19/91	0	29194	3	738	29932	375	13580
08/22/91 0 29194 0 785 29979 800 15848 08/23/91 0 29194 0 785 29979 0 15848 08/24/91 0 29194 0 785 29979 0 15848 08/25/91 0 29194 0 785 29979 0 15848 08/26/91 0 29194 0 785 29979 0 15848 08/27/91 0 29194 0 785 29979 0 15848 08/28/91 0 29194 2 787 29981 900 16748 08/28/91 0 29194 1 788 29982 569 17317 08/29/91 0 29194 0 788 29982 210 17527 08/30/91 0 29194 0 810 30004 0 17527 08/31/91 0 29194 0 810	08/20/91	0	29194	35	773	29967	468	14048
08/23/91 0 29194 0 785 29979 0 15848 08/24/91 0 29194 0 785 29979 0 15848 08/25/91 0 29194 0 785 29979 0 15848 08/26/91 0 29194 0 785 29979 0 15848 08/27/91 0 29194 2 787 29981 900 16748 08/28/91 0 29194 1 788 29982 569 17317 08/29/91 0 29194 0 788 29982 210 17527 08/30/91 0 29194 2 810 30004 0 17527 08/31/91 0 29194 0 810 30004 0 17527	08/21/91	0	29194	12	785	29979	1000	15048
08/24/91 0 29194 0 785 29979 0 15848 08/25/91 0 29194 0 785 29979 0 15848 08/26/91 0 29194 0 785 29979 0 15848 08/27/91 0 29194 2 787 29981 900 16748 08/28/91 0 29194 1 788 29982 569 17317 08/29/91 0 29194 0 788 29982 210 17527 08/30/91 0 29194 0 810 30004 0 17527 08/31/91 0 29194 0 810 30004 0 17527	08/22/91	0	29194	0	785	29979	800	15848
08/25/91 0 29194 0 785 29979 0 15848 08/26/91 0 29194 0 785 29979 0 15848 08/27/91 0 29194 2 787 29981 900 16748 08/28/91 0 29194 1 788 29982 569 17317 08/29/91 0 29194 0 788 29982 210 17527 08/30/91 0 29194 22 810 30004 0 17527 08/31/91 0 29194 0 810 30004 0 17527	08/23/91	0	29194	0	785	29979	0	15848
08/26/91 0 29194 0 785 29979 0 15848 08/27/91 0 29194 2 787 29981 900 16748 08/28/91 0 29194 1 788 29982 569 17317 08/29/91 0 29194 0 788 29982 210 17527 08/30/91 0 29194 22 810 30004 0 17527 08/31/91 0 29194 0 810 30004 0 17527	08/24/91	0	29194	0	785	29979	0	15848
08/27/91 0 29194 2 787 29981 900 16748 08/28/91 0 29194 1 788 29982 569 17317 08/29/91 0 29194 0 788 29982 210 17527 08/30/91 0 29194 22 810 30004 0 17527 08/31/91 0 29194 0 810 30004 0 17527	08/25/91	0	29194	0	785	29979	0	15848
08/28/91 0 29194 1 788 29982 569 17317 08/29/91 0 29194 0 788 29982 210 17527 08/30/91 0 29194 22 810 30004 0 17527 08/31/91 0 29194 0 810 30004 0 17527	08/26/91	0	29194	0	785	29979	0	15848
08/29/91 0 29194 0 788 29982 210 17527 08/30/91 0 29194 22 810 30004 0 17527 08/31/91 0 29194 0 810 30004 0 17527	08/27/91	0	29194	2	787	29981	900	16748
08/30/91 0 29194 22 810 30004 0 17527 08/31/91 0 29194 0 810 30004 0 17527	08/28/91	0	29194	1	788	29982	569	17317
08/31/91 0 29194 0 810 30004 0 17527	08/29/91	0	29194	0	788	29982	210	17527
	08/30/91	0	29194	22	810	30004	0	17527
09/01/91 0 29194 0 810 30004 0 17527	08/31/91	0	29194	0	810	30004	0	17527
	09/01/91	0	29194	0	810	30004	0	17527

09/02/91	0	29194	0	810	30004	0	17527
09/03/91	0	29194	4	814	30008	0	17527
09/04/91	0	29194	19	833	30027	1205	18732
09/05/91	0	29194	12	845	30039	402	19134
09/06/91	0	29194	7	852	30046	1003	20137
09/07/91	0	29194	0	852	30046	0	20137
09/08/91	0	29194	0	852	30046	-0	20137
09/09/91	0	29194	15	867	30061	1008	21145
09/10/91	0	29194	21	888	30082	917	22062
09/11/91	0	29194	7	895	30089	225	22287
09/12/91	0	29194	12	907	30101	641	22928
09/13/91	0	29194	0	907	30101	0	22928
09/14/91	0	29194	0	907	30101	0	22928
09/15/91	0	29194	0	907	30101	0	22928
09/16/91	0	29194	0	907	30101	0	22928
09/17/91	0	29194	20	927	30121	0	22928
09/18/91	0	29194	11	938	30132	0	2292
09/19/91	0	29194	8	946	30140	0	2292
09/20/91	0	29194	3	949	30143	0	2292
09/21/91	0	29194	0	949	30143	0	2292
09/22/91	0	29194	** 0	949	30143	0	2292
09/23/91	0	29194	6	955	30149	0	2292
09/24/91	0	29194	0	955	30149	0	2292
09/25/91	0	29194	0	955	30149	0	2292
09/26/91	0	29194	0	955	30149	0	2292
09/27/91	0	29194	0	955	30149	0	2292
09/28/91	0	29194	0	955	30149	0	2292
09/29/91	0	29194	0	955	30149	0	2292
09/30/91	0	29194	0	955	30149	0	2292


** This is the last day worked at Bldg 644.


10/01/91	0	29194	0	955	30149	0	22928
10/02/91	0	29194	0	955	30149	800	23728
10/03/91	0	29194	0	955	30149	1020	24748
10/04/91	0	29194	0	955	30149	1000	25748
10/05/91	0	29194	0	955	30149	0	25748
10/06/91	0	29194	0	955	30149	0	25748
10/07/91	0	29194	0	955	30149	1004	26752
10/08/91	0	29194	0	955	30149	2265	29017
10/09/91	0	29194	0	955	30149	1000	30017
10/10/91	0	29194	0	955	30149	998	31015


Note: *** -- Total number of 37-mm projectiles uncovered is a correct number.


Total destroyed number was not an accurate number before 7/25/91.


That's why uncovered total number was not matching destroyed total number. It should read 30149 total destroyed.






















COMMENTS

COMMENTS

FOR

SPECIFIC ANALYSIS

HPLC ANALYSIS:

(OG70759):

The intact sample or extract for sample CB0331 required dilution resulting in elevated method detection limits (MDL's).

ETC

TABULATED ANALYTICAL RESULTS

MAR 24, 1992

QG70759

TABLE 1: QUANTITATIVE RESULTS AND QUALITY ASSURANCE DATA SPEC - HPLC ANALYSIS DATA (QR63)

Chain of Custody Data Required for ETC Data Management Summary Reports

CB0330 IT CORP ITCENJINT X 125704 03-06-92 1245

ETC Sample No. Company Facility Sample Point Date Time

	Resu	lts .	QC Repl	icate	QC Blank	and Spiked	l Blank	QC I	Matrix Sp.	ike
PDES umber Compound	Sample Concen. ug/l	MDL ug/1	First ug/l	Second ug/1	Blank Data ug/l	Concen. Added ug/l	X Recov	Unspiked Sample ug/l	Concen. Added ug/1	7 Reco
2,4,6-Trinitrotoluene	ND	5.0	435	655	0	20	72	0	500	87
					į	:				:
						:				
									:	
										-
										1.
			:							
						:				
										:
6				ì					_	
				<u> </u>					, ,	

MAR 18, 1992 QM70569

TABLE 1: QUANTITATIVE RESULTS

Metals - Analysis Data (QR52)

Chain of Custody Data Required for ETC Data Management Summary Reports

CB0330 IT CORP

ETC Sample No.

ITCENJTHT X125704

Company Facility Sample Point Date Time Hours

	<u>. </u>									
			Resu	ilts		. A text.				
	Compound		Sample Concen ug/l	MDL ug/l						
Lead			6.0	5.0						
]							
					·					
						! !				
									i.	
					:					
(
7					:					
							<u></u>			,

WED, MAR 18, 1992, 4:45 PM

TABLE 1: QUANTITATIVE RESULTS

Metals - Analysis Data (QR52)

Chain of Custody Data Required for ETC Data Management Summary Reports

Q70569

ETC Sample No. Company Facility Sample Point Date Time Hours

		Results				 	• 1		
	Compound	Sample Concen	MDL				i de		
Aluminum Antimony Arsenic Barium Beryllium Boron Cadmium Chromium Chromium Cobalt Copper Iron Lead Magnesium Manganese Mercury Molybdenum Nickel Osmium Potassium Selenium Silver Sodium Strontium Thallium Tin Titanium Vanadium Zinc		ND	5.0						

MAR 24, 1992

TABLE 1: QUANTITATIVE RESULTS AND QUALITY ASSURANCE DATA SPEC - HPLC ANALYSIS DATA (QR63)

Chain of Custody Data Required for ETC Data Management Summary Reports

CBO331 IT CORP

ITCENJINT X 125705

03-06-92 1245 QG70759

ETC Sample No.

Company

Facility Sample Point Date

Time

		Resu	1ts	QC Rep.	licate	QC Blank	and Spiked	i Blank	QC .	Matrix Sp.	ike
NPDES Number	Compound	Sample Concen. ug/l	MDL ug/l	First ug/l	Second ug/l	Blank Data ug/l	Concen. Added ug/l	% Recov	Unspiked Sample ug/l	Concen. Added ug/1	% Recov
2,4,6-Trir	nitrotoluene	ND	125	435	655	0	20	72	0	500	. 87
		:									
						^					
						:			: : :		
. 6			:						i i		

MAR 18, 1992 QM70569

TABLE 1: QUANTITATIVE RESULTS

Metals - Analysis Data (QR52)

Chain of Custody Data Required for ETC Data Management Summary Reports ITCENJINT X125705 CB0331 IT CORP

ETC Sample No.

Company

Facility

920306 1245 0

Sample Point Date Time Hours

Results Compound Sample Concen. ug/l MDL ug/l 170 5.0 Lead

EXTRACTABLE HPLC

(High Performance Liquid Chromatography)

LC QUALITY CONTROL DATA

Calibration Summary

- Initial Calibration Report
- Continuing Calibration Report

Laboratory Blank

- Chromatogram
 Quantitation Report

Calibration Report

Title: TNT Calibrated: <Never>


RF - Response Factor (Subscript is amount in)

RRT - Average Relative Retention Time (RT Std/RT Istd)

RF - Average Response Factor

- Percent Relative Standard Deviation

Page 1 of 1



* - 1

*** Height Percent ***

Report by Retention Time

Operator: CAO 23 Mar 92 5:00 pm

Method File Name: DUPONT1.M Sample Info: QC70759,QC70759 Misc Info: QC70759,QC70759

Integration File Name : DATA:QC59A27A.I

consisting of channels: 1. A 254,4 450,80 of QC59A27A.D


2. C 210,4 450,80

Sequence Index: 1 Bottle Number: 27 Repetition Number: 1

Ret Time	Signal	Descr	Туре	Area	Height	Height% Ratio%	Width	Sym
2.164 C	210,4	450,80	BV	147.42	16.9851	52.73 100.00	0.134	0.58
2.205 A	254,4	450,80	VB	9.8480	0.9696	18.64 100.00	0.144	0.69
2.549 C	210,4	450,80	VV	7.5217	0.7237	2.25 100.00	0.122	0.72
2.937 C	210,4	450,80	VV	2.7111	0.3447	1.07 100.00	0.109	2.31
3.602 A	254,4	450,80	₽V	3.7616	0.8382	16.12 100.00	0.059	1.49
3.811 C	210,4	450,80	PV	17.1718	4.0638	12.62 100.00	0.063	1.68
3.896 C	210,4	450,80	vv	40.7454	3.7149	11.53 100.00	0.150	0.37
4.293 C	210,4	450,80	VV	46.7687	2.4183	7.51 100.00	0.242	1.11
6.948 A	254,4	450,80	BV	89.6819	3.3926	65.24 100.00	0.318	0.76
7.044 C	210,4	450,80	BV	35.7074	1.0343	3.21 100.00	0.426	0.84
8.352 C	210,4	450,80	BV	112.24	2.9250	9.08 100.00	0.457	0.94

LC SAMPLE DATA

- Chromatogram
 Quantitation Report
 Confirmation Chromatogram (when required)
 Confirmation Quantitation Report (when required)



Report by Retention Time

Operator: CAO 23 Mar 92 6:02 pm

Method File Name: DUPONT1.M Sample Info: CB0330C,QC70759 Misc Info: CB0330C,QC70759


Integration File Name: DATA:QC59A29A.I

consisting of channels: 1. A 254,4 450,80 of QC59A29A.D

2. C 210,4 450,80

Sequence Index: 1 Bottle Number: 29 Repetition Number: 1

Ret	Time	9	Signal	Descr	Type	Area	Height	Height%	Ratio	Width	Sym
====	====	===	======= 254,4	450,80	====== BV	354.56	19.8506	13.24	100.00	0.239	1.23
2.	.297	c	210,4	450,80	BV	1973.74	91.7440	18.40	100.00	0.313	2.08
			254,4 210,4	450,80 450,80	VV VV	1006.55 2236.19	47.2022 114.87	31.48 23.03	41.09 100.00	0.279 0.258	0.58 0.31
			254,4 210,4	450,80 450,80	VV VV		12.4564 33.3003	8.31 6.68	37.41 100.00	0.067 0.068	2.12
			254,4 210,4	450,80 450,80	VV VV		17.4616 43.4842	11.64 8.72	40.16 100.00	0.094 0.085	1.07 1.36
			254,4 210,4	450,80 450,80	VV VV		18.8110 55.2933		34.02 100.00	0.123 0.154	0.94 1.06
4	.358	С	210,4	450,80	VV	56.6593	4.4275	0.89	100.00	0.159	0.92
4.	663	С	210,4	450,80	VV	125.91	8.2503	1.65	100.00	0.210	1.30
5.	.001	C	210,4	450,80	VV	105.95	6.7823	1.36	100.00	0.212	1.47
5.	403	С	210,4	450,80	VV	467.06	26.3603	5.29	100.00	0.278	1.03
			254,4 210,4	450,80 450,80	PV PV	28.2407 68.2721	1.6503 3.8156	1.10 0.77	43.25 100.00	0.223 0.277	1.46 1.39
6.	959	A	254,4	450,80	VV	105.32	3.5744	2.38	100.00	0.364	0.78
9.	133	С	210,4	450,80	PV	101.17	3.7956	0.76	100.00	0.339	1.17
9.	503	С	210,4	450,80	VV	49.1973	2.4650	0.49	100.00	0.248	0.55
10.	371	С	210,4	450,80	PV	628.97	21.0005	4.21	100.00	0.502	0.89
			254,4 210,4	450,80 450,80	BV VV		14.2130 41.5841		34.18 100.00	0.485 0.620	
			254,4 210,4	450,80 450,80	BB VV	29.3729 955.50	1.8583 15.2324		12.20 100.00	0.195 0.915	0.75 0.61
			254,4 210,4	450,80 450,80	BB VB	655.81 1412.89	12.8742 25.4392		50.61 100.00	0.651 0.828	180.71
29.	416	C	210,4	450,80	BBA	56.5024	0.8643	0.17	100.00	0.819	3.46



Report by Retention Time

24 Mar 92 1:36 pm Operator: CAO

Method File Name: TNTCOF.M Sample Info: CB0330,QC70759


Misc Info:

Integration File Name : DATA: TNCFA44A.I

consisting of channels: 1. A 254,4 450,80 2. C 210,4 450,80 of TNCFA44A.D

Bottle Number: 44 Repetition Number: 1 Sequence Index: 1

Sequence Index: 1	Bott1	le Numb	er : 44	Repe	cition Number: 1		
Ret Time Signal		Туре	Area	Height	Height% Ratio%	Width	Sym
1.654 A 254,4 1.669 C 210,4	450,80 450,80	BV BV	6.0587 22.4428		0.18 25.97	0.098 0.102	0.63
2.301 A 254,4 2.300 C 210,4	450,80 450,80	VV VV	2035.67 5895.00	243.90 649.45	50.37 37.56 49.47 100.00	0.107 0.116	1.54 1.52
3.366 A 254,4	450,80	VB	1.9203	0.2301	0.05 100.00	0.116	0.63
3.409 C 210,4	450,80	vv	191.98	8.0759	0.62 100.00	0.310	1.85
3.667 C 210,4	450,80	vv	157.27	9.1675	0.70 100.00	0.217	0.39
4.172 A 254,4 4.168 C 210,4	450,80 450,80	VV VV	58.7124 862.23	3.5205 54.2615		0.216 0.210	1.42
4.545 A 254,4	450,80	VV	24.5026	2.0967	0.43 100.00	0.151	3.99
4.692 A 254,4 4.692 C 210,4	450,80 450,80	vv vv	68.0810 263.61	6.5542 25.3656		0.141 0.143	0.55
4.950 A 254,4 4.933 C 210,4	450,80 450,80	vv vv	51.1543 230.55	6.6114 17.7196		0.110 0.177	2.55 0.62
5.020 A 254,4	450,80	VV	34.6421	6.5053	1.34 100.00	0.065	0.48
5.187 A 254,4 5.194 C 210,4	450,80 450,80	VV	110.60 194.40	9.0928 20.6615		0.164 0.133	0.80
5.457 A 254,4 5.460 C 210,4	450,80 450,80	VV VV		12.3827 88.2987		0.169 0.138	0.60 0.67
5.889 A 254,4 5.889 C 210,4	450,80 450,80	VV VV	537.56 1644.29	62.7766 182.48		0.126 0.131	0.69 0.68
6.300 A 254,4	450,80	vv	29.6164	3.2680	0.67 100.00	0.131	1.19
6.589 A 254,4 6.588 C 210,4	450,80 450,80	VV VV		61.9262 61.9353		0.163 0.142	0.54 1.32
6.718 C 210,4	450,80	vv	413.53	44.3470	3.38 100.00	0.134	0.32
6.985 A 254,4 7.006 C 210,4	450,80 450,80	VV VV	79.7046 230.02	15.6147		0.171 0.204	0.53 0.44
7.675 A 254,4 7.686 C 210,4	450,80 450,80	VV VV	222.86	12.8707 30.3114		0.232 0.233	1.23 1.08
8.018 A 254,4	450,80	VV	34.9682	2.6471	0.55 100.00	0.156	0.30
8.052 C 210,4	450,80	vv	194.83	11.1383	0.85 100.00	0.238	0.42
9.218 C 210,4	450,80	۷V	41.0906	3.1907	0.24 100.00	0.177	2.21
9.455 C 210,4	450,80	VV	111.89	7.3494	0.56 100.00	0.215	0.77
10.671 A 254,4 10.672 C 210,4	450,80 450,80	BV VV	4 .	42.1829 80.0218		0.226 0.227	0.92 0.94



Report by Retention Time

Operator: CAO 23 Mar 92 7:04 pm

Method File Name : DUPONT1.M

Sample Info: CB0331C ,QC70759 (1:25)

Misc Info: CB0331C ,QC70759 1:25


Integration File Name: DATA:QC59A31A.I

consisting of channels: 1. A 254,4 450,80 of QC59A31A.D

2. C 210,4 450,80

Sequence Index: 1 Bottle Number: 31 Repetition Number: 1

1	Ret Time	Signal	Descr	Туре	Area	Height	Height%	Ratio%	Width	Sym
•	2.065 A 2.071 C	•	450,80 450,80	BV PV	594.92 1259.61	52.2331 117.88		44.31 100.00	0.173 0.150	1.47
•	2.213 C	210,4	450,80	vv	3538.36	104.75	19.29	100.00	0.422	0.12
_	2.246 A	254,4	450,80	VV	1375.32	36.1539	18.89	100.00	0.469	0.12
•	3.692 A 3.694 C		450,80 450,80	vv vv	594.12 1454.97	52.3502 125.43	27.35 23.10	41.74 100.00	0.145 0.148	0.49
•	3.951 A 3.953 C		450,80 450,80	VV VV		33.3806 90.7523		36.78 100.00	0.111 0.124	0.87 0.69
	4.448 C	210,4	450,80	VV	141.62	7.5366	1.39	100.00	0.248	1.12
	5.049 A 5.051 C		450,80 450,80	BV VV	- , ,	10.6108 74.5485		14.23 100.00	0.253 0.270	1.39
	6.001 A 5.984 C	•	450,80 450,80	VB VV	39.1733 223.90	2.0729 6.0685		34.16 100.00	0.255 0.505	1.27
	6.957 A	254,4	450,80	BB	38.5301	1.3818	0.72	100.00	0.363	0.66
	8.326 C	210,4	450,80	BB	79.4017	2.1382	0.39	100.00	0.469	0.80
	10.094 C	210,4	450,80	BB	42.8581	1.5091	0.28	100.00	0.351	0.91
	14.727 A 14.733 C		450,80 450,80	BB BV	156.64 301.79			46.34 100.00	0.586 0.567	0.59 0.71
_	16.190 C	210,4	450,80	VV	256.35	5.3794	0.99	100.00	0.566	1.19



Report by Retention Time

Operator: CAO 24 Mar 92 12:19 pm

Method File Name : TNTCOF.M

Sample Info : CB0331C ,QC70759 20---500

Misc Info:

Integration File Name : DATA: TNCFA41A.I

consisting of channels: 1. A 254,4 450,80 of TNCFA41A.D

2. C 210,4 450,80

Sequence Index: 1 Bottle Number: 41 Repetition Number: 1

seq	uence	index: I	ВОС	TTE NUMB	er: 41	vebe	1		
Ret	Time	Signal	Descr	Туре	Area	Height	Height% Ratio%	Width	Sym
		254,4 210,4	450,80 450,80	BV BV	24.2125 55.9301	3.3001 7.3212	1.04 45.08 0.82 100.00	0.105 0.112	0.53 0.55
		254,4 210,4	450,80 450,80	vv vv	3314.68 8220.64	248.80 598.19	78.73 41.59 66.73 100.00	0.172 0.188	1.11 1.00
3	.627 C	210,4	450,80	vv	25.0782	2.5784	0.29 100.00	0.123	0.66
3	.992 A	254,4	450,80	PV	12.0834	1.3760	0.44 100.00	0.110	7.33
		254,4 210,4	450,80 450,80	vv vv	33.0298 184.61	2.8899 10.0449		0.171 0.244	1.43 2.62
		254,4 210,4	450,80 450,80	vv vv	28.2597 156.30	2.2700 12.6664		0.164 0.170	2.2
		254,4 210,4	450,80 450,80	vv vv	20.9922 155.73			0.128 0.166	0.8 0.5
		254,4 210,4	450,80 450,80	vv vv	89.3635 250.31	5.0926 13.1713	1.61 38.66 1.47 100.00	0.237 0.242	0.70 0.5
5	.337 A	254,4	450,80	vv	86.5434	8.7972	2.78 100.00	0.134	2.1
		254,4 210,4	450,80 450,80	vv vv	187.53 1088.77	19.7845 110.65	6.26 17.88 12.34 100.00	0.135 0.138	0.5 1.4
5.	.680 C	210,4	450,80	VV	445.24	41.2199	4.60 100.00	0.149	0.4
6	545 C	210,4	450,80	vv	1910.88	42.1027	4.70 100.00	0.558	0.7
		254,4 210,4	450,80 450,80	BV VV	40.4100 338.46		0.96 22.61 1.50 100.00	0.180 0.324	1.3
		254,4 210,4	450,80 450,80	PV VV		14.2613 28.8971	4.51 49.35 3.22 100.00	0.166 0.206	0.8 0.6
		254,4 210,4	450,80 450,80	BB BV	83.6657 71.1225			0.304 0.266 2	0.8

CHAIN OF CUSTODY DOCUMENTATION

- Chain of Custody Forms Laboratory Chronicles Subcontract

CHAIN OF CUSTODY

COMPANY:	T	
ADDRESS: LACIT	an Arsenal Fa	cilita
Attn:		
SAMPLE DESCRIPTION:		
CUSTOMER ID	DESCRIPTION	ETC #
125704	(2) ILTR Ext Hz U Total Lead + Nitro Exp	CB0330
	C*3 2 111 11 12 12 12 12 12 12 12 12 12 12	
125705	1	C B 0 3 3/
	<u> </u>	
	<u></u>	
Sample(s) relinquish		
Date: 3/6/92		1406
Sample(s) received	by: Nana Payler	
Date: 3-6-91		
	Ck// Seal Number:	Afe unly Temp:

INTERNATIONAL
COPPODATION

ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD*

Reference Document l	No. 363597
Page 1 of	

CORPORAT	TION ,		AIM OF L	,05 I OI	,		raye i ui		
Project Name/	No. 1 USACE/30	5ๆๆ] _{Sam}	ples Shipm			6/92 1	Bill to:5 IT Cor P.O.Bu Ed:30	PR	A.
	pers 2 Dolly Li		Lab De	estination	8 ET (- -	F1 130	n N	T 08837
Profit Center	No. 3 3811		Lab	Contact	Cath			1 1 1 - 1	J
Project Mana	oger4 Chick Mag	WHOM Proj	ect Contac	t/Phone	12 Dah	1 548-8775 Hepc	ort to: 10 IT Car	P. R.	A
Purchase Order	No.6 ,470274		Carrier/W				P.O.Bo	x 590	22
Required Report C	Date 11 3/21/92					PER LINE	Edison	. NJ	0882.1
Sample ¹⁴ Number	Sample ¹⁵ Description/Type	Date/Time 16 Collected	Gontainer Type	⁷ Sample ¹⁸ Volume	Pre- ¹⁹ servative	Program /	Condition on Receipt	21	Disposal ²² Record No.
125704	Blank	1245	glass	21	None	12 Potal Lead 2 Nitro-explos	siles		
125705	Wastewaler	↓ ↓	V	1	U	′			
				:					
)									
			†	,					
				i i					
:									
Special Instruction	ons: ²³			<u> </u>	<u> </u>				
Possible Hazard Non-hazard _J F		ritant _ Po	oison B 🔟	Unknowr	n Ki	Sample Disposal: 25 Return to Client	5 Disposal by Lab	Archive	(mos.)
Turnaround Time	Required: 26			C Level: 2		Project Specific (spec			
1. Relinquished by (Signature/Affiliation)	Dolly X.	Dat Tim		192	T	ived by 28 \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	\sim 1	Date: Time:	3-6-92 1406
2. Relinquished by (Signature/Affiliation)		Dat Tim	ite:		2. Rece (Signature/A			Date: Time:	
3. Relinquished by (Signature/Affiliation)	1	Dat Tim			3. Rece (Signature/A			Date: Time:	
Comments 29								• .	





ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD (cont.)*

Reference Document No.30 _____ Page____of ____

Project Name USACE	Arcona (Project No. 305777	Samples Shipment
TOO MAA GO MI TON	Arcon a	

Sample ¹⁴ Number	Sample 15 Description/Type	Date/Time ¹⁶ Collected	Container 17 Type	Sample 18 Volume	Pre-19 servative	Requested Testing 20 Program	Condition on 21 Receipt	Disposal 2 Record No.
25704	Blank	3/6/92 12:45 pm	glasze	2L	None	Q Total Lead	X 2-14	glass
						2 Nitro-explosive		
25705	Wastewater	V	V	V	V	V	x 12-12	
	_					·		
			1			<u> </u>	R B4 2 DF	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
								:
							,	
* SENO	RESULT3	TC	SITE	TRAI	LER			
	P.O. BOX 59	22						
	Edison. ng	- 08817	-5902					· .
	Attn. Dolly	Li	:		:			
	7							
	Any questin		2 400	11 91 11	(908)	(ZID-8005		
	1 9 Busses	7 //~	WIL	au	(700)	770 0 7 70		
								`

		VER	SAMPLE	Sample Preparation LE MOIST DRY EXTRACT VO			T VOL (ml		REPEAT	CH NO: QG70759		
OB NO.	LOGLINK	SUR	AMT	MOIST %	WT	57		CRI	ORIGINAL QS NO.] A	TYPES	
30330	101630				gm	ECLC 5.0		95	us ito.	SPECLC		
0331	101630		500			5.0		08		SPECLC		
								83			·	
					<u> </u>			_				
Pup					ļ							
033/	101630		20 ml			5.0		03		SPECCE	1:25	
	131630		10 MI			2.0		Za		SPELLE	1:50	
											. "	
	· · · · · · · · · · · · · · · · · · ·				<u> </u>	+				<u> </u>		
		; ;										
				<u> </u>	<u> </u>					<u> </u>		
A7 /=/								 			· · · · · · · · · · · · · · · · · · ·	
	VERIFY SPIKE			<u> </u>	+	5.0		OS			,	
707 81 Si MS1k	970s 31242 970s 31242				+	5.0		9 5	+			
Si MSD1	SIBR3-1292		<u> </u>	<u> </u>	+	5.0		09	 			
	900 3-23-92	· ·· · · · · · · · · · · · · · · · · ·										
82									<u></u>	ļ.,,		
	STOR 3-25-97		<u> </u>	ļ	-	5.0			ļ	ļ		
MMENT	STOE 3-23-92			/	<u> </u>					- 1 2		
		Set			Copy		Elhad.	u	Se CE	3 0 3 3 /	ENTRACTION A	
DÉCA	EDUKE		SIGNA	TURE Vkur		3-12-	97	SPIKE	ml	ug/ml	LOT NUMBER	
PROC			J . (2)				/ -		2.1. 21			
SPE	iuous		3 . C	NA	<u> </u>		<u> 7µ7</u>	THAMA S	P IDIA	100	1618	
SPE	IUOUS INNEL		X O	<u>, </u>	. <u>-</u>	PNP	<u> 7µ7</u>		P IDIA	100	1618	
SPE CONTIN SEP. FU SONICA SOXHLE	IUOUS INNEL LTION ET		3 . O	<u>, </u>	. <u>-</u>		<u> 7µ7</u>		P IDIA		1618	
SPE CONTIN SEP. FU	ÍUOUS ÍNNEL ATION ET DN		<i>y</i> . <i>G</i>	<u>, </u>	. <u>-</u>	PNP	<u> 7µ7</u>		P IDIA	100		
SPE CONTIN SEP. FU SONICA SOXHLE DILUTIO DERIVA	ÍUOUS ÍNNEL ATION ET DN	ONING	<i>y</i> 0	<u>, </u>	. <u>-</u>	PNP	<u> 7µ7</u>		P IDIA	100		
SPECONTIN SEP. FU SONICA SOXHLE DILUTIO DERIVA ACID BAFLORISI	IUOUS INNEL ATION ET DN TION ASE PARTITI		<i>S O</i>	<u>, </u>	. <u>-</u>	PNP	<u> 7µ7</u>		P IDIA	100		
SPE CONTIN SEP. FU SONICA SOXHLE DILUTIO DERIVA ACID BA FLORISI ALUMIN	IUOUS INNEL ATION ET ON TION ASE PARTITI IL CARTRIDGI NA		<i>S C</i>	<u>, </u>	. <u>-</u>	PNP	<u> 7µ7</u>		P IDIA	100		
SPE CONTIN SEP. FU SONICA SOXHLE DILUTIO DERIVA ACID BA FLORISI ALUMIN SULFUR GPC	IUOUS INNEL ITION ET ON TION ASE PARTITI IL CARTRIDG			Í NA		PMP 3/23/9	TNT		P IDIA	100		
SPE CONTIN SEP. FU SONICA SOXHLE DILUTIO DERIVA ACID BA FLORISI ALUMIN SULFUR GPC CONCER	IUOUS INNEL ATION TION ASE PARTITI IL CARTRIDG IA R/COPPER			<u>, </u>		PNP	7N7		(MS,D) 1.0 JO.E	100 100 345 save 100 100		
SPE CONTIN SEP. FU SONICA SOXHLE DILUTIO DERIVA ACID BA FLORISI ALUMIN SULFUR GPC	IUOUS INNEL ITION ET ON TION ASE PARTITI IL CARTRIDG NA R/COPPER			Í NA		PMP 3/23/9	7N7	INTER	(MS,D) 1.0 JO.E	100 100 100	16 11	
SPE CONTIN SEP. FU SONICA SOXHLE DILUTIO DERIVA ACID BA FLORISI ALUMIN SULFUR GPC CONCER	IUOUS INNEL ITION ET ON TION ASE PARTITI IL CARTRIDG NA R/COPPER			Í NA	EHD:	PMP 3/23/9	7/17 7/17 7/17 7/17 7/17 17/17	INTER	(MS,D) 1.0 JO.E	100 100 100	16 11	

ETC Corp.			1005	CLE : L	C	Departm	ent 30	Page	_of_
te_3/23/92	•	•	-	1		 1	Conc	Lot	-
Type_ 24 6-7N	! Ste	ndar	d i	ppm	No.	1			
. file 047070	9,	_		'	T4/T	51D 2	0,5	001	-
hod file Pa	PONTI		- .			亚		!	- (
file		,				77			- ' - '
newed by/Date	- CH	U	_	 		<u> </u>		<u> </u>	- <mark>1</mark>
ch #'s	470759	•				!			!
	The second secon	······································	_					!	. 1
Standards Un			-						. ¹ . 1
Standards Up			. 1 . 1					1	. l
e #	In	ر س	1 _			I		1	1
 1		init.							-
NAME I	File (m1/g	*	Dil 			Comme	nts	
0.5 ppm 74751D1	QC59A 201	ا	20	l				· · · · · · · · · · · · · · · · · · ·	,
1 ppm	214	1	2/	11				· · · · · ·	
2 gpm	227		<u> </u>	1 11					
5 ppm	234		×3					•	
10 pm	244	1	24	 <u></u>					
Blank	25 A	ا :	<u>ئ</u>			,	*· ·· *		
Cal CHK SID	264	 	26	l					
GC707596	274 I	ı	27	l 					
Q17075905	284	 1	28						
CB0330C	294		29	l 1				 	
CB 0331C	301	 .	30	1:10		·			
CB033/C	311		31	217500					
CB 0 33/CS	321	l	32	007-60C					
CB 0331CR	334	 	33	20-2500					
CB 0331C	341		34	10-7500					
Cal CHIL SID	351		35						
Black	36 A	. ا ا	36	1					
 	· [1	I	1					- , ,
· 		P : -e	0	· · · · · · · · · · · · · · · · · · ·					-31

Type 246-7	NT Confi	•		Sta	ndard	Conc	Lot No.	1 .
q. file			_	1 2 P	PPM TNT SID	a_	00/	- 1 - 1
alyst wrewed by/Date tch #'s	Land Co	<u> </u>	_					1
_ Standards Up ateBy			_1					!
Pe #	DATA I	init.	ALS	l l l		Comme	nts	-1
1 2 ppm 51D	TACFA 40A		40					
CB0331 C	41A		41	207500			·	
CB0331CS	42A		42	20-3500			<u></u>	
UB0331C	43A		43	1:10	C.			
(B0330C	44A		44	l 				
CVC 70 ZEGCS	454		45	 				·
-				 	·		····	-i
 		<u></u>	_	i	<u></u>		····	
			4 · 200 0	i. İ				
							· · · · · · · · · · · · · · · · · · ·	
								
				! 		<u> </u>		
				¦¦				
								<u></u>
1			,					71

SAMPLE PREPARATION LOG - METALS

BATCH #	04705K9	

MATRIX	water	

		P	Fun	nace	Mer	cury	Boron		
Sample ID	Initial	Final	Initial	Final	Initial	Final	Initial	Final	
LCS) Control			1	5.0			`` - · ·		
PB) Q -1			0.5 m						
BS) Q -A1	-		50	50					
50) 4 41			0.5 ml	50					
C80336			50	50					
CB 0331			→ 	7					
				X					
									
									
				 ‡					
		·							

Matrix Spike and Duplicate Information

Sample ID			CBc		. 40	
	-1		50	50		
(MS)	A1	·	0.5	50		. ,
(D)	-2		50	50		

Sample ID		· · · · · · · · · · · · · · · · · · ·
•1		
(MS) A1		
(D) -2		

Analyst:	Aitalk
Date:	3/202

No. 2 FUEL OIL UST CLOSURE REPORT MIDDLESEX COUNTY COLLEGE

PREPARED FOR:

U.S. ARMY CORPS OF ENGINEERS FORMER RARITAN ARSENAL P.O. BOX 6433 EDISON, NEW JERSEY 08818-6433

PREPARED BY:

IT CORPORATION
P.O. BOX 7809
EDISON, NEW JERSEY 08818-7809

JANUARY 1992

PROJECT NO. 305788/029



January 21, 1992

Project No. 305788

Mr. Matthew McDermott
Bureau of Underground Storage Tanks
Division of Responsible Party Site Remediation
New Jersey Department of Environmental Protection and Energy
CN 029
Trenton, New Jersey 08625-0029

No. 2 Fuel Oil UST Closure Report

Middlesex County College, Edison, New Jersey
Case No. 91-19-1559-04; UST No. 0119829

Dear Mr. McDermott:

Enclosed for your review are two copies of the above-referenced report, prepared in accordance with NJAC 7:14B-9.5. As stated in my November 21, 1991 letter, this 1,500 gallon underground storage tank (UST) was removed on October 23, 1991 as part of the U.S. Army Corps of Engineers (USACE) Ordnance Removal project at the former Raritan Arsenal.

Postexcavation soil samples were collected after the UST was removed and analytical results are included in this Closure Report. The results were evaluated according to the new site assessment procedures for soils, effective November 1991, which require remediation of total petroleum hydrocarbons (TPHC) levels over 1,000 milligrams per kilogram (mg/kg). Due to the presence of unexcavated ordnance in the immediate vicinity of the former UST, it is impossible to safely remove contaminated soil within the standard 90 day period for completing a closure report. Consequently, this report reflects TPHC concentrations of insitu soil that directly contacted the tank bottom. The remaining affected soils and piping will be removed after ordnance removal is complete, which should be by June 1, 1992. Additional soil sample results will be included in the DICAR report to be submitted by September 30, 1992.

Mr. Matthew McDermott

2

January 21, 1992

Please contact me or Jim Wagner at (908) 225-2000 if you have any questions or would like to discuss this matter.

Very truly yours,

IT CORPORATION

Barbara Maginn, P.E.

Sr. Project Engineer

BM:kp

Attachments

cc:

B. Bauman - USACE

P. Dalal - USACE

P. Hilf - Middlesex County College

C. Magilson - IT

J. Wagner - IT

Ta	h	01	f	C	ní	۵	n	te
				_	 	=		

	Page
1.0	Introduction
2.0	Closure Activities
	2.1 Tank Decommissioning
	2.2 Excavation Screening
	2.3 Site Assessment
3.0	Site Assessment Results
4.0	Conclusion and Future Actions
List	of Tables
Table	Title
1	Postexcavation Analytical Results
List	of Figures
Figur	e Title
1	Postexcavation Sample Locations
2	Cross-sectional View 1500 Gallon No. 2 Fuel Oil UST
List	of Appendices
Appe	ndix Title
Α	Site Assessment Summary
В	Tanknology Corporation International
	Tank Integrity Test Report
C	Middlesex County College Site Plan
Ď	Analytical Results

1.0 Introduction

On September 19, 1991, a 1,500 gallon single wall underground storage tank (UST) containing No. 2 fuel oil was partially uncovered behind Building 118 at Middlesex County College (MCC), located in Edison, New Jersey. The tank was uncovered during unexploded ordnance removal by contractors for the U.S. Army Corps of Engineers (USACE) Ordnance Removal project. Petroleum contaminated soil was encountered while excavating for ordnance around the tank. The New Jersey Department of Environmental Protection and Energy (NJDEPE) hotline was notified on September 19, 1991 and assigned Case No. 91-9-19-1559-04.

As noted in correspondence to NJDEPE from IT Corporation (IT) dated November 21, 1991 and January 2, 1992, the 1,500 gallon tank was removed on October 23, 1991. The required form for removal (Standard Reporting Form) was sent to the NJDEPE, Bureau of Underground Storage Tanks (BUST) on October 30, 1991.

Section 2.0 of this report describes the closure procedures, while Section 3.0 presents site assessment postexcavation soil sampling results. Section 4.0 presents conclusions and future actions. A completed Site Assessment Summary form is presented in Appendix A of this report. Tightness testing results and a site map are provided in Appendices B and C, respectively. Appendix D includes the analytical results for the postexcavation soil samples.

2.1 Tank Decommissioning

Shortly after the NJDEPE-Hotline was notified on September 19, 1991 concerning the discovery of contaminated soil near the 1,500 gallon UST, the contents of the tank were pumped out by MCC. In an effort to identify the cause of the discharge, approximately 1,000 gallons of clean water were then placed in the tank.

On October 4, 1991, Tanknology Corporation International tested the integrity of the tank only. It was found to be tight and the probable cause of contamination was concluded to be spillage during refueling and/or the piping and connections. The complete integrity test report is presented in Appendix B.

Decommissioning activities were initiated by IT Remediation Services (ITRS) and Lionetti Oil Recovery. A backhoe was used to excavate the area around the UST so that work could begin on cleaning and removing the tank. Approximately 1 cubic yard of soil demonstrating slightly elevated HNU readings was excavated staged on and covered with polyethylene sheeting.

On October 23, 1991, Lionetti Oil Recovery and ITRS pumped the water out of the tank, flushed the tank and piping with a low pressure steam cleaner, and then pumped out the rinsate and pumpable tank residuals. The specialty ordnance removal contractor, EOD Technology (EODT), excavated the area around the tank and using a chain and backhoe, hoisted the tank out of the excavation. It was then staged in a secured area adjacent to the excavation on plastic sheeting. The disconnected piping was located in an area not yet cleared of ordnance, and was therefore left in the ground.

2.2 Excavation Screening

Immediately after the UST and surrounding soils were removed, an HNU was used to screen the walls and floor of the excavation in order to determine possible "hot spots" for postexcavation sampling. All HNU readings in the excavation were low. There were no visible or sensory signs of leakage into the soil. No further excavation (other that needed to remove the tank) was conducted.

2.3 Site Assessment

A site plan of the entire facility can be found in Appendix C. This site plan was furnished by MCC, and it should be noted that Building 118 in Figure 1 is labeled Building 21 on the

MCC site plan. Three postexcavation soil samples and one field blank were collected on October 23, 1991, immediately following the tank removal. Figure 1 shows the location of the UST excavation and soil samples collected.

The minimum number of samples required by the September, 1990 BUST Closure Guidelines is three for a UST with a capacity of less than 2,000 gallons. The base of the excavation for the UST was approximately six feet below grade. Soil samples were collected along the center line of the tank outline, six inches below the base of the excavation. A cross-section of the excavation is shown in Figure 2. All samples were collected, labelled and transported according to NJDEPE protocol.

3.0 Site Assessment Results

Based on the fact that the tank stored No. 2 fuel oil, all three samples were analyzed for total petroleum hydrocarbons (TPHC). TPHC concentrations were not detected in Sample B-1. Samples B-2 and B-3 contained TPHC at concentrations of 950 milligrams per kilogram (mg/kg), and 3,900 mg/kg, respectively. Analytical results for postexcavation samples collected are presented in Appendix D.


Because of the elevated TPHC levels in samples B-2 and B-3 and the fact that additional soil excavation would be conducted for ordnance removal, the samples were not analyzed further for base neutral compounds (as per NJDEPE guidance then).


4.0 Conclusions and Future Actions

Sample B-3, with a TPHC concentration of 3,900 mg/kg, exceeded the current BUST action level of 1,000 mg/kg. Comparison of the individual concentrations detected in Samples B-1 and B-2 and with the results of the tank integrity test support the contention that the contamination is likely attributable to the piping connections at the north end of the tank.

In order to determine the extent of contamination, further soil removal and sampling beneath the former UST is proposed. This will be performed in conjunction with ordnance removal by EODT. In addition, all existing piping will be assessed as ordnance removal proceeds in this area. When excavation of unexploded ordnance surrounding the tank and piping is concluded, piping will be located, removed and disposed of properly. Additional samples will be collected for each 15 feet of piping, and analyzed for TPHC.

If groundwater is encountered during excavation and remediation of contaminated soil, a monitoring well will be installed, sampled and analyzed in accordance with NJ.A.C. 7:14B-9.2. However, if required, one will not be installed until after June 1, 1992 due to the presence of unexcavated ordnance. Groundwater analytical results will be included in the DICAR report to be submitted to NJDEPE by September 30, 1992. This report will address both this UST system and the 112 gallon gasoline UST removed on August 27, 1991 (Case No. 91-08-22-1645).





LAYER(S)

DATE INITIATED

12/13/91

DRAWING NUMBER

305788E1

4. SECTION B-B TAKEN FROM FIGURE 1.

APPENDIX A SITE ASSESSMENT SUMMARY

UST-014 291

STATE OF NEW JERSEY DEPARTMENT OF ENVIRONMENTAL PROTECTION

FOR STATE USE DALL

UST Dess Rec'd

TAS

Suff

DIVISION OF WATER RESOURCES BUREAU OF UNDERGROUND STORAGE TANKS TANK MANAGEMENT SECTION

> CN 029, 401 EAST STATE STREET TRENTON, N.J. 08625-0029

UNDERGROUND STORAGE TANK SITE ASSESSMENT SUMMARY

Under the provisions of the Underground Storage of Hazardous Substances Act in accordance with N.J.A.C. 7:148

This Summary form shall be used by all owners and operators of Underground Storage Tank Systems (USTS) who have either reported a release and are subject to the site assessment requirements of N.J.A.C. 7:148-8.2 or who have closed USTS pursuant to N.J.A.C. 7:14B-9.1 et seq. and are subject to the site assessment requirements of N.J.A.C. 7:14B-9.2 and 9.3.

INSTRUCTIONS:

- Fill in all applicable blanks. This form will require various attachments in order to complete the Summary. The technical guidance document, Interim Closum Requirements for UST's, explains the regulatory (and technical) requirements for closure and the Scope of Work Investigation and Corrective Action Requirements to: Discharges from Underground Storage Tanks and Piping Systems explains the regulatory (and technical) requirements for corrective action.
- Return one original of the form and all required attachments to the above address.
- Attach a scaled site diagram of the subject facility which shows the information specified in item IV B of this form.
- Explain any "No" or "N/A" response on a separate sheet.

Expient		Date of Submission_	January 13, 1992
		011 FACI	9829 LITY REGISTRATION #
	ITY NAME AND ADDRESS		
	Middlesex County College 155 Mill Road - P. C. Box 3050 Edison, NJ Shone No. (908) 906-2568	County_Middles	S P X
OWA.	IERS NAME AND ADDRESS, If different from above		_

11	DISCHARGE REPORTING REQUIREMENTS
	A. Was contamination found? X Yes No # Yes, Case No. 9-19-1559-04 (Note: All discharges must be reported to the Environmental Action Hotline (609) 292-7172)
	B. The substance(s) discharged was(were) No. 2 Fuel 0il
	C. Have any vapor hazards been mitigated?YesNo _X_N/A
III.	DECOMMISSIONING OF TANK SYSTEMS Closure Approval No. Fxempt *See II Corporation letter of November 21, 1991 letter of November 21, 1991
	The site assessment requirements associated with tank decommissioning are explained in the Technica: Guidance Document, Interim Closure Requirements for UST's, Section V. A-D. Attach complete documentation of the methods used and the results obtained for each of the steps of tank decommissioning used. Please include a site map which shows the locations of all samples and borings, the decommissioning used. Please include a site map which shows the locations of all samples and borings, the location of all tanks and piping runs at the facility at the beginning of the tank closure operation and annotated to differentiate the status of all tanks and piping (e.g., removed, abandoned, temporarily closed, etc.). The to differentiate the status of all tanks and piping (e.g., removed, abandoned, temporarily closed, etc.). The same site map can be used to document other parts of the site assessment requirements, if it is properly and legibly annotated.
IV.	SITE ASSESSMENT REQUIREMENTS
	A. Excavated Soil .
	Any evidence of contamination in excavated soil will require that the soil be classified as either Hazardous Waste or Non-Hazardous Waste. Please include all required documentation of compliance with the requirements for handling contaminated excavated soil (if any was present) as explained in the technical guidance documents for closure and corrective action. Describe amount of soil removed, its classification, and disposal location.
	B. Scaled Site Diagrams
	 Scaled site diagrams must be attached which include the following information:
	a. North arrow and scale b. The locations of the ground water monitoring wells c. Location and depth of each soil sample and boring d. All major surface and sub-surface structures and utilities e. Approximate properly boundaries f. All existing or closed underground storage tank systems, including appurtenant piping g. A cross-sectional view indicating depth of tank, stratigraphy and location of water table h. Locations of surface water bodies
	C. Soil samples and borings (check appropriate answer)
	1. Were soil samples taken from the excavation as prescribed?YesNoNA
	2. Were soil borings taken at the tank system closure site as prescribed?YesNoX_N A
	3. Attach the analytical results in tabular form and include the following information about each sample a. Customer sample number (keyed to the site map) b. The depth of the soil sample c. Soil boring logs d. Method detection limit of the method used e. QA/QC Information as required * See 1/92 closure report. (Appendix D and Figures 2 & 3)

I.

E

D. Ground Water Monitoring	
A CONTRACT MANAGEMENT WELL TO LANGUE WAS A CONTRACT OF THE CON	
1. Number of ground water monitoring wells installed	
Number of global water samples in tabular form, include the following Attach the analytical results of the ground water samples in tabular form, include the following	
information for each sample from each well:	
a. Site diagram number for each well installed	
b. Depth of ground water surface c. Depth of screened interval	
d. Method detection limit of the method used	
e. Weil logs	
f Well permit numbers	
g. QAQC information as required	
V. SOIL CONTAMINATION	
A. Was soil contamination found? X_YesNo	
M -Act Digate submet Onesign D-2	
H .NO." Diese gusmei Constitut o	
B. The highest soil contamination still remaining in the ground has been determined to be: B. The highest soil contamination still remaining in the ground has been determined to be: B. The highest soil contamination still remaining in the ground has been determined to be:	
2. N/A ppb total B/N. N/A (for non-petroleum substance)	
4. N/A ppb N/A (16) Non-patients	
The investigation was done on nro	perty
C. Remediation of free product contaminated soils boundary; only in UST excavation	. No off
to be a second to the second t	M site
and and an the property boundaries and above the water table	BILE
1. All free product contaminated soil on the property boundaries and above the water table are believed	pacts
1. All free product contaminated soil on the property boundaries and above the water table. 1. All free product contaminated soil on the property boundaries and above the water table. 1. All free product contaminated soil on the property boundaries and above the water table. 1. All free product contaminated soil on the property boundaries and above the water table. 1. All free product contaminated soil on the property boundaries and above the water table. 1. All free product contaminated soil on the property boundaries and above the water table. 1. All free product contaminated soil on the property boundaries and above the water table. 1. All free product contaminated soil on the property boundaries and above the water table. 1. All free product contaminated soil on the property boundaries and above the water table. 1. All free product contaminated soil on the property boundaries and above the water table. 1. All free product contaminated soil on the property boundaries and above the water table. 1. All free product contaminated soil on the property boundaries and above the water table. 1. All free product contaminated soil on the property boundaries and above the water table. 1. All free product contaminated soil on the property boundaries and above the water table. 1. All free product contaminated soil on the property boundaries and above the water table. 1. All free product contaminated soil on the property boundaries and above the water table. 1. All free product contaminated soil on the property boundaries and above the water table. 1. All free product contaminated soil on the property boundaries and above the water table. 1. All free product contaminated soil on the property boundaries and above the water table. 1. All free product contaminated soil on the property boundaries and above the water table. 1. All free product contaminated soil on the property boundaries and above the prope	pacts spected.
1. All free product contaminated soil on the property boundaries and above the water table. 1. All free product contaminated soils are suspected to exist below the water table. 2. Free product contaminated soils are suspected to exist off the property boundariesYes	pacts spected.
have been removed from the substitutes	spected.
have been removed from the substitute	spected.
have been removed from the substitute	spected.
have been removed from the substitute	spected.
2. Free product contaminated soils are suspected to exist below the water table? Yes X No 3. Free product contaminated soils are suspected to exist off the property boundaries. Yes X No D. Was the vertical and horizontal extent of contamination determined? Yes X No *See E. Does soil contamination intersect ground water? Yes No N/A *Unknown4.0 of Clo	spected.
2. Free product contaminated soils are suspected to exist below the Water table? Yes X No 3. Free product contaminated soils are suspected to exist off the property boundaries. Yes X No D. Was the vertical and horizontal extent of contamination determined? Yes X No NA *See E. Does soil contamination intersect ground water? Yes No NA *Unknown4.0 of Cloud Contamination intersect ground water? Yes No NA *Unknown4.0 of Cloud Contamination intersect ground water?	spected.
2. Free product contaminated soils are suspected to exist below the Water table? Yes X No 3. Free product contaminated soils are suspected to exist off the property boundaries. Yes X No D. Was the vertical and horizontal extent of contamination determined? Yes X No NA *See E. Does soil contamination intersect ground water? Yes No NA *Unknown4.0 of Cloud Contamination intersect ground water? Yes No NA *Unknown4.0 of Cloud Contamination intersect ground water?	Section sure Rpt
2. Free product contaminated soils are suspected to exist below the Water table? Yes X No 2. Free product contaminated soils are suspected to exist off the properly boundaries. Yes X No 3. Free product contaminated soils are suspected to exist off the properly boundaries. Yes X No	Section sure Rpt
2. Free product contaminated soils are suspected to exist below the Water table? Yes X No 3. Free product contaminated soils are suspected to exist off the properly boundaries. Yes X No D. Was the vertical and horizontal extent of contamination determined? Yes X No E. Does soil contamination intersect ground water? Yes No No VI. GROUND WATER CONTAMINATION A. Was ground water contamination found? Yes X No Unable to install wells due possibility of unexploded on the North Please answer Questions B-G. VI. See Section 4.0 of Closure in the North Please answer and Question B.	Section sure Rpt
2. Free product contaminated soils are suspected to exist below the Water table? Yes X No 3. Free product contaminated soils are suspected to exist off the properly boundaries. Yes X No D. Was the vertical and horizontal extent of contamination determined? Yes X No E. Does soil contamination intersect ground water? Yes No No VI. GROUND WATER CONTAMINATION A. Was ground water contamination found? Yes X No Unable to install wells due possibility of unexploded on the North Please answer Questions B-G. VI. See Section 4.0 of Closure in the North Please answer and Question B.	Section sure Rpt
2. Free product contaminated soils are suspected to exist below the Water 1209 Yes X No 3. Free product contaminated soils are suspected to exist off the properly boundaries. Yes X No 3. Free product contaminated soils are suspected to exist off the properly boundaries. Yes X No N/A D. Was the vertical and horizontal extent of contamination determined? Yes X No N/A *See E. Does soil contamination intersect ground water? Yes No N/A VI. GROUND WATER CONTAMINATION A. Was ground water contamination found? Yes X No Unable to install wells due possibility of unexploded on the Notation of the property boundaries. Yes X No N/A Unable to install wells due possibility of unexploded on See Section 4.0 of Closure See Section 4.0 of Cl	Section sure Rpt
2. Free product contaminated soils are suspected to exist below the water table? 3. Free product contaminated soils are suspected to exist off the property boundaries. D. Was the vertical and horizontal extent of contamination determined? Pes x* No	Section sure Rpt
2. Free product contaminated soils are suspected to exist below the water table? 2. Free product contaminated soils are suspected to exist off the property boundaries. 3. Free product contaminated soils are suspected to exist off the property boundaries. 4. Ves	Section sure Rpt
2. Free product contaminated soils are suspected to exist below the water table? Yes X No 3. Free product contaminated soils are suspected to exist off the property boundaries. Yes X No 3. Free product contaminated soils are suspected to exist off the property boundaries. Yes X No 3. Free product contaminated soils are suspected to exist off the property boundaries. Yes X No 3. No	Section sure Rpt
2. Free product contaminated soils are suspected to exist below the water table? Yes X No 3. Free product contaminated soils are suspected to exist off the property boundaries. Yes X No 3. Free product contaminated soils are suspected to exist off the property boundaries. Yes X No 3. Free product contaminated soils are suspected to exist off the property boundaries. Yes X No 3. No	Section sure Rpt
2. Free product contaminated soils are suspected to exist below the water table? Yes X No 3. Free product contaminated soils are suspected to exist off the property boundaries. Yes X No 3. Free product contaminated soils are suspected to exist off the property boundaries. Yes X No 3. Free product contaminated soils are suspected to exist off the property boundaries. Yes X No 3. No 4. Was the vertical and horizontal extent of contamination determined? Yes X No 4. Was 2. No 4. Was ground water contamination found? Yes X No 5. No 6. No 6. No 6. No 6. No 7. No 7. Please answer Questions 8. See Section 4.0 of Closure 1. No 7. Please answer only Question 8. See Section 4.0 of Closure 1. No 7. Please answer contamination at any 1 sampling location and at any 1 sampling event to date 1. No 7. Pob total BTEX 5. Pob total non-targeted WCC 5. Pob total MTBE, 5. Pob total TBA 7. Pob total MTBE, 5. Pob total TBA 7. Pob total MTBE, 5. Pob total TBA 7. Pob total MTBE, 7. Pob total MTBE, 7. Pob total TBA 7. Pob total MTBE, 7. Pob total MTBE, 7. Pob total TBA 7. Pob total MTBE, 7. Pob total MTBE, 7. Pob total TBA 7. Pob total MTBE, 7	Section sure Rpt
2. Free product contaminated soils are suspected to exist below the water table? Yes X No 3. Free product contaminated soils are suspected to exist off the property boundaries. Yes X No 3. Free product contaminated soils are suspected to exist off the property boundaries. Yes X No 3. Free product contaminated soils are suspected to exist off the property boundaries. Yes X No 3. No 4. Was the vertical and horizontal extent of contamination determined? Yes X No 4. Was 2. No 4. Was ground water contamination found? Yes X No 5. No 6. No 6. No 6. No 6. No 7. No 7. Please answer Questions 8. See Section 4.0 of Closure 1. No 7. Please answer only Question 8. See Section 4.0 of Closure 1. No 7. Please answer contamination at any 1 sampling location and at any 1 sampling event to date 1. No 7. Pob total BTEX 5. Pob total non-targeted WCC 5. Pob total MTBE, 5. Pob total TBA 7. Pob total MTBE, 5. Pob total TBA 7. Pob total MTBE, 5. Pob total TBA 7. Pob total MTBE, 7. Pob total MTBE, 7. Pob total TBA 7. Pob total MTBE, 7. Pob total MTBE, 7. Pob total TBA 7. Pob total MTBE, 7. Pob total MTBE, 7. Pob total TBA 7. Pob total MTBE, 7	Section sure Rpt
2. Free product contaminated soils are suspected to exist below the water table? Yes X No 3. Free product contaminated soils are suspected to exist off the property boundaries. Yes X No 3. Free product contaminated soils are suspected to exist off the property boundaries. Yes X No 3. Free product contaminated soils are suspected to exist off the property boundaries. Yes X No 3. No 4. Was the vertical and horizontal extent of contamination determined? Yes X No 4. Was 2. No 4. Was ground water contamination found? Yes X No 5. No 6. No 6. No 6. No 6. No 7. No 7. Please answer Questions 8. See Section 4.0 of Closure 1. No 7. Please answer only Question 8. See Section 4.0 of Closure 1. No 7. Please answer contamination at any 1 sampling location and at any 1 sampling event to date 1. No 7. Pob total BTEX 5. Pob total non-targeted WCC 5. Pob total MTBE, 5. Pob total TBA 7. Pob total MTBE, 5. Pob total TBA 7. Pob total MTBE, 5. Pob total TBA 7. Pob total MTBE, 7. Pob total MTBE, 7. Pob total TBA 7. Pob total MTBE, 7. Pob total MTBE, 7. Pob total TBA 7. Pob total MTBE, 7. Pob total MTBE, 7. Pob total TBA 7. Pob total MTBE, 7	Section sure Rpt to rdnance. Report.
2. Free product contaminated soils are suspected to exist below the water table? Yes X No 3. Free product contaminated soils are suspected to exist off the property boundaries. Yes X No X X No X X No X No X No X No X No	Section sure Rpt
2. Free product contaminated soils are suspected to exist below the Water Table? Yes X No 3. Free product contaminated soils are suspected to exist off the property boundaries. Yes X No D. Was the vertical and horizontal extent of contamination determined? Yes X No N/A	Section sure Rpt to rdnance. Report.
2. Free product contaminated soils are suspected to exist below the Water 1999 Ves X No 3. Free product contaminated soils are suspected to exist off the properly boundaries. Yes X No D. Was the vertical and horizontal extent of contamination determined? Yes X No	Section sure Rpt to rdnance. Report.
2. Free product contaminated soils are suspected to exist below the Water 1999 Ves X No 3. Free product contaminated soils are suspected to exist off the properly boundaries. Yes X No D. Was the vertical and horizontal extent of contamination determined? Yes X No	Section sure Rpt to rdnance. Report.
2. Free product contaminated soils are suspected to exist below the Water Table? Yes X No 3. Free product contaminated soils are suspected to exist off the property boundaries. Yes X No D. Was the vertical and horizontal extent of contamination determined? Yes X No N/A	Section sure Rpt to rdnance. Report.

T.

2/91	t description of
VIÏI.	TANK DECOMMISSIONING CERTIFICATION [person performing tank decommissioning portion of closure plan - N.J.A.C. 7:148-9.5(a)4]
	"I certify under penalty of law that tank decommissioning activities were performed in compliance with NJA.C. 7:14B-9.2(b)3. I am aware that there are significant penalties for submitting false, inaccurate, or incomplete information, including fines and/or imprisonment."
	NAME (Print or Type) J. DENNIS RECCA SIGNATURE DATE 1/15/92
	COMPANY NAME IT Corporation DATE 1/15/92 (Performer of Tank Decommissioning)
DX.	CERTIFICATIONS BY THE RESPONSIBLE PARTY(IES) OF THE FACILITY
	A. The following certification shall be signed by the highest ranking individual with everall responsibility for that facility [N.J.A.C. 7:148-2.3(c)11].
	"I certify under penalty of law that the information provided in this document is true, accurate, and complete. I am aware that there are significant penalties for submitting false. inaccurate, or incomplete information, including fines and/or imprisonment."
	NAME (Print or Type)SIGNATURE
	COMPANY NAME Middlesex County College DATE
	B. The following certification shall be signed as follows [according to the requirements of N.J.A.C. 7:14B-2.3(C)2i]:
	 For a corporation, by a principal executive officer of at least the level of vice president. For a partnership or sole proprietorship, by a general partner or the proprietor, respectively; or For a municipality, State, Federal or other public agency by either the principal executive officer or ranking
	elected official. 4. In cases where the highest ranking corporate partnership, governmental officer or official at the facility as required in A above is the same person as the official required to certify in B, only the certification in A specific be made. In all other cases, the certifications of A and B shall be made.
	"I certify under penalty of law that I have personally examined and am familiar with the information submitted in this application and all anached documents, and that based on my inquiry of those individuals immediately responsible for obtaining the information. I believe that the submitted information is true, accurate, and complete. I am aware that there are significant penalties for submitting false, inaccurate, or incomplete information, including fines and/or imprisonment."
	NAME (Print or Type)SIGNATURE
	DATE
	COMPANY NAME

471	
VIII.	TANK DECOMMISSIONING CERTIFICATION [person performing tank decommissioning portion of closure plan - N.J.A.C. 7:148-9.5(a)4]
	"I certify under penalty of law that tank decommissioning activities were performed in compliance with N.J.A.C. 7:14B-92(b)3. I am aware that there are significant penalties for submitting false, inaccurate, or incomplete information, including fines and/or imprisonment."
	NAME (Print or Type) SIGNATURE
	COMPANY NAMEIT_CorporationDATE
DX.	CERTIFICATIONS BY THE RESPONSIBLE PARTY/JES) OF THE FACILITY
	A. The following certification shall be signed by the highest ranking individual with oversit responsibility for that facility [N.J.A.C. 7:148-2.3(c)11].
	"I certify under penalty of law that the information provided in this document is true, accurate, and complete. I am aware that there are significant penalties for submitting false, inaccurate, or incomplete information, including fines and/or imprisonment."
	NAME (Print or Type) PAUL HILF SIGNATURE Pull Hof
	COMPANY NAME Middlesex County College DATE 1 16 92
	B. The following certification shall be signed as follows [seconding to the requirements of N.J.A.C. 7:148-2.3(C)21]:
	 For a corporation, by a principal executive officer of at least the level of vice president. For a partnership or sole proprietorship, by a general partner or the proprietor, respectively; or For a municipality, State, Federal or other public agency by either the principal executive officer or ranking elected official. In cases where the highest ranking corporate partnership, governmental officer or official at the facility as required in A above is the same person as the official required to certify in B, only the certification in A need to be made. In all other cases, the certifications of A and B shall be made.
•	"I certify under penalty of law that I have personally examined and am familiar with the information submitted in this application and all attached documents, and that based on my inquiry of those individuals immediately responsible for obtaining the information, I believe that the submitted information is true, accurate, and complete. I am aware that there are significant penalties for submitting false, inaccurate, or incomplete information, including fines and/or imprisonment."
	NAME (Print or Type) PAUL HILF SIGNATURE JULIAN
	COMPANY NAME MID DIEGEX COUNTY COLLEGE DATE 1/16/77

APPENDIX B TANKNOLOGY CORPORATION INTERNATIONAL TANK INTEGRITY TEST REPORT



VACUTECT^{T.M.} TANK TESTING REPORT

S.O.# 36440

Customer:	IT	Corr	orati	ion				Cust	. Ref. #_4	70360			Date: October 4, 1991
Billing Add	dress	<u>: 165</u>	Field	icrest	Aven	ie, Ed	dison, W	08837					Phone: (908) 225-2000
Service Ad	dres	s: Mid	ld1ese	ex Cou	nty C	ollege	,155 Mil	1 Road &	Woodbrid	ge,Edi	ison, N	J 088	37Attention: Barb Maginn
					TANK	TEST	Г			· ·	LI	NE	COMMENTS: Note alterations or repairs!
Tank # and Date Tested. See Diagram For Location. DATE/TANK #	TYPE PROD.	TANK DIA.	TANK GAL.	Water	Dipped Prod. Level START	Rec. Water Level START	Water Ingress Detected At Computer Time HR/MIN	Bubble Ingress Detected At Computer Time HR/MIN	Ullage Air Ingress Detected At Computer Time HR/MIN	TIGHT (T) or FAIL (F)	TANK # LINE A,B,C.	TIGHT (T) or FAIL (F)	TANKS and LINES TESTED TO CFR# 40, Parts 280-281 & NFPA329 Specifications. Others: SUCTION (SS) or PRES. SYSTEM (PS) FIBERGLASS (FG) or STEEL (ST) LEAK DETECTORS Installed ? (LDI)
#1 10/4/91	WTR	64	1500	<u>49.5</u> 49.5	49.5 49.5	1.38 1.38	NO	NO	NO	Т			
						<u></u>		!					
•			<u> </u>										
									ļ.			ļ	IT CORPORATION ON NEW JERSEY
	,		ļ	<u> </u>						 	 	<u> </u>	IT CORPORATION DERSEY
		!						<u>.</u>			ļ	<u> </u>	
		<u> </u>	<u>'</u>									 	OCT + 7 1991
													DM 100 alex lou
:	ı					!			·				RECEIVED BY: 133 G29 OV
	is .												JOB No.
<u> </u>	,						<u> </u>			i			
TANKNOLO	GY SE	RVICE	E DIVIS	SION:_	Nort	heast	994	U	NIT #	46			TANKNOLOGY CORPORATION INTERNATIONAL 5225 Hollister St. • Houston, TX 77040-6294

5225 Hollister St. • Houston, TX 77040-6294 (713) 690-8265 • Fax: (713) 690-2255

D# <u>3</u>	6440		_ Cu	st. <u>-'</u>	(076	MATO	<u>v · </u>		_ Sit	e#		
ONITO	R WEI	LLS											
	umber	_1_	_2_	_3	4	5	6	7	8	9	10	_11_	12
	Depth		1,000		ļ	ļ	-\	 					
	Water				ļ	-		-					
	tected T Det.		+			 	-						
	on D	iagi	ram	l			J.,	J			<u> </u>		ł
ocau		146	am	•	•	•	•	•	•	•	ľ	•	•
•	•	• ,	. .	•	•	٠ ر	diegr	13/dg	•	•	•	•	•
•	•	•		•	•	•	•		•	•	•	•	•
•	•	•	l_ :_				I				٠ا	•	•
•	•	•	•	•	•	•	•	•	•	•	•	•	•
•	•	•	•	•	•	•	13	1500 6	in.	•	•	•	•
•	•	•	•	•	•.	•	154	· WATE		•	•	•	•
•	•	•	•	•	•	•	•	•	•	•	•	•	•
•	•	•	•	•	•	•	•	•	•	•	•	•	•
•	•	•	•	•	•	•	•	•	•	•	• "	.•	•
•	•	•	•	•	•	•	•	•	•	•	•	•	•
•	•	•	. •	•	•	•	•	•	•	•	•	•	•
•	•	•	•	•	•	•	•	•	•	•	•	•	•
•	•	•	•	•	•	•	•	•	•	•	•	•	•
·	٠.	····											
neral wk u r. w. c y c /d) St. ::	Commo	ents	7 NA (Viai 5 Viai 4 9 Viai 4 9	1 1 1 1 2 2 1 2 3 1 1 5 1 1	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	(17 (12)	11 WE 1-16-14	-Nico Arrixi Izo S	LINT. LIX VICE	Est.	tion his	1000	E 17 .
en loca PORT	d regulared to:	ativa	s requi		Cdiate Neme	}			cm lea	k-Con	nplete (Time	
	INT	13	10 - e			J. NUL			OIS:	<i>(</i>)		4-116	
	Red Teste			1,1 4#			Vac	tect ^{IH} C			mber		
	Inc		Cere i					2/4/	,				
1	· · · · · · · · · · · · · · · · · · ·		<u>C </u>								Form-		

Certifi	cate of Tight	Y CORPORATION IN Phone: (713) 690-TANI Phone	Fax: (713) 690-2255 Test date 10/4/91
() Tan	k(s) & Piping,	[1] Tank(s) Only,	[0] Piping only.
		iddlesex County College ill Road & Woodbridge, Ediso	on, NJ 08837
Tank size	es & products test	ted Tank #1 Water 1500 Ga	a1.
Piping Te	ested		
#0190	09/23/93	Chan Ken	
U. S. Patent # 44 TANKNOLOGY & V		Unit Mgr. Signature 5693. European Patent Appl. 9 169263 NOLOSY CORPORATION INTERNATIONAL Int. Identification and alte location drawing.	Valid only with Corporate Seal

APPENDIX D ANALYTICAL RESULTS



ANALYTICAL **SERVICES**

CERTIFICATE OF ANALYSIS

Raritan Arsenal

Date: October 29, 1991

c/o IT Corp.

165 Fieldcrest Ave.

Edison, NJ 08837

Attn: Ms. Barbara Maginn

NJ Lab Certification ID#: 12064

Job No.: 305788 P.O. Number: 082691-B

This is the Certificate of Analysis for the following samples:

Client Project ID: SOIL

Date Received:

10/23/91

Number of Samples: 4

Sample Type:

SOIL

I Samples were labeled as follows:

SAMPLE IDENTIFICATION	LABORATORY #
B-1/0-6"/SOIL	F1-10-223-01
B-2/0-6"/SOIL	F1-10-223-02
B-3/0-6"/SOIL	F1-10-223-03
FIELD BLANK	F1-10-223-04

Reviewed and Approved:

Project Manager

Page: 2

Company:

Raritan Arsenal

Date:

October 29, 1991

Client Job No.: 305788

IT ANALYTICAL SERVICES EDISON, NJ

(201) 225-2000

Work Order: F1-10-223

SAMPLE ID	B-1/0	-6"/SOIL	B-2/0	-6"/SOIL	B-3/0	-6"/SOIL	
SAMPLED EST		10/23/91	······································	10/23/91		10/23/91	UNITS
etroleum Hydrocarbons	ŧ	ND 24]	t -	950 480]	t	3900 480]	mg/Kg Dry Wt
otal Solids	t	85 0.01]	t	83 0.01]	t	84 0.01]	Percent

ND indicates the parameter was not detected. Detection limits are specified in [].

Page: 3

Company: Date:

Raritan Arsenal

October 29, 1991

Client Job No.: 305788

IT ANALYTICAL SERVICES

EDISON, NJ (201) 225-2000

Work Order: F1-10-223

SAMPLE ID	FIELD BLANK		
SAMPLED TEST	10/23/91		UNITS
Petroleum Hydrocarbons	ND [1.0]		mg/L
•	, 5,5,	••	
·			
		•	

ND indicates the parameter was not detected. Detection limits are specified in [].

Page: 4

Company:

Raritan Arsenal

Date:

October 29, 1991

Client Job No.:

305788

IT ANALYTICAL SERVICES EDISON, NJ (201) 225-2000

Work Order: F1-10-223

II ANALYTICAL RESULTS/METHODOLOGY

The analytical results for this report are presented by Analytical test. Each set of data will include sample identification information, the analytical results, and the appropriate detection limits. Detection limits may vary due to factors arising from concentration/dilution of the sample and sample matrix. ND denotes that the compound is not detected at or above the indicated detection limit. The methodologies for the analytical results requested are described below.

Petroleum Hydrocarbons - IR

The analysis of petroleum hydrocarbons is based on EPA Method, 418.1. Water samples are prepared by separatory funnel liquid-liquid extraction using freon as the extracting solvent. Soils are prepared by soxhlet extraction using freon as the extracting solvent. Silica gel is added to remove interferences. Extracts are analyzed by infrared spectrophotometer and concentrations are determined by direct comparison with standards.

Petroleum Hydrocarbons - IR

The analysis of petroleum hydrocarbons is based on EPA Method, 418.1. Water samples are prepared by separatory funnel liquid-liquid extraction using freon as the extracting solvent. Soils are prepared by soxhlet extraction using freon as the extracting solvent. Silica gel is added to remove interferences. Extracts are analyzed by infrared spectrophotometer and concentrations are determined by direct comparison with standards.

Total Solids

The analysis of total solids is based on Standard Methods, 16th Edition - (209F). A well mixed sample is evaporated in a weighed dish and dried to constant weight. The increase in weight over that of the empty dish represents the total solids.

III QUALITY CONTROL

The Determinations were performed in accordance with EPA/NJDEP approved methodology.

DEFINITIONS

- ND(U) Analyte was analyzed for, but not detected. The value given after the ND or U is the detection limit for that compound.
 - A The compound denoted with an "A" indicates a suspected aldol condensation product.
 - B Indicates the compound was also detected in the blank, but at levels less than SX the detection limit. Values for this compound may be suspect
 - J Indicates the compound was detected in the sample, but at levels less than the detection limit.

 Results should be regarded as estimated.

MS - Matrix Spike ug/L - Micrograms/Liter %ReC - Precent Rec	MS - Matrix Spi	ug/L - Micro	grams/Liter
--	-----------------	--------------	-------------

MSD - Matrix Spike Duplicate ug/Kg - Micrograms/Kilogram mg/L - Milligrams/Liter

RPD - Relative Percent Difference mg/Kg - Milligrams/Kilogram DL - Detection Limit

QUALITY CONTROL WINDOWS

Surrogate Recoveries			Surrogate Recoveries				
CAS Volatiles (624, 8240)	Water	So11_	CC/MS SemiVolatiles (625, 827)		Soil		
D4-1,2-dichloroethers	76-114	70-121	D5-Nitroberzere	35-114	23-120		
D8-toluene	88-110	81-117	2-Fluorobiphenyl	43-116	30-115		
4-Bromofluorobergene	86-115	74-121	D14-Terphenyl	33-141	18-137		
			D5-Phenol	10-94	24-113		
			2-Fluorophenol	21-100	25-121		
			2,4,6-Trobromophenol	10-123	19-122		
Surrogate Reco	æries		Surrogata Recov	ries			
Pesticides* (608, 8080)	Water	Sol1	Method 602, BTEX, 8020	Vater	Soi1		
.Tetrachloro-m-xylene	60-150	60-150	4-Brosofluoroberzers	62-139	62-138		
Dibutyl chlorendate	24-154	20-150	- · · · · · · · · · · · · · · · · · · ·				

^{*} SAB46 allows one surrogate to be outside recovery windows.

Surrogate Recoveries			Surrogate Recoveries			
Method 601 (8010)	Water	Soil Soil	Method 8060**	Water	Soil.	
Bromochloromethane	74-121	74-121	Tetrachloro-m-xylems	60-150	60-150	
			Decachlorobiphenyl	60-150	60-150	
Method 8015	Water	So11	Herbicides**	Water	Soil	
Acetone	68-132	68-132	2.4-DB	60-150	60-150	
			** Adviso	xry Limits		
METALS / WET CHEMISTRY						
	Recovery	RED		Recovery	RFD	
Lank Spike	75-125		Replicate		<20€	
Blank Spike Duplicate	75-125	<20€	Check Standard	90-110		
Matrix Spiles	75-125					
Matrix Spike Duplicate	75-125	<20€				

GASOLINE TANK CLOSURE REPORT

PREPARED FOR:

US ARMY CORPS OF ENGINEERS
FORMER RARITAN ARSENAL
P.O. BOX 6433
EDISON NJ 08818-6433

PREPARED BY:

IT CORPORATION
P.O. BOX 7809
EDISON, NEW JERSEY 08818-7809

NOVEMBER 1991

PROJECT NO. 305788/027



November 27, 1991

Project No. 305788

Mr. Matthew McDermott
Bureau of Underground Storage Tanks
Division of Responsible Party Site Remediation
New Jersey Department of Environmental
Protection and Energy
CN 029
Trenton, New Jersey 08625-0029

Gasoline Tank Closure Report

Middlesex County College, Edison, NJ

Case No. 91-08-22-1645; UST No. 0119829

Dear Mr. McDermott:

Enclosed for your review are two copies of the above-referenced report, prepared in accordance with N.J.A.C. 7:14B-9.5. As stated in my November 21, 1991 letter, this 112 gallon underground storage tank (UST) was removed on August 27, 1991 as part of the U.S. Army Corps of Engineers (USACE) Ordnance Removal project at the former Raritan Arsenal.

Postexcavation soil samples were collected after the gasoline UST was removed and the analytical results are included in this Closure Report. According to the September 1990 Closure Guidelines, a monitoring well is required because the former UST stored gasoline. Due to the presence of unexcavated ordnance in the immediate vicinity of the former UST, it is impossible to safely install a monitor well within the standard 90 day period for completing a Closure Report. Consequently, this report includes soil results only. The monitor well will be installed after ordnance removal is complete, which should be by June 1, 1992. The groundwater sample results will be included in the DICAR report to be submitted by September 30, 1992.

Also in accordance with the Closure Guidelines, the 112 gallon UST, previously unknown to Middlesex County College, was registered with NJDEPE on September 16, 1991. At that

time, Middlesex County College was understood to be the owner of this tank. It has since been determined that the USACE owned the tank; a Standard Reporting Form indicating this is included as part of the enclosed closure report.

Please contact me or Lapyan Chan at (908) 225-2000 if you have any questions or would like to discuss.

Very truly yours,

IT CORPORATION

Barbara Maginn, P.E. Sr. Project Engineer

BM:lh

305788-029-01-001

CC:

B. Bauman - USACE

P. Dalal - USACE

P. Hilf - Middlesex Co. College

L. Chan - IT

C. Magilson - IT

File 305788

Table of Contents_

1.0	Introduction
2.0	Closure Activities
	2.1 Tank Decommissioning
	2.2 Excavation Screening
	2.3 Site Assessment
3.0	Site Assessment Results
4.0	Conclusion and Future Actions
•••	
l iei	t of Tables
ĻI3(· · · · · · · · · · · · · · · · · · ·
1	Postexcavation Analytical Results
List	t of Figures
1	Postexcavation Sample Locations
2	Cross-Sectional View 112-Gallon
	Gasoline UST Removal
l iei	t of Appendices
LIS	oi Appeliaices
A	Site Assessment Summary
B C	Middlesex County College Site Plan
	Standard Reporting Form

1.0 Introduction

On August 22, 1991, a 112 gallon underground storage tank (UST) containing leaded gasoline was uncovered behind Building 118 at Middlesex County College (MCC), located in Edison, New Jersey. The tank's existence was unknown to the MCC administration, and was uncovered when contractors for the U.S. Army Corps of Engineers (USACE) Ordnance Removal project encountered it during their excavation of the area. Because gasoline odors were noted in the soils surrounding the UST and holes were observed in the top and sides of the UST, the New Jersey Department of Environmental Protection and Energy (NJDEPE) hotline was notified that day. NJDEPE assigned Case No. 91-8-22-1645-09.

The 112 gallon tank was removed on August 27, 1991. The forms for registration and removal (Standard Reporting Form) were sent to the NJDEPE, Bureau of Underground Storage Tanks (BUST) on September 16, 1991. The following closure activities were undertaken for this tank: cleaning, removal and disposal; postexcavation soil sampling and analysis; and completion of this closure report.

2.0 Closure Activities

2.1 Tank Decommissioning

Decommissioning activities were initiated by IT Remediation Services (ITRS) by pumping the residual gasoline from the UST into a 55 gallon drum. The tank was then cleaned with a high pressure water jet and the rinsate was drummed. The specialty ordnance removal contractor, EOD Technology (EODT), hand dug around the tank to expose it for removal. Approximately 0.5 cubic yards of impacted soils from around the UST were also removed and placed in two 55 gallon drums.

The UST was removed as follows: one 3/4-inch diameter pipe connected to the top of the UST and running into the south wall of the excavation (towards the building) was cut and both ends were crimped. Each end was then folded over itself three times to seal it. No product was found in or around the piping. The disconnected piping was left in the ground because it is located in an area not yet cleared of ordnance. ITRS used chains and a backhoe to lift the tank out of the excavation, and placed it on plastic sheeting. ITRS removed the tank from the site the same day for proper disposal.

2.2 Excavation Screening

Immediately after the UST was removed, an HNU was used to screen the walls and floor of the excavation in order to determine possible "hot spots" for postexcavation sampling. No additional samples other than the three collected for the site assessment were required as all HNU readings were low.

2.3 Site Assessment

Three postexcavation soil samples and one field blank were collected on August 27, 1991, immediately following the tank removal. Figure 1 shows the location of the UST excavation and soil samples collected from the base of it. A site plan of the entire facility can be found in Appendix B. This site plan was furnished by MCC, and it should be noted that Building 118 in Figure 1 is labeled Building 21 on the MCC site plan.

The minimum number of samples required by the BUST is three for a UST with a capacity of less than 2000 gallons. The base of the excavation for this 112 gallon UST was five feet below grade. Soil samples were collected along the center line of the tank outline, 6" below the base of the excavation. The three samples are spaced 1.5 feet apart. A cross section of the excavation is shown in Figure 2.

After sample collection was complete the hole was lined with PVC plastic and backfilled with clean soil.

3.0 Site Assessment Results

According to the NJDEPE Closure Guidelines, postexcavation soil samples for gasoline UST closures must be analyzed for volatile organic compounds with a forward library search (VO+15), xylene and lead. Due to the fact that the tank had been out of service for longer than 12 months and the gasoline stored was suspected of being leaded, the soil samples were also analyzed for Total Petroleum Hydrocarbons (TPHC) and Base Neutrals (B/N) +15. As required by the NJDEPE's Closure Guidelines, the lead was analyzed by "Test Methods for Evaluating Solid Waste", USEPA SW846. The levels of TPHC, B/N +15, xylene, and VO+15 were all non-detectable. Sample B1 had a lead concentration of 24 ppm; B2, a lead concentration of 28 ppm; and B3, a lead concentration of 20 ppm. All three of these samples are well below the NJDEPE guidelines of 250 ppm for lead in soil (non-industrial areas).

The concentration of base neutral library search compounds in samples B2 and B3 were 14.9 ppm and 62.0 ppm respectively. These levels exceeded the NJDEPE guideline for priority pollutant base neutral compounds of 10 ppm. All analytical results are presented in Table 1.

TABLE 1 POSTEXCAVATION ANALYTICAL RESULTS 112 GALLON UST REMOVAL FORMER RARITAN ARSENAL MIDDLESEX COUNTY COLLEGE EDISON, NEW JERSEY

SAMPLE	TPH (ppm)	BASE NEUTRALS (ppb)	BASE NEUTRALS LIBRARY SEARCH * (ppb)	VOC (ppb)	VOA LIBRARY SEARCH • (ppb)	LEAD (ppm)
В1	ND [22]	ND [370]	2,700 (B) 1,220	ND-1	ND-2	24 [2.2]
B2	ND [24]	ND [400]	14,910	ND-1	11	28 [2.4]
В3	ND [24]	ND [390]	62,020 (B) 2,030	ND-1	30	20 [2.4]
Field Blank	ND [1.0]	ND [10].	18	ND [5]	ND-2	ND [0.005]

NOTES:

Sample Date: 08-27-91

Excavation Depth: 5' below ground surface.

Sample Depth: 6" below bottom of excavation.

B: Indicates the compound was also detected in the blank, but at levels less than 5x the detection limit. Values for this compound may be suspect.

ND: Analyte was analyzed for, but not detected.

[]: Detection limit

•: Library Search does not have detection limits.


1: Detection limit varied between 6 and 60, with the majority being 6.


2: No non-targeted compounds found.

Numbers in bold are above NJDEPE Guidelines

4.0 Conclusions and Future Actions

Based on the fact that the postexcavation analytical results were either non-detectable or below NJDEPE action levels, no further excavation was conducted or is planned near the former 112 gallon gasoline UST. According to the Closure Guidelines, a monitoring well is required because the UST stored gasoline. Due to the presence of unexcavated ordnance, a monitoring well cannot be installed until after June 1, 1992. Groundwater analytical results will be included in the DICAR report to be submitted to NJDEPE by September 30, 1992.





LIST-D14 291

STATE OF NEW JERSEY DEPARTMENT OF ENVIRONMENTAL PROTECTION

DIVISION OF WATER RESOURCES BUREAU OF UNDERGROUND STORAGE TANKS TANK MANAGEMENT SECTION

> CN 029, 401 EAST STATE STREET TRENTON, N.J. 08625-0029

UNDERGROUND STORAGE TANK SITE ASSESSMENT SUMMARY

Under the provisions of the Underground Storage of Hazardous Substances Act In accordance with N.J.A.C. 7:148

This Summary form shall be used by all owners and operators of Underground Storage Tank Systems (USTS) who have afther reported a release and are subject to the site assessment requirements of N.J.A.C. 7:148-8.2 or who have closed USTS pursuant to N.J.A.C. 7:148-9.1 et seq. and are subject to the alse assessment requirements of N.J.A.C. 7:148-9.2 and 9.3.

INSTRUCTIONS

- Piease pant legibly or type.
- Fill in all applicable blanks. This form will require various attachments in order to complete the Summary. The technical guidance document. Interim Closure Requirements for UST's, explains the regulatory (and technical) requirements for closure and the Scope of Work Investigation and Corrective Action Requirements to Exchange from Underground Storage Tanks and Pipmo Systems explains the regulatory (and technica) requirements for corrective action.
- Return one original of the form and all required attachments to the above address.
- Attach a scaled site diagram of the subject facility which shows the information specified in Rem \mathbb{R}' B of this form
- Explain any "No" or "N/A" response on a separate sheet.

0119829

FACILITY REGISTRATION .

FOR STATE USE DALY

ĽSŤ Ø

TAG I Suff

Day Res

		V-1-1-1-1	
Į.	FACILITY NAME AND ADDRESS		
	Middlesex County College	`	
	Telephone No. (908) 906-2568	County_Middlesex	
	OWNER'S NAME AND ADDRESS, I different from	above .	
	U.S. Army Corps of Engineers		
	Former Raritan Arsenal	00010-6433	
	P.O. Box 6433, Edison New Jersey Telephone No. (908)603-9517	TIAN IN COLUMN	

A1	
11.	DISCHARGE REPORTING REQUIREMENTS
	A. Was contamination found? X Yes No E Yes, Case No. 91-08-22-1645 (Note: All discharges must be reported to the Environmental Action Hotline (609) 292-7172)
	The substance(s) discharged was(were)
	C. Have any vapor hazards been mitigated?YesNoNA
	Closure Approval No
111.	The site assessment requirements associated with tank decommissioning are explained in the Technical The site assessment requirements associated with tank decommissioning are explained in the Technical Guidance Document, InterIm Closure Requirements for USTs, Section V. A-D. Attach complete Guidance Document, InterIm Closure Requirements obtained for each of the steps of tank documentation of the methods used and the results obtained for each of the steps of tank document and borings, the decommissioning used. Please include a site map which shows the locations of all samples and annotated location of all tanks and piping runs at the facility at the beginning of the tank closure operation and annotated location of all tanks and piping runs at the facility at the beginning of the tank closure operation and annotated location of all tanks and piping (e.g., removed, abandoned, temporarily closed, etc.). The to differentiate the status of all tanks and piping (e.g., removed, abandoned, temporarily closed, etc.). The to differentiate the status of all tanks and piping (e.g., removed, abandoned, temporarily closed, etc.). The to differentiate the status of all tanks and piping (e.g., removed, abandoned, temporarily closed, etc.). The to differentiate the status of all tanks and piping (e.g., removed, abandoned, temporarily closed, etc.).
IV.	SITE ASSESSMENT REQUIREMENTS
	A. Excavated Soil .
•	A. Excavated Soil. Any evidence of contamination in excavated soil will require that the soil be classified as either Hazardous Any evidence of contamination in excavated soil will required documentation of compliance with the Waste or Non-Hazardous Waste. Please include all required documents for handling contaminated excavated soil (if any was present) as explained in the termical requirements for handling contaminated excavated soil (if any was present) as explained in the termical requirements for handling contaminated excavated soil (if any was present) as explained in the termical requirements for handling contaminated excavated soil (if any was present) as explained in the termical requirements for handling contaminated excavated soil will require that the soil be classified as either Hazardous and the soil requirements for handling contaminated excavated soil will require documentation of compliance with the termical requirements for handling contaminated excavated soil (if any was present) as explained in the termical requirements for handling contaminated excavated soil (if any was present) as explained in the termical requirements for handling contaminated excavated soil (if any was present) as explained in the termical requirements for handling contaminated excavated soil (if any was present) as explained in the termical requirements for handling contaminated excavated soil (if any was present) as explained in the termical requirements for handling contaminated excavated soil (if any was present) as explained in the termical requirements for handling contaminated excavated soil (if any was present) as explained in the termical requirements for handling contaminated excavated soil (if any was present) as explained in the termical requirements for handling contaminated excavated soil (if any was present) as excavated as e
	B. Scaled Site Diagrams
	Scaled site diagrams must be attached which include the following information:
	b. The locations of the ground water and boring
	An maint during and supporting
	Approximate property All existing or closed underground storage tank systems, excuting apparatus All existing or closed underground storage tank, stratigraphy and location of water table A cross-sectional view indicating depth of tank, stratigraphy and location of water table
	h. Locations of surface water bodies
	C. Soil samples and borings (check appropriate answer)
	C. Soil samples and sorings (creat type properties as prescribed? X YesNoNA 1. Were soil samples taken from the excervation as prescribed? X YesNoNA
	Were soil borings taken at the tank system closure site as prescribed? X YesNoN A Were soil borings taken at the tank system closure site as prescribed? X YesNoN A
	i cital mouths in tabular form and include the topowing and include the
	A PINIONAL PRIMAR INCIDENT INC
	b. The depth of the soil sample *See 11/91 Closure 10/91
	A Marked detection time of the matthes are
	e. QAQC Information as required

I

	information for each sample from each well:	
	a. Site diagram number for each well installed b. Depth of ground water surface c. Depth of acreened interval d. Method detection limit of the method used	*Unable to install wells due to unexcavated ordnance. See 11-27-91 coverletter to 11/91 closure report.
	e. Well isos	
	1. Well permit numbers	•
	g. QA/QC Information as required	
	SOIL CONTAMINATION	
	A. Was soil contamination found? X Yes No No Y'Yes', please answer Question B-E	
	# "No", please answer Question 8	
	B. The highest soil contamination still remaining in the g	round has been determined to be:
	1 Non-Detect pop tetal STEX. 30	200 baternan later deg
	2. Non-Detect pob total BN. 62.1	ppb texal non-targeted B/N
	3. Non-Detect com TPHC	(for non-pietroleum substance)
	4	(is non-pairoleum succiarios)
	C. Remediation of free product contaminated soils	
	All free product contaminated soil on the property have been removed from the subsurface. X Ye	y boundaries and above the water table are believed to
	2. Free product contaminated soits are suspected to	To Calculate the standards Man V Ale
		exist delow the water ladie Yes A. No
	3. Free product contaminated soils are suspected to	exist off the property boundariesYes No
	Free product contaminated soils are suspected to D. Was the vertical and horizontal extent of contamination	exist off the property boundaries. Yes No
	3. Free product contaminated soils are suspected to	exist off the property boundaries
1.	Free product contaminated soils are suspected to D. Was the vertical and horizontal extent of contamination	exist off the property boundariesYesNo in determined? X_YesNoN/A
l.	Tree product contaminated soils are suspected to D. Was the vertical and horizontal extent of contamination. E. Does soil contamination intersect ground water? GROUND WATER CONTAMINATION A. Was ground water contamination found? Yes.	exist off the property boundaries
	3. Free product contaminated soils are suspected to D. Was the vertical and horizontal extent of contamination E. Does soil contamination intersect ground water? GROUND WATER CONTAMINATION A. Was ground water contamination found? If "Yes", please answer Questions B-G.	* No *Not able to install wells due unexcavated ordnance. See
•	Tree product contaminated soils are suspected to D. Was the vertical and horizontal extent of contamination. E. Does soil contamination intersect ground water? GROUND WATER CONTAMINATION A. Was ground water contamination found? Yes.	exist off the property boundaries
1.	3. Free product contaminated soils are suspected to D. Was the vertical and horizontal extent of contamination E. Does soil contamination intersect ground water? GROUND WATER CONTAMINATION A. Was ground water contamination found? If "Yes", please answer Questions B-G.	* No *Not able to install wells due unexcavated ordnance. See coverletter closure report.
	3. Free product contaminated soils are suspected to D. Was the vertical and horizontal extent of contamination E. Does soil contamination intersect ground water? GROUND WATER CONTAMINATION A. Was ground water contamination found? If "Yes", please answer Questions 3-G. If "No", please answer only Question 3. B. The highest ground water contamination at any 1 sail been determined to be: 1. and total STEX.	* No *Not able to install wells due unexcavated ordnance. See coverletter closure report. ** Incompling leastion and at any 1 sampling event to date has
	3. Free product contaminated soils are suspected to D. Was the vertical and horizontal extent of contamination E. Does soil contamination intersect ground water? GROUND WATER CONTAMINATION A. Was ground water contamination found? If "Yes", please answer Questions B-G. If "No", please answer only Question B. B. The highest ground water contamination at any 1 sail been determined to be: 1	* No *Not able to install wells due unexcavated ordnance. See coverletter closure report. ** pob total non-targeted BN
	3. Free product contaminated soils are suspected to D. Was the vertical and horizontal extent of contamination E. Does soil contamination intersect ground water? GROUND WATER CONTAMINATION A. Was ground water contamination found? If "Yes", please answer Questions B-G. If "No", please answer only Question B. B. The highest ground water contamination at any 1 sailbeen determined to be: 1	* No *Not able to install wells due unexcavated ordnance. See coverletter closure report. ** Incompling location and at any 1 sampling event to date has peb total non-targeted \$N - Spot total TBA
l.	3. Free product contaminated soils are suspected to D. Was the vertical and horizontal extent of contamination E. Does soil contamination intersect ground water? GROUND WATER CONTAMINATION A. Was ground water contamination found? If "Yes", please answer Questions B-G. If "No", please answer only Question B. B. The highest ground water contamination at any 1 sail been determined to be: 1	* No *Not able to install wells due unexcavated ordnance. See coverletter closure report. mpling location and at any 1 sampling event to date has pob total non-targeted 8/N pob total non-targeted 8/N pob total TBA (for non-potroleum substance)
1.	3. Free product contaminated soils are suspected to D. Was the vertical and horizontal extent of contamination E. Does soil contamination intersect ground water? GROUND WATER CONTAMINATION A. Was ground water contamination found? If "Yes", please answer Questions B-G. If "No", please answer only Question B. B. The highest ground water contamination at any 1 sailbeen determined to be: 1	* No *Not able to install wells due unexcavated ordnance. See coverletter closure report. mpling location and at any 1 sampling event to date has per total non-targeted B/N per total TBA (for non-petroleum substance)
1.	3. Free product contaminated soils are suspected to D. Was the vertical and horizontal extent of contamination E. Does soil contamination intersect ground water? GROUND WATER CONTAMINATION A. Was ground water contamination found? If "Yes", please answer Questions B-G. If "No", please answer only Question B. B. The highest ground water contamination at any 1 sail been determined to be: 1	* No *Not able to install wells due unexcavated ordnance. See coverletter closure report. mpling location and at any 1 sampling event to date has per total non-targeted B/N per total TBA (for non-petroleum substance)
'1.	3. Free product contaminated soils are suspected to D. Was the vertical and horizontal extent of contamination E. Does soil contamination intersect ground water? GROUND WATER CONTAMINATION A. Was ground water contamination found? If "Yes", please answer Question B. If "No", please answer only Question B. B. The highest ground water contamination at any 1 samples determined to be: 1	* No *Not able to install wells due unexcavated ordnance. See coverletter closure report. mpling location and at any 1 sampling event to date has pob total non-targeted B/N pob total non-targeted B/N pob total TBA (for non-petroleum substance) nd YesNoN/A
11.	3. Free product contaminated soils are suspected to D. Was the vertical and horizontal extent of contamination E. Does soil contamination intersect ground water? GROUND WATER CONTAMINATION A. Was ground water contamination found? If "Yes", please answer Question B. If "No", please answer only Question B. B. The highest ground water contamination at any 1 sail been determined to be: 1	* No *Not able to install wells due unexcavated ordnance. See coverletter closure report. mpling location and at any 1 sampling event to date has pob total non-targeted B/N pob total non-targeted B/N pob total TBA (for non-potroleum substance) md YesNoN/A

D. Ground Water Monsoring

1. Number of ground water mentoring wells installed ___


Vli

D. Preximity of wells and contaminant plume N/A
1. The shallowest depth of any well noted in the well search which may be in the horizontal or vertical potential path(s) of the contaminant plume(s) is
2. The shallowest depth to the top of the well acreen for any well in the actential path of the plume(s) (as described in D1 above) istest below grade. This well is tecessedtest from the source
3. The closest horizontal distance of a private, commercial or municipal well in the potential path of the plume (as determined in D1) istest from the source. This well is test deep and acreening begins at a depth oftest.
E. A plan for separate phase product recovery has been includedYesNo _XNA
F. A ground water contour map has been submitted which includes the ground water elevations for each well. Yes No _X_NA :
G. Delinestion of contamination
The ground water contaminants have been delinested to MCLs or lower values at the property boundariesYesNo
2. The plume is suspected to continue off the property & concentrations greater than MCLs. Yes No
3 Off property access (circle ene): is being sought has been approved has been denied
SITE ASSESSMENT CERTIFICATION [preparer of site assessment plan - N.J.A.C. 7:148-8.3(b) &9.5(a)3;
The person signing this certification as the "Qualified Ground Water Consultant" (as defined in N.J.A.C.7:148-1 6) responsible for the design and implementation of the site assessment plan as specified in N.J.A.C. 7:148-8.3(a) 8 9.2(b)2, must supply the name of the certifying organization and certification number.
"I certify under penalty of law that the information provided in this document is true, accurate, and complete and was obtained by procedures in compliance with NJA.C. 7:148-8 and 9.1 am aware that there are significant penalties for submitting false, inaccurate, or incomplete information, including fines and/or imprisonment."
NAME (Print or Type) Barbara Maginn SIGNATURE & Maguny
NAME (Print or Type) Barbara Maginn IT Corporation DATE 11/26/91
(Preparer of Site Assessment Plan)
CERTIFYING N.J. Professional Engineer CERTIFICATION CE34387

I

COMPANY NAME_

291	
VIII.	TANK DECOMMISSIONING CERTIFICATION [person performing tank decommissioning portion of closure plan - N.J.A.C. 7:148-9.5(a)4]
	"I certify under penalty of law that tank decommissioning activities were performed in compliance with NJA.C. 7:14B-9.2(b)3. I am aware that there are significant penalties for submitting false, inaccurate, or incomplete information, including fines and/or imprisonment."
	NAME (Print or Type) Jerry Bishop SIGNATURE
	COMPANY NAME IT Corporation DATE ///-27-9/
DX.	CERTIFICATIONS BY THE RESPONSIBLE PARTY/IES) OF THE FACILITY
	A. The following certification shall be signed by the highest ranking individual with everall responsibility for that facility [N.J.A.C. 7:148-2.3(c)11].
	"I certify under penalty of law that the information provided in this document is true. accurate, and complete. I am aware that there are significant penalties for submitting false. inaccurate, or incomplete information, including fines and/or imprisonment."
	NAME (Print or Type) Major B. Bauman SIGNATURE But I Dumo
)	COMPANY NAME U.S. Army Corps of Engineers DATE 26 Nov 9/
	B. The following certification shall be signed as follows [seconding to the requirements of N.J.A.C. 7:148-2.3(C)2I]: N/A
	 For a corporation, by a principal executive officer of at least the level of vice president. For a partnership or sole proprietorship, by a general partner or the proprietor, respectively; or For a municipality, State, Federal or other public agency by either the principal executive officer or ranking elected official. In cases where the highest ranking corporate partnership, governmental officer or official at the facility as
	required in A above is the same person as the official required to certify in B, only the certification in A need to be made. In all other cases, the certifications of A and B shall be made.
	"I certify under penalty of law that I have personally examined and am familiar with the information submitted in this application and all attached documents, and that based on my inquiry of those individuals immediately responsible for obtaining the information, I believe that the submitted information is true, accurate, and complete. I am aware that there are significant penalties for submitting false, inaccurate, or incomplete information, including fines and/or imprisonment."
	NAME (Print or Type)SIGNATURE





For	State U	se Onh	
Date Rec'd.			
Auth ·			
Routing			
UST NO.		-	

Sinte of New Bersey DEPARTMENT OF ENVIRONMENTAL PROTECTION

TRENTOIL NEW JERSEY 84426 ATTN: BUST Program (609) 984-3156

STANDARD REPORTING FORM ist the:

Installation/Abandon/Remove Sale-Transfer/Substantial Modification

Circle Only One - Use One Form Per Activity

(More than one tank can be listed per tank activity)

Answer questions	1 through 5 a	and others as	applicable.
WALEMAL COSTINCIS	1 2000200		

•••	swer questions 1 through 5 and others as applicable	
-	Company name and address: (as B	Middlesex County College
•	appears on registration questionnaire)	155 Mill Road
		P.O. Box 3050
		Edison, New Jersey 08818-3050
	•	· · · · · · · · · · · · · · · · · · ·
2.	Facility name and location: (If different from above)	
_		
	Contact person for this activity:	Major Ben Bauman
	Telephone Number:	(908) 603-9517
	The identification number of the affected tank as it	appears in Question Number 12 on the Registration
	Ouestionnaire: C1	

registration as Middlesex County College. For TRANSFER OF OWNERSHIP: Department of the Army * **New Company Name** (Tank Removed 8-27-91) New Facility Name . P.O. Box 6433 Address ... Edison, New Jersey 08818-6433 Major Ben Bauman New owner/operator (print) . For ABANDONMENT or REMOVAL Describe the proposed procedure in detail on an attached sheet. b. Specify the product last stored in the tank: ____ d. Is Site Assessment Compliance Statement being completed? YES or NO Date abandoned or removed. Form MUST be completed and returned within 90 days of tank closure. (per 40 CFR 280.72) For SUBSTANTIAL MODIFICATIONS: Describe the reason for the modification and, in detail, the proposed procedure to be used on an attached sheet. Specify the product presently stored in the tank: ____ c. Specify the product to be stored in the tank: _). For NEW OR REPLACEMENT INSTALLATIONS: Attach the specifications as required by the attached instructions. b. Specify the product (s) to be stored in the tank: __ All appropriate and applicable permits, licenses and certificates from any local, state OTE: and/or federal agency must be obtained separately from this notification as required by the above stated activity. CERTIFICATION *** This registration form shall be signed by the highest ranking individual at the facility with overall responsibility for that facility. (7:148-23 (a) 1). *** "I certify under penalty of law that the information provided in this document is true, accurate and complete. I am aware that there are significant civil and criminal penalties for submitting take, inaccurate or incomplete information, including fines end/or imprisionment." Bignature: BEN ame (print or type): Date: 26 Nov Margae

*Tank was not transferred with rest of property in 1963 when Middlesex County College purchased property from Department of the Army. Owner Mistakenly shown on 9-16-91



ANALYTICAL **SERVICES**

CERTIFICATE OF ANALYSIS

Raritan Arsenal

Date: September 17, 1991

c/o IT Corp.

165 Fieldcrest Ave.

Edison, NJ 08837

Attn: Ms. Barbara Maginn

NJ Lab Certification ID#: 12064

Job No.: 305788

P.O. Number: 082691-B

This is the Certificate of Analysis for the following samples:

Client Project ID:

Soil

Date Received:

08/27/91

Number of Samples:

Sample Type:

SOIL

I Samples were labeled as follows:

SAMPLE IDENTIFICATION	LABORATORY #
FIELD BLANK	F1-09-007-01
BLDG. 118-B1	F1-09-007-02
BLDG. 118-B2	F1-09-007-03
BLDG. 118-B3	F1-09-007-04

Regiewed and Approved:

Project Manager

Company: Date: Raritan Arsenal

September 17, 1991

Client Job No.: 305788

IT ANALYTICAL SERVICES

EDISON, NJ (201) 225-2000

Work Order: F1-09-007

SAMPLE ID	FIELD BLANK	BLDG. 118-B1	BLDG. 118-B2	
SAMPLED TEST	08/27/91	08/27/91	08/27/91	UNITS
Petroleum Hydrocarbons	ИÐ [1.0]			mg/L
Petroleum Hydrocarbons	1	ND [22]	ND [24]	mg/Kg Dry Wt.
Total Solids	1	90 [0.01]	83 [0.01]	Percent
·				
	,			
1				ļ

ND indicates the parameter was not detected. Detection limits are specified in [].

Company: Date:

Raritan Arsenal

September 17, 1991

Client Job No.: 305788

IT ANALYTICAL SERVICES

EDISON, NJ (201) 225-2000

Work Order: F1-09-007

SAMPLE ID	BLDG. 118-B3	
SAMPLED TEST	08/27/91	UNITS
Petroleum Hydrocarbons	ND [24]	mg/Kg Dry Wt.
Total Solids	84 [0.01]	Percent

ND indicates the parameter was not detected. Detection limits are specified in [].

Company: Date:

Raritan Arsenal

September 17, 1991

Client Job No.: 305788

IT ANALYTICAL SERVICES

EDISON, NJ (201) 225-2000

Work Order: F1-09-007

TEST NAME: Metals

SAMPLE ID: FIELD BLANK SAMPLE DATE: 08/27/91 ANALYSIS DATE: 09/04/91

> Results in ___mq/L Detection

Limit

Lead 0.005 ND

Comments: ND indicates the compound is not detected at the level indicated.

Company: Date:

Raritan Arsenal

September 17, 1991

Client Job No.: 305788

IT ANALYTICAL SERVICES EDISON, NJ (201) 225-2000

Work Order: F1-09-007

TEST NAME: Base Neutrals

SAMPLE ID: FIELD BLANK SAMPLE DATE: 08/27/91 ANALYSIS DATE: 08/31/91

Results in	ug/L	Detection Limit
Acenaphthene	ND	10
Acenaphthylene	ND	10
Anthracene	ND	10
Benzidine	ND	10
Benzo(a)Anthracene	ND	10
Benzo(b)Fluoranthene	ND	10
Benzo(k)Fluoranthene	ND	10
Benzo(a)Pyrene	ND	10
Benzo(g,h,i)perylene	ND	10
bis(2-Chloroethyl)Ether	ND	10
bis(2-Chloroethoxy)Methane	ND	10
bis(2-Ethylhexyl)Phthalate	ND	10
bis(2-Chloroisopropyl)Ether	<u>ND</u>	10
4-Bromophenyl Phenyl Ether	<u>ND</u>	10
Butyl Benzyl Phthalate	ND	10
2-Chloronaphthalene	ND	10
4-Chlorophenyl Phenyl Ether	<u>ND</u>	10
Chrysene	<u>ND</u>	10
Dibenzo(a,h)anthracene	<u>ND</u>	10
Di-n-butylphthalate	<u>ND</u>	<u> 10</u>
1,2-Dichlorobenzene	<u> </u>	10
1,3-Dichlorobenzene	<u>ND</u>	10
1,4-Dichlorobenzene	<u>ND</u>	10
3,3'-Dichlorobenzidine	<u>ND</u>	10
Diethylphthalate	<u>ND</u>	10
Dimethylphthalate	<u>ND</u>	10
2,4-Dinitrotoluene	<u>ND</u>	10
2,6-Dinitrotoluene	<u>ND</u>	10
Di-n-Octylphthalate	<u>ND</u>	10
1,2-Diphenylhydrazine	ND	10
Fluoranthene	ND	10
Fluorene	<u>ND</u>	10
Hexachlorobenzene	ND	10
Hexachlorobutadiene	<u>ND</u>	10
Hexachloroethane	ND	10

Company: Date: Raritan Arsenal

September 17, 1991

Client Job No.:

305788

IT ANALYTICAL SERVICES EDISON, NJ (201) 225-2000

Work Order: F1-09-007

TEST NAME: Base Neutrals

SAMPLE ID: FIELD BLANK SAMPLE DATE: 08/27/91 10 Hexachlorocyclopentadiene ND Indeno(1,2,3-cd)pyrene ND 10 10 Isophorone ND Naphthalene ND 10 ND 10 Nitrobenzene N-nitroso-dimethylamine ND 10 N-Nitrosodipropylamine ND 10 ND 10 N-Nitrosodiphenylamine Phenanthrene ND 10 10 Pyrene ND 1,2,4-Trichlorobenzene ND 10

Comments: ND indicates the compound is not detected at the level indicated.

Company: Date:

Raritan Arsenal

September 17, 1991

Client Job No.: 305788

IT ANALYTICAL SERVICES EDISON, NJ (201) 225-2000

Work Order: F1-09-007

TEST NAME: Volatile Organics

SAMPLE ID: FIELD BLANK SAMPLE DATE: 08/27/91 ANALYSIS DATE: 08/28/91

Results in	ug/L	Detection Limit
Acrolein	ND	50
Acrylonitrile	ND	50
Benzene	ND	5
Bromoform	ND	5
Bromomethane	ND	5
Carbon Tetrachloride	ND	5
Chlorobenzene	ND	5
Chlorodibromomethane	ND	5
Chloroethane	ND	5
2-Chloroethylvinyl Ether	ND	5
Chloroform	ND	5
Chloromethane	ND	5
Dichlorobromomethane	ND	5
1,1-Dichloroethane	ND	5
1,2-Dichloroethane	ND	5
1,1-Dichloroethene	ND	5
1,2-Dichloroethene	ND	5
1,2-Dichloropropane	ND	5
cis-1,3-Dichloropropene	ND	5
trans-1,3-Dichloropropene	ND	5
Ethylbenzene	ND	5
Methylene Chloride	ND	5
1,1,2,2-Tetrachloroethane	ND	5
Tetrachloroethene	ND	5
Toluene	ND	5
1,1,1-Trichloroethane	ND	5
1,1,2-Trichloroethane	<u>ND</u>	5
Trichloroethene	ND	5
Trichlorofluoromethane	<u>ND</u>	5
Vinyl Chloride	ND	5
Xylenes	<u>ND</u>	10

Comments: ND indicates the compound is not detected at the level indicated.

Company:

Raritan Arsenal

Date:

September 17, 1991

Client Job No.: 305788

IT ANALYTICAL SERVICES EDISON, NJ (201) 225-2000

Work Order: F1-09-007

TEST NAME: NBS Search Base Neutrals

SAMPLE ID: FIELD BLANK SAMPLE DATE: 08/27/91

Tentatively

Identified Compounds

Scan Number Estimated

Concentration (ug/L)

Unknown

192

____18

Company: Date:

Raritan Arsenal

September 17, 1991

Client Job No.: 305788

IT ANALYTICAL SERVICES EDISON, NJ (201) 225-2000

Work Order: F1-09-007

TEST NAME: NBS Search for VOA's

SAMPLE ID: FIELD BLANK SAMPLE DATE: 08/27/91

Tentatively Identified Compounds

Scan Number Estimated

Concentration (ug/L)

No non-targeted compounds found

Company:

Date:

Raritan Arsenal

September 17, 1991

Client Job No.: 305788

IT ANALYTICAL SERVICES EDISON, NJ (201) 225-2000

Work Order: F1-09-007

TEST NAME: Metals

SAMPLE ID: BLDG. 118-B1 SAMPLE DATE: 08/27/91 ANALYSIS DATE: 09/05/91

Lead

Results in mg/Kg Detection Dry Wt. Limit

> 2.2 24

Comments: ND indicates the compound is not detected at the level indicated.

Company: Date:

Raritan Arsenal

September 17, 1991

Client Job No.: 305788

IT ANALYTICAL SERVICES EDISON, NJ (201) 225-2000

Work Order: F1-09-007

TEST NAME: Base Neutrals

SAMPLE ID: BLDG. 118-B1 SAMPLE DATE: 08/27/91 ANALYSIS DATE: 09/06/91

Results in	ug/Kg Dry Wt.	Detection Limit
	.	
Acenaphthene	ND	370
Acenaphthylene	ND	<u> 370</u>
Anthracene	<u>ND</u>	<u> 370</u>
Benzidine	ND	370
Benzo(a)Anthracene	ND	370
Benzo(b)Fluoranthene	ND	370
Benzo(k)Fluoranthene	<u>ND</u>	<u>370</u>
Benzo(a)Pyrene	ND	<u> 370</u>
Benzo(g,h,i)perylene	ND	<u>370</u>
bis(2-Chloroethyl)Ether	<u>ND</u>	370
bis(2-Chloroethoxy)Methane	<u>ND</u>	370
bis(2-Chloroisopropyl)Ether	ND	370
bis(2-Ethylhexyl)Phthalate	<u>ND</u>	370
4-Bromophenyl Phenyl Ether	<u>ND</u>	<u> </u>
Butyl Benzyl Phthalate	ND	370
2-Chloronaphthalene	ND	<u> 370</u>
4-Chlorophenyl Phenyl Ether	ND	<u>370</u>
Chrysene	ND	37.0
Dibenzo(a,h)anthracene	ND	<u> 370</u>
Di-n-butylphthalate	ND	<u> 370</u>
1,2-Dichlorobenzene	ND	370
1,3-Dichlorobenzene	ND	<u> 370</u>
1,4-Dichlorobenzene	ND	<u> 370</u>
3,3'-Dichlorobenzidine	ND	<u>370</u>
Diethylphthalate	ND	370
Dimethylphthalate	ND	<u> 370</u>
2,4-Dinitrotoluene	ND	370
2,6-Dinitrotoluene	ND	<u> 370</u>
Di-n-Octylphthalate	ND	<u> 370</u>
1,2-Diphenylhydrazine	ND	<u> 370</u>
Fluoranthene	ND	<u> 370</u>
Fluorene	<u>ND</u>	<u> 370</u>
Hexachlorobenzene	ND	370
Hexachlorobutadiene	ND	<u>370</u>
Hexachloroethane	ND	<u>370</u>

Company: Date:

Raritan Arsenal

September 17, 1991

Client Job No.: 305788

IT ANALYTICAL SERVICES EDISON, NJ (201) 225-2000

Work Order: F1-09-007

TEST NAME: Base Neutrals

SAMPLE ID: BLDG. 118-B1 SAMPLE DATE: 08/27/91

Hexachlorocyclopentadiene	ND	370
Indeno(1,2,3-cd)pyrene	ND	370
Isophorone	<u>ND</u>	370
Naphthalene	ND	370
Nitrobenzene	ND	370
N-nitroso-dimethylamine	ND	370
N-Nitrosodipropylamine	<u>ND</u>	3.7.0
N-Nitrosodiphenylamine	<u> </u>	370
Phenanthrene	ND	<u>370</u>
Pyrene	<u>ND</u>	37.0
1,2,4-Trichlorobenzene	ND	370

Comments: ND indicates the compound is not detected at the level indicated.

Company: Date: Raritan Arsenal

September 17, 1991

Client Job No.: 305788

EDISON, NJ (201) 225-2000

Work Order: F1-09-007

IT ANALYTICAL SERVICES

TEST NAME: Volatile Organics

SAMPLE ID: BLDG. 118-B1
SAMPLE DATE: 08/27/91
ANALYSIS DATE: 08/30/91

Results in	ug/Kg Dry Wt.	Detection Limit
Acrolein	ND	60
Acrylonitrile	<u>ND</u>	60
Benzene	<u>ND</u>	<u> </u>
Bromoform	ND	6
Bromomethane	ND	6
Carbon Tetrachloride	ND	<u> </u>
Chlorobenzene	ND	6
Chlorodibromomethane	ND	6
Chloroethane	ND	6
2-Chloroethylvinyl Ether	ND	6
Chloroform	ND	6
Chloromethane	ND	6
Dichlorobromomethane	ND	<u> , 6</u>
1,1-Dichloroethane	ND	6
1,2-Dichloroethane	ND	6
1,1-Dichloroethene	ND	<u> 6 </u>
1,2-Dichloroethene	ND	6
1,2-Dichloropropane	ND	<u> </u>
cis-1,3-Dichloropropene	ND	6
trans-1,3-Dichloropropene	ND	<u> </u>
Ethylbenzene	ND	<u>6</u>
Methylene Chloride	ND	6
1,1,2,2-Tetrachloroethane	ND	6
Tetrachloroethene	ND	<u> 6 </u>
Toluene	ND	6
1,1,1-Trichloroethane	ND	<u> </u>
1,1,2-Trichloroethane	ND	6
Trichloroethene	ND	6
Trichlorofluoromethane	ND	6
Vinyl Chloride	ND	6
Xylenes	ND	11

Comments: ND indicates the compound is not detected at the level indicated.

Company:

Raritan Arsenal

Date:

September 17, 1991

Client Job No.: 305788

IT ANALYTICAL SERVICES EDISON, NJ (201) 225-2000

Work Order: F1-09-007

TEST NAME: NBS Search Base Neutrals

SAMPLE ID: BLDG. 118-B1 SAMPLE DATE: 08/27/91

Tentatively Identified Compounds	Scan Number	Estimated Concentration	(ug/Kg Dry Wt.)
Unknown	154	2700B	
Unknown Alkane	306	260	
Substituted Hexenedione	331	510	
Unknown	384	320	
Pyrene	1315	130	

Company:

Date:

Raritan Arsenal

September 17, 1991

Client Job No.: 305788

IT ANALYTICAL SERVICES

EDISON, NJ (201) 225-2000

Work Order: F1-09-007

TEST NAME: NBS Search for VOA's

SAMPLE ID: BLDG. 118-B1 SAMPLE DATE: 08/27/91

Tentatively

Identified Compounds

Scan Number **Estimated**

Concentration (ug/Kg Dry Wt.)

No non-targeted compounds found

Company:

Raritan Arsenal

Date:

September 17, 1991

Client Job No.: 305788

IT ANALYTICAL SERVICES EDISON, NJ (201) 225-2000

Work Order: F1-09-007

TEST NAME: Metals

SAMPLE ID: BLDG. 118-B2 SAMPLE DATE: 08/27/91 ANALYSIS DATE: 09/05/91

> Results in mg/Kg Detection Dry Wt. Limit

2.4 28 Lead

Comments: ND indicates the compound is not detected at the level indicated.

Company: Date:

Raritan Arsenal

September 17, 1991

Client Job No.: 305788

IT ANALYTICAL SERVICES EDISON, NJ (201) 225-2000

Work Order: F1-09-007

TEST NAME: Base Neutrals

SAMPLE ID: BLDG. 118-B2 SAMPLE DATE: 08/27/91 ANALYSIS DATE: 09/06/91

Results in	ug/Kg Dry Wt.	Detection Limit
Acenaphthene	ND	400
Acenaphthylene	ND	400
Anthracene	ND	400
Benzidine	<u>ND</u>	400
Benzo(a) Anthracene	ND	400
Benzo(b)Fluoranthene	<u>ND</u>	400
Benzo(k)Fluoranthene	ND	400
Benzo(a) Pyrene	ND	400
Benzo(g,h,i)perylene	ND	400
bis(2-Chloroethyl)Ether	<u>ND</u>	400
bis(2-Chloroethoxy)Methane	ND	400
bis(2-Chloroisopropyl)Ether	<u>ND</u>	400
bis(2-Ethylhexyl)Phthalate	ND	400
4-Bromophenyl Phenyl Ether	ND	400
Butyl Benzyl Phthalate	ND	400
2-Chloronaphthalene	<u>ND</u>	400
4-Chlorophenyl Phenyl Ether	ND	400
Chrysene	ND	400
Dibenzo(a,h)anthracene	<u> </u>	400
Di-n-butylphthalate	<u>ND</u>	400
1,2-Dichlorobenzene	<u>ND</u>	400
1,3-Dichlorobenzene	ND	400
1,4-Dichlorobenzene	ND	400
3,3'=Dichlorobenzidine	ND	400
Diethylphthalate	ND	400
Dimethylphthalate	ND	400
2,4-Dinitrotoluene	ND	400
2,6-Dinitrotoluene	ND	400
Di-n-Octylphthalate	ND	400
1,2-Diphenylhydrazine	ND	400
Fluoranthene	ND	400
Fluorene	ND	400
Hexachlorobenzene	ND	400
Hexachlorobutadiene	ND	400
Hexachloroethane	ND	400

Company: Date:

Raritan Arsenal

September 17, 1991

Client Job No.: 305788

1,2,4-Trichlorobenzene

IT ANALYTICAL SERVICES EDISON, NJ (201) 225-2000

Work Order: F1-09-007

TEST NAME: Base Neutrals

SAMPLE ID: BLDG. 118-B2 SAMPLE DATE: 08/27/91 400 Hexachlorocyclopentadiene ND 400 Indeno(1,2,3-cd)pyrene ND 400 Isophorone ND Naphthalene ND 400 400 Nitrobenzene ND N-nitroso-dimethylamine ND 400 N-Nitrosodipropylamine ND 400 N-Nitrosodiphenylamine ND 400 400 Phenanthrene ND 400 Pyrene ND

Comments: ND indicates the compound is not detected at the level indicated.

ND

400

Company: Date:

Raritan Arsenal

September 17, 1991

Client Job No.: 305788

IT ANALYTICAL SERVICES EDISON, NJ (201) 225-2000

Work Order: F1-09-007

TEST NAME: Volatile Organics

SAMPLE ID: BLDG. 118-B2 SAMPLE DATE: 08/27/91 ANALYSIS DATE: 08/30/91

Results in	ug/Kg Dry Wt.	Detection Limit
•		
Acrolein	<u>ND</u>	60
Acrylonitrile	ND	60
Benzene	. ND	.6
Bromoform	<u>ND</u>	6
Bromomethane	<u>ND</u>	6
Carbon Tetrachloride	ND	6
Chlorobenzene	ND ND	6
Chlorodibromomethane	ND	6
Chloroethane	ND	6
2-Chloroethylvinyl Ether	ND	6
Chloroform	ND	6
Chloromethane	ND	6
Dichlorobromomethane	<u>ND</u>	6
1,1-Dichloroethane	ND	<u> </u>
1,2-Dichloroethane	ND	6
1,1-Dichloroethene	ND	<u> 6</u> .
1,2-Dichloroethene	ND	6
1,2-Dichloropropane	<u>ND</u>	6
cis-1,3-Dichloropropene	<u>ND</u>	6
trans-1,3-Dichloropropene	ND	6
Ethylbenzene	ND	6
Methylene Chloride	<u>ND</u>	6
1,1,2,2-Tetrachloroethane	<u>ND</u>	6
Tetrachloroethene	<u>ND</u>	6
Toluene	ND	6
1,1,1-Trichloroethane	ND	6
1,1,2-Trichloroethane	<u>ND</u>	6
Trichloroethene	<u>ND</u>	6
Trichlorofluoromethane	<u>ND</u>	6
Vinyl Chloride	ND	6
Xylenes	ND	12

Comments: ND indicates the compound is not detected at the level indicated.

Company: Date:

Raritan Arsenal

September 17, 1991

Client Job No.: 305788

IT ANALYTICAL SERVICES EDISON, NJ (201) 225-2000

Work Order: F1-09-007

TEST NAME: NBS Search Base Neutrals

SAMPLE ID: BLDG. 118-B2 SAMPLE DATE: 08/27/91

Tentatively	Scan	Estimated	
Identified Compounds	Number	Concentration	(ug/Kg Dry Wt.)
Unknown	331	570	
Unknown	385	490	
Unknown Alkene	1397	120	
Substituted Hexanedioic Ester	1458	180	
Dotriacontanol Isomer	<u> 1603</u>	<u> 170</u>	
Unknown Alkane	1690	180	
Unknown Alkane	<u> 1806</u>	200	
Substituted Ester	1455	13000	

Company: Date:

Raritan Arsenal

September 17, 1991

Client Job No.: 305788

IT ANALYTICAL SERVICES EDISON, NJ

(201) 225-2000

Work Order: F1-09-007

TEST NAME: NBS Search for VOA's

SAMPLE ID: BLDG. 118-B2 SAMPLE DATE: 08/27/91

Tentatively

Identified Compounds

Scan Number Estimated

Concentration (ug/Kg Dry Wt.)

Unknown

22

_____11

Company: Date:

Raritan Arsenal

September 17, 1991

Client Job No.: 305788

IT ANALYTICAL SERVICES EDISON, NJ

(201) 225-2000

Work Order: F1-09-007

TEST NAME: Metals

SAMPLE ID: BLDG. 118-B3 SAMPLE DATE: 08/27/91 ANALYSIS DATE: 09/05/91

Results in mg/Kg Detection

Dry Wt.

Limit

Lead

20

2.4

Comments: ND indicates the compound is not detected at the level indicated.

Company: Date:

Raritan Arsenal

September 17, 1991

Client Job No.: 305788

IT ANALYTICAL SERVICES EDISON, NJ (201) 225-2000

Work Order: F1-09-007

TEST NAME: Base Neutrals

SAMPLE ID: BLDG. 118-B3 SAMPLE DATE: 08/27/91 ANALYSIS DATE: 09/06/91

Results in	ug/Kg Dry Wt.	Detection Limit
Acenaphthene	ND	<u>390</u>
Acenaphthylene	ND	<u>390</u>
Anthracene	ND	390
Benzidine	ND	<u>390</u>
Benzo(a)Anthracene	ND	390
Benzo(b)Fluoranthene	ND	<u>390</u>
Benzo(k)Fluoranthene	ND	390
Benzo(a) Pyréné	ND	390
Benzo(g,h,i)perylene	ND.	<u>390</u>
bis(2-Chloroethyl)Ether	ND	<u>390</u>
bis(2-Chloroethoxy)Methane	ND	<u>390</u>
bis(2-Chloroisopropyl)Ether	ND	390
bis(2-Ethylhexyl)Phthalate	ND	<u> 390</u>
4-Bromophenyl Phenyl Ether	ND	<u>390</u>
Butyl Benzyl Phthalate	ND	390
2-Chloronaphthalene	ND	<u> 390</u>
4-Chlorophenyl Phenyl Ether	ND	<u>390</u>
Chrysene	ND	<u> 390</u>
Dibenzo(a,h)anthracene	ND	<u> 390</u>
Di-n-butylphthalate	<u> </u>	<u> 390</u>
1,2-Dichlorobenzene	<u>ND</u>	<u> 390</u>
1,3-Dichlorobenzene	ND	390
1,4-Dichlorobenzene	<u>ND</u>	390
3,3'-Dichlorobenzidine	ND	390
Diethylphthalate	ND	<u> 390</u>
Dimethylphthalate	ND	<u> 390</u>
2,4-Dinitrotoluene	ND	<u>390</u>
2,6-Dinitrotoluene	ND	390
Di-n-Octylphthalate	ND	390
1,2-Diphenylhydrazine	<u>ND</u>	390
Fluoranthene	ND	390
Fluorene	ND	390
Hexachlorobenzene	<u>ND</u>	390
Hexachlorobutadiene	ND	390
Hexachloroethane	ND	390

Company: Date: Raritan Arsenal

September 17, 1991

Client Job No.:

305788

IT ANALYTICAL SERVICES EDISON, NJ

(201) 225-2000

Work Order: F1-09-007

TEST NAME: Base Neutrals

SAMPLE ID: BLDG. 118-B3 SAMPLE DATE: 08/27/91 390 ND Hexachlorocyclopentadiene 390 ND Indeno(1,2,3-cd)pyrene 390 Isophorone ND Naphthalene ND 390 390 Nitrobenzene ND N-nitroso-dimethylamine 390 ND 390 N-Nitrosodipropylamine ND N-Nitrosodiphenylamine ND 390 390 Phenanthrene ND 390 ND Pyrene 1,2,4-Trichlorobenzene ND 390

Comments: ND indicates the compound is not detected at the level indicated.

Company: Date:

Raritan Arsenal

September 17, 1991

Client Job No.: 305788

IT ANALYTICAL SERVICES EDISON, NJ (201) 225-2000

Work Order: F1-09-007

TEST NAME: Volatile Organics

SAMPLE ID: BLDG. 118-B3 **SAMPLE DATE: 08/27/91** ANALYSIS DATE: 08/30/91

Results in	<u>ug/Kg</u>	Detection
	Dry Wt.	Limit
Acrolein	ND	60
Acrylonitrile	ND	60
Benzene	ND	6
Bromoform	ND	6
Bromomethane	ND	6
Carbon Tetrachloride	ND	6
Chlorobenzene	ND	6
Chlorodibromomethane	ND	6
Chloroethane	<u>ND</u>	6
2-Chloroethylvinyl Ether	<u>ND</u>	6
Chloroform	ND	6
Chloromethane	ND	6
Dichlorobromomethane	ND.	6
1,1-Dichloroethane	<u>ND</u>	6
1,2-Dichloroethane	ND	6
1,1-Dichloroethene	ND	6
1,2-Dichloroethene	ND	6
1,2-Dichloropropane	<u>ND</u>	6
cis-1,3-Dichloropropene	ND	6
trans-1,3-Dichloropropene	ND	6
Ethylbenzene	ND	<u> </u>
Methylene Chloride	ND	6
1,1,2,2-Tetrachloroethane	ND	<u> </u>
Tetrachloroethene	ND	6
Toluene	<u>ND</u>	6
1,1,1-Trichloroethane	<u>ND</u>	6
1,1,2-Trichloroethane	<u>ND</u>	<u> </u>
Trichloroethene	ND	6
Trichlorofluoromethane	<u>ND</u>	6
Vinyl Chloride	<u>ND</u>	6
Xylenes	ND	12

Comments: ND indicates the compound is not detected at the level indicated.

Company: Date:

Raritan Arsenal

September 17, 1991

Client Job No.: 305788

IT ANALYTICAL SERVICES EDISON, NJ

(201) 225-2000

Work Order: F1-09-007

TEST NAME: NBS Search Base Neutrals

SAMPLE ID: BLDG. 118-B3 SAMPLE DATE: 08/27/91

Tentatively	Scan	Estimated		
Identified Compounds	Number	Concentration	(ug/Kg	Dry Wt.)
Unknown	155	4200B		•
Unknown	194	56000B		
Substituted Alkane	214	330B		
Substituted Alkane	224	<u> 390B</u>	•	
Unknown	287	1100B		
Ünknown	<u>331</u>	680		
Unknown Alkane Alcohol	1602	140		
Unknown Alkane	1690	250		
Unknown Alkane	<u> 1806</u>	250		
Unknown	<u> 1959</u>	230		
Unknown	2028	480		

Company:

Raritan Arsenal

Date:

September 17, 1991

Client Job No.: 305788

IT ANALYTICAL SERVICES EDISON, NJ

(201) 225-2000

Work Order: F1-09-007

TEST NAME: NBS Search for VOA's

SAMPLE ID: BLDG. 118-B3 SAMPLE DATE: 08/27/91

Tentatively Identified Compounds	Scan Number	Estimated Concentration	(ug/Kg Dry Wt.)
Cyclohexane	323	18	
Substituted Alkane	34 <u>5</u>	6	
Substituted Alkane	<u> 565</u>	6	

Company: Date: Raritan Arsenal September 17, 1991

Client Job No.:

305788

IT ANALYTICAL SERVICES EDISON, NJ (201) 225-2000

Work Order: F1-09-007

II ANALYTICAL RESULTS/METHODOLOGY

The analytical results for this report are presented by Analytical test. Each set of data will include sample identification information, the analytical results, and the appropriate detection limits. Detection limits may vary due to factors arising from concentration/dilution of the sample and sample matrix. ND denotes that the compound is not detected at or above the indicated detection limit. The methodologies for the analytical results requested are described below.

Metals

The analysis of metals is based on Method 200.7 from 40CFR, Part 136. Samples to be analyzed by flame AA or ICP are digested with hydrochloric and nitric acid. Furnace analysis requires nitric acid digestion and mercury samples are digested with nitric and sulfuric acid.

Lead, Arsenic, Selenium, Antimony and Thallium are analyzed by graphite furnace, Mercury by cold vapor AA and all other metals by flame AA or ICP.

Base/Neutral Extractable Organics - GC/MS (Water)

The analysis of base/neutral extractable organics is based on EPA Method 625. An aliquot of sample is serially extracted with methylene chloride at a pH greater than 11.0. The extracts are dried through sodium sulfate, concentrated and analyzed by mass spectroscopy.

Volatile Organics - GC/MS (Clean water)

For the analysis of volatile organics, EPA Methods 624 is used. An inert gas is bubbled through a sample contained in a specifically designed purging chamber. The purgeables are efficiently transferred from the aqueous phase to the vapor phase. The vapor is swept through a sorbent column where the purgeables are trapped. After purging is completed, the sorbent column is heated and backflushed with the inert gas to desorb the purgeables onto a gas chromatographic column. The gas chromatograph is temperature programmed to separate the purgeables which are then detected with a mass spectrometer.

Petroleum Hydrocarbons - IR

The analysis of petroleum hydrocarbons is based on EPA Method, 418.1. Water samples are prepared by separatory funnel liquid-liquid extraction using freon as the extracting solvent. Soils are prepared by soxhlet extraction using freon as the extracting solvent. Silica gel is added to remove interferences. Extracts are analyzed by infrared

Company: Date: Raritan Arsenal September 17, 1991

Client Job No.:

305788

IT ANALYTICAL SERVICES EDISON, NJ (201) 225-2000

Work Order: F1-09-007

spectrophotometer and concentrations are determined by direct comparison with standards.

Base/Neutral Extractable Organics - GC/MS (Solid)

The analysis of base/neutral extractable organics is based on Methods 3550 and 8270, Test Methods for Evaluating Solid Waste (SW-846), 3rd Edition. The extraction method (SW-846, Method 3550) uses an aliquot of sample sonicated three times with methylene chloride. The extracts are combined, dried through sodium sulfate, concentrated and analyzed by mass spectroscopy.

Volatile Organics - GC/MS (Solid)

For the analysis of volatile organics in soils, SW-846, 3RD Edition, Method 8240 is employed. The volatile organic compounds are introduced into the gas chromatograph by the purge and trap method. The purgeables are efficiently transferred from the aqueous phase to the vapor phase. The vapor is swept through a sorbent column where the purgeables are trapped. After purging is completed, the sorbent column is heated and backflushed with the inert gas to desorb the purgeables onto a gas chromatographic column. The gas chromatograph is temperature programmed to separate the purgeables which are then detected with a mass spectrometer.

Total Solids

The analysis of total solids is based on Standard Methods, 16th Edition - (209F). A well mixed sample is evaporated in a weighed dish and dried to constant weight. The increase in weight over that of the empty dish represents the total solids.

III QUALITY CONTROL

The Determinations were performed in accordance with EPA/NJDEP approved methodology.

DEFINITIONS

- ND(U) Analyte was analyzed for, but not detected. The value given after the ND or U is the detection limit for that compound.
 - A The compound denoted with an "A" indicates a suspected aldol condensation product.
 - B Indicates the compound was also detected in the blank, but at levels less than 5% the detection limit. Values for this compound may be suspect
 - Indicates the compound was detected in the sample, but at levels less than the detection limit.
 Results should be regarded as estimated.

MS -	Matrix Spike	ug/L - Micrograms/Liter	Rec - Precent Recovery
MSD -	Matrix Spike Duplicate	ug/Kg - Micrograms/Kilogram	mg/L - Milligrams/Liter
RPD -	Relative Percent Difference	mg/Kg - Milligrams/Kilogram	DL - Detection Limit

QUALITY CONTROL WINDOWS

Surrogate Recove	eries		Surrogate Recoverie	2 S	
GC/MS Volatiles (624, 8240)	Water	Soil	GC/MS SemiVolatiles (625, 8270)	Water	Soil
04-1,2-dichloroethane	76-114	70-121	D5-Nitrobenzene	35-114	
D8-toluene	88-110	81-117	2-Fluorobiphenyl	43-116	30-115
4-Bromofluorobenzene	86-115	74-121	D14-Terphenyl	33-141	18-137
			D5-Phenol	10-94	24-113
			2-Fluorophenol	21-100	25-121
			2,4,6-Trobromophenol	10-123	19-122
Surrogate Recove	eries		Surrogate Recoverie	es .	
Pesticides* (608, 8080)	Water	Soil	Method 602, BTEX, 8020	Water	Soil
Tetrachloro-m-xylene	60-150	60-150	4-Bromofluorobenzene	62-139	62-138
Dibutyl chlorendate	24-154	20-150			

^{*} SW846 allows one surrogate to be outside recovery windows.

Surrogate R	ecoveries		Surrogate Recoveries	
Method 601 (8010)	Water	<u>Soil</u>	Method 8060** Water	Soil
Bromochloromethane	74-121	74-121	Tetrachloro-m-xylene 60-150	60-150
			Decachlorobiphenyl 60-150	60-150
Method 8015	Water	Soil	Herbicides** Water	Soil
Acetone	68-132	68-132	2,4-DB 60-150	
•			** Advisory Limits	
METALS / WET CHEMISTRY			·	
_	Recovery	<u>RPD</u>	Recovery	<u>RPD</u>
Blank Spike	75-125		Replicate	<20%
Blank Spike Duplicate	75-125	<20%	Check Standard 90-110	
Matrix Spike	75-125			
Matrix Spike Duplicate	75- <u>12</u> 5	<20%		



ANALYTICAL SERVICES

CERTIFICATE OF ANALYSIS

Raritan Arsenal

c/o IT Corp.

165 Fieldcrest Ave. Edison, NJ 08837

Attn: Ms. Barbara Maginn

Date: October 29, 1991

NJ Lab Certification ID#: 12064

Job No.: 305788

P.O. Number: 082691-B

This is the Certificate of Analysis for the following samples:

Client Project ID:

SOIL

Date Received:

10/23/91

Number of Samples:

•

Sample Type: SOIL

I Samples were labeled as follows:

SAMPLE IDENTIFICATION

LABORATORY #

B-1/0-6"/SOIL

F1-10-223-01

B-2/0-6"/SOIL

F1-10-223-02

B-3/0-6"/SOIL

F1-10-223-03

FIELD BLANK

F1-10-223-04

Reviewed and Approved:

Patrick B. Brown

Project Manager

Company:
Date:

Raritan Arsenal October 29, 1991

Client Job No.: 305788

IT ANALYTICAL SERVICES

EDISON, NJ (201) 225-2000

Work Order: F1-10-223

		2,400		
SAMPLE ID	B-1/0-6"/SOIL	B-2/0-6"/SOIL	B-3/0-6"/SOIL	
SAMPLED TEST	10/23/91	10/23/91	10/23/91	ÜNITS
Petroleum Hydrocarbons	ND [24]	950 [480]	3900 [480]	mg/Kg Dry Wt.
Total Solids	85 [0.01]	83 [0.01]	84 [0.01]	Percent

ND indicates the parameter was not detected. Detection limits are specified in [].

Company: Date:

Raritan Arsenal October 29, 1991

Client Job No.: 305788

IT ANALYTICAL SERVICES EDISON, NJ

(201) 225-2000

Work Order: F1-10-223

SAMPLE ID	FIELD BLANK	
SAMPLED TEST	10/23/91	UNITS
Petroleum Hydrocarbons	ND [1.0]	mg/L
	•	

ND indicates the parameter was not detected. Detection limits are specified in [].

Company: Date:

Raritan Arsenal October 29, 1991

Client Job No.: 305788

IT ANALYTICAL SERVICES EDISON, NJ (201) 225-2000

Work Order: F1-10-223

II ANALYTICAL RESULTS/METHODOLOGY

The analytical results for this report are presented by Analytical test. Each set of data will include sample identification information, the analytical results, and the appropriate detection limits. Detection limits may vary due to factors arising from concentration/dilution of the sample and sample matrix. ND denotes that the compound is not detected at or above the indicated detection limit. The methodologies for the analytical results requested are described below.

Petroleum Hydrocarbons - IR

The analysis of petroleum hydrocarbons is based on EPA Method, 418.1. Water samples are prepared by separatory funnel liquid-liquid extraction using freon as the extracting solvent. Soils are prepared by soxhlet extraction using freon as the extracting solvent. Silica gel is added to remove interferences. Extracts are analyzed by infrared spectrophotometer and concentrations are determined by direct comparison with standards.

Petroleum Hydrocarbons - IR

The analysis of petroleum hydrocarbons is based on EPA Method, 418.1. Water samples are prepared by separatory funnel liquid-liquid extraction using freon as the extracting solvent. Soils are prepared by soxhlet extraction using freon as the extracting solvent. Silica gel is added to remove interferences. Extracts are analyzed by infrared spectrophotometer and concentrations are determined by direct comparison with standards.

Total Solids

The analysis of total solids is based on Standard Methods, 16th Edition -(209F). A well mixed sample is evaporated in a weighed dish and dried to constant weight. The increase in weight over that of the empty dish represents the total solids.

III QUALITY CONTROL

The Determinations were performed in accordance with EPA/NJDEP approved methodology.

DEFINITIONS

- ND(U) Analyte was analyzed for, but not detected. The value given after the ND or U is the detection limit for that compound.
 - A The compound denoted with an "A" indicates a suspected aldol condensation product.
 - B Indicates the compound was also detected in the blank, but at levels less than 5X the detection limit. Values for this compound may be suspect
 - Indicates the compound was detected in the sample, but at levels less than the detection limit.
 Results should be regarded as estimated.

MS -	Matrix Spike	ug/L - Micrograms/Liter	Rec - Precent Recovery
MSD -	Matrix Spike Duplicate	ug/Kg - Micrograms/Kilogram	mg/L - Milligrams/Liter

RPD - Relative Percent Difference mg/Kg - Milligrams/Kilogram DL - Detection Limit

QUALITY CONTROL WINDOWS

Surrogate Recov	ries		Surrogate Recover	ies	
MS Volatiles (624, 8240)	Water	Soil	CC/MS SemiVolatiles (625, 8270)	Water	Soil
4-1,2-dichloroethane	76-114	70-121	D5-Nitrobenzene	35-114	23-120
D8-toluene	88-110	81-117	2-Fluorobiphenyl	43-116	30-115
4-Bromofluorobenzene	86-115	74-121	D14-Terphenyl	33-141	18-137
			D5-Phenol	10-94	24-113
			2-Fluorophenol	21-100	25-121
			2,4,6-Trobromophenol	10-123	19-122
Surrogate Recov	eries		Surrogate Recover	ies	
Pesticides* (608, 8080)	Water	Soil	Method 602, BTEX, 8020	Water	Soil
Tetrachloro-m-xylene	60-150	60-150	4-Bromofluorobenzene	62-139	62-138
Dibutyl chlorendate	24-154	20-150			

^{*} SW846 allows one surrogate to be outside recovery windows.

Surrogate R	ecoveries		Surrogate Rec	coveries	
Method 601 (8010)	Water	Soil	Method 8060**	Water	Soil
Bromochloromethane	74-121	74-121	Tetrachloro-m-xylene	60-150	60-150
			Decachlorobiphenyl	60-150	60-150
Method 8015	Water	Soil	Herbicides**	Water	Soil
Acetone	68-132	68-132	2,4-DB	60-150	60-150
,			** Advisory 1	Limits	
METALS / WET CHEMISTRY					
	Recovery	RPD		Recovery	<u>rpd</u>
ank Spike	75-125		Replicate		<20%
Blank Spike Duplicate	75-125	<20%	Check Standard	90-110	
Matrix Spike	75-125				
Matrix Spike Duplicate	75-125	<20%			

	TERNATIONAL
لك	TECHNOLOGY CORPORATION

LOT IP

ANALYSIS RESPECT AND

107	Reference Page 1 of	N 4440	5
	Page 1 0		

CORPORA			OF CUSTO			e 1 of	
	NO. 1 RARITAN AR); ⁵	
	ers 2 R. M. Millin		ab Destination	8 1TA	S, EDISON		-
Profit Center	No. 3 3514		Lab Contact	9 K.	COCSIS ECT.		
Project Mana	ager 4 LAPYAN CH	AN Project C	ontact/Phone	12 225	-2000 239 Report to	:10	
	No.6 305788.2		er/Waybill No	13			
Required Report C	Date. 11	0	NE CONT	AINER	PER LINE		
Sample ¹⁴ Number	Sample ¹⁵ Description/Type	Date/Time 16 Collected Ty	pe Volume	servative	Program	Condition on ²¹ Receipt	Disposal ²² Record No.
125281	B-1/0-6/80ic	10/23/91 1500 AM	350M 250M	NP	Peterlaum Hypeconeson	15 Good 8° PY 10/24	
125282	B-210-61 Soic	10/23/91/570		1			
125283	B-310-6/80ic	d/23/11/521	VV	1	4		
	FIELD BLANK	10/23/91/450 A	med 1×200	HS04	TPAC		
	Fiers Blank	10/23/91 1450	11200	AP	BN +15	V V- EV	ļ
					i	表 (Ping i i i i i i i i i i i i i i i i i i	<u></u> 2
		·				And anyone (special or of the	i deci
Special Instruction	ne: 23			<u> </u>	:	<u> </u>	1
	Identification: 24				Sample Disposal: 25		_
Non-hazard 🔟 🗜	lammable 🔟 Skin Irr	itant 🔟 Poison E			Return to Client Disp	osal by Lab 🔔 Archive	9(mos
Turnaround Time Normal _J Rush	Bequired: 26 48hr.	TAT	QC Level:		Project Specific/(specify);		
	28 Rodney Mills	ITFAS Date:Time:	102391.	_	gived by 28	Date: Time:	
2. Relinquished by		Date: Time:		2. Rece	eived by	Date: Time:	
3. Relinquished by Signature/Affiliation)		Date: Time:		(Signature/		Date: Time:	take and the state of the state of the state of
Comments: 29	TPHC analysis	- Jaz 48hg. T.	AT to de	temin	e which 2 Sa	mples	
i	need to be a	natured 60	UZ BN+1	5			
		. ()0	•				MCA 3



ANALYTICAL SERVICES

CERTIFICATE OF ANALYSIS

Raritan Arsenal

Date: November 11, 1991

c/o IT Corp.

165 Fieldcrest Ave.

Edison, NJ 08837

Attn: Ms. Barbara Maginn

NJ Lab Certification ID#: 12064

Job No.: 305788

P.O. Number: 082691-B

This is the Certificate of Analysis for the following samples:

Client Project ID:

SOIL

Date Received:

10/24/91

Number of Samples: Sample Type: 1 SOIL

I Samples were labeled as follows:

SAMPLE IDENTIFICATION

LABORATORY #

WASTE PILE AND 2 DRUM COMP F1-10-232-01

Reviewed and Approved:

Patrick B. Brown

Project Manager

Company: Date: Raritan Arsenal

November 11, 1991

Client Job No.: 305788

IT ANALYTICAL SERVICES

EDISON, NJ

(908) 225-2000

Work Order: F1-10-232

SAMPLE ID	WASTE PILE AND 2 DRUM COMP	
SAMPLED TEST	10/24/91	UNITS
Flash Point	Non-ignitable	Observation
Petroleum Hydrocarbons	ŃD [22]	mg/Kg Dry Wt.
Total Solids	89 [0.01]	Percent
Total Organic Halogen	ND { 220]	mg/Kg Dry Wt.
		·

ND indicates the parameter was not detected. Detection limits are specified in [].

Company: Date:

Raritan Arsenal

Client Job No.: 305788

November 11, 1991

IT ANALYTICAL SERVICES

EDISON, NJ

(908) 225-2000

Work Order: F1-10-232

TEST NAME: PCB's

SAMPLE ID: WASTE PILE AND 2 DRUM COMP

SAMPLE DATE: 10/24/91 ANALYSIS DATE: 10/31/91

		Results	in	ug/Kg Dry Wt.	Detection Limit
Arochlor	1016			<u>ND</u>	37
Arochlor	1221			<u>ND</u>	37
Arochlor	1232			ND	<u> </u>
Arochlor	1242			ND	37
Arochlor	1248			ND	37
Arochlor	1254			ND	37
Arochlor	1260			ND	37

Comments: ND indicates the compound is not detected at the level indicated.

Company:

Raritan Arsenal

Date:

November 11, 1991

Client Job No.: 305788

IT ANALYTICAL SERVICES

EDISON, NJ

(908) 225-2000

Work Order: F1-10-232

TEST NAME: Volatile Organics

SAMPLE ID: WASTE PILE AND 2 DRUM COMP

SAMPLE DATE: 10/24/91 ANALYSIS DATE: 10/29/91

	Results in	ug/Kg Dry Wt.	Detection Limit
Benzene		ND	1.1
Ethylbenzene		ND	1.1
Toluene		ND	1.1
Total Xylenes		ND	1.1

Comments: ND indicates the compound is not detected at the level indicated.

Company:

Raritan Arsenal

Date:

November 11, 1991

Client Job No.: 305788

IT ANALYTICAL SERVICES

EDISON, NJ

(908) 225-2000

Work Order: F1-10-232

TEST NAME: Metals

SAMPLE ID: WASTE PILE AND 2 DRUM COMP

SAMPLE DATE: 10/24/91 ANALYSIS DATE: 11/07/91

Results in mg/Kg Detection

Dry Wt.

Limit

Lead

<u> 29</u>

5.6

Comments: ND indicates the compound is not detected at the level

indicated.

Company:

Date:

Raritan Arsenal

November 11, 1991

Client Job No.: 305788

IT ANALYTICAL SERVICES EDISON, NJ

(908) 225-2000

Work Order: F1-10-232

IA COMMENTARY

Blank spike recoveries for PCB-1016 did not meet QC acceptance criteria for WASTE PILE AND 2 DRUM COMP (F110232-01). Batch acceptance based upon matrix spike/duplicate recoveries.

Company: Date:

Raritan Arsenal November 11, 1991

Client Job No.: 305788

IT ANALYTICAL SERVICES EDISON, NJ

(908) 225-2000

Work Order: F1-10-232

II ANALYTICAL RESULTS/METHODOLOGY

The analytical results for this report are presented by Analytical test. Each set of data will include sample identification information, the analytical results, and the appropriate detection limits. Detection limits may vary due to factors arising from concentration/dilution of the sample and sample matrix. ND denotes that the compound is not detected at or above the indicated detection limit. The methodologies for the analytical results requested are described below.

PCB's (Soil)

The analysis of PCB's is based on Methods 8080 and 3550 of Test Methods for Evaluating Solid Waste, SW-846, 3rd Edition. An aliquot of sample is diluted in hexane. The extract is then separated by gas chromatography and the analytes are measured using an electron capture detector.

Volatile Organics - GC (Soil)

For the analysis of volatile organics EPA Method 8020 of Test Methods for Evaluating Solid Waste (SW-846), 3rd Edition is used. An inert gas is bubbled through a sample dispersed at 40 degrees C in water and the purgeables are efficiently transferred to the vapor phase. The vapor is swept through a sorbent column where the purgeables are trapped. After purging is completed, the sorbent column is heated and backflushed with the inert gas to desorb the purgeables onto a gas chromatographic column. The gas chromatograph is temperature programmed to separate the purgeables which are then detected with a photoionization detector.

Total Organic Halogens

The analysis of total organic halogens (TOX) in liquid is based on Standard Methods, 16th Edition (506), the Dohrmann Manual and the EPA Manual, Volume 1C. The sample is absorbed on granular activated carbon and undergoes combustion at 800 degrees celsius. The amount of halide is quantified in a microcoulometric titration cell.

Metals

The analysis of metals is based on Method 200.7 from 40CFR, Part 136. Samples to be analyzed by flame AA or ICP are digested with hydrochloric and nitric acid. Furnace analysis requires nitric acid digestion and mercury samples are digested with nitric and sulfuric acid.

Company:

Date:

Raritan Arsenal

November 11, 1991

Client Job No.: 305788 IT ANALYTICAL SERVICES EDISON, NJ

(908) 225-2000

Work Order: F1-10-232

Lead, Arsenic, Selenium, Antimony and Thallium are analyzed by graphite furnace, Mercury by cold vapor AA and all other metals by flame AA or ICP.

Ignitability - Soils

A flame is introduced to an aliquot of sample at standard temperature and pressure. If the sample burns persistently and vigorously, it is considered to be ignitiable.

Petroleum Hydrocarbons - IR

The analysis of petroleum hydrocarbons is based on EPA Method, 418.1. Water samples are prepared by separatory funnel liquid-liquid extraction using freon as the extracting solvent. Soils are prepared by soxhlet extraction using freon as the extracting solvent. Silica gel is added to remove interferences. Extracts are analyzed by infrared spectrophotometer and concentrations are determined by direct comparison with standards.

Total Solids

The analysis of total solids is based on Standard Methods, 16th Edition -(209F). A well mixed sample is evaporated in a weighed dish and dried to constant weight. The increase in weight over that of the empty dish represents the total solids.

III QUALITY CONTROL

The Determinations were performed in accordance with EPA/NJDEP approved methodology.



ANALYTICAL SERVICES

CERTIFICATE OF ANALYSIS

IT CORPORATION 165 FIELDCREST AVENUE EDISON NJ 08837 PAT BROWN Date: 11/06/91

Work Order: B1-10-249

P.O. Number: L01534

This is the Certificate of Analysis for the following samples:

Client Work ID: RARITAN ARSENAL F110232

599990

Date Received: 10/26/91 Number of Samples: 1 Sample Type: SOIL

I. Introduction

Samples were labeled as follows:

SAMPLE IDENTIFICATION
W PILE & SUPPLY F110232

LABORATORY #

W. PILE & 2DRUM F110232 B1-10-249-01

Reviewed and Approved:

Donnie Heinrich

Western Regional Analytical Director

IT ANALYTICAL SERVICES AUSTIN, TX

Company: IT CORPORATION

Date: 11/06/91

Client Work ID: RARITAN ARSENAL F110232

599990

Work Order: B1-10-249

II. QA/QC

The results presented in this report meet the statement of work requirements in accordance with Quality Control and Quality Assurance protocol except as noted in Section IV or in an optional sample narrative at the end of Section III.

III. Analytical Data

The following page(s) supply results for requested analyses performed on the samples listed above.

The test results relate to tested items only. ITAS-Austin reserves the right to control report production except in whole.

IT ANALYTICAL SERVICES AUSTIN, TX

Company: IT CORPORATION

Date: 11/06/91

Client Work ID: RARITAN ARSENAL F110232

599990

Work Order: B1-10-249

SAMPLE SAME TEST		E & 2DRUM F110232 10/24/91		UNITS
TOX 90	20 [ЙD 200]		mg/kg
	+		+	

ND indicates the parameter was not detected. Detection limits are specified in [].

IT ANALYTICAL SERVICES AUSTIN, TX

Company: IT CORPORATION

Date: 11/06/91

Client Work ID: RARITAN ARSENAL F110232

599990

Work Order: B1-10-249

IV. Methodology

Requested analyses were performed according to the following methods.

TEST NAME TOX

9020

TEST CODE TOX

Total Organic

Halogen

Method 9020-Test Methods for Evaluating Solid Wastes, 3rd Edition, November 1986. Coulometric titration.

DEFINITIONS

- ND(U) Analyte was analyzed for, but not detected. The value given after the ND or U is the detection limit for that compound.
 - A The compound denoted with an "A" indicates a suspected aldol condensation product.
 - Indicates the compound was also detected in the blank, but at levels less than 5% the detection limit. Values for this compound may be suspect
 - Indicates the compound was detected in the sample, but at levels less than the detection limit.
 Results should be regarded as estimated.

MS -	Matrix Spike	ug/L - Micrograms/Liter	Rec - Precent Recovery
MSD -	Matrix Spike Duplicate	ug/Kg - Micrograms/Kilogram	mg/L - Milligrams/Liter

RPD - Relative Percent Difference mg/Kg - Milligrams/Kilogram DL - Detection Limit

QUALITY CONTROL WINDOWS

Surrogate Recover	ries	Surrogate Recove	eries
CC/MS Volatiles (624, 8240)	Water Soil	GC/MS SemiVolatiles (625, 8270)) Water Soil
04-1,2-dichloroethane	76-114 70-121	D5-Nitroberzene	35-114 23-120
D8-toluene	88-110 81-117	2-Fluorobiphenyl	43-116 30-115
4-Bromofluorobenzene	86-115 74-121	D14-Terphenyl	33-141 18-137
		D5-Phenol	10-94 24-113
		2-Fluorophenol	21-100 25-121
		2,4,6-Trobromophenol	10-123 19-122
Surrogate Recover	ries	Surrogate Recov	eries
Pesticides* (608, 8080)	Water Soil	Method 602, BTEX, 8020	Water Soil
Tetrachloro-m-xylene	60-150 60-150	4-Bromofluorobenzene	62-139 62-138
Dibutyl chlorendate	24-154 20-150		

^{*} SW846 allows one surrogate to be outside recovery windows.

Surrogate R	ecoveries		Surrogate Re	coveries	
Method 601 (8010)	Water	Soil	Method 8060**	Water	Soil.
Bromochloromethane	74-121	74-121	Tetrachloro-m-xylene	60-150	60-150
			Decachlorobiphenyl	60-150	60-150
Method 8015	Water	Soil	Herbicides**	Water	Soil
Acetone	68-132	68-132	2,4-DB	60-150	60-150
			** Advisory	Limits	
METALS / WET CHEMISTRY					
	Recovery	RPD		Recovery	RPD
Blank Spike	75-125		Replicate		<20€
Blank Spike Duplicate	75-125	<20%	Check Standard	90-110	
Matrix Spike	75-125				
Matrix Spike Duplicate	75-125	<20%			



ANALYSIS RECEEST AND CHAIN OF CUSTODY RECORD*

eference	Document	N	30240
age 1 of			

CORPORA		0000					o:5 ITAS Edica	_
Project Name/	No. 17 T Edison S	799 Gamp				,	o:5 LIAS Edito	2N
ample Team Memb	pers 2					and the state of t	165 Fieldere Edison / S	08 837
Profit Center	ners ² No. ³ 46/4		Lab	Contact	9 peul	Salcher		-
Project Mana	ager 4 Pat Brown	n Proje	ect Contact	:/Phone	12/G+A	roun 908 but 5 a 000 Report to	1.10 Harp 10	St Brown
Purchase Order	No.6 L01534		Carrier/W	aybill No.	13		IT AS EXIS	on,
Purchase Order No. 6 LO 1534 Carrier/Waybill No. 13 Required Report Date 11 11/15/91 ONE CONTAINER PER LINE Ed.: son N J 088 37								
			Container 17				Condition on 21	Disposal ²²
Sample ¹⁴ Number	Sample ¹⁵ Description/Type	Date/Time 10 Collected	Container Type	Volume	servative	Program	Receipt	Record No.
	Waste Pile + 2 Drum Comp	10/24/91	120 ML 6/A	MOEL	None	TOX	File 0/26/91	
		'						
			-					Mark Super III
							- 19 PA	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
							After Asia Police Asiasa	AN DAGES REED.
Special Instruction	ons: 23 Analy	Le For	10	Υ				
Possible Hazard Non-hazard _J F	Identification: 24		ison B 🔟	Unknow	n 🗓	Sample Disposal: ²⁵ Return to Client Disp	oosal by Lab 🔔 💮 Archive	(mos.)
Turnaround Time			Q(C Level: 2	:7 Ⅲ.: <u> </u>	Project Specific (specify);		100 (7 2 1 2 1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2
1 Relinquished by 28 1 Date: 10-25-9 1 1. Received by 28 1 Date: 10/25-9					10/26/91			
2. Relinquished by Date:			2. Received by Signeture/Affiliation) Date:Time:					
3. Relinquished by Signature/Affiliation Time:			3. Received by Signature/Affiliation) Date: Time:					
Comments: 29								



F 232 ANALYSIS REGUEST AND CHAIN OF CUSTODY RECORD*

Reference	Document N	330238
Page 1 of	l	

CORPORA	- 3	05788 29.01,00	IN OF C			'11 v -	e 1 or <u>C</u>	
Project Name/	No. 1 RARITAN ARSEN	AC Sam	ples Shipm	ent Date	7 10	-24-91 Bill to	o: ⁵	
mple Team Memb	pers? Y. Petrusli	J	Lab De	stination	8 77	Edisod		
Profit Center	No. 3 4614	er. de	Lab	Contact	9 Ste	we voell		
Project Mana	ager ⁴	Proje	ect Contac	t/Phone	12 (908)	725 - 2000 # 429 Report to	:10	MARKAN MINET WIT THE ST DE RIS AND INSTRUMENTAL TO ST
Purchase Order	No. ⁶		Carrier/W	aybill No.	13	<u> </u>		
Required Report D	Date 11		ONE	CONT	AINER	PER LINE	10. MILES O 1 2 1 7 1 9 10 10 10 10 10 10 10 10 10 10 10 10 10	
Sample ¹⁴ Number	Sample ¹⁵ Description/Type	Date/Time ¹⁶ Collected	Container ¹ Type	Sample ¹⁸ Volume	p _{re-} ¹⁹ servative	Program /	Condition on ²¹ Receipt	Disposal ²² Record No.
32658 A	Waste pile Ard 2 Drum Comp.	10-23/24/91 1130	Qt.Gl.	950ML	NONE	total lead/tPMG/tox PCB15/total solids/Flash		
1 8	1		60ml	bonl	1	BLEX		
d c	V		60 MC	60 ML		BLEX		
							•	
							man area de	
				 	-			
				 				Self team at
				 				<u> </u>
				<u> </u>			<u> </u>	<u> </u>
pecial Instructio	ons: 23 Lot#	9091						
ossible Hazard		itant 🔟 Poi	ison Bl	Unknowi		Sample Disposal: ²⁵ Return to Client Disposal	osal by Lab 🕰 🛚 Archiv	e (mos
lon-hazard 🔟 Fl urnaround Time		icanic 🔟 Pol		C Level: 2		newitt to client Disp	osal by Laboa Archiv	e (mo
Iormal 🗂 Rush			1.1.		III. 🔟	Project Specific (specify)		
. Relinquished by lignature/Affiliation)	Elonaw. Fet	Dat W <i>SW</i> Tim		24-91 1525	1. Rece (Signature/	ived by 28	TTAS Time:	1525
2. Relinquished by (Signature/Affiliation) Date: Time:			2. Rece (Signature/A	ived by (Affiliation)	Date: Time:			
3. Relinquished by Signature/Affiliation) Date: Time:			3. Rece (Signature/	ived by Affiliation)	Date: Time:			
Comments: ²⁹					-			



ANALYTICAL SERVICES

CERTIFICATE OF ANALYSIS

Raritan Arsenal

c/o IT Corp.

165 Fieldcrest Ave. Edison, NJ 08837

Attn: Ms. Dolly Li

Date: March 20, 1992

NJ Lab Certification ID#: 12064

Job No.: 305788

P.O. Number: 305788-02

This is the Certificate of Analysis for the following samples:

Client Project ID: USACE - RARITAN ARSENAL

Date Received:

03/13/92

Number of Samples:

Sample Type:

SOIL

Samples were labeled as follows:

SAMPLE IDENTIFICATION

LABORATORY #

SOIL 135334

F2-03-155-01

SOIL MS

F2-03-155-02

Reviewed and Approved:

Ralph A. Kocsis

Project Manager

Company: Date:

Raritan Arsenal March 20, 1992

Client Job No.: 305788

IT ANALYTICAL SERVICES EDISON, NJ

(908) 225-2000

Work Order: F2-03-155

SAMPLE ID	SOIL 135334	SOIL MS	
SAMPLED	03/13/92	03/13/92	**********
TEST			ÜNITS
Total Solids	92 [0.01]		Percent
TCLP Extraction	03/17/92	03/17/92	Date
		•	
-	=		₹

ND indicates the parameter was not detected. Detection limits are specified in [].

Company:

Date:

Raritan Arsenal

March 20, 1992

Client Job No.: 305788

IT ANALYTICAL SERVICES EDISON, NJ

(908) 225-2000

Work Order: F2-03-155

TEST NAME: TCLP - Metals

SAMPLE ID: SOIL 135334 SAMPLE DATE: 03/13/92

TCLP EXTRACTION: 03/17/92 ANALYSIS DATE: 03/18/92

> Analysis Results in MG/L Detection Method Limit

Lead (Pb) 0.051 0.050 **Furnace**

Comments: ND indicates the compound is not detected at the level indicated. Results have NOT been adjusted for matrix spike recoveries.

Raritan Arsenal

Date:

March 20, 1992

Client Job No.: 305788

IT ANALYTICAL SERVICES EDISON, NJ

(908) 225-2000

Work Order: F2-03-155

TEST NAME: TCLP - Metals

SAMPLE ID: SOIL MS SAMPLE DATE: 03/13/92

TCLP EXTRACTION: 03/17/92 ANALYSIS DATE: 03/18/92

Results in <u>% Rec</u>

Lead (Pb) <u>82</u>

Company: Date:

Raritan Arsenal March 20, 1992

Client Job No.: 305788

IT ANALYTICAL SERVICES EDISON, NJ

(908) 225-2000

Work Order: F2-03-155

II ANALYTICAL RESULTS/METHODOLOGY

The analytical results for this report are presented by Analytical test. Each set of data will include sample identification information, the analytical results, and the appropriate detection limits. Detection limits may vary due to factors arising from concentration/dilution of the sample and sample matrix. ND denotes that the compound is not detected at or above the indicated detection limit. The methodologies for the analytical results requested are described below.

TCLP - Metals

The analysis of metals is based on Method 200.7 from 40CFR, Part 136. Samples to be analyzed by flame AA or ICP are digested with hydrochloric and nitric acid. Furnace analysis requires nitric acid digestion and mercury samples are digested with nitric and sulfuric acid.

Lead, Arsenic, Selenium, Antimony and Thallium are analyzed by graphite furnace, Mercury by cold vapor AA and all other metals by flame AA or ICP.

Total Solids

The analysis of total solids is based on Standard Methods, 16th Edition -(209F). A well mixed sample is evaporated in a weighed dish and dried to constant weight. The increase in weight over that of the empty dish represents the total solids. In other words a sample is first weighed then subjected to tempatures of 103 degrees celsius for four hours after which the sample is re-weighed; the difference in the two weights being the % total solids.

TCLP Extraction

USEPA Method 1311-Federal Register Vol. 55, No. 61., March 29, 1990. Solid phase is extracted with a predetermined extraction fluid, based on alkalinity of the solid phase, equal to twenty times the weight of the solid phase.

III QUALITY CONTROL

The Determinations were performed in accordance with EPA/NJDEP approved methodology.

DEFINITIONS

ND(U)	-	Analyte was analyzed for, but not detected. The value given after the ND or U is the detection
		limit for that compound.

- A The compound denoted with an "A" indicates a suspected aldol condensation product.
- B Indicates the compound was also detected in the blank, but at levels less than 5X the detection limit. Values for this compound may be suspect
- Indicates the compound was detected in the sample, but at levels less than the detection limit.
 Results should be regarded as estimated.

MS -	Matrix Spike	ug/L - Micrograms/Liter	*Rec - Precent Recovery
MSD -	Matrix Spike Duplicate	ug/Kg - Micrograms/Kilogram	mg/L - Milligrams/Liter
RPD -	Relative Percent Difference	mg/Kg - Milligrams/Kilogram	DL - Detection Limit

OUALITY CONTROL WINDOWS

Surrogate Reco	veries		Surrogate Recoveri		
GC/MS Volatiles (624, 8240) Water	Soil	GC/MS SemiVolatiles (625, 8270)	Water	Soil
D4-1,2-dichloroethane		70-121	D5-Nitrobenzene	35-114	23-120
8-toluene	88-110	81-117	2-Fluorobiphenyl	43-116	30-115
-Bromofluorobenzene	86-115	74-121	D14-Terphenyl	33-141	18-137
<u></u>			D5-Phenol	10-94	24-113
			2-Fluorophenol	21-100	25-121
			2,4,6-Trobromophenol	10-123	19-122

Surrogate Reco	veries		Surrogate Reco	Surrogate Recoveries		
Pesticides* (608, 8080)	Water	Soil	Method 602, BTEX, 8020	Water	Soil	
Tetrachloro-m-xylene	60-150	60-150	4-Bromofluorobenzene	62-139	62-138	
Dibutyl chlorendate	24-154	20-150				

^{*} SW846 allows one surrogate to be outside recovery windows.

Surrogate R	ecoveries		Surrogate Recoveries			
Method 601 (8010)	Water	Soil	Method 8060**	Water	Soil	
Bromochloromethane	74-121	74-121	Tetrachloro-m-xylene	60-150	60-150	
			Decachlorobiphenyl	60-150	60-150	
Method 8015	Water	Soil	Herbicides**	Water	Soil	
Acetone	68-132	68-132	2.4-DB	60-150	60-150	
recure	***************************************		** Advisor	ry Limits		
METALS / WET CHEMISTRY	5			_		
	Recovery	RPD		Recovery	RPD	
Blank Spike	75-125	•	Replicate		<20%	
Blank Spike Duplicate	75-125	<20%	Check Standard	90-110		
latrix Spike	75-125					
Jatrix Spike Duplicate	75-125	<20%				



ANALYSIS REQUEST AND CHAIN OF CUSTODY RECORD*

Reference Doc	ument N 363598
Page 1 of	_

CORPORA				ı			gc 1 6	
Project Name/	NO. 1 USACE -	Ravitous f	trsenal ples Shipm	ent Date	7 3/13	/92 Bill	to:5 P.O.BOX 590 Edison, NJ	2
Sample Team Memb	bers? Dolly Li		Lab De	stination	8 IT	Edison	Edison, NJ	08878
Profit Center	No. 3 3811		Lab	Contact	9 Rale	h Kocsis		
Project Man	ager4Chick Magi	lsm Proj	ect Contac	t/Phone	12 Dal	4Li (908)548-877 Report t	O IT COMP	Attn. Dolly4
Purchase Order	No. 6 305788-02		Carrier/W	aybill No.	13	, marries - 146-110 - 17100000	P.O.BOX 590 Edison, NJ	2
Required Report (Date 11 3/23/92		ONE	CONT	AINER	PER LINE	Edison, NJ	08818
Sample ¹⁴ Number	Sample ¹⁵ Description/Type	Collected	Container 1	Sample ¹⁸			Condition on ²¹	Disposal ²² Record No.
135334	soil	313192	glassjan	1602	None	TCLP Lead	good no worker AV	er-wine and company
							And Camp Sur	BK in I
			;		1			
						-		
					1			कार्क स्ट्रेश्च अपूर्
	Lot # 104	23.			:			
Special Instruction	ons: 23 TCLP L	ead (w	ith moe	trix g	pike	at I-WK r	ush	
Possible Hazard Non-hazard 🔟 F		ritant 🔟 Poi	son B	Unknowr	Xi	Sample Disposal: ²⁵ Return to Client D isp	posal by Lab 🔏 Archive	(mos.)
Turnaround Time Normal _ Rush	V	week	QC I.	Level: 2		Project Specific (specify):		
1. Relinquished by [Signature/Affiliation]	28 Oelly &	Dat Tim	- / -//-	9.2 30	1. Recei (Signature/A	ived by 28 /// f	Date: Time:	
2. Relinquished by (Signature/Affiliation)		Dat Tim			2. Recei (Signature/A	ived by (ffiliation)	Date: Time:	- V/ 1 8 8 8 15 8 8 4 4 4 4
3. Relinquished by (Signature/Affiliation)		Dat Tim			3. Recei	ived by Miliation)	Date: Time:	
Comments: 29		· 1-4				*		
								•



ANALYTICAL SERVICES

CERTIFICATE OF ANALYSIS

USACE

Date: May 06, 1992

c/o IT Corporation 165 Fieldcrest Avenue Edison NJ 08837

Attn: Ms. Dolli Li

NJ Lab Certification ID#: 12064

Job No.: 305788

P.O. Number: 30578805

This is the Certificate of Analysis for the following samples:

Client Project ID:

USACE

Date Received:

04/28/92

Number of Samples:

2

Sample Type:

SOIL

I Samples were labeled as follows:

SAMPLE IDENTIFICATION

LABORATORY #

SOIL SAMPLE B-2

F2-04-258-01

SOIL SAMPLE B-3

F2-04-258-02

Reviewed and Approved:

Patrick B. Brown

Project Manager

Company:

USACE

Date:

May 06, 1992

Client Job No.: 305788

IT ANALYTICAL SERVICES

EDISON, NJ

(908) 225-2000

Work Order: F2-04-258

	MPLE B-3	SOIL SA	SOIL SAMPLE B-2	SAMPLE ID
UNITS	04/28/92		04/28/92	SAMPLED EST
mg/Kg Dry Wt	54 24]	ſ	1700 [240]	etroleum Hydrocarbons
Percent	84 0.01]		84 [0.01]	otal Solids

ND indicates the parameter was not detected. Detection limits are specified in [].

Company:

USACE

Date:

May 06, 1992

Client Job No.: 305788

IT ANALYTICAL SERVICES

EDISON, NJ

(908) 225-2000

Work Order: F2-04-258

IA COMMENTARY

Matrix spike / duplicate and replicate analyses for petroleum hydrocarbons could not be performed due to insufficient sample volume. A blank spike and blank spike duplicate were analyzed with the samples to meet QC requirements.

Company:

USACE

Date:

May 06, 1992

Client Job No.:

305788

IT ANALYTICAL SERVICES EDISON, NJ

(908) 225-2000

Work Order: F2-04-258

II ANALYTICAL RESULTS/METHODOLOGY

The analytical results for this report are presented by Analytical test. Each set of data will include sample identification information, the analytical results, and the appropriate detection limits. Detection limits may vary due to factors arising from concentration/dilution of the sample and sample matrix. ND denotes that the compound is not detected at or above the indicated detection limit. The methodologies for the analytical results requested are described below.

Petroleum Hydrocarbons - IR

The analysis of petroleum hydrocarbons is based on EPA Method, 418.1. Water samples are prepared by separatory funnel liquid-liquid extraction using freon as the extracting solvent. Soils are prepared by soxhlet extraction using freon as the extracting solvent. Silica gel is added to remove interferences. Extracts are analyzed by infrared spectrophotometer and concentrations are determined by direct comparison with standards.

Total Solids

The analysis of total solids is based on Standard Methods, 16th Edition - (209F). A well mixed sample is evaporated in a weighed dish and dried to constant weight. The increase in weight over that of the empty dish represents the total solids. In other words a sample is first weighed then subjected to tempatures of 103 degrees celsius for four hours after which the sample is re-weighed; the difference in the two weights being the % total solids.

III QUALITY CONTROL

The Determinations were performed in accordance with EPA/NJDEP approved methodology.

DEFINITIONS

ND(U)	-	Analyte was analyzed for, but not detected. The value given after the ND or U is the detection
		limit for that compound.

- A The compound denoted with an "A" indicates a suspected aldol condensation product.
- B Indicates the compound was also detected in the blank, but at levels less than 5% the detection limit. Values for this compound may be suspect
- Indicates the compound was detected in the sample, but at levels less than the detection limit.
 Results should be regarded as estimated.

Ms -	Matrix Spike	ug/L - Micrograms/Liter	%Re
			* * K =

MSD - Matrix Spike Duplicate ug/Kg - Micrograms/Kilogram mg/L - Milligrams/Liter

RPD - Relative Percent Difference mg/Kg - Milligrams/Kilogram DL - Detection Limit

QUALITY CONTROL WINDOWS

Surrogate Recove	eries		Surrogate Recoveri	es	
GC/MS Volatiles (624, 8240)	Water	Soil	GC/MS SemiVolatiles (625, 8270)	Water	Soil
D4-1,2-dichloroethane	76-114	70-121	D5-Nitrobenzene	35-114	23-120
D8-toluene	88-110	81-117	2-Fluorobiphenyl		30-115
4-Bromofluorobenzene	86-115	74-121	D14-Terphenyl	33-141	
			D5-Phenol		24-113
			2-Fluorophenol		
			2,4,6-Trobromophenol		19-122
Surrogate Recoveries			Surrogate Recoveri	es	

Surrogate Reco	AST TES		Surrogate Recovi	eries	
Pesticides* (608, 8080)	Water	Soil	Method 602, BTEX, 8020	Water	Soil
Tetrachloro-m-xylene	60-150	60-150	4-Bromofluorobenzene		62-138
Dibutyl chlorendate	24-154	20-150		QE-137	72. T.M

^{*} SW846 allows one surrogate to be outside recovery windows.

Surrogate Recoveries			Surrogate Recoveries				
Method 601 (8010)	Water	Soil	Method 8060**	Water	Soil		
Branochloromethane	74-121	74-121	Tetrachloro-m-xylene	60-150	60-150		
			Decachlorobiphenyl	60-150	60-150		
Method 8015	Water	Soil	Herbicides**	Water	Soil		
Acetone	68-132	68-132	2,4-DB	60-150	60-150		
MERIAL C. / LEEP CERSONS			** Advisory Limits				
METALS / WET CHEMISTRY							
	Recovery	<u>RPD</u>		Recovery	<u>RPD</u>		
Blank Spike	75-125		Replicate		<20%		
Blank Spike Duplicate	75-125	<20%	Check Standard	90-110			
Matrix Spike	75-125			70 110			
Matrix Spike Duplicate	75-125	~20e	;				

INTERNATIONA	AL	A	NALYSI	S REQ	UEST A	AND F 204 - 2 CORD*	SS Reference Document	No. 37197
TECHNOLOGY	I USACE!							
Project Name/No.	USACE/305	788 Samp	ples Shipm	ent Date	7 4/2	28/92	Bill to:5 P.O. BOX	5902
Sample Team Members	2 Dolly Li		Lab De	stination	8 Ed	ison IT Lab	IT Corp1 Edison. N	RA T 08X1A
Dooft Conton No.	3 ADS 166 - 29	Q11	16	0	9 Dal	-h Vinceie		
Project Manager	*Chick Magu	CAOW Proje	ect Contac	t/Phone	12 Dol	ly Li /548-87	rt to: 10 Dolly Li	Apple of the contract of the c
Purchase Order No. '	0		Carrier/W	aybill No.	13		IT - Ed,30	n
Required Report Date	" / Week					PER LINE	908-548-8	<i>5777</i> .
Sample ¹⁴ Number D	Sample ¹⁵ Description/Type	Date/Time ¹⁶ Collected	Type	Volume	servative	Progrem	20 Condition on ²¹ Receipt	Disposal ²² Record No.
131703 5	011	428/92 11:00 am	Bottle		None	TPHC	Good P.Y.	
131704 5	soil .	4/28/92 11:00 aw	glass	1607	None	TPHC	V	<i>A</i> .6
		715001000	Conce				USEC	N. E. Y
								†
			ļ	ļ				
			ļ	ļ				V
							AND THE PERSON NAMED IN COLUMN	3,000
Special Instructions:	23 Please cal	el Wolly	Li who	en 401	ı get	verbal result	of TPHC by 12-1	W TAT
Possible Hazard Ident	tification: 24	,		•	<u> </u>	Sample Disposal: ²⁵ Return to Client		g (mos.)
Turnaround Time Red Normal Rush 2				Level: 2	7	Project Specific (speci	if y):	
1. Relinquished by ²⁸ (Signature/Affiliation)	elluxi	Dat Tim		93 18am	1. Recei	ived by ²⁸	Date: Time:	4-28-9- 1140
2. Relinquished by (Signature/Affiliation)	7	Dat Tim			2. Recei	ived by (Miliation)	Date: Time:	
3. Relinquished by (Signature/Affiliation)		Dat Tim			3. Recei	ived by Affiliation)	Date: Time:	
Comments: 29	f# 107	 38						



ANALYTICAL **SERVICES**

CERTIFICATE OF ANALYSIS

USACE

Date: May 08, 1992

c/o IT Corporation 165 Fieldcrest Avenue Edison NJ 08837

Attn: Ms. Dolli Li

NJ Lab Certification ID#: 12064

Job No.: 305788 P.O. Number: 30578807

This is the Certificate of Analysis for the following samples:

Client Project ID:

POST EXCAVATION SOIL SAMPLES

Date Received:

05/04/92

Number of Samples:

Sample Type:

SOIL

4

Samples were labeled as follows:

SAMPLE IDENTIFICATION	LABORATORY #
PS-1	F2-05-034-01
PS-2	F2-05-034-02
PS-3	F2-05-034-03
PS-4	F2-05-034-04

Reviewed and Approved:

Patrick B. Project Manager

> American Council of Independent Laboratories International Association of Environmental Testing Laboratories American Association for Laboratory Accreditation

Company:

USACE

Date: May 08, 1992

Client Job No.: 305788

IT ANALYTICAL SERVICES

EDISON, NJ

(908) 225-2000

Work Order: F2-05-034

SAMPLE ID		PS-1		PS-2		PS-3	
SAMPLED EST		05/04/92	(05/04/92		05/04/92	UNITS
etroleum Hydrocarbons	ı	21 21]	ι	ND 22 j	ι	ND 21]	mg/Kg Dry Wt
otal Solids	ι	94 0.01]	ι	92 0.01]	Į	95 0.01]	Percent
·							
·							
							·
		·					

ND indicates the parameter was not detected. Detection limits are specified in [].

Company: Date:

USACE

May 08, 1992

Client Job No.: 305788

IT ANALYTICAL SERVICES

EDISON, NJ

(908) 225-2000

Work Order: F2-05-034

SAMPLE ID	PS-4	
SAMPLED TEST	05/04/92	UNITS
Petroleum Hydrocarbons	ND [21]	mg/kg Dry Wt.
Total Solids	94 [0.01]	Percent
+		₹

ND indicates the parameter was not detected. Detection limits are specified in [].

Company:

USACE

Date:

May 08, 1992

Client Job No.:

305788

IT ANALYTICAL SERVICES EDISON, NJ

(908) 225-2000

Work Order: F2-05-034

IA COMMENTARY

Matrix spike / duplicate and replicate analyses for petroleum hydrocarbons could not be performed due to insufficient sample volume. A blank spike and blank spike duplicate were analyzed with the samples to meet QC requirements.

Company:

USACE

Date:

May 08, 1992

Client Job No.: 305788

IT ANALYTICAL SERVICES EDISON, NJ

(908) 225-2000

Work Order: F2-05-034

II ANALYTICAL RESULTS/METHODOLOGY

The analytical results for this report are presented by Analytical test. Each set of data will include sample identification information, the analytical results, and the appropriate detection limits. Detection limits may vary due to factors arising from concentration/dilution of the sample and sample matrix. ND denotes that the compound is not detected at or above the indicated detection limit. The methodologies for the analytical results requested are described below.

Petroleum Hydrocarbons - IR

The analysis of petroleum hydrocarbons is based on EPA Method, 418.1. Water samples are prepared by separatory funnel liquid-liquid extraction using freon as the extracting solvent. Soils are prepared by soxhlet extraction using freon as the extracting solvent. Silica gel is added to remove interferences. Extracts are analyzed by infrared spectrophotometer and concentrations are determined by direct comparison with standards.

Total Solids

The analysis of total solids is based on Standard Methods, 16th Edition - (209F). A well mixed sample is evaporated in a weighed dish and dried to constant weight. The increase in weight over that of the empty dish represents the total solids. In other words a sample is first weighed then subjected to tempatures of 103 degrees celsius for four hours after which the sample is re-weighed; the difference in the two weights being the % total solids.

III QUALITY CONTROL

The Determinations were performed in accordance with EPA/NJDEP approved methodology.

DEFINITIONS

- ND(U) Analyte was analyzed for, but not detected. The value given after the ND or U is the detection limit for that compound.
 - A - The compound denoted with an "A" indicates a suspected aldol condensation product.
 - В - Indicates the compound was also detected in the blank, but at levels less than 5% the detection limit. Values for this compound may be suspect
 - J - Indicates the compound was detected in the sample, but at levels less than the detection limit. Results should be regarded as estimated.

MS - Matrix Spike

ug/L - Micrograms/Liter

Rec - Precent Recovery

MSD - Matrix Spike Duplicate

ug/Kg - Micrograms/Kilogram

mg/L - Milligrams/Liter

RPD - Relative Percent Difference mg/Kg - Milligrams/Kilogram

DL - Detection Limit

QUALITY CONTROL WINDOWS

Surrogate Recoveries					
GC/MS Volatiles (624,	8240)	Water	Soil		
D4-1,2-dichloroethane		76-114			
D8-toluene		88-110	81-117		
4-Bromofluorobenzene		86-115	74-121		

Surrogate Recoveries

Surrogate Recoveries

Pesticides* (608, 8080)	Water	Soi 1
Tetrachloro-m-xylene Dibutyl chlorendate	60-150 24-154	60-150

Surrogate Recoveries

Method 602			Water	Soil
4-Bromofluo	robenz	ene	62-139	

^{*} SW846 allows one surrogate to be outside recovery windows.

74-121 74-121

Surrogate	Recoveries
Method 601 (8010)	Water
Bromochloromethane	74-121

Method 8015 Acetone	Water 68-132	<u>Soil</u> 68-132
METALS / WET CHEMISTRY		
Blank Spike	Recovery 75-125	RPD
Blank Spike Duplicate Matrix Spike	75-125 75-125	<20%
Matrix Spike Duplicate	75-125	<20%

Surrogate Recoveries

MELLING BUBUAN	Water	Soil
Tetrachloro-m-xylene	60-150	
Decachlorobiphenyl	60-150	
Herbicidocht		

Herbicides	Water Water	Soil
2,4-DB	60-150	

** Advisory Limits

Replicate	Recovery	<u>RPD</u> <20€
Check Standard	90-110	₹20%

INTERNAT TECHNOL CORPORA	OGY
--------------------------------	-----

ANALYSIS REQUEST AND *

		- b	
V=7-05-	Perence Document No.		
1 20	Reference Document No.	572	001
D*	Page 1 of/_		

CORPORA		•		IN OF C	,03101	DY REC	JUND	raye	1 UI <u>/</u>	
Project Name/	No. 1 USACE	30518	Samp	oles Shipm	ent Date	7 5/4	1/92	Bill to:5	IT Corp -R	Α
Sample Team Memi	pers 2 Dolly	Li/	Jim Wagi	W Lab De	stination	8 Edis	on Lab		P.O. BOX 59 Edison N.	02
Profit Center	Nn 3 3811'	•	•	l ah	Contact	9 Pat	Brown			1 00010
Project Man	ager4 Chick	Magi	lum Proje	ect Contact	t/Phone	12 Doll	4 Li /548-87	77.	o Dolla Li	
Purchase Order	No. ⁶	,		Carrier/W	avbill No.	13	Нер	ort to: 1	IT COMP.	
Required Report (11.190	12						Edison, NT	o %831
							PER LINE			
Semple ¹⁴ Number	Sample Description/	Туре	Date/Time ¹⁶ Collected	Container' / Type	Sample 18 Volume	Pre- ¹⁹ servative	Requested Testin Program	g ²⁰	Condition on ²¹ Receipt	Disposal ²² Record No.
135502	Soil Samy	R PS	11200am	16 03 91ass Lar	1602	None	TPHC	(100 PDT	ge STANG SERVICES
135503	11	PS-2	12:05 pm	W (I						
135504	,1	P5-3	1255pm	11						
135505	M	P5-4	14:00	11	V	٧	V		1 +	
				'						
										Police Man Va
					 	:				
							,			
Special Instruction	ons: 23 Verb	al re	port rea	sults	in r	12 hr	نام			
Possible Hazard	Identification:	24)			. 1	Sample Disposal: 4	25	\ <u>/</u>	
		Skin Irrita	ant 🔟 Pois	son B	Unknown		Return to Client	Disposi	al by Lab 🔼 Archive	(mos.)
Turnaround Time Normal 🔟 Rush	Required: 26	TA1	-	1.18	Level: 2	MI 🖢	Project Specific (spe	cify];	•	
Relinquished by (Signature/Affiliation)		太。	Dat Tim		<i>-92</i> 30	1. Rece	ived by 28 1 Roly	No.	Date: Time:	5-4-92
	2. Relinquished by Date:						2. Received by (Signature/Affiliation) Date:			
3. Relinquished by (Signature/Affiliation)	! :		Dat Tim	e:		3. Rece	ived by Affiliation)		Date: Time:	
Comments: 29	Loft	7/1	792			1	**************************************			



ANALYTICAL SERVICES

CERTIFICATE OF ANALYSIS

USACE

Date: May 19, 1992

c/o IT Corporation 165 Fieldcrest Avenue Edison NJ 08837 Attn: Ms. Dolli Li

NJ Lab Certification ID#: 12064

Job No.: 305788 P.O. Number: 30578806

This is the Certificate of Analysis for the following samples:

Client Project ID: USACE

Date Received:

04/28/92

Number of Samples: Sample Type:

SOIL

2

I Samples were labeled as follows:

SAMPLE IDENTIFICATION

LABORATORY #

WASTEPILE SOIL

F2-04-259-01

WASTEPILE SOIL MS

F2-04-259-02

Reynewed and Approved:

Patrick B.

Project Manager

Company:

USACE

Date:

May 19, 1992

Client Job No.: 305788

IT ANALYTICAL SERVICES

EDISON, NJ

(908) 225-2000

Work Order: F2-04-259

SAMPLE ID	WASTEPILE SOIL	WASTEPILE SOIL MS	
SAMPLED TEST	04/28/92	04/28/92	UNITS
Ignitability	Non-ignitable	·	Observation
Petroleum Hydrocarbons	2300 [480]		mg/Kg Dry Wt.
рн	5.3 [0.01-14]		pH (Units)
Total Solids	84 [0.01]		Percent
TCLP Extraction	05/07/92	05/07/92	Date
Total Organic Halogen	ND [240]		mg/Kg Dry Wt.

ND indicates the parameter was not detected. Detection limits are specified in [].

Company:

USACE

Date:

May 19, 1992

Client Job No.: 305788

IT ANALYTICAL SERVICES

EDISON, NJ

(908) 225-2000

Work Order: F2-04-259

TEST NAME: Volatile Organics

SAMPLE ID: WASTEPILE SOIL SAMPLE DATE: 04/28/92 ANALYSIS DATE: 04/29/92

	Results in	ug/Kg Dry Wt.	Detection Limit
Benzene		ND	1.2
Ethylbenzene		19	1.2
Toluene		3.6	1.2
Total Xylenes		120	1.2

Comments: ND indicates the compound is not detected at the level indicated.

Company:

USACE

Date:

May 19, 1992

Client Job No.: 305788

IT ANALYTICAL SERVICES EDISON, NJ

(908) 225-2000

Work Order: F2-04-259

TEST NAME: PCB's

SAMPLE ID: WASTEPILE SOIL SAMPLE DATE: 04/28/92 ANALYSIS DATE: 05/02/92

		Results	in	ug/Kg	Detection
				Dry Wt.	Limit
Arochlor	1016			ND	46
Arochlor	1221			ND	<u>46</u>
Arochlor	1232			<u> </u>	46
Arochlor	1242			ND	46
Arochlor	1248			ND	46
Arochlor	1254			ND	46
Arochlor	1260			ND	46

Comments: ND indicates the compound is not detected at the level indicated.

Company:

USACE

Date:

May 19, 1992

Client Job No.: 305788

TEST NAME: TCLP - Metals

SAMPLE ID: WASTEPILE SOIL SAMPLE DATE: 04/28/92

TCLP EXTRACTION: 05/07/92 ANALYSIS DATE: 05/18/92

> Results in mg/L Detection Analysis Limit Method

Lead 0.050 (Pb) ____ND Furnace

Comments: ND indicates the compound is not detected at the level indicated. Results have NOT been adjusted for matrix spike recoveries.

IT ANALYTICAL SERVICES

Work Order: F2-04-259

EDISON, NJ

(908) 225-2000

Company:

USACE

Date:

May 19, 1992

Client Job No.:

305788

IT ANALYTICAL SERVICES EDISON, NJ

(908) 225-2000

Work Order: F2-04-259

IA COMMENTARY

Matrix spike / duplicate recoveries did not meet QC acceptance criteria for ethylbenzene and xylenes for WSTERPILE SOIL (F204259-01) due to matrix effects. Results were accepted on the basis of blank spike recoveries.

The sample underwent an acid wash and a TBA cleanup for PCB analysis.

pH analysis was requested on 5/12/92. The pH was analyzed on 5/12/92 which is thirteen days past holding time.

Matrix spike / duplicate recoveries did not meet QC acceptance criteria for lead for WASTEPILE SOIL (F204259-01) due to matrix effects. Results were accepted on the basis of blank spike recoveries.

TCLP - Metals Matrix Spike

TCLP Extraction: 05/07/92 Analysis Date: 05/18/92

Percent Recovery

Lead 74

Company:

USACE

Date:

May 19, 1992

Client Job No.:

305788

IT ANALYTICAL SERVICES EDISON. NJ

(908) 225-2000

Work Order: F2-04-259

II ANALYTICAL RESULTS/METHODOLOGY

The analytical results for this report are presented by Analytical test. Each set of data will include sample identification information, the analytical results, and the appropriate detection limits. Detection limits may vary due to factors arising from concentration/dilution of the sample and sample matrix. ND denotes that the compound is not detected at or above the indicated detection limit. The methodologies for the analytical results requested are described below.

Volatile Organics - GC (Soil)

For the analysis of volatile organics EPA Method 8020 of Test Methods for Evaluating Solid Waste (SW-846), 3rd Edition is used. An inert gas is bubbled through a sample dispersed at 40 degrees C in water and the purgeables are efficiently transferred to the vapor phase. The vapor is swept through a sorbent column where the purgeables are trapped. After purging is completed, the sorbent column is heated and backflushed with the inert gas to desorb the purgeables onto a gas chromatographic column. The gas chromatograph is temperature programmed to resolve the purgeables which are then detected with a photoionization detector.

PCB's (Soil)

The analysis of PCB's is based on Methods 8080 and 3550 of Test Methods for Evaluating Solid Waste, SW-846, 3rd Edition. An aliquot of sample is sonicated three times with a 1:1 solution of methylene chloride/acetone and exchanged to hexane. The extracts are column cleaned and concentrated. The extract is then separated by gas chromatography and the analytes are measured using an electron capture detector.

Total Organic Halogens

The analysis of total organic halogens (TOX) in Soil is based on Test Methods for Evaluating Solid Waste, 3rd Edition, November 1986, Method 9020. Coulometric titration.

TCLP - Metals

The analysis of metals is based on Method 200.7 from 40CFR, Part 136. Samples to be analyzed by flame AA or ICP are digested with hydrochloric and nitric

Company:

USACE

Date:

May 19, 1992

Client Job No.:

305788

IT ANALYTICAL SERVICES EDISON, NJ

(908) 225-2000

Work Order: F2-04-259

acid. Furnace analysis requires nitric acid digestion and mercury samples are digested with nitric and sulfuric acid.

Lead, Arsenic, Selenium, Antimony and Thallium are analyzed by graphite furnace, Mercury by cold vapor AA and all other metals by flame AA or ICP.

Ignitability - Soils

A flame is introduced to an aliquot of sample at standard temperature and pressure. If the sample burns persistently and vigorously, it is considered to be ignitiable.

Petroleum Hydrocarbons - IR

The analysis of petroleum hydrocarbons is based on EPA Method, 418.1. Water samples are prepared by separatory funnel liquid-liquid extraction using freon as the extracting solvent. Soils are prepared by soxhlet extraction using freon as the extracting solvent. Silica gel is added to remove interferences. Extracts are analyzed by infrared spectrophotometer and concentrations are determined by direct comparison with standards.

pH (Soil)

The analysis of pH is based on SW-846, 3rd Edition (9045). An aliquot of sample is diluted and mixed into deionized water. The intensity of the acidic or basic character of the solution at a specific temperature is determined by pH or hydrogen ion activity.

Total Solids

The analysis of total solids is based on Standard Methods, 16th Edition - (209F). A well mixed sample is evaporated in a weighed dish and dried to constant weight. The increase in weight over that of the empty dish represents the total solids. In other words a sample is first weighed then subjected to tempatures of 103 degrees celsius for four hours after which the sample is re-weighed; the difference in the two weights being the % total solids.

Company:

USACE

Date:

May 19, 1992

Client Job No.: 305788

IT ANALYTICAL SERVICES EDISON, NJ

(908) 225-2000

Work Order: F2-04-259

TCLP Extraction

USEPA Method 1311-Federal Register Vol. 55, No. 61., March 29, 1990. Solid phase is extracted with a predetermined extraction fluid, based on alkalinity of the solid phase, equal to twenty times the weight of the solid phase.

III QUALITY CONTROL

The Determinations were performed in accordance with EPA/NJDEP approved methodology.

DEFINITIONS

- ND(U) Analyte was analyzed for, but not detected. The value given after the ND or U is the detection limit for that compound.
 - A The compound denoted with an "A" indicates a suspected aldol condensation product.
 - B Indicates the compound was also detected in the blank, but at levels less than 5X the detection limit. Values for this compound may be suspect
 - Indicates the compound was detected in the sample, but at levels less than the detection limit.
 Results should be regarded as estimated.

MS - Matrix Spike

ug/L - Micrograms/Liter

Rec - Precent Recovery

MSD - Matrix Spike Duplicate

ug/Kg - Micrograms/Kilogram

mg/L - Milligrams/Liter

RPD - Relative Percent Difference

mg/Kg - Milligrams/Kilogram

4-Bromofluorobenzene

DL - Detection Limit

62-139 62-138

QUALITY CONTROL WINDOWS

Tetrachloro-m-xylene

Dibutyl chlorendate

Surrogate Rec			Surrogate Recoveri	es	
olatiles (624, 824	0) Water	Soil	GC/MS SemiVolatiles (625, 8270)	Water	
-dichloroethane	76-114	70-121	D5-Nitrobenzene	35-114	
luene	88-110	81-117	2-Fluorobiphenyl	43-116	
omofluorobenzene	86-115	74-121	D14-Terphenyl	33-141	
			D5-Phenol	10-94	
			2-Fluorophenol	21-100	
			2,4,6-Trobromophenol	10-123	
Surrogate Rec	overies		Surrogate Recoverie	es	
<u>icides* (608, 8080)</u>	Water	Soil	Method 602, BTEX, 8020	Water	

* SW846 allows one surrogate to be outside recovery windows.

60-150 60-150

24-154 20-150

Surrogate F	<i>lecoveries</i>		Surrogate Recoverie	s	
Method 601 (8010)	Water	Soil	Method 8060**	Water	Soil
Bromochloromethane	74-121	74-121	Tetrachloro-m-xylene	60-150	60-150
			Decachlorobiphenyl	60-150	60-150
Method 8015	Water	Soil	Herbicides**	Water	Soil
Acetone	68-132	68-132	2,4-DB	60-150	60-150
MITALO / LTT CITATION			** Advisory Limits		
METALS / WET CHEMISTRY	_				
	Recovery	<u>RPD</u>	Recove	rv.	RPD
Blank Spike	75-125		Replicate	_	<20%
Blank Spike Duplicate	75-125	<20%	Check Standard 90-1		
Matrix Spike	75-125				
Matrix Spike Duplicate	75 -1 25	<20%			

							F704-75	Petropos Document N	No. 371975
INTERNATION TECHNOLOGICAL	ONAL GY		AN CHA	MALYSIS	REQU USTOD	IEST AI Y REC	ND' F	Reference Document No age 1 of Bill to:5	- 1 (0)
CORPORAT	ION	cuar Das	nest.	Obligano	at Nate 7	4/28	<i>192</i> 1	Bill to:5 POBOX 5	RA =
Project Name/N	Vo. 1 U	ALE/30	Sample	les Shipme Lab Des	stination (Edison	1-IT Lab	Edison A	JJ 08818
ample Team Membe	ers 2 d	2011		Lab	Contact S	Palpi	h Koscis	D. 11.	mpa
Profit Center I	No. San	JO II	1001 Proje	ct Contact	/Phone	12 Delly	548 377 Repo	ort to: 10 DOILLI CI	7
Project Mana	ger <i>T.M</i>	CK My	()	Carrier/W	aybill No.	13	Community of	41. = Ca 150.	amp
Purchase Order	No	2.1006	741	CALE	CONT	MINER	PER LINE		T . 22
Required Report D)ate '	3 Week	Date/Time 16	ONE Container	Sample 18	Pre - ¹⁹	Requested Testing	Condition on 21 Receipt	Disposal 22 Record No.
Sample ¹⁴ Number	Descr	Sample ¹⁵ iption/Type	Date/Time Collected	Type	Volume	servative	Program	Good Ry.	Yellow
131705	soil	Bample 15 iption/Type from waste	pile 100	6 gar	1602	porce			Teo Co
75113		+						1 1	C
	+								
	 								
				+		1			
				 	+	1		(4) (2) (4) (4) (4) (4) (4) (4) (4) (4) (4) (4	1
						 		The state of the s	
	1						ļ		
				Τ.					
		11 . 11 /	00/46:6					05	
Special Instruct	tions: ²³	Hold for	unarys13	>			Sample Disposal: Return to Client	Disposal by Lab 🔏 🛚 Arch	ive (mos.)
Possible Hazar	d Identifi Flammat	Caucii.	ritant 💄 F	Poison B 🚚	Unkno	wn 🔼	Heturn to Cheric		
T ensuind Tim	ne Requ	ired: 28 ,	2 weeks	10	C Level	<u> </u>	Project Specific (5	pecify): Dat	e: 4-28-42
Normal XI Rus	sh _1 \ / e	A DICK - J	y was		28/92		ceived by ²⁸	Much STAS Edim	ie: 11:50
1. Relinquished (Signature/Affiliation)	by 28	ollyotz		ime: //	1so an	2 Rei	eived by	Dat Tim	
2 Relinguished	by	7)ate: Time:		(Signatur	e/Affiliation)	Dat	te:
(Signature/Affiliation)				Date:	-	3. Re	ceived by e/Affiliation)	Tin	10:
3. Relinquished	Dy .			Time:					

3. Relinquished by (Signature/Affiliation)

mments: 29



May 22, 1992

Mr. Chuck Magilson IT Corporation 2790 Mosside Boulevard Monroeville, Pennsylvania 15146-2792

Subject:

Submission of UXO Removal After-Action Report For UXO Remediation

Support Services at the Former Raritan Arsenal, Edison, New Jersey;

Subcontract No. CRS91-0001, Order for Services No. 0001, 0002, 0003, 0006

Dear Mr. Magilson:

Enclosed is the Final UXO Removal After-Action Report pertaining to UXO Remediation Support Services at the Former Raritan Arsenal, Edison New Jersey. EOD Technology, Inc. provided UXO Removal Services at Area 16, Building 118 and Areas 1, 4, 17 and 10 at the Former Raritan Arsenal, Edison, New Jersey.

If there are any questions regarding this report, please contact me at your earliest convenience. Unless otherwise notified within ten days, we will consider the report to be accepted.

It has been our pleasure to work with you and other personnel of IT Corporation on this contract, and we look forward to an opportunity to work with you again in the near future. I wish to thank you and your staff for the cooperation and support receive during the performance of this contract.

Sincerely,

C.M. Read

Project Manager

UXO REMEDIATION SUPPORT SERVICES FORMER RARITAN ARSENAL EDISON, NEW JERSEY

UXO REMOVAL AFTER - ACTION REPORT

SUBCONTRACT NO. CRS91-0001

ON

CONTRACT NO. DACA87-91-D-0009

ORDER FOR SERVICES NO. 0001, 0002, 0003, 0006

SUBMITTED TO:

IT Corporation

Monroeville, Pennsylvania

SUBMITTED BY:

EOD Technology, Inc.

Oak Ridge, Tennessee

May 20, 1992

"The view, opinions, and/or findings contained in the report are those of the author(s) and should not be constructed as an official Department of the Army position, policy, or decision, unless so designated by other documentation."

TABLE OF CONTENTS

SEC'	<u> </u>		<u>PAGE</u>								
1.0	INTR	ODUCTION	1								
=,	1.1	General Information	2								
	1.2	Right-of-Entry Permits									
	1.3	Key Personnel Contacts									
	1.4	News Media Opportunity									
2.0	ODED	ATIONS	4								
2.0	2.1	Area 16, Building # 643									
	2.1	Area 16, Building # 644									
	2.3	Area 16, Building Sites # 645, # 646									
	2.4	Building # 118									
	2.5	Area # 4									
	2.6	Area # 17									
•	2.7	Area # 10									
	2.8	Area 1									
	2.9	Disposal Operation									
	2.10	Equipment Utilized by EODT									
	2.11	On Site Training	23								
		2.11.1 Personnel Training	23								
		2.11.2 Daily Training	23								
		2.11.3 Visitor Training	23								
		2.11.4 End of Contract Debrief									
	2.12	Daily Activities	23								
	2.13	Weather and Terrain									
	2.14	Daily Operations Brief									
	2.15	Report of Findings									
2.0	OTTA	LETY CONTROL	24								
3.0	•	LITY CONTROL									
	3.1	UXO/OEW									
	3.2	Surface Sites									
	3.3	Subsurface Sites									
	3.4	Equipment Calibration	25								
4.0	SITE SAFETY										
	4.1	Safety Briefing (Tailgate)	25								
	4.2	Safety Violations									
	4.3	Safety Training									

TABLE OF CONTENTS

SECTION		<u>PA</u>	GE
5.0	ORDNANCE ACCOUNTABILITY RECORD		
•••	5.1	Area # 16, Building Site # 643	
	5.2	Area # 16, Building Site # 644	
	5.3	Area # 4 (ATTACHMENT 13)	
	5.4	Building # 118	
	5.5	AREA # 10	
	5.6	Ordnance/Explosive Compilation	
6.0	DEMOBILIZATION		. 27
	6.1	Area # 16, Building # 643	
	6.2	Area # 16, Building # 644	
	6.3	Area # 17	
	6.4	Area # 4	
	6.5	Building # 118	
	6.6	Area # 10	
	6.7	Personnel	
	6.8	Inventory	
7.0	ARE	AS OF CONCERN AND RECOMMENDATIONS	28
8.0	MANHOURS AND MILEAGE		
	8.1	Manhours	. 28
	8.2	Mileage Data (Mob/Demob)	
	8.3	Mileage Data (Home Leave)	
	8.4	Air Flights	
9.0	STIM	MARY	29

ATTACHMENTS

ATTACHMENT (1) News Articles
ATTACHMENT (3) Ordnance Explosive Information
ATTACHMENT (4)
ATTACHMENT (5) Survey - Area 16, Buildings # 645, # 646
ATTACHMENT (6) Ordnance Record - Area 16
VATTACHMENT (7) Building # 118 - Maps # 1 through 5
ATTACHMENT (8) Building # 118 - Ordnance Record
ATTACHMENT (9) Area 17 - Sector Maps
ATTACHMENT (10) Area 17 - Gym Site Information
✓ATTACHMENT (11)
VATTACHMENT (12) Area 4 - Ordnance Recovery Logs
ATTACHMENT (13) Area 4 - Explosive (TNT) Recovery Log
✓ATTACHMENT (14) Area 4 - Explosive (TNT) Storage Log
✓ATTACHMENT (15) Area 10 - Sector Maps
VATTACHMENT (16) Area 10 - Ordnance Record
✓ATTACHMENT (17) Area 10 - Fill Pile Information
TTACHMENT (18) Disposal Area - Map
ATTACHMENT (19) Disposal Area - Standard Operating Procedure (SOP)
ATTACHMENT (20) Disposal Area - Disposal Log
ATTACHMENT (21) Disposal Area - Sound Readings
ATTACHMENT (22) Activity Log Area 1 - Area 16, Building # 643
ATTACHMENT (23) Activity Log - Area 16, Building # 644
ATTACHMENT (24) Activity Log - Building # 118
ATTACHMENT (25)
ATTACHMENT (26) Activity Log - Area 17
ATTACHMENT (27) Activity Log - Area 10
ATTACHMENT (28) Activity Log - Disposal Operation
ATTACHMENT (29) Personnel Roster

Anchedel with It Carpenation Final to the USACE. Other vailey information on file in Hi 396. Office

1.0 INTRODUCTION

EOD Technology, Inc. (EODT) of Oak Ridge, Tennessee was awarded a subcontract by IT Corporation (IT) to perform UXO/OEW Removal Activities at the Former Raritan Arsenal (FRA), Edison, NJ on 8 February 1991. The FRA site is approximately 3200 acres, and was used extensively for US Army operations from 1917 to 1963. The site is located in Middlesex County, New Jersey within Edison and Woodbridge Townships. It is situated on the banks of the Raritan River, approximately 20 miles southwest of lower Manhattan. The site is bordered on the north and northwest by Woodbridge Avenue and to the southwest by Millville Road and the ILR Landfill.

The topography of the site is generally flat. Elevations vary from mean sea level near the Raritan River to approximately 100 feet above mean sea level at the northwest boundary of Woodbridge Ave. Within the last 25 years, the northern half of the FRA has been developed. The southern half of the site is primarily brackish marshland with limited development. Other major areas of development include the EPA Facility, Middlesex County College and Thomas Edison County Park on the western part of the site.

During the period of 1917 - 1963, the U.S. Army performed a myriad of activities including storage and decommissioning of ordnance, arms, machinery and various other military hardware. During this period, some waste materials, including ordnance and components were reportedly buried on site. In addition, some explosive materials were routinely destroyed by surface or pit burning. Occasional accidental explosions in magazine buildings and outdoor storage areas reportedly scattered explosive materials over large areas. During a 1963 cleanup operation conducted by Letterkinney Army Depot, seventeen areas were designated as potentially contaminated. Four facilities now occupy the major portion of the former Raritan Arsenal. They are the Middlesex County College, Middlesex County's Edison Park, US Environmental Protection Agency offices and Raritan Center (Summit Associates and Federal Business Centers). Fourteen of the seventeen sites designated as potentially contaminated are currently owned by Raritan Center.

EODT was initially requested to provide UXO removal support in five areas (Areas 16, 4, 3, 2, 1) of the Arsenal. In May of 1991, Areas 6, 7, 8, 9, 10, 17 and Building 118 of the Arsenal, plus the Spoil Area of Middlesex County Utilities Authority property, were added to the list. Additionally, EODT was tasked to provide an on site disposal operation in June 1991.

EODT personnel arrived on site to commence UXO removal activities on May 7, 1991. Mr. C.M. Read was assigned as EOD Project Manager. Four UXO Specialists rounded out the crew. By July, the field crew had grown to one Senior UXO Supervisor and fourteen UXO Supervisors. Due to funding restrictions, the work force was reduced by three in January 1992. A further reduction in March cut the removal team to four. Final demobilization of all EODT site personnel took place on May 15, 1992.

1.1 General Information

Prior to commencement of activities, an overview of the work plan and an in-depth safety brief was presented to all site personnel in accordance with established EODT procedures.

Daily safety briefs were presented prior to the start of each work day. A weekly safety class was conducted on the first day of each week. This class covered topics from the Site Safety, Health and Emergency Response Plan (SHERP) and other applicable subjects, such as safe work practices, treatment for heat/cold injuries, etc. A re-cap of the days activities was conducted at the close of each day.

The primary instrument used for all UXO sweeps was the Schonstedt Heli-flux magnetometer. Quality Control checks were performed periodically by the EODT Site QA Specialist, EODT Corporate QA/QC Manager and the U.S. Army Corps of Engineers (USACE).

1.2 Right-of-Entry Permits

The Raritan Arsenal was closed in 1963 and all property has since been transferred to other government agencies and commercial interests. Right-of-entry permits to access work sites was coordinated by IT Corporation via the U.S. Army Corp of Engineers. Work on specific areas

commenced as the Right-of-Entry Permits were obtained.

1.3 Key Personnel Contacts

The following personnel were contacted and meetings were arranged as necessary. Various key personnel were involved in one area or another throughout this project. A complete list is provided in Attachment (4).

- U.S. Army Corps of Engineers, Huntsville
 LTC B. Peterman Contracting Officer (205) 955-5632
- U.S. Army Corps of Engineers, NY District (Raritan)
 MAJ Ben Bauman Contracting Officer Representative (908) 603-9517
- U.S. Army Corps of Engineers, Huntsville
 Mike Carillo Project Manager (205) 955-1512
- International Technology Inc. (Edison, NJ)

 Lapyan Chan, Ph.D., Project Manager (908) 225-2000
- International Technology, Inc. (Monroeville, PA)
 C.W. Magilson, Project Manager (908) 588-8775
- EOD Technology, Inc. (Oak Ridge, TN)

 Mark Read, Project Manager (615-483-0007)

1.4 News Media Opportunity

Numerous media and press conferences were held during the course of this project. These events were coordinated by the USACE (New York District). EODT participation was always preplanned and clearly defined. News articles are provided in Attachment (1).

2.0 OPERATIONS

UXO/OEW Removal Actions occurred within five (5) areas of the FRA. In conjunction with these actions, an on site disposal operation was also initiated in June 1991 by EODT. Operations conducted at each individual work site are discussed individually in the following subparagraphs.

2.1 Area 16, Building # 643

Building # 643 (Magazine S-643) is located on Magazine Lane 16. The road leading to the site is an old railroad bed covered with fill dirt. Generally, the area is considered to be a tidal basin, in that the water level changed with the tide of the Raritan River. The only semi-dry areas are those adjacent to the actual magazine sites, which have been built up and used as "turn around" areas for ammunition transport vehicles.

This Magazine was destroyed by fire. Personnel involved in the fire fighting and subsequent activities reported numerous pieces of ordnance (37mm APHE) in the general area. The Army Explosive Ordnance Disposal Team (54th Ord Det (EOD), Ft. Monmouth, NJ) responded, recovered and subsequently destroyed in excess of 1200 rounds.

EODT personnel arrived on site May 13, 1991 and efforts were initiated to prepare the site for remediation activities. Vegetation in the area was cut and removed to facilitate removal operations. The removal action commenced with the laying out of magnetometer sweep lanes. A large concrete slab, believed to be a former railroad loading dock, was a major concern. Subsequently, a track hammer was requested to break the slab up into sections small enough to move.

Due to the large number of rounds discovered on or close to the surface, and numerous subsurface anomalies detected with magnetometers, an additional 25' was cleared on the eastern side of the site. The area was divided into two sub-areas, using the concrete slab as a center point. Hand digging to a depth of 24" resulted in the recovery of 289 each 37mm APHE projectiles on the first day.

On May 14 the track hammer arrived and broke up the large concrete slab to manageable pieces. This allowed the site to be completely swept both visually and with a magnetometer. At this point, the basic plan of action was to:

- 1. Perform a visual surface survey.
- 2. Grid the area into sweep lanes and perform a subsurface magnetometer survey.
- 3. Flag all anomalies.
- 4. Investigate anomalies.
- 5. Sift the soil as required.
- 6. Backfill as necessary.
- 7. Stage all non-hazardous material.
- 8. Stage all UXO/OEW for disposal.

All UXO/OEW was placed in plastic containers. At the end of each day all UXO/OEW was inventoried and placed into triple locked non-sparking storage containers. These boxes were numbered and stored within a chain link fence enclosure (security area), which was also locked.

On May 15, a sift-all (mechanical sifter) was positioned and set up for operation. Utilizing a track hoe and back hoe, sifting operations commenced and continued throughout this task to remove and store all UXO items encountered.

On May 16, an Army EOD Team from Fort Monmouth arrived to perform disposal operations. The disposal area used was in poor condition and required extensive backfill to build up the area. As disposal operations continued, additional fill was required.

In accordance with the Work Plan, EODT recovered UXO to a depth of the water table. However, it soon became obvious that there were large numbers of UXO below the water table which required removal. This was brought to the attention of USACE, Huntsville and we were instructed to excavate as deep as necessary to recover the rounds. In some areas we found UXO

as deep as 15 feet below the surface. The tide tables played a key role in deciding on what particular areas could be worked. In some locations, portable pumps were utilized to control the water level.

Early in the operation it became obvious that UXO was either buried or dumped in mass. On occasion, hundreds of UXO was excavated and sifted at a time. There was always a risk of missing some UXO and allowing it to fall into the clean soil being used for backfill. To eliminate this problem we commenced double sifting. The soil that went through the sifter would be re-sifted before being used as fill.

In early June, the security storage area was enlarged to accommodate the large number of UXO being recovered. By June 11, EODT had recovered over 20,000 rounds, most of which were in the secured staging area. Due to other military commitments, Army EOD could not keep up with the disposal requirements. It became apparent that disposal operations required full time attention. Subsequently, EODT was tasked to perform a full time disposal operation on or about July 10, 1991. Work continued on this site through July 18, 1991. A total of 29,234 UXO items were recovered from this site. This site activity and UXO logbooks are provided in Attachment (22).

The disposal operation had become highly visible, and numerous individuals representing various organizations were interested in the operation. As a result, representatives of these organizations were provided a tour of the site. Tours were always planned ahead of time and scheduled during break periods. No individuals were ever allowed on site during removal/disposal operations, except the USACE Safety Representative, the Site Engineer and EODT personnel.

2.2 Area 16, Building # 644

This site is adjacent to Building # 643. EODT commenced work on July 19, 1991. Removal operations in this area were performed in the same matter as Building # 643. However, due to lessons learned on the previous site, this area proceeded at a much faster pace. The

concentration of ordnance in this area was much less than at Building # 643. By August 2 we recovered 598 each 37MM APHE rounds.

On September 25, 1991 site work was completed. A total of 955 UXO items were recovered. This site activity and UXO logbooks are provided in Attachment (23).

2.3 Area 16, Building Sites # 645, # 646

A visual and magnetometer surface/subsurface survey was conducted at selected areas at Building # 645 and Building # 646 on August 8 and August 15, 1991 respectively. No UXO/OEW was discovered. Refer to Attachment (5).

2.4 **Building # 118**

Building 118 is currently utilized as an Administrative Building housing the staff and faculty of Middlesex County College, Division of Business Technologies. This building is commonly referred to as "NORTH HALL". The Dean of Business and Industry, Dr. Fishco, was provided with frequent briefings to inform him of any changes in our operations and to maintain his confidence. **EODT** maintained an excellent relationship with the faculty staff and they were content with the services being provided by **EODT**. This office performed business as usual during the entire remediation project. The site boundaries, underground utilities, and operational phases (work sectors) are identified on maps found in Attachment (7).

Specific safety procedures were formulated and utilized for the following unique circumstances encountered:

- Boosters within root system of live trees: Trees were cut approximately 3 ft. above ground. Major roots were cleared by hand and cut 360 degrees around remaining stump. Stump was removed by utilizing chain and backhoe. Soil removed from stump and entire root system was scanned with magnetometer.

Unmarked utilities encountered: Excavation was stopped and college maintenance
personnel were called to identify status of object (active/inactive) encountered and
direction of burial. Unmarked utilities encountered included water lines, electrical
cables, telephone cables and fuel storage tanks.

Major Activities Performed by Other Organizations:

- Ground penetrating radar and IRR survey of site conducted by a US Army Laboratory on August 21-22, 1991.
- Buried 155 gal. gasoline storage tank was removed by IT on August 27, 1991.
- Buried 1500 gal. Heating fuel tank was removed by IT Corporation on October 2, 1991.
- Concrete drive behind Building #118 was broken-up and removed by IT on December 16-18, 1991.

The initial subsurface UXO survey was conducted on June 20, 1991. The area was measured and marked off in 5 foot magnetometer sweep lanes. Each lane was surveyed utilizing a hand held magnetometer. All anomalies were flagged and plotted on site map. Due to the location and inhibitants of Building #118, several safety and operational factors were considered before commencement of excavation in this area. The entire work area around the site was fenced because of heavy pedestrian traffic. Traffic requirements made it necessary to fence in half of the area at a time, which facilitated entry/exit to Building #118 while maintaining restricted access to the excavation area. (i.e., rear entry to the building during Phase I and the front entry during Phase II).

The fence was constructed and EODT commenced operations on June 19, 1991. Ten ordnance related items were recovered at the northeast corner of the blacktop around Building # 118. Items recovered were non-explosive adaptors for artillery projectiles; the area was cleared to a depth of 6 ft., and UXO items were recovered at a depth of 3 to 5 ft. All other items recovered were a variety of metallic construction debris. All excavations were backfilled and

all operations ceased until placement of fence around Phase II area.

Construction of the fence in the next half of the area was completed and, on June 27, 1991, EODT commenced operations at the northwest edge of Building # 118. This area was previously identified as a hot area during the initial survey. Mk-IIA booster adaptors were found in this area. The operational plan was to expand excavation in all directions until no further boosters found. This plan was modified due to the large size and irregular shape of excavation. Attachment (7) shows the detailed area of major excavation. The density of boosters recovered, direction of burial and magnetometer readings indicated that excavation Area #1 (refer to Attachment (7), Map 4) was located on the edge of what proved to be a major trench burial site. Safety and operational factors called for a decision to limit further excavations to a 15 x 15 ft. grid. All further excavations were numbered, cleared and backfilled before starting on the next area. This system was utilized until encountering booster contaminated utility lines in Area # 7A.

All recovered explosive filled ordnance was transported daily (police escort) to the security staging area in Area 16 and locked in boxes. The initial requirement was to transport items in a woodlined steel box. This requirement limited the amount of boosters transported to a maximum of 900 per delivery, due to box capacity. Additionally, the loading and unloading of the box was very time consuming. Approval to transport items in sandbagged and wood lined truck bed was given by Mr. Wayne Galloway, USACE Safety Office, on June 16, 1991. This increased the number of boosters that could be transported by 50%.

Refer to Attachment (7), Map 4 regarding following discussions concerning Areas 1-17.

Area #1 boundaries were determined and the area was cleared and backfilled on July 9, 1991.

Area #2 excavation was started on July 10, 1991. This area contained a 30 ft. maple tree with a large number of boosters lodged within the root system. Another maple tree of approximately same size was located 15 to 20 ft. from this tree (Area #6). A hand dig was performed around

both trees to determine the degree of booster contamination. Exploration results lead to the decision to remove the trees for safety purposes. On July 11, excavations were backfilled to cover exposed boosters for safety purposes. Work in Area #2 and #6 was stopped until these trees were removed. Operations recommenced at Area #2 on August 5, 1991, when both stumps were removed and cleared of UXO. Area #2 was completed, cleared and backfilled on August 8, 1991.

Area #3 was started on July 11, 1991. Boosters in this area were glued together in a tar-like substance and had to be individually pried apart before removal. This area was cleared and backfilled on July 24, 1991.

Area #4 was started on July 24, 1991. Boosters found in this area were also glued together in same substance as found in Area #3. Several boosters in "Pristine" condition were found in this area with the stamped marking "Adaptor Mark II". This information was passed to the USACE. This area was cleared and backfilled on July 31, 1991.

Area #5 was started on July 31, 1991. Boosters found in this area were glued together in same manner as described in Area #3 and Area #4. This area was cleared and backfilled on August 5, 1991.

Area #6 was started on August 3, 1991. This area contains a large quantity of magnetic (ferrous oxide bearing) rock as fill material. Additionally, the root system of the tree which had been removed pushed boosters into a clay subsurface that had been clear in all previous excavations. This area was cleared and backfilled on Aug 15, 1991.

Area #7 was started on August 15, 1991. This area contained an old stump with booster contamination within the root system. Removal of this stump revealed boosters running beneath the asphalt apron of the drive area adjacent to Building #118. The filler tube of what proved to be a 115 gallon gasoline storage tank was also uncovered. The fuel tank was removed on August 27, 1991 by IT personnel. Boosters were then recovered beneath the tank area. A large

amount of magnetic rock and construction debris was found in this area. On August 29, 1991 concrete encased electrical and telephone cables were uncovered. These utilities were not on drawings provided to EODT. Boosters were found encased in the concrete with these cables. Area #7 was terminated at this point (September 6, 1991). The area was backfilled, while leaving the utilities uncovered.

An exploratory dig around North "I" building was started on September 6, 1991, per the request of Mr. Bob Nore, USACE Project Manager. The purpose was to ascertain if this building area required removal actions due to booster contamination. Four boosters were found along the front side of the building. This area was cleared and backfilled on September 11, 1991.

Area #8 was started on September 11, 1991. This area contained a buried 1500 gallon heating fuel tank, fuel contaminated soil and boosters (which were discovered under this tank on September 17, 1991). A large quantity of boosters was found within the root system of a large tree located adjacent to this area (Area #12). This area was backfilled on September 20, 1991 until a decision could be made by IT and the USACE regarding problems associated with the Operations recommenced at Area #8 on October 9,1991. fuel tank and tree. contaminated soil was screened to a depth of nine feet and all located boosters were removed. Due to the depth of excavation, personnel were not allowed to enter the hole. Fuel contaminated soil was replaced, covered with polysheet and backfilled to a depth of 4 ft. on September 24, 1991. Due to depth of boosters in this area, a decision was made to leave all excavations open on the north side of the concrete encased utility lines. Excavations were limited to a depth of 4 ft., designated "LEVEL 1" of the numbered area. ("Note" Due to boosters being located at depths greater than 5 feet, these areas were separated into 2 levels. Zero to four feet depth is considered "Level 1" and beyond a depth of four feet is considered "Level 2". Once "Level 1" was cleared, the required sloping of the work areas was accomplished and then "Level 2" was cleared.) This procedure allowed for proper sloping of the excavation and provided future access to utilities. Additionally, proper sloping of Area #7A required removal of the concrete drive.

Excavation to expose the remainder of the utility lines between Building # 118 and North I Building began on September 20, 1991, at the request of LTC Poirrier, USACE. This portion of the utility lines proved to be clear of booster contamination and was backfilled on October 1, 1991.

Area #9 was started on October 1, 1991 and completed on October 2, 1991. This area contained a large quantity of magnetic rock.

Area #10 was started, cleared and backfilled on October 3, 1991. This area contains a large quantity of magnetic rock.

Area #11 was started on October 3, 1991, cleared and backfilled on October 7, 1991.

Excavation started on the area designated "street light cable" on October 7, 1991. Boosters were found along the cable to a distance of 50 ft. from the trench area. This area was cleared for a distance of 60 ft. from the trench and backfilled on October 9, 1991.

Area #12 started on October 10, 1991. The tree in this area was cut down on October 21, 1991, and the stump was removed on October 30, 1991. "Level 1" operations were completed on November 22, 1991. "Level 2" operations started on November 22, 1991 and were completed on November 27, 1991.

Areas #13 started on October 15, 1991. An electrical cable for street lights running between Areas #12 and #13 was found to contain boosters within its concrete encasement. The electrical line and concrete were removed and transported to the demo range with the stump from Area #12. "Level 1" operations were completed on November 20, 1991. "Level 2" operations commenced November 20, 1991 and were completed on December 9, 1991.

Area #14 was started on November 13, 1991. "LEVEL 1" operations were completed on November 15, 1991. "LEVEL 2" operations were started and completed on December 10, 1991.

Area #15 "Level 1" operations were started and completed on November 13, 1991. "Level 2" operations were started on November 22, 1991 and completed on December 11, 1991. The boosters found in Areas #13, #14 and #15 were glued together in the same tar-like substance as previously discussed.

Area #16 "Level 1" operations were started and completed on November 19, 1991. "Level 2" operations started on December 10, 1991 and were completed on December 11, 1991.

Area #17 started on November 20, 1991 and was completed on February 18, 1992.

The "Drive Area" was started on December 16, 1991 with the breaking up and removal of the asphalt and concrete layers. These layers were removed on December 18, 1991. Excavation activities commenced on December 19, 1991, and boosters were located within the excavation.

The entire site was shut down from December 20, 1991 through January 6, 1992. Excavation resumed on January 7, 1992. The drive was excavated the entire length of the area. Shoring was placed along electrical line to prevent washout and possible collapse. The fill in this area contains high magnetic content. All areas of drive were cleared to a minimum of depth of 4 feet. This area was checked by Mr. Wayne Shaw (USACE Safety Office) and considered clear on March 3, 1992. The concrete encased utilities (Area 7A) running through this area were still contaminated with boosters.

Sector #1 (Attachment 7, map #5) was surveyed, marked and plotted beginning on December 3, 1991. All "Hot Spots" were exposed and left open for QA inspection by the USACE on December 6, 1991. No UXO/OEW items were found in this area. All items recovered were magnetic materials and construction debris.

Sector #2 (Attachment #7, map #5) was surveyed, marked and plotted beginning on December 12, 1991. Excavation on "Hot Spots" began on February 18, 1992. This area contained debris from old nurses quarters that had been torn down. Three boosters were found scattered in this

area. All "Hot Spots" were exposed and a QA check performed by Mr. Wayne Shaw on February 19, 1992, and then backfilled.

Sector #3 (Attachment #7, map #5) was surveyed, marked and plotted on February 25, 1992. All "Hot Spots" were exposed and inspected by Mr. Wayne Shaw on March 3, 1992. No ordnance items were found in this area. The area was backfilled on March 4, 1992.

Sector #4 (Attachment #7, map #5) survey, marking and plotting operations began on March 17, 1992. One empty MKII Hand Grenade, unfuzed, was discovered on March 18, 1992. An isolated pocket of boosters (167 each) was discovered on March 19, 1992.

Area #7A (Attachment #7, map #5). EODT placed additional bracing in the excavation to compensate for the removal of concrete from electrical cable. Concrete removal began on March 24, 1992. An electric jack hammer was originally used, however an air hammer was eventually needed due to the hardness and thickness of the concrete. Concrete was cut into four portable pieces. Two of these pieces contained boosters and were transported to the demolition range, where the encased boosters were detonated. This area was completed on April 8, 1992.

Drive Area (Attachment #7, map #5). Work was resumed in this area on March 30, 1992. The accumulated water in the excavation was pumped out and the area was sloped in order to gain safe access to the concrete encased utility lines. This area was completed on April 9, 1992.

New Electrical Cable (Attachment #7, map #5). Trenching for the new electrical cable began on March 5, 1992. An unprotected and unrecorded electrical line was hit. Trenching was completed on March 12, 1992 and backfilled on March 17, 1992.

The USACE QA Inspection was started on April 17, 1992 by Wayne Shaw. The stockpiled soil from numerous areas was checked. EODT had been directed not to back fill and this prevented area/soil re-inspection. When this fill was removed, a concrete walkway was uncovered. This walkway was then removed and several boosters were discovered. A total of 487 boosters were

recovered from this area. The QA Inspection resumed on April 27, 1992. No additional ordnance was located.

2.5 Area # 4

Area # 4 is a 2 acre section (see Attachment #11) completely fenced in by a six foot high chain link fence which was constructed by the USEPA. The entire area was deemed to be the Exclusion Zone for this project. This site was used as a high explosive salvage and melt-out area for demilitarization of various ordnance items. All personnel who worked in the Exclusion Zone were required to take a full physical prior to any soil excavation operations being conducted and an exit physical was required upon their departure.

Basic site preparation began on September 24, 1991 with the arrival of a five (5) man work crew, miscellaneous equipment and work trailer. The crew conducted a surface search for ordnance and found a 75mm projectile which contained some explosive residue. Also, at this time we marked all known explosive contaminated areas with stakes and day-glo tape to insure the areas were conspicuously marked and identified. The next phase included removal of all vegetation and trees 3 inches or less in diameter, all railroad ties, trash and debris which littered the entire work site, which was collected and placed in one area. This clean-up phase took two weeks to complete and was conducted concurrently with other tasks. Everything that was removed from the main area was stored along the east side of the site as a temporary measure. A 10' wide area along the western edge of the site was cleared of UXO/OEW and the debris was placed there, with the exception of the trees and large shrubs which were run through a chipper and spread out in designated areas.

On October 1, 1991, IT provided a Health and Safety class on Site # 4. Also, we were issued full-face masks and were fit tested. Tracy Estes presented the class for IT. On this date, we also installed the Geofabric material to the chain link fence for dust suppression.

On October 2, 1991, a magnetometer survey was conducted and all "hits" were cleared from the area that we used as the Contamination Reduction Zone (CRZ). The CRZ was located in the

Northeast corner of the site, which contained the double gates leading into the area. This 30' by 50' CRZ was completed in two days. The decontamination pad was built to accommodate a track-hoe excavator, which was the largest piece of equipment used in this area. The pad was dug out and sloped to one side in order to channel all water to a sump. Concurrently with this operation, we received a Front-End Loader (Model 916), Sifter-Shaker and one conveyor assembly. The Sifter was placed on the street as a temporary measure until we cleared and prepared the area to accept the equipment. The conveyor assembly was returned for modifications to reduce the speed of the conveyor belt and the 110VAC motor was replaced with a 220VAC motor. In addition, we received a track-hoe, a pressure washer and PPE from IT. A water source was connected on October 16, 1991.

On October 4, 1991, a magnetometer survey of the entire area commenced, with the exception of the known explosive steam out area (Pit 6) and the area adjacent and parallel to the east side fence line due to a know sewer line pipe three feet underground. Five foot wide sweep lanes were established using stakes and hemp in a systematic pattern. When subsurface anomalies were located, we used 12" high red flags to mark them.

On October 22, 1991, hand digging of the "hits" commenced in the area where the sifter would be placed. After clearing this area, the sifter was placed in position. Digging operations commenced with the track-hoe on November 1, 1991 in Pit #1. The wooden hopper system on the rear of the sifter did not work due to the damp soil sticking to the sides and clogging the hopper. This required one person to constantly push the soil down to keep the system in operation. The hopper assembly was removed and operations continued smoothly.

The first drums for hazardous waste (contaminated protective clothing) to be stored in were received. To date, waste had been placed in plastic bags and stored on site. A 5000 gallon trailer for liquid waste was placed on site and water that collected in the sump was pumped into the holding trailer.

EODT continued digging out the various pits known to contain explosives. While digging out Pit #4, we found the first piece of ordnance which was an intact WWI Aerial Bomb. We dug out all of the smaller pits that contained traces of high explosive and recovered approximately 10 pounds of TNT.

Excavation started in the Southwest corner of the site on November 12, 1991 and the entire corner of Site #4 was systematically excavated to a depth of six feet and cleared of all explosives and metal. The procedures were then modified with the agreement of the Corps of Engineers representative to excavate to a depth of three feet. If nothing was found, we would proceed down to natural soil and then mag the area. If the depth did not reach natural soil within six feet we would dig test holes to insure no residue was left under the natural soil. This procedure was used during the entire period that we excavated OEW from the major explosive laden pit.

Whenever pockets of explosives were located, all mechanical excavation would cease and removal by hand was initiated. This was the most time consuming part of the removal operation. At times it would require many days of hand excavation before we were able to return to digging with the track-hoe. At the end of February 1992, EODT had excavated over 10,000 lbs of bulk explosives (TNT) from Area # 4 and over 30 UXO items, which varied in size from 75mm adapter boosters to a 9.2 inch howitzer projectile.

The explosive removal operation at Area # 4 was completed on March 18, 1992. During the month of March we removed 2,629 pounds of HE residue and OEW. Explosive removal in Pit 6 (Brown Pit) was completed on March 11, 1992. All areas suspected of having explosives were excavated. While digging adjacent to the CRZ, we uncovered two steam pits and recovered 611 pounds of HE (TNT). The remaining area which had to be surveyed was finished and all "hits" were excavated. EODT recovered two 75mm HE projectiles (unfuzed) and two projectile adapter-boosters (loaded).

We experienced many different problems during our tenure in Area # 4. The weather provided some minor challenges however, it never caused us to cease operations. Although there was

only one major equipment failure, the problem always encountered was having to decontaminate the equipment to remove it from the area for repair work, which averaged out to 3 hours per occasion.

All heavy equipment was decontaminated and turned over to IT for removal and return to vendors. The trailers were emptied, cleaned and readied for return.

Exit physicals were accomplished on March 25, 1992 at Enviro-Care for Becker, Bucy, Die and Rodgers. We concluded all last minute details at Area # 4 and demobilized.

A Q/C Inspection of Area # 4 was performed by EODT on March 12, 1992, and no UXO/OEW was located. A subsequent QA check was performed by USACE personnel. Again, no UXO/OEW was located.

2.6 Area # 17

This area was used as a property disposal and salvage storage area. Presently, the area makes up part of the Middlesex County College campus. It is adjacent to a student center and is a hub of student activity.

On September 9, 1991 the crew arrived on site. Because of heavy pedestrian traffic and the general location, a decision was made to only locate and mark magnetometer "hits". No intrusive work would occur until decisions were made regarding the best way to proceed.

Sweep lanes were established and, as the survey began, it immediately became obvious we would have a tremendous amount of "hits". Initially, red flags were used to mark same. This was stopped due to the enormous number involved, and all barriers and signs had to be removed at the end of each work day. The decision was made to use nails with marking tape to designate "hits". This system worked very well. A total of 7,654 "hits" were recorded (see Attachment 6).

The determination was made that five exploratory digs would be made. The excavation would be 6' x 6' x 3' deep. On October 3, 1991 excavation began and continued until October 10, 1991. No UXO was discovered. One piece of OEW scrap (60MM mortar fins) was recovered.

During this operation, there was an additional tasking on September 17, 1991, when we returned from a four day break. During the break period, a hand grenade (empty) had been found on the Middlesex College campus in the general area of the tennis courts. The decision was made that the team from Area # 17 would surface sweep the area, check the area where the grenade was found and any other suspicious locations with a magnetometer. All "hits" would be recorded. (Attachment #7)

Operations began at 11 a.m. on September 17, 1991 and were completed at approximately 5:15 p.m. No UXO/OEW was located.

2.7 Area # 10

Area # 10 is located on what was the northeastern corner of the arsenal. This report covers only part 1 and 2, which are located in the south western corner of Area # 10. Original depot maps would show this area to have been in Magazine Rows E and F. This area is presently part of the Thomas A. Edison Park of Middlesex County. The terrain is generally flat with one portion being heavily vegetated, and the rest is grass and an asphalt parking lot. The parking lot has concrete curbs, access roads and a lighting system.

This area was known to have been in the "fan" of at least two magazine detonations. One of the magazines scattered several hundred thousand French Rifle Grenades throughout the area when it detonated. The other magazine contained MK II Grenades.

A three person crew started working at this area on October 1, 1991. The general plan was to:

- 1. Divide the designated area into manageable sub areas.
- 2. Lay out lanes for the magnetometer survey.
- 3. Mark all magnetometer "hits" and items found on a map.

- 4. Dig to 12" by hand.
- 5. Use back hoe to dig deeper "hits".

It became obvious we were going to encounter a tremendous amount of "hits", the majority being magnetic rocks. The decision was made by the USACE, Huntsville to only record ordnance discovered, thus saving time.

There was a desire to finish this area as soon as possible because this was a high visibility site. We took personnel from other sites, as they had down time, and put them to work in this area. This proved to be a worthwhile procedure.

On October 18, 1991 we located the first French Rifle Grenade in Area # 5. This had a dramatic impact on how we looked at this site. On October 21, 1991 the second grenade was discovered. This resulted in security being put on the site when the crew was not working.

The "hits" along the road (former Magazine Line F) were so heavy that a decision was made to remove eight to ten inches of the surface along the shoulder of the road with a bucket loader, inspect the removed soil for ordnance and mag the exposed surface. This system proved to be both efficient and effective. During this entire period, EODT constantly discovered parts and components of both types of grenades. By March 17, 1992, fourteen French Rifle Grenades had been discovered and the decision was made to fence in the area. On March 25, 1992 fence construction began.

Due to down sizing of project, removal action was curtailed on March 25, 1992. The remaining technicians were used to complete Building # 118 and fulfill all demolition requirements. On April 27, 1992, three (3) UXO Supervisors returned to the area and final demobilization occurred on May 15, 1992.

An additional short notice tasking in Area # 10 was given on August 21, 1991. This area is located in Edison Park on the boundary of Raritan Center. It is approximately 115' x 65' and

contained a fill pile 25' at the base and about 9' high. The area was required to be checked for and cleared of UXO/OEW.

The crew that was working at Area #16 was used on this task. Work commenced by laying sweep lanes and checking the entire area with a magnetometer. All "hits" were recorded and dug to a depth of 12" by hand. The deeper "hits" were excavated by use of a Case 580 Loader/Backhoe. Each bucket of excavated soil was examined for UXO/OEW. All excavated areas were backfilled.

Two pieces of OEW, (one 37MM shell casing, and one 40MM shell casing) were recovered and work was completed on August 28, 1992. (see Attachment 8).

2.8 Area 1

Area 1 is approximately 3 acres, with heavy vegetation throughout. On May 8, 1992 the field team started by marking off grids, and then laying out 5 foot wide sweep lanes. Numerous pieces of metallic debris (i.e. fence posts, railroad spikes, etc.) were excavated and staged in one area. There was no UXO/OEW located at this site and all operations were completed on May 9, 1992.

2.9 Disposal Operation

All UXO/OEW found was disposed of within the boundaries of the former arsenal at a designated disposal site. Initial disposal operations were performed by military EOD personnel (54th Ord Det (EOD), Ft. Monmouth, NJ). Due to a lack of personnel and other military commitments, they were unable to maintain the schedule required by the volume of ordnance being recovered. Additionally, the constraints involving noise, ground shock and fragmentation containment were proving to be exceedingly difficult to maintain. Subsequently, all disposal operations were turned over to EODT. The tremendous back log of UXO at this time was in excess of 25,000 items. Disposal operations continued throughout the project. The backlog of ordnance was destroyed. The ground shock, noise and fragmentation constraints were more than adequately addressed. There were virtually no complaints from local residents or

municipalities after the transition.

The demolition site was surface swept after each disposal shot. All scrap was placed in a locked container pending certification that it was explosive free and then transported to a designated DOD Property Disposal Facility.

2.10 Equipment Utilized by EODT

The following equipment was utilized by **EODT** during this project:

- 6 Schonstedt magnetometers
- 1 Schonstedt MAC 51B, Magnetic and Cable Locator
- 3 Rubber Tire Back Hoes
- 1 Excavator EL-240 (20 ton)
- 1 Articulating Bucket Loader
- 1 Case Uni-Loader (BOBCAT)
- 4 Trucks for equipment and personnel
- Common hand tools, shovels, rakes, etc.
- Marker flags and string/sisal for lane marking
- 1 Non-magnetic tool set
- 1 4KW Generator
- 2 2" Pumps
- 1 High Pressure Washer
- 2 110 Volt Sump Pumps
- 1 Dirt Sifter/Screen All
- 2 Conveyors 20 feet long
- 1 Electric Jack Hammer
- 1 Compressor w/Air Driven Jack Hammer
- 1 Decibel Meter
- 1 Pow/Gal-27 Blasting Machine
- 3 Explosive Storage Magazines

- 4 Site Logistics Trailers
- 4 Portable Telephones
- 7 Motorola Radios MT-1000

2.11 On Site Training

2.11.1 Personnel Training

All personnel assigned to this project were trained on ordnance recognition, heavy equipment, site specific hazards, operations and safety precautions.

2.11.2 Daily Training

Prior to the start of each work day, a Tailgate Safety Brief was conducted. A minimum of the weather conditions, site conditions, UXO hazards, insects and other safety concerns from the previous day were covered. At the end of the work day, a debrief was conducted outlining problems encountered, suggestions, progress made and plans for the following day.

2.11.3 Visitor Training

All visitors were briefed on the specific operations, emergency evacuation route and procedures and specific hazards prior to being allowed into any work area.

2.11.4 End of Contract Debrief

During the demobilization phase, a final debrief was conducted covering lessons learned. Driver safety was stressed for the final trip home.

2.12 Daily Activities

See Attachment(s) 22 through 28.

2.13 Weather and Terrain

Daily work hours would vary depending on sunrise and sunset. Generally, the work week was 10 hour days from Monday through Thursday. The weather varied from high temperatures in the 90's to lows in the teens. We encountered a moderate amount of rain, sleet, and snow. The

terrain is generally flat, from just above sea level to approximately 100' above sea level. Much of the area is marsh and has heavy reed and grass growth.

Daily work hours from 0630 until 1700 were established for this project. This permitted the crew to be off-site prior to the late afternoon thunderstorms in the summer months, which could have created a loss of productive time due to safety concerns regarding electromagnetic hazards.

2.14 Daily Operations Brief

An operations briefing was conducted each day by the Senior UXO Supervisor prior to the start of work to coordinate site locations and tasks to be performed in each specific area. Problem areas were addressed at this time, and any suggestions to improve our plan of action were considered. All equipment in use was evaluated and any necessary changes were implemented.

2.15 Report of Findings

During this project 114,117 UXO items and 12,361 pounds of trinitrotoluene (TNT) were recovered, transported and disposed of on site without incident and within the requirements of the Disposal Plan and Range SOP.

See Attachment(s) 6, 8, 12, 13, 20.

3.0 QUALITY CONTROL

3.1 UXO/OEW

All UXO/OEW found was inspected by a qualified UXO Supervisor and confirmed as either inert or hazardous, and then appropriately dealt with in accordance with the Work Plan.

3.2 Surface Sites

Each surface site was checked visually for any UXO or OEW contamination. The area checked was approximately 5% of the areas that were remediated. All areas met or exceeded the on site EODT QC requirements. A corporate QC check was performed by the EODT Corporate QC Manager, and Q/A was performed by a U.S. Army Corp of Engineers representative.

3.3 Subsurface Sites

Each subsurface site was checked visually and with a magnetometer for any UXO or OEW contamination. The area checked was approximately 5% of the area remediated. All areas met or exceeded QC requirements after following the same procedures as stated in paragraph 3.2 above.

3.4 Equipment Calibration

The magnetometers were checked each morning and after every break against a known source. The batteries were changed as needed and the magnetometers were cleaned and serviced every Friday. Whenever they were exposed to rain, they were checked, cleaned and serviced at the end of that day.

4.0 SITE SAFETY

4.1 Safety Briefing (Tailgate)

A Tailgate Safety Brief was conducted each morning prior to any work being started. The safety topics varied but always included protective equipment and clothing, physical hazards, emergency procedures, emergency medical procedures and special equipment. These briefings are documented in the daily activity logs.

4.2 Safety Violations

None.

4.3 Safety Training

A weekly safety training class was conducted the first work day of each week prior to start of operations. This class covered topics in the SHERP, explosive ordnance, explosive and demolition procedures, and other applicable topics.

5.0 ORDNANCE ACCOUNTABILITY RECORD

5.1 Area # 16, Building Site # 643

A total of 29,234 each 37MM Armor Piercing, High Explosive Projectiles were recovered.

Refer to Attachment (6).

5.2 Area # 16, Building Site # 644

A total of 955 each 37MM Armor Piercing, High Explosive Projectiles were recovered. Refer to Attachment (6).

5.3 Area # 4 (ATTACHMENT 13)

The below listed UXO items and explosives were recovered from this area. Refer to Attachment (13).

<u>NOMENCLATURE</u>	QUANTITY
Trinitrotoluene (TNT)	12,361 lbs.
75MM Projectile	21 each
155MM Projectile	1 each
9.2 Inch Projectile	1 each
Aerial Bomb, WWI	1 each
Fuze, Projectile, Point Detonating	2 each
Fuze, Projectile, Powder Train Time	1 each
Adaptor Booster, Projectile	10 each
Booster, 37MM Projectile	3 each

5.4 **Building # 118**

A total of 83,873 Projectile Adaptor Booster, MK II, Mod I and 1 each MKII Hand Grenade was recovered. Refer to Attachment (8).

5.5 AREA # 10

A total of 13 French Rifle Grenades (V.B. Rifle Grenade, Mark I) were recovered. In addition, 1 each 3 Pound U.S. Practice Bomb was recovered. Refer to Attachment (16).

5.6 Ordnance/Explosive Compilation

The following is a listing of total explosives and UXO items recovered during this project.

NOMENCLATURE	•	QUANTITY
Trinitrotoluene (TNT)		12,361 lbs.
Adapter Booster MK11 Mod 1		83,873
37MM Armor Piercing, High Explosive Pr	rojectiles (APHE)	30,189
75MM Projectiles (HE)		21
French Rifle Grenade (V.B. Rifle Grenade	MK 1)	13
Adapter Booster Projectile		10
Booster, 37MM Projectile		3
Fuze Projectile, Point Detonating		2
Hand Grenade MK11		1
U.S. Practice Bomb 3 pound		1
155MM Projectile		1
9.2 inch Projectile		1
World War I Aerial Bomb British		1
37MM Cartridge Case		1
	TOTAL UXO ITEMS	114,117

6.0 DEMOBILIZATION

6.1 Area # 16, Building # 643

Site demobilized 19 July 1991.

6.2 Area # 16, Building # 644

Site demobilized 25 September 1991.

6.3 Area # 17

Site demobilized 10 October 1991.

6.4 Area # 4

Site demobilized 25 March 1992.

6.5 Building # 118

Site demobilized 27 April 1992.

6.6 Area # 10

Site demobilized 14 May 1992.

6.7 Personnel

The following is a list of demobilization dates for **EODT** personnel assigned to the FRA project.

Date Demobilized	No./Grade	No. of Personnel
		Remaining
10 Jan 92	3 UXO Supervisors	12
26 Mar 92	8 UXO Supervisors	4
21 Apr 92	1 Site Supervisor	3
15 May 92	3 UXO Supervisors	0

6.8 Inventory

All equipment was collected, cleaned, and inventoried. This inventory was jointly verified by representatives from EODT, IT Corporation, and US Corps of Engineers (USACE).

7.0 AREAS OF CONCERN AND RECOMMENDATIONS

Many interested parties came by the working sites and this tended to disrupt operations. We recommend making up packages containing information stated below. These could then be given out to interested parties, as approved by the client.

- 1. An overview of the entire operation.
- 2. A specific overview of the individual site.
- 3. Names and phone numbers to call for more specific information.

8.0 MANHOURS AND MILEAGE

8.1 Manhours

A total of 21,564.5 manhours were utilized to support this contract. This included site visits, plans, field operations, Project Manager and Corporate QC Manager visits, and reports.

8.2 Mileage Data (Mob/Demob)

A total of 15,784 vehicle miles were accumulated to support the mobilization/demobilization of this project.

8.3 Mileage Data (Home Leave)

A total of 15,278 miles were accumulated to support personnel going on home leave.

8.4 Air Flights

A total of 74 round trip and 8 one way air fares were utilized in support of this project.

9.0 SUMMARY

IT Corporation received Delivery Orders 0001, 0002, 0003, and 0006 from the US Army Corps of Engineers (USACE), Huntsville, Alabama to perform UXO removal actions at the Former Raritan Arsenal (FRA) located in Middlesex County, New Jersey. IT subsequently selected EOD Technology, Inc. (EODT) as its unexploded ordnance (UXO) subcontractor. This project consisted of Areas 1, 2, 3, 4, 6, 7, 8, 9, 10, 17, Building 118, Buildings 643 and 644 of Area 16 and the Spoils Area. Areas 2, 3, 4, 6, 7, 8, 9, and Buildings 643 and 644 in Area 16 were located within the Raritan Center Industrial Park. Area 10 is located in the Middlesex County Park. The area designated #1 is on land occupied by the US Environmental Protection Agency (USEPA). Building 118 (North Hall) and Area 17 are both located on land owned by the Middlesex County College. The Spoils Area is located across the river from the Raritan Center Industrial Park on land owned by Middlesex County Utilities Authority. Although there were numerous areas designated by delivery order for UXO/OEW removal actions, time and funding only allowed us to complete Areas 1, 4, 17, Building 118, and Buildings 643 and 644.

The Scope of Work included vegetation removal, identification and removal of UXO/OEW, and recovery and turn in of inert ordnance and ordnance related scrap. All live UXO and bulk explosive was destroyed on site by detonation.


The **EODT** Field Team followed Standard Operating Procedures (SOP's) that were outlined in the approved Work Plans. During the field operations portion on this project, a total of 114,117 UXO items and 12,361 lbs. of TNT were disposed of by detonation.

The number of **EODT** personnel on site fluctuated from 3-15 over a period of 12 months. From mobilization through demobilization, no time was lost to accidents or weather. However, when one considers this work took place within one of the most heavily populated corridors in the nation, the true scope of this accomplishment becomes obvious.

ATTACHMENT 5

SURVEY PLAN OF AREA 16 BUILDING SITES FORMER RARITAN ARSENAL, EDISON, NEW JERSEY

FIGURE 2



	инивинивиний инивинивиний инивинивиний инивинивиний инивиниви инивинивиний инивинивиний инивинивиний инивиниви	
	ROAD	
. *	:	
Buildibg # 10410		••
Duliding # W70		


Date Completed BAUG 91

Results Neg. No Explosure Old Nance

Note: * — Scrap metals/Wire/Ruber, etc.

SURVEY PLAN OF AREA 16 BUILDING SITES FORMER RARITAN ARSENAL, EDISON, NEW JERSEY

FIGURE 1




ROAD


Building # <u>645</u> Date Completed 16 Aug '91


Results Neg. - No Explosive Ordnance


Note: * — Scrap metals/Wire/Ruber, etc.


ATTACHMENT 7














ATTACHMENT 8

ATE	GRDNANCE	LOCATION (REF ATTACHED MAP)	CONDITION	QUANTITY	REMARKS (REF DAILY LLG)
31 Jul 91 03 Jul 91 03 Jul 91 05 Jul 91 05 Jul 91 05 Jul 91 05 Jul 91 05 Jul 91 17 Jul 91 17 Jul 91 17 Jul 91 17 Jul 91 17 Jul 91 17 Jul 91 18 Aug 91	MKTA BOOSTER APAPTOR II	(REF ATTACHED MAP)	UNFUSED/RUSTED 11 11 11 11 11 11 11 11 11	744118 124053 802 334177592802465	FINISHED # 3 FINISHED # 4 FINISHED # 4 FINISHED # 4 FINISHED # 6 FULL TANK SIDEWALK
3 Aug 91 4 Aug 91 15 Aug 91 16 Aug 91 16 Aug 91		5.04 1 77777777777777777777777777777777777	n 11 r 11 li 11	28 02 46 5 19 29 7 34 17 02 3 1 2 2 2 4 2 8 3 0 2 1 4 2 8 3 1 2 7 2 9 5 0 6 0 2 1 4 2 8 3 1 2 7 2 9 5 0 6 0 2 1 4 2 8 3 1 2 7 2 9 5 0 6 0 2 1 4 2 8 3 1 2 7 2 9 5 0 6 0 2 1 4 2 8 3 1 2 7 2 9 5 0 6 0 2 1 4 2 8 3 1 2 7 2 9 5 0 6 0 2 1 4 2 8 3 1 2 7 2 9 5 0 6 0 2 1 4 2 8 3 1 2 7 2 9 5 0 6 0 2 1 4 2 8 3 1 2 7 2 9 5 0 6 0 2 1 4 2 8 3 1 2 7 2 9 5 0 6 0 2 1 4 2 8 3 1 2 7 2 9 5 0 6 0 2 1 4 2 8 3 1 2 7 2 9 5 0 6 0 2 1 4 2 8 3 1 2 7 2 9 5 0 6 0 2 1 4 2 8 3 1 2 7 2 9 5 0 6 0 2 1 4 2 8 3 1 2 7 2 9 5 0 6 2 1 4 2 8 3 1 2 1 2 1 2 1 2 1 2 1 2 1 2 1 2 1 2 1	FINISHED #6. FUEL TANK

				1	1	
1	DATE	ORDNANCE	(REF. MAP)	CONDITION	QUANTITY	(PEF. DALLY LOG)
	0952991	MK I A BUDIES APPRE	3	UNIUSCO/RUSTED	206	
	105411	ti ii ii		4 ' 11	619	
	1150891	n n n	8	k k	225	
	1255941	K to to	l R	10 11	1369	
	1754991	je 86 11	8	a u	1267	ACTIVE FLEE PANK
	1858891	10 11 .1	S	11 11	1074	
	195EP91	pl st x	8	· 10 11	1369	,
	205EP91	H H H	8.	2"	1290	BACKFILL / NUSARIETE
	23500 91	k k V	POUSE LINE [7		73	
	1150 91	r 2	4 (7)	A) " "	16	FINISHED
	2652091	, 16 P	The CARLE (7	n) " "	8	FINISHED
	020491	a h h	9	"	101	FINISHED
	0400191	W & #	8	H H	131	FUCE THE TEST
	0700-91	ic ic 4	1/	H II	23	FINISHED
	H K H	JC 4C 41	STBALT LITE	u u	31	0,-00
		11 11 1C	8	11 4		PRET WARE
	0800191	a b u	STREET LIFE	at 11	2/2	FINISHED
	1	A 11 1	8	и и	208	
4	1900 91	4 11 11	8		609	
	15 OCT 91	a u u	12	1	1370	
	1300 41	n 11 11	12	u is	236	
	14 11	12 14 11	13	n "	2 55	
	16 Oct 91	4 4 11	13	11 11	977	
	14 11 11	11 11 10	12	ii ii	392	
	1700791	4 11 11	12	A 4	966	
	A H H	1 11 11	12	À A	1035	TRANSBET XZ
	18 OCT 91	u u u	12	n u	_	***************************************
	H H H	11 11 11	13	μ //	817	TRANSPORT x 2
	210ct91	OF H H	12.	# #	462	> TRANSPORT XZ
	uk "	fr is 11	13	10 11	2192	
	1200191	H K H	12	l u u	1400	AROUND STUMP
	130ct 91	A H	12	" "	1403	STUMP AGAIN
	2400 91	u u u	8	# #	302	UNDER BEHIND
	390591	MKIII BAOSTER	12	1 1 k	===	SAME AS SOLULY
À	k K	MILIE A BOOSTER/APAPIZA	12	h H	1596	STILL AROUND STUMP
	30 OCT 91	u u n	1232	u u	2443	STUMP OUT
	y. y .	, , ,	13	1	63	i
	31007 91		12	H 4	1313	
	01NOV91		1	H 41	1078	
		11 11 11	/ 3	11 11	200	
`	18 house	pt n n	12	, ,	1305	TRANCE OF WA
	USNUV 91	u ac #	12	11 4	2500	TRINGBET XZ
	16 NOV 91	6L +2 n	12	7 0	2300	>TRANSPORT XZ
1	27 NOV 91	* * *	12	11 4	2856	TRANSBET XZ
	47 May 16	g, ti ĝi	13	le 4	1240	
			, , ,	•		

200			1 .			
, 5	DATE	ORDHANCE	LOCATION (REF MAP)	CONDITION	QUANTITY	REMARKS (REF DALLY LOG)
	13 NOV91 14 NOV91 18 NOV91 18 NOV91 18 NOV91 21 NOV91 21 NOV91 25 NOV91 25 NOV91 25 NOV91 25 NOV91 25 NOV91 19	ORD PADCE UKTEA BOOKEA AND THE HE H	CREFINATION DE LA CONTRACTION DEL CONTRACTION DE LA CONTRACTION DEL CONTRACTION DE LA CONTRACTION DEL CONTRACTION DE LA CONTRACTION DE LA CONTRACTION DEL CONTRACTION DEL CONTRACTION DEL CONTRACTION DEL CONTRACTION DEL CONTRACTIO	CUSTED FOR FORE 1) 11 11 11 11 11 11 11 11 11	530214707 26090091112537227335005425290 94000831 18431 1125372273345 122 937	FINISHED LEVEL # 2 FINISHED LEVEL # 1 TRANSBORT X 2 TRANSBORT X 2 TRANSBORT X 2 FINISHED LEVEL # 1 FINISHED LEVEL # 1 SHORING TODAY STRANSBORT X 2 FINISHED LEVEL # 2 HUNG WITHIN 2 ME II "" II " II
	128, JAN 92	of 11 11	DRIVE	1	226786112196	POCKET ADJACENT AREA 2 ALONG OLD THE CARE SEE PLOT MAP SEE PLOT MAP AMM WASHOUT

DATE ORDIANCE LACATION (REF AIRS) ASTERDAL MILITA RESTORMED DRIVE PRINCE PRINCE PRINCE COSMULA II	25 FED 9 2 MKITA PEAPOR FROM DRIVE DRIVE DRIVE DRIVE OF AME 12 MKITA PEAPOR FROM DRIVE DRIVE DRIVE MI MI MI MI MI MI MI M						
25 FBG C MAKEA HEATOGROUP DRIVE DATES / RUSTY 03 MAR	25 1839 92 11 11 11 11 11 11 11 11 11 11 11 11 11	DATE	ORDNANCE	LOCATION (REF MAO)	CONDITION	QUANTUM	REMARKS
		25 FBB 92 03 MAR 92 15 MAR 92 18 MAR 92 18 MAR 92 16 MAR 92 18 APR 92 06 APR 92 18 APR 92 20 APR 92 21 APR 92 22 APR 92 23 APR 92 23 APR 92	HAKTER ABAPTOSPENDER OF A A A A A A A A A A A A A A A A A A A	CREP MADO) DRIVE DRIVE BUSH GA THE SECTOR TH SECTO	ANFUSCOS PLUSTY IN IN INFINST OF RUSTY II II II III II II II III II II II III II II II III II II II III II II II III II II 3483 1743328084222222222 143 2 3 45550770	RAIN WASHOUT SECTOR # 4 RAIN WASHOUT WASHOU BRACIAL, JACK HAMMEL UNDER DRIVE	

EXCAVATION AREA SYNOPSIS BY AREA TITLE NUMBER

MUNITIONS RECOVERED (MK-II BOOSTER/ADAPTOR)

AREA	#1							•
/III.		JUN	άi		712			
		JUL						
	. 02	JUL			654			٠,
	03				678			
		JUL			189		•	
,		JUL			483			
		JUL			1130			
,	US	JUL	3.1		135			-
					TOTAL	3981		
AREA	#2							
CHARLE.		JUL	91		87.0			
	11				89			
		AUG			241			
٠.		AUG			917			
		AUG			267			•
	UO	AUG	91		15			
					TOTAL	2399		
AREA	.40							
AKEA		JUL	0.1	•	1100			
		JUL			1129	•		
		JUL			1220			
	4				432			
	19	JUL			1000			, .
		JUL			1578			
		JUL			1309			
٠,	4	JUL	91		80			
					TOTAL	. 6748		
AREA	#4							
AKEA		JÚL	0.1					
	25	JUL			851			
	30	JUL			1097			•
				1 =4 144=4 ===	216			
	**30	JUL		1 EA MARK-III		APTOR		
	31	JUL	91		29			
					TOTAL	. 2194		
AREA	4 5							
ANEA	-	JUL	à٦		007			
		AUG			307			
		AUG			1336			
		AUG			1162			
,	03	AUG	91		154			
/					TOTAL	. 2959		
AREA	#6							
VKEW.		AHO	0.1					
		AUG			1189			
		AUG			632			
		AUG			148			
	12	AUG	91		10			
					TOTA	L 1979		

```
AREA #7
       15 AUG 91
                                        572
       16 AUG 91
                                       1804
       19 AUG 91
                                        326
       20 AUG 91
                                        135
       21 AUG 91
                                        271
       22 AUG 91
                                        729
       27 AUG 91
                                        222
       28 AUG 91
                                        949
       29 AUG 91
                                        527
       30 AUG 91
                                       1082
       03 SEP 91
                                        681
       04 SEP 91
                                       1008
       05 SEP 91
                                        421
                                         TOTAL
                                                 8727
AREA #8
       09 SEP 91
                                        206
       10 SEP 91
                                        619
       11 SEP 91
                                        225
       12 SEP 91
                                       1369
       17 SEP 91
                                       1267
       18 SEP 91
                                       1074
       19 SEP 91
                                       1369
       20 SEP 91
                                       1290
       04 OCT 91
                                        131
       07 OCT 91
                                        95
       08 OCT 91
                                        208
       09 OCT 91
                                        609
       15 OCT 91
                                        236
       24 OCT 91
                                       .302
                                         TOTAL
                                                 9000
AREA #9
       02 OCT 91
                                       101 TOTAL
AREA #11
        07 OCT 91
                                         23 TOTAL
AREA #12 (LEVEL 1)
        10 OCT 91
                                        1370
        15 OCT 91
                                         649
        16 OCT 91
                                         977
        17 OCT 91
                                         966
        18 OCT 91
                                        1773
        21 OCT 91
                                         462
        22 OCT 91
                                        1400
        23 OCT 91
                                        1403
      **29 OCT 91
                    1 EA. MK-III BOOSTER/ADAPTOR
        29 OCT 91
                                        1596
        30 OCT 91
                                        2443
        31 OCT 91
                                        1313
        01 NOV 91
                                        1078
        04 NOV 91
                                        1395
        05 NOV 91
                                        3000
        06 NOV 91
                                        2500
        07 NOV 91
                                        2856
                                           TOTAL 25092
```

AREA	15 OCT 91 16 OCT 91 17 OCT 91 18 OCT 91 21 OCT 91 30 OCT 91 01 NOV 91 06 NOV 91 12 NOV 91 13 NOV 91	255 392 1035 877 2192 63 200 644 1240 856 TOTAL 7754
AREA	#14 (LEVEL 1) 13 NOV 91 14 NOV 91 15 NOV 91	487 2001 2022 TOTAL 4510
AREA	#15 (LEVEL 1) 18 NOV 91	1011 TOTAL
AREA	#16 (LEVEL 1) 19 NOV 91	841 TOTAL
AREA	#12 (LEVEL 2) 22 NOV 91 27 NOV 91	65 11 TOTAL 76
AREA	#13 (LEVEL 2) 20 NOV 91 21 NOV 91 25 NOV 91 27 NOV 91 09 DEC 91	373 1122 300 14 22 TOTAL 1831
	#14 (LEVEL 2) 10 DEC 91	152 TOTAL
AREA	#15 (LEVEL 2) 22 NOV 91 11 DEC 91	802 71 Total 873
AREA	#16 (LEVEL 2) 10 DEC 91 11 DEC 91	32 28 Total 60
AREA	#17 20 NOV 91 21 NOV 91 18 FEB 92	79 9 110 Total 198


PAGE 3


EET LIGHT CABLE - 07 OCT 91 08 OCT 91	31 12 TOTAL 4 3
AREA #7A	
23 SEP 91 24 SEP 91 26 SEP 91 20 NOV 91 25 NOV 91 26 NOV 91 27 NOV 91 09 DEC 91 19 FEB 92	73 11 8 103 492 101 92 113
DRIVE AREA	
19 DEC 91 08 JAN 92 09 JAN 92 10 JAN 92 14 JAN 92 15 JAN 92 21 JAN 92 22 JAN 92 23 JAN 92 27 JAN 92 28 JAN 92 28 JAN 92 04 FEB 92 11 FEB 92 12 FEB 92 13 FEB 92 14 FEB 92 24 FEB 92 25 FEB 92 03 MAR 92	23 372 33 103 40 50 5 4 12 5 22 29 69 132 87 266 18 16 13
SECTOR #2 18 FEB 92 19 FEB 92	2


AS OF 04 MARCH 1992, THE TOTAL NUMBER OF EXPLOSIVE FILLED MUNITIONS RECOVERED FROM THIS SITE IS 82,762 MK-IIA BOOSTER ADAPTORS AND 2 MARK-III BOOSTER ADAPTORS. THE NET EXPLOSIVES WEIGHT OF THESE ITEMS IS 22,760 LBS.

TOTAL 3

ATTACHMENT 9









WEAK.

4077 MAG HITS



Date.	Subject	AREA	2. 5	TE 17	SI	neet No. 2	_ of
Chkd. ByDate	TA 50 = 3'APP					roj. No	
Cirku. Dy	(85)	0	(1)				
2 4	79	2 8 9	120	8 8	3 8	2 3	
	1- ap 18" Pao						LANE! 34 81 118 115 115 115 115 115 115 115 115



Date Subject AREA 3 STE 17 Sheet No. 3 of Proj. No. Sheet No. 3 of Shee	CORPORATION				\bigcirc
Denn For Where Zanoff	DateDateDateDateDate	Subject <u>ARER</u> 0 = 3'MP , 5' s	3, SITE!	7 Sheet No.≤ Proj. No	3_ of
W. Large At - 18 Provs Add Drain For Ware Zwoff	825 HITS		1		
W. Large At - 18 Provs Add Drain For Ware Zwoff		9,~	, 🕠		
W. LARGE HT - B'RADUS AND BY DRAIN FOR WARE ZUNOFF	111111 E Q	= 2 m n m	~~	2 8 8 3 6	336
	(X) = LARGE HT - 1	B' PADIUS ADP	6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6		81 78 75 72 64 66 63 60 57 54 51 48 45 42 33 36 31 34 21 18 15 12 9 6



y 890 HtTS Date_	Subject A	EEA 4, SIT	E171	Sheet No.	<u>#</u> _ of
Chkd. ByDate_	A SQ = 3' APP			Proj. No.	
Circu. by butom			(N)		
2 01 12 X	>	102'	10 03 10	W	700
413 32	3 2 2 3	8 8 B	B 63 8	7 6 9	8 2 2 X
1 1 XXXX	X X X	X X X X X	X X X X	k*x	
\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	1 × ×	* * * * * *	`44 \\		_ *
Θ ,	* * *	3.	< × @		\$ 1 m
* X	* * × ×		X X X		** ** * * *
× ×	3 ×	4 4 * 4	X X X	[1 1 1 1 K
> × × ×	4	* * * * *	X X X	1	* 8
		x x	* X		
×		* .	× × ×		
7 7 4 4	1. 1. 1	x * 4			X*
		-[* +]	, *x *		* 2 PN
** * * *	*				+ + + 3
	* * * .	x	* * K		
	** × *	* *	****		
Tine	* *	x f x	XX X	([] *]	* * + 20
	* *	× ^	~ × ×		* * * * * * * * * * * * * * * * * * *
auch .] / * *		X X X		* * * * * * * * * * * * * * * * * * * *
* , * , * , * , * , * , * , * , * , * ,		X X Y Y		1 × 1 · 10 al	4. 8
407	1 1 1 1	x x x	* * * * * *	(x x x	* + + B
	*	x x	(4 × ×;	14 - 4x *	4 × 4 0 0
		_ ×	, X	. × .	* * * * 6
V. 24 X 3			x x x	* * * * * * * * * * * * * * * * * * * *	* * * * * * * * * * * * * * * * * * * *
		1 4		* × × ×	* * * * * * * * * * * * * * * * * * * *
\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	1 × 1 × 1	<u>"</u>	* * *	12. 1 . 4 3	4.7 . 4
71.		2 4	× x ,	* * * * * * * * * * * * * * * * * * * *	7 7 7 7 7
	(a) (a)	× × × × @		(k, " (b : k	* 4 *
W+ " = ~	+ + *	x	* * v v v	** (), * + +	- T
15/12	1 - 1	, x x x			9 1 1 1
	+ 4 × ×	1 4 4	+7,7 x2 .	(-	3*
5 8 E	5 T F G	5 6 5 6	0 8 1	+ 0 0 ±	w 4 -

G=TREE 5'-LANES

(8 = HEAVY / CONTINUOUS DITS /18"R APP



D-TREE

4		y <u>!0.</u>	52	#17 D	75 ate_		S	ubjec	1 <i>A</i>	PE	7 3	5, .	Sįz	<u>-</u> /	7		_ She	eet No	<u>.5</u>	_ _ of .		
	Ç CI	hkd.	Ву_	D	ate 🚄	A 5	9=	3'A	PP				+	•			_ Pro	j. No				
,	7X7.									16	2'		(N)									
	33	х		\		0.		Δ.	7	\	1	26	~	52	63	8	0	_	2	۸	٨	
	San Sega	7	n	*	1/2	1/2	8	8	15	0	00	7	9	3	14	'	8	2	3	\$	7	20
			4	×		* 4 .×	X X	4 4	٠ <u>,</u> ۲	4	*.	K.	*	ę	¥ ×	\(\frac{1}{2}\)		u ×	ų k	<u>ک</u> ۲	-	22
		×	*	R.	¥		×	اب `	x x	**	*	X X	, X .	4 1	*	ķ	,	.	, w	~ X		E
	1	×,e	1	×			×	~ ~	× .	ą.	ж ж	•	* *	¥ ¥	* *	, t	ľ.	^	, X	* *		78
	{	×	. ¥	x	4	x x	¥	**	ر * _ع ا	, R	4	¥	, k	•	* *	4	1	, x	* *	, , ,		2 2
-	7	_			×	, v	A X	Я	`	×	ž	ik X	XX	**	X ¥	× ×	*	•	, K	, ,	*	69
K	š			×	×	`*	ν × ν	e 4	3	ж.*	4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4	£.	* *	×		-	47.		¥	× 4,		99
	۱ د		×	* *,	×	¥	-× 4	1	X X	3	* 4	k V V	ZX.	v	**	,	X *	x x	* *		1	60 63
	×			××	* *		35.V	* * * *	4	¥ 2 Y 2	- N	*	* *	# ¥ 4	- ^	*		K *	* * *	××		27 6
		•		4	×		***	. *	*	, a.	4 4	* *	×	*		*	*	× ×	*	*	*	34
ş	,	•		**		***	* * *	7.7%	* *	**	4 3	× ×	4 4	Y.	* 3		< ×	* - *	* *			15 8
UME	اد		, L	**x	*	, x	ž	Ð	4.4	•	74	*		a.	۲ ×	Ö,	-	X WA	*	•		4 4
d	٠	ر.			, X	*, *	××.	24.4	u. u.	1 VV 4		× ×	*	.:5		, x	4	KK X	*	.>		2
~	*	Š.	,	*	X.	4 4 4	* *	4,	×	4 ×	£ , ¥		i.*	4.		١,	· _×	Y Y	4 3	, a		36
	×	,		1 ,		O,	x * "	7,	~ <u>`</u> ``	*.	×,	x	1 5	*	<u> </u>		w .	٠,	4 	, ×		if.
	<u>بر</u> د	×	*	**	× ;	×	- ×	* ***		2.4%	7	١,	**	A X	.0	\ * \	(x	•	**	••		3. S.
	۲ پ		*	*	×,	\ * _\	×	1 +4	*	*+	1 × ,		•	A, X	 *,	, ×	*	X	+ "+	-	*	25
- 1	ا د	لخي	××	, x	4 *	×	* *	4	١ ٠	+	, **	4 × ×	, ×	×	ني	-	1	37	+ +	*		40 h
((E			X X	1	* * *	x x x	1.	⊙*	< 4		*	- *	× ×		F 4.	× *	* *	_+	1	*+	11
	۲	×		\ ×	^	*	+ ×	+*	K				8	× ×	14,		•	*, *	*			Ø
1		*	1	. *	× ×		×4X	-	^	-	+	, X	4	*	`	4) *		1,0) · ·	-	7
		X.	-		Х	4	3	'	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	1	1	;		\.\`.	, 3		, (G)	ሳ ""	*		†	
4		***	x	X X	**	×	**		× *		+	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	××	4	, 4 X		×	2.	1 2	x	+ -	100
	,	Y, C	k	k s	x x	- 29	12	1	1.	7 2	4 +	13,	9		-	1-3	1 7	, *	1 4	1 × ×	1	1
		⊗• ⊘?	is Heavy	, Ken	- הממומדים	. <u> </u>	•			`			•									



Date Subject As	EFA 6, SITE M	Sheet No. <u>6</u> of	
m 100		Proj. No	
Chkd. By Date FA SG = 5 Kir	,09/		-
35 454 454 454 454 454 454 454 454 454 4	11/1/	Wille III	3
34 2002 - 200 LE 20 18 12			Ŋ
k.)			
wax way		Kenny Middle Marin	\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\
(2) (3) (3) (4) (4) (4) (4) (4)	EL A HILLIAN		3
10 8 Jun + - 4 4 8 8	Street American		
/ 1/ 18 / 1 × 1 × 0			
16 x x x x x x x x x x x x x x x x x x x	B 1		1
THE THE REAL PROPERTY AND A REAL PROPERTY AND		XXXXXIII	2
建 16 14 15 15 15 15 15 15 15 15 15 15 15 15 15	×		4
20 × × × × × × × × × × × × × × × × × × ×	1, W		
12 14 xx x x x x x x x x x x x x x x x x x	S.D.C.		9 3
- 10 E	VI -	WALK WAY	7
	15 k, 15 k, 15 A.	White why	¥
WALEUMY SEE SURVEY SEE SURVE	SHRUBOLE STORY	De la	뒥
/ / / (4 N 4 K			ž
	2 4 2 4 3 3 3 2 5 3 3 2 2 2 3 3 2 3 3 2 3 3 2 3 3 3 3		1
			1
The state of the s			
			8
/- / 2 1 2 C			Ø
/* x/ . King			9
/+ x/ 18/2		م المالية الما	0 5
4.7		COCKE TO THE COCKE	00
	N N JELES		10
	13 8 m	P174	•
	~ <u> </u>	, []]	
	<i>\ceil</i>		

NOTE: IVY COVERED EXARPMENTS VERY DIFFICULT TO MAG EFFECTIVELY.
THE MAKS WELL EXPLEMELY AFFECTED BY STEEL WALLS OF BLDG.

D=4GHT

3=36NE

D= Contravais Heavy the /18'R APP



Date _____ Subject Area BA, SITE 17 ____ Sheet No. 7_ of ____ Chkd. By____Date_<u>EA_S0 = 5' APP</u> Proj. No. _____ 505 HITS 51 LANES PIT5 HÒ UD. **&**





V	Date.	Sub	ject PITA, SITE 17	Sheet No of _5
Chkd By	Date	1/2" = 1'		Proj. No

1) 73 METALIC OBJECTS RECOVERED


A. AT APP 24' BELOW SURFACE, MAJORITY OF HEAVY CAST IRON FRAGMENTS WERE FOUND, SPREAD UNIFORMLY THEW-OUT THE PIT.

B. AT APP 6" BELOW SURFACE A LAYER OF TOP SOIL & FILL INCLUDING A LAYER OF MAGNETIC ROCKS.


C. BETWEEN THE 6"924" LAYER, SO MANY NAILS, COKE CANS, REBAR, + METAL STRAPPING ITEMS WERE LICATED ACROSS THE WIDTHY DEPTH OF THE PIT.

D. CONCENTRATIONS OF METAL FRAGMENTS WORL NOT PIN PUNTED IN ANY SPECIFIC AREA, RATHER EVENLY DISPERSED.

E. NO SUBSURFACE CEN/OEN RELATED SCRAP RECOVERED.








- 1. 1330 ITEMS RECEVERED, ALL ARE SCRAP HEAVY METAL ITEMS, PRIMARILY OLD HINGES, SPRINGS, PINS, + YOKE CLAMPS ASSICIATED WITH DOORS ON OUD STILE AMMO MAGAZINES FOR STORAGE.
- 2 AT APP 18" BELOW SURFACE WE EXCOUNTERED SCAT-TERED POCKETS OF WHAT APPEARS TO BE DRIVE FIT PINS THROUGHOUT THE PIT.
- 3. AT APP 24" BELIN SUFFAIE WE ENCOUNTERED SEVERAL HEAVY HUKES, SPRINGS, Y YOKE CLAMPS EVENLY DIS-PERSED, SUGHTLY HEAVIER IN THE CENTER OF THE PIT.
- 4. CONCENTRATIONS, OTHER THAN CLUMPS OF THE DRIVE PINS, WELL NOT NOTICEABLE SPECIFIC IN LOCATION.

5. NO SUBSURFACE DEN / VEW RELATED SURAP RECOVERED.







By______ Date_____ Subject PITC, ACCA 17 _ Sheet No.<u>3_</u> of <u>5</u>

_ Proj. No. ___


1.39 ITEMS RECOVERED, ALL WERE SCRIP METAL, MANY PIECES OF HEAVY "4" WIRE, REBAR, 55 GAL DOWN LID, + METAL FING.

2. IN THE COUTER OF THE PIT AT THE E'LEVER WE LUATED A LARGE CONCRETE DEAIN PIPE THAT RAN COMPLETELY THEN THE PIT CONNECTING 2 GROUND LEVEL DRAINS OUTSIDE OF PITC.


3. MAJORITY OF THE ITEMS WELE RECEIVED NO MORE THAN 18" BELLIN THE SURFACE.

4. CONCENTRATIONS WERE NOT SPECIFIC IN LOCATION.

5. NO SUBSURFACE CETU/ NON-OUTU RELATED SCRAP RECOVERED








1. THERE WERE 39 RECEVERED ITEMS FOR THIS ASEA.

2. ALL ITEMS WERE CONSTRUCTION MATERIALS IR., REBAR(
1-10' FT PIECE, 1-6'FT PIECE, \$1-4'FT PIECE), THE WIRE,
NAILS, ETC. SEVERAL LARGE CHUNKS OF CONCRETE WI WIRE
\$ REBAR INIT.

3. THERE WAS NO SPECIFIC LOCATION OR CONSTRUCTION
OF HITS. THIS HEAR WAS EVIDENTLY A CONSTRUCTION
BACKFILL AREA.


4. THERE WERE NO GEW/ DEW-RELATED SCRAP ITEMS LOCATED.





V	Date	Subject.	AREA 7.	SITE	<u>/7</u>	Sheet No.	5 of <u>5</u>
bkd By				.,		Proj. No	

- 1. 162 ITEMS WERE RECOVERED FROM THE PIT DUG IN AREA 7, SITE 17.
- 2. ITEMS RECOVERED WERE: BAYONET, END OF MI CARBINE BARREL, 60MM MORTAL FINS, ASSOCIATED PIECES OF ANGLE IRON, SEVERAL PIECES OF PIPE + ASSOCIATED FITTINGS, SAFETY GLASS WITH WIRE LACED THRUIT, SPARK PLUG, MOTORCYCLE KICK STAND, FOOT PEGS, 55 GAL BARREL (EMPTY), OLD FIRE EXTINGUISHER, CABLE, & MISC. BOLTS, NUTS, NAMES.
- 3. THERE WAS NO SPECIFIC LOCATION OF CONCENTRATION OF HITS. WE ONLY DUG DOWN TO APPROXIMATELY 24" & DETEC-TED NO FURTHER MAGNETIC HITS.
- 4. WE DID LOCATE I PC OF DEW-ROLATED SCRAP I EAR



ATTACHMENT 10

FORMER RARITAN ARSENAL PROJECT

18 September 1991

SUBJECT: Memorandum for Record (Gym Site)

On 17 Sep 91 we returned to work from a four day break. During the break, a hand grenade (empty) had been found on the Middlesex College Campus in the area of the tennis courts. As I was checking the sites, I received a call from Dr. Chan, the Project Manager for IT, stating that Mr. Bob Nore, ACE, Huntsville, wanted to visit the site of the hand grenade discovery. We met at approximately 1000 hrs.

The people present at the meeting on site (The Gym Site) were:

- Dr. L. Chan, IT Corp.
- Mr. F. Javorka, IT Corp.
- Mr. R. Nore, ACE, Huntsville, AL
- Mr. T. McLaren, EODT

Mr. Nore was concerned that the site get immediate appropriate attention. After walking the site, the plan presented by Mr. Nore was to:

- Surface Sweep the area.
- Check the immediate grenade location w/ magnatomiter.
- Check any other suspicious areas w/ magnatomiter.
- Record "Hits".

The team from Site # 17 (Hank Hubbard, et al) was given this mission. At approximately 1100 hrs the team commenced operation.

The area was checker as per the original plan presented by Mr. Nore. No type of explosive ordnance was discovered. The operation was completed at approximately 1715 hrs.

On the morning of 18 Sep 91 Dr. L. Chan and Mr. F.

Javorka were briefed on the results of the sweep.

It is my opinion that we (EODT) responded in a rapid, professional manor and met the needs of ACE, IT and Middlesex College. The Crew conducted the operation in a rapid and skilled manor that met the very highest standards.

Prepared by:

THOS A. MCLAREN

Senior Site Supervisor



Sheet No.___ Chkd. By____Date_EA GRID = Proj. No. . APP I ACRE SEEA 2871 113 1. PERFORMED SURFACE SWEET - NOTHING FOUND 2. MAGGED AREA AROUND WHERE GRENDE WAS FOUND (15' RADUS) NOTHING-ORDINAL RELATED-FOUND

3. MAGGED APP 24' OF EASTERN EDGE PRONG (2701) QUILLIANDY, 44 HITS - DUG 25% OF THEM - ROCKS, WIRE, PIPE -NO ORDNANCE RELATED ITEMS RECOVERED.

4. MAGGED APP 3500 3Q FT WITHIN THE ADEA, APP 105 HITS, DUG THEM ALL, ROCKS, FIRE, ETC., NO ORDINANCE RECATED SCRAP FOUND.

MEMORANDUM FOR RECORD : EODT RESPONSE TO MIDDLESEX COMMUNITY COLLEGE, EDISON NEW JERSEY ON 14 SEP 1991.

PERSONNEL DISPATCHED: ED PINSON AND SAM NEWBERRY.

ORDNANCE RECOURTED: I EA., GRENADE, HAND, FRAGMENTATI MK II. UNFUSED, WOODEN PLUG, EMPTY.

SUMMARY: TEAM RESPONCED PER REQUEST OF DOUG LAMONTHE, EOOT. TEAM DEPARTED MOTEL AT 1220 HE AND ARRIVED SITE AT 1245 HRS. SCENERGO AND CURCUMSTANCES AT SITE AS DESCRIBED IN ATTACHED OPELATIONS REPORT FROM CAMPUS POLICE. ITEM POSITIVE I.D. AND DETERMINED SAFE TO HANDLE AND TRANSPORT. DEPARTED SITE AT 1300 AFTER SEARCH OF IMMEDIATE AREA FOR ADDITIONAL ITEMS. ITEM TAKEN TO MAG STORAGE AREA IN SITE #16. WOODEN PLUG REMOVED AND ITEM FOUND TO BE EMPTY, ITEM SECURED IN MAGAZINE AND TEAM, DEPARTED SITE #16 AT 1350. ARRIVED MOTEL AT 1415.

AFTER ACTION! CALLED DOUG LAMONTHE TO REFRET ACTIONS TAKEN AND ARRANGED MEETING BETTUESU CAMPUS POLICE, EDISON POLICE AND LTC PURRER, COE, FOR 0900 HRS

17 SEP 91 TO DISCUSS PROCEDURES AND PROPER NOTIFICATION FOR EMERGENCY RESPONSE.

I ATTACHMENT AS STATED:

ED PINSON

EUDI TEAM LEADER

OPERATIONS REPORT

DATE: SEPTEMBER 14, 1991

TIME OF INCIDENT: 1044 HOURS

LOCATION: WOODED AREA ON RIGHTSIDE OF WEST ROAD

BETWEEN GYM AND TENNIS COURTS.

INCIDENT: LIVE HAND-GRENADE FOUND IN TREE STUMP.

RICHARD CHARTIER/#117

ON THE ABOVE DATE AND TIME THIS OFFICER WAS DISPATCHED TO THE TEENIS COURTS AREA OFF WEST ROAD TO MEET A MAN IN REFERNCE TO A LIVE HAND-GRENADE HE HAD FOUND. AT 1045 HOURS THIS OFFICER ARRIVED AT THE LOCATION AND MET EMPLOYEE OF SILAGY LANDSCAPING WHO LIVES AT US FOLAEX (b)(6) AN EDISON, NU STOLAEX (D)(6) IN REFERENCE TO THE ABOVE MATTER. MR. STOLAEX (D)(6) EDISON, NU STOLAEX (D)(6) IN REFERENCE TO THE ABOVE MATTER. MR. STOLAEX (D)(6) EDISON, NU STOLAEX (D)(6) AN EDISON, NU S

AT THIS POINT THIS OFFICER AFTER LISTENING TO MR. CHECKED THE AREA AND FOUND WHAT APPEARED TO BE A HAND-GRENADE, THIS OFFICER THEN REQUESTED SGT. ELMEYER FROM EDISON POLICE AT 1055 HOURS FOR ASSISTANCE. SGT. ELMYER ARRIVED AT 1112 HOURS AND ALSO EXAMINED THE AREA AND THE GRENADE.

SGT. ELMYER LEFT THE SCENE AND RESPONDED TO COLLEGE POLICE HEADQUARTERS TO TRY AND NOTIFY THE PERSONNEL WHO HAVE BEEN DIGGING UP THE MUNITIONS AT THE NORTH HALL AREA. THAT COMPANY IS E.O.D.T.. HOWEVER BEFORE DOING THAT SGT. ELMYER FIRST HAD TO CALL THE (I.T.) COMPANY FOR THEIR PHONE NUMBER AS WELL AS AUTHORIZATION TO HAVE THEM COME OUT.

AT 1132 THIS OFFICER REQUESTED OFFICER DIAKUNCZAK TO COME IN EARLY, ALSO FOR ASSISTANCE.

AT 1154 HOURS SGT. ELMYER MADE CONTACT WITH THE (I.T.) COMPANY REPRESENTATIVE WHO STATED THEY WOULD GET BACK TO HIM.

AT 1208 HOURS (I.T.) DID GET BACK AND E.O.D.T. WAS NOTIFIED AND STATED THEY WOULD BE OUT IN ABOUT A HALF HOUR. THEY ADVISED SGT. ELMYER TO SEAL OFF THE AREA WHICH WAS DONE PRIOR TO THEIR ARRIVAL.

AT 1246 HOURS ED PINSON OF E.O.D.T ARRIVED ON THE SCENE AFTER EXAMINING THE ITEM HE DETERMINED IT WAS A WORLD WAR II MK-II TYPE GRENADE. MR. PINSON ALSO STATED THAT IT DIDNOT HAVE A FUSE BUT APPEARED TO HAVE A SPALER PLUG WHICH MEANT IT COULD HAVE BEEN FILLED WITH BLACK POWDER BUT WAS NOT SURE AND FURTHER TESTING WOULD BE NEEDED TO PROVE THAT.

AT 1259 HOURS MR. PINSON LEFT THE AREA WITH THE GRENADE. THE AREA WAS TAPED OFF WITH POLICE LINE TAPE AND ALL OFFICERS CLEARED.

(615) 483-0007

FAX (615) 481-0653


EOD Technology, Inc.

Services, Investigations, Remedial Actions

ED PINSON

Team Ldr./ Safety Supervisor Master EOD Tchnician





Sections

Sectio

INTERNATIONAL TECHNOLOGY CORPORATION	<(N)
By Date Subject AREA	4 Sheet No of
Child. ByDate	Proj. No.
PARKWAY PLACE	FIRE PRIVA
	92'
275' 27'-> (Survey Zone) 275'	5
DEGN TO THE TOTAL PROPERTY OF THE PROPERTY OF	
STAL Z PAD	178 4173
1	
190 HIT	Oxo Halla
	158 HITS
	,,,,
SO DO SO DE	60' - 52
1 1 S8/2 S8/2 S8/2	
	N VIIIIIII
	1
THE	C.V.
1 Age	
The state of the s	THE STATE OF THE S
1 CE AT THE WAR THE WA	SG HITS
THAT HALL	775
	###### Sarvin
	56 HITS 50000
till the till the contract	73-3
/= 3 9'	. !'
	1250
	1387 TUTAL HITS


1387 TUTAL HITS

INCLIDING;

NAIL BEDS

RK METAL PILES,

ETZ





EOD TECHNOLOGY, INC. ORDNANCE RECOVERY LOG FOR SITE 4

BAG	ORDNANCE	EXCAVATED	DISPOSITION
NUMBER	RECOVERED	AT:	AND DATE
1011		PIT 4	TO DOMO/STURACE M
1311- A.OO1	WWI ACRIAL BOINB	Section 55	NOVEM BER 6, 1991
1318-A001	75MM EMPTY CASE	PIT 6	10 05M0/STUAPGE NOU. 14,1991
1322 - AWI	ARTY FUZE POW TRAIN TIME	SECTION 9	NOV. 18, 1991
1344-AUDI	155mm a ASING/HE RETIGE	SECTION SEC	12-10-91 for
1345-A001	75mm HE Wo FURE	3ct 1700	TO Demolstores
1345- A002	4 CA PROJECTICE A/13	SCETION	5 5
1346-A001	1 CA PROJECTILE A/13	SETTION 93	12-12-91 fec
1351 - Avol	9.2" HOW ITZER H. C. RESIDUE	50000	TU DEMO 12-17-91 Jean
1352-Acol	75mm HE 401475	SCETTUM 36	70 Demo 12-18-91 fec
2009 - A 00 1	1 GA PROJO Ala	Scenier	To Deno
2015- A001	75mm HE W/O FUZE SEL	Section	TO Demelstease
A002	((((47	1-15-92 ta
A003		-	
		f ·	,
2049- AUDI	FUZE, COMPLETE, PD	Seria 77	70 25m0/5702265
2049- AUDI 2051- AUDI	TUZE, COMPLETE, PD 75 MM HE W/O PUZE STAR	seenin 37	2-19-92 dealy
	TUZE, COMPLETE, PD 75 MM HE W/O PUZE, STEAM		2-19-92 dealy
2051-A001			2-19-92 dealy
2051-A001 2 3 4 5 6 7 8			2-19-92 dealy
2051-A001 2 3 4 5 6 7 8 9 10 11	75mm HE W/o Pure snap	senery	2-19-92 dealy
2051-A001 2 3 4 5 6 7 8 9 10 11	75mm HE W/o Pure snap	senery	2-19-92 dealy
2051-A001 2 3 4 5 6 7 8 9 10 11		senery	2-19-92 dealy

EOD TECHNOLOGY, INC. ORDNANCE RECOVERY LOG FOR SITE 4

BAG NUMBER	ORDNANCE RECOVERED	EXCAVATED AT:	DISPOSITION AND DATE
92066-A001	1 GA PROJO A/BOOTTER	PIT 6	3-6-92 flotyr
2070-A001	1 GA PROJU A/BOOSTER	Section 14	3-10-92 Scorleggel
2077-A001	1 GA 75 mm HE	SCETTURGE	3-14-92 Scorlegg
(02	1 CP 75 mm HE		
63	1 CA PRUJU A/BOOSTOR		
11) / 04	I EA PROTU MBGOSTER		
			:
			.,,
		-	
			
			ļ
		-	
		-	
		<u> </u>	
		-	
		.	

ATTACHMENT 13

BAG NUMBER	EXPLOSIVE WEIGHT	SERIALIZED PAIL #	EXCAVATED AT:	DISPOSITION AND DATE
1312-6001	5.5 LBS	1312-5001	PITS 1 THEY 5	70 0000/STURASS 11-7-91 (20)
- 6002	10. LBS		PITG	7 7
- 6003	9. LBS)	PIT 6	
1317-6004	5. (35	1317-5002	pire 6	10 0000/Stuesco
- 6005	C. CBS	1317 - 5002	BU CORNER	5 5
L1318-6006	5. LBS	4318-5003		10 Dems/ STURAGE
E007	S. LAS	< C \(\)	7	C
	6. LBS	<i>L</i>)		
1318_ 6001	6.560	1318-5001	SECTION 9 PIT 6	10 0000/STORAGE
1318-5002	S.0 CBS	5 5	5	s 5
1319-6001	5.0 (Br	1319-5001		TO DEMO /STURDE
(302	5.0			
(E00 3	5.0			
6004	3,5	7		
1322 - 5001	10. LB5	1322 - Sw 1	SECTION 9 PIT L	70 DEMO/STURAGE
- E002	10.			
_ (- Ew3	10.			
- 6004	יטן			
- 6005	10.	7		
- 500 C	10.	1322-5002		
- 6007	/6,	((
J - 1308	10,			
1322 - 6208	11.			
1323- 6001	10. (85	1323-5001	Pit 6	TO DEMO/STORAGE
(- 8002	10.			
- E003	10.			
- 6004	10.			
- 6005	10.	 		
	255.20 (85	I	

BAG NUMBER	EXPLOSIVE WEIGHT	SERIALIZED PAIL #	EXCAVATED AT:	DISPOSITION AND DATE
1323-E006	10. LBS	1323-5002	DITG	TU 03/10/570 EAGE
- 6007	10. LBS		CC	
-E008	10. LBS			
	7. BS		,,,	
1324-E001	10 (35	1324-5001	PITG	TO DEMOSTOR AGO
<u> </u>	10 (
E 003	10		7	
Eooy				
E005	10			
E006		1324-5002		
<u>= 607</u>	10			
E008	10			
EW9	/0			
E010	10 LBS			
1325- 6001	10.05	1325-5001	PITG	10 DONO/SPORPE
(6207	10			
E003	10			
E 004	10			
	10.		7	
1325- EOCL	10 (85	1325-5002	P176	11-21-91
- EU07				
) -6008	14,)			
1325- EOU9	31 LBS	1325-S03	PITE	10 Demo /STORAC
) <i>E</i> 010	21.5	5		S
1326-6001	10 LBS	1326-5001	PIT 6	11-22-51
<u> </u>	-(-(-			
(न्यश्र				
E204				
601	10 CBS			

SUB 326 CBS

BAG NUMBER	EXPLOSIVE WEIGHT	SERIALIZED PAIL #	EXCAVATED AT:	DISPOSITION AND DATE
	JO CBS	1330-5001 1330-5002 1330-5003 1330-5003		

		•		
BAG NUMBER	EXPLOSIVE WEIGHT	SERIALIZED PAIL #	EXCAVATED AT:	DISPOSITION AND DATE
1331- E00/	10.CBS	1331-5001	pir6	TU OSMU/STURAGE
((2002)				
<i>E0</i> 03				
E00 Y				
1331,- 6005	.,	1331-5001		
1331- 6006	1 1 .	1331-5002		
(7007				
E008				
£709				
1331 - 6010	10 CBS	1331-5002	PITC	11-27-91 Jac
1337- EOUI	13. UBS	1337-5001		12-3-91 -fe
	101			
GW 3	12			
<u> </u>	22			
1337- 605	12,185	1337-5001		12-3-91 Ju
1338-E001	10 CBS	1338-5001	PITG	12-4-91 fl
E CO2				
E003				
<u> </u>))		
6005		1338-5001		
E00L		1338-5002		
(7227		-		
(300)	-/ -			
1338 5010	/			
	10 LBS	1338 - 5002	PITC	12-4-91 fcc
1339- E001	10 CBS	1339-5001		125-91 SOC
<u> </u>	10	-		
<u> </u>	<u>/0</u>	<u> </u>		
Sub	299 CBS			

BAG NUMBER	EXPLOSIVE WEIGHT	SERIALIZED PAIL #	EXCAVATED AT:	DISPOSITION AND DATE
1340-E001	10 CAS	1340-5001	PIT 6	10 DONU/STOLAGE
5 1702	10 (35	5 5	3	5 5
1343-6001	6	1343-5001	PIT 6	TO DEMOISTURAGE
(-2102	÷.			
(203				
czwy				
1505				
(306		1343-5002	PIT 6	
CZX07	10 CBS	((, <u> </u>	
6001	7 LBS			
1344- 601	10 CBS	1344-5001	Pir 6	70 Deno/Sτοκούς 12-ω-91 fa
6302	((((72-0 41 7-
E303	111			
Edoy				
EUS		1344-5001		
EOOL		1344-5002		
<i>E</i> 007				
E008	1			
5009	10 LBS	1344-5002		
1345- 001	10 LBS	1345- 3001	Dr 6	TO DEMOSSIONER
<u></u>	(
E7:03				
(-700 4				
ET. S		5.001		
פינים ל		5002		
(- &u)	10 CBS	500).		
46-6201	10 CBS	1346-5001		12-12-01 Ja
J48-	267 68			
	1			

BAG NUMBER	EXPLOSIVE WEIGHT	SERIALIZED PAIL #	EXCAVATED AT:	DISPOSITION AND DATE
1352-6001	10 LBS	1352-501	Pr (12-18-91 for
- (EUO)	8 /			()
	*			1
(700 4	Special Control of the Control of th			
1 6705	#	5001		
1352 - Elol	*	Jeo)		
<u> </u>	(4)			
-508	10 (BS	5002		
1353 - Evol	10	1353- 5001	PIT 6	70 Demo / STURBET
(002	45			(2-19-91 fee
(10 3	10			
004	8 (B)		- 	
AS OF SUB 5	116 CB1 92 2	1544.5 85	2017/e	o suc
2009-6201	10.0(B)	2009-5001	PITZ	TO Demo/STURBUL-
(2			7776	1-9-92 fec
3	13/4			
4	10 mg/ 10			
5	8.	2009-5001		
		2009-5002		
7	i i	50.0		
i			-/	
1 9	*/0.0(B)			
10/0	12.5 (85	2009-5002	pric	
2010-6001		20/0 - 500/	71, 6	TO Demo/STORAGE
(6002	40 (8)	C - 500).		1-10-92 for
E003	46.5 (BS	1 2003		- (- ((
(704	50. (B)	3004		
			- /	<u> </u>
SUB	289.00	> 407 GRO	SS to mc F	in one

BAG NUMBER	EXPLOSIVE WEIGHT	SERIALIZED PAIL #	EXCAVATED AT:	DISPOSITION <u>AND</u> <u>DATE</u>
2014-6001	10 (85	2014-5001	PIT (10 Demo/sturacé
$-\int \int 2$		((
3	- 1 197 · 1			
4		J		
3		2014-2001		
(
/7	***\			
ŝ	iqu.			
9				
T C0/0	10 CBS	2007		
E011	22,(BS	\$203		
/ 12	10 (85			
/3				
14		J		
15	4:	540.3		
/6	24	500 4		
/1	- 4			
/1				
19				
t 20		5004		
21		5005		
- 12				
23				
24				
25	1.	Soos		
عد ا		5006		
07)		
2014 - EC28	10 (BS	Dar4-5006		
E029	to CBS	5 5006		
	302 (B) Fel	2014		

2	BAG NUMBER	EXPLOSIVE WEIGHT	SERIALIZED PAIL #	EXCAVATED AT:	DISPOSITION AND DATE
15 Soo 3 Soo 4 Soo 9 Soo 9	NUMBER 2015- 600/ 3 4 3 4 5 6 7 8 9 010 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28	WEIGHT ** ** ** ** ** ** ** ** **	2015- S001 S001 S002 S003 S004 S005 S006	AT:	AND DATE / // S- 92 Jec_ to Demo/s tonnes

S removation

BAG	EXPLOSIVE WEIGHT	SERIALIZED PAIL #	EXCAVATED AT:	DISPOSITION AND DATE
2015-6031	Man CBS	2015-5007	PIT 6	to Dence /s Tolk of
32	4	007		
33		\$008		
34				
35				
36		5008		
37	18 CES	5004		
34	34'UBS	\$009	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
39	By CBS	2010	ر در المحادث ا المحادث المحادث المحاد المحادث المحادث المحاد	
40	# ICBS	5011		
10 41	CBS	2015-5012		Z T
SUB-TOPL	467 cos		N 1-15-9	2 december 1
2017-6001	LBS	2017-5001	PIT 6	1-17-92 Jec 10 0000/5 TORAGE
02				
03				
04				
05	CBS	500/		
06	SE CBS	5002	1	
07	Se Ces			
08	10 CBS	5002		
09	SA · CBS	5003		
A Section				
2021-6001	(BS	2021-5001	PIT 6	1.21.5
02				
03				
04	J			
05	(B)		-	
18 18 18 18 18 18 18 18 18 18 18 18 18 1				The state of the s

.उ५व ८८४

BAG NUMBER	EXPLOSIVE WEIGHT	SERIALIZED PAIL #	EXCAVATED AT:	DUSPOSITION AND DATE
2021-6001	CBS	2021-5002	PIT 6	TO DE SISTEMA
07				
01				
09				
/0		5002		
		5003	5	
12	CBS			
/3	LBS			
14	DE CBS	5003		
		5009		
	9 2'	5005		
	20	5006		
		5007	1.00	
Control of the second of the s			# 9 M	
2022-6001	MONCES	2022-500/	タノナし	10 0 5 10 5 10 10 10 10 10 10 10 10 10 10 10 10 10
_ 62				
63				
04				
05		8001	7.00	
		5007		
67				
08	G (4)			\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \
09				
	-			
0/0		5002		
010		5002 5003		
		5002 5003		
23 CARREL 11		5002 5003		
/1				
11 12 13		5002 5003 5003		

BAG NUMBER		EXPLOSIVE WEIGHT	SERIALIZED PAIL #	EXCAVATED AT:	DISPOSITION AND DATE
200	22-6-016	10 (85	2002 - 500y	PIT 6	to DEMO/STORAGE
	18	ÿ /			
-	19				
	20		Y00 G		
	ر ح		SCNIS		
	22				
	23				
	24	(/			
	25	10 (85	5005		
	26	20	5006		
	27	20	S		
	28	20	5006		
	29	15	.5007		
	30	20	1		
	E031	40	5000		
202	13 - 6701	20 (35	2023-5001	Pit 6	1-23-92 fcc to Demo/STURAGE
	62	*	(* (18 Dem 6/ 3/ Vicinit
	03	à.	5001		
	04		5002		
	C2		<u> </u>		
	06	.:	5000		
	07		5003		
	GY		5		
	09	20 (8)	5:003		
	E010	2 4 (BS	\$ 004		

BAG NUMBER	EXPLOSIVE WEIGHT	SERIALIZED PAIL #	EXCAVATED AT:	DISPOSITION AND DATE
2024-6001	20 (35	2024 2001	PIT 6	1-24-52 JCL +0 DEMO/STORAGE
	*	() OF		
03	*	-2		
04	27	c2		
05		C-2-		
06		62		
	#5	0.3		
(c) ¹	r	03		
09		C3		
0/0		C.Y		
2024-011		64		
2027- (201)	Du (BS	2027-8001		1-27-92 - See To promo/ source
02	*.			
03		01		. /
cy	3	500.2		. :
(1)	•	102		
06	*	_\ ०३		
67	<u> </u>	_\ _\$00,3		
08	30 (BS	. 03		
05	15 (BS			7
2628-6001	20 CBS	2028-5001	DIT 6	1-29-92- Sec-
(.2				
3	\$.	5001		
1 4	<u> </u>	Sco. 2.		
5	31			
6	Ş.	5007		
0/7	*	5003		
1	*			
7 9				

BAG NUMBER	EXPLOSIVE WEIGHT	SERIALIZED PAIL #	EXCAVATED AT:	DISPOSITION AND DATE
2028-6010	DOCBS	2028.5004	PM 6	1-28-92 Jec to DEMO/STURM
	<u> </u>)
2029-5001	20 (BS	2029-5001	DIT 6	1-29 92 SCC TO DEMO/STORAL
02				
		5001		
04	1	5.02		
05		5		
06	` \	Sou 2		
67		500 3		
69				
09		500 3		
10		500 c		
		5		
12		500 0		
2030-6001	20 (B)	2430-5001	PITG	1-30-52 Secrety,
62		01		
		01		
64		وي م		
- 70		ره		
96		02		
01		03		
		03		
09	20 CBS	03		
2035- 6001	20 085	2035-2001	PIT 6	J-4-92 Scenly
(02		01		
03		0)		
04	£:			
	*	02		
66	25 CBJ 600 CBS	02		
	600 00			

BAG NUMBER	EXPLOSIVE WEIGHT	SERIALIZED PAIL #	EXCAVATED AT:	DISPOSITION AND DATE
2035-6007	ON CBS	2035-5003	Pit 6	TO Dems/Stude
08	*	03		
09	念	03		
	75 J	04		
) 6011	Jo CBS	5004		
2036- 6001	20 CBS	2036. Soo1	PIT 6	to Other Stands
62	<u>e</u>			
	/	01		
04		02		
05	<u> </u>	62		
06	3	02		
07	Š.	\ ಚ		
09	χ	03		
09		03		
010	+1/	04		
011	20 BS	04		
012	#6 CBS	04		
2037-6001	20 CBS	2037-5001	Pit 6	2-6-92 delotage
62	*			
	X	01		
04	6	0.2	7	
05	#	0.2		
06	*	0.2		
07	*	0.3		
08	*	03		
09	*	0.3		
0/0	*	. 04		
	*	04		
11	*/	091		
/ · · · · · · · · · · · · · · · · · · ·	576 US	ध		
•	~			

BAG EXPLOSIVE WEIGHT		SERIALIZED PAIL #	EXCAVATED AT:	DISPOSITION AND DATE
2037 - E-013 14 15 16 17 18 2038 - E-001 03 04 05 06 67 68 09 10 11 12 13 14 15 16 17 18 2042 - E001			AT:	
62		0)		
08		0/		
	20 CBS			
ſ	l i		(180)	+ 80(8)

480 + 80(B)

BAG NUMBER	EXPLOSIVE WEIGHT	SERIALIZED PAIL #	EXCAVATED AT:	DISPOSITION AND DATE
2042-6005	20 CBS	2042-5002	Pot 6	70 Domo/STORAGE
6 06		62		
07		03		
07		03		
	7	l 		
09	20 CBS	03	pot (2-12-92 Jeerly
2043- 6001	20 (85_	2043-5001	700	TO DEM STORAGE
62		01		
03		01		
04		02		
05		0.2		
06		02		
67		03		
No.	1	63		
		03	\ <u> </u>	
09	-	-		
/0	·	of	·	
		04	.	_
	20 CBS	04		3-13-12 SCOU
2044-6001	20 CBS	2044- 5001	Post 6	pe and stone
02		01		
03		01		
04		ره	1 /	
05		02	1 1	
OC		02		
	- 	03		
07	-	03	-	
01	-	_	-	
09		03	-	-
10	-	04	- 	_
) of	-	
/	20 CBS	04	t	' /
4	TYU (B)			

BAG NUMBER	EXPLOSIVE WEIGHT	SERIALIZED PAIL #	EXCAVATED AT:	DISPOSITION AND DATE
2045-6001	20 CBS	2045-5001	PITE	11 Dams / States
02				
		01		
04		02		
05		02		
06		02		
07		03		
01		03		
09		03		
		04	n.	
		oy		
		OY		
13		05		
14		05		
15		05		:
/16		66		
		66		
18		00		
2049-6001	20 CBS	2049-5001	pol 6	2-11-12 States
02				10 pms/street
03		0/		
04		62	l <u> </u>	
OS		02		
OÇ.		02	- - 1	
07		03		
09		03		
09		0.3		
10		84		
11/12		04		
12	600 CBS	/ 04		•
	800 C 61			

<u> </u>	BAG UMBER	EXPLOSIVE WEIGHT	SERIALIZED PAIL #	EXCAVATED AT:	DISPOSITION AND DATE
2050	१-६४० /	Qu CBS	2050-5001	Pro 6	7-19-92 Scores
_	02		01		
	03		0/	_	
	04		02		
	05		١٥٦		
	06		02		
	07		03		
	A		03		
	09		03		
	/0		04		
	//		04		
	12		05		
	13		1 05		
	14		05		
205	-60 15	20 LBS	05		
	- 600/	20 (BS	2057-5001	PFT 6	2-20-92 gcodagy
	ری				TO and Storey
	03		01		
	04		02		
	05		02		
	06		02		
	07		03		
	08		03		
	09		03		
	/0		04		
	//		04		
	12	20185	04		
			/		
	075	5U3 (A			

540 CBI

BAG NUMBER	EXPLOSIVE WEIGHT	SERIALIZED PAIL #	EXCAVATED AT:	DISPOSITION AND DATE
2052- 6001	20 CBS	2052-5001	PITG	2-21-92 Joenty 16
1 02		(01		
03		01		
OY		02		
US		02		
06		02		
07		03)
2052 08	20 CBS	03	1	
2055-6001	20 CBS	2055-5001	Pit 6	2-24-92 Jary
1 02		100		
		01		
04		02		
os		02		
06		02		
07		03		
OY		03		
09		703		
/0		04		
/ //		04		
2055-6012	20 CBS	OY		lee e
2055-E012 2056-E001	20 LB	2056-5001	Pit 6	2-25-92 dala Ma
		01		
03		0/		
04		02		
01		02		
06		02		
7		03		
01		a		
09		03		

BAG NUMBE		EXPLOSIVE WEIGHT	SERIAL <u>PAIL</u>		EXCAVATED AT:	DISPOSITION AND DATE
2056-	G010	20 CBS	2056-	5004	PITC	2-galgin
(//			04		po Demo / Storing
	12			04		1011
2057-	E001	20 (85	2057.	5001	PITC	70 Demo/s runner
	02			0/		
	03			0/		
	04			02		
	05			02		
	06			02		
	07			03		
	01	\		03		
	09	\		<i>U3</i>		
	10			04		
				04		
	12			04	, , , , , , , , , , , , , , , , , , ,	As look
2058-	E001	20 (BS	2058-	8-001	PTT 6	to Demo/Sturier
	02			01		
	03			0/		
	04			02		
	05			02		
	06			02		
	07			03		
	OP			03		
	09			<i>U</i> 3		
	10			04		
	//			04		
	12	20CBS		04		

540 CBS

BAG EXPLOSIVE WEIGHT		SERIALIZED PAIL #	EXCAVATED AT:	DISPOSITION AND DATE
2058- 5013	20 (85	2058-5005	PIT 6	TO Demo/STORAGE
14		/ 05		
15		05		
/(06		
17		20		
18	20 CBS	06		
19	826 (BS	07		
20	96 CBS	08		
2063-0001	20 (BS	2063-5001	Rit (3-3-92 Jeorle Jol
0.1		(01		
<u>C3</u>		01		
04		62-		
01		02.		
06		02		
07		03		!
O ś		. 03		
		03		
10	1	04		
		04		
1.2		04		
		01		
		1 05		
		06		
				<u> </u>
2063 5018	20 (B)	66		/
	I	I i	İ	I

480 + 426 +96 = 1402 (B)

BAG NUMBER	EXPLOSIVE WEIGHT	SERIALIZED PAIL #	EXCAVATED AT:	DISPOSITION AND DATE
NUMBER 2.06 4- 600 1 03 04 05 07 07 07 09 11 12 13 14		PAIL # 2064-\$001 01 02 02 03 03 04 05 05 05		
17 .2064-60 18 2065-60 1 02 03 04 05 06 07 08 10 11 2065-6012	20 (B) 20 (B)	61 01 02 02 02 03 03 03 04	P, T 6	3-5-92 16.1076

BAG NUMBER	EXPLOSIVE WEIGHT	SERIALIZED PAIL #	EXCAVATED AT:	DISPOSITION AND DATE
2065-6013	20 CBS	2065- 5005	PIT 6	To Cam/Stone
14		05		
		05		
/6		06		
) 17		06		
2065-6011	20 CBS) 66		
2065-E011 2066-E001	20 CBS	2066-5001	Prs 6	7 Das/ Strap
02_		100		
03		01		
04		02		
or		02		
. 06		02	:	
07		03	•	
or		03	:	
09		03		
10		04		
//		04	***************************************	
12-		04		
13		05	**************************************	
14		as)
15		05		
16		/ 06		
17		06		
2066-6018	20 (8)	2066-5006		1
()		07		
		01		
21	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	67		/
3)-		OF		,
23		vi vi		
1 24	100C	es		

			4	
BAG NUMBER	EXPLOSIVE WEIGHT	SERIALIZED PAIL #	EXCAVATED AT:	DISPOSITION AND DATE
2070-6001	20 (85	2070-5001	PIT 6	10 Demo/String
02		C 01		
03		01		
04		02		
05		02		· .
06		02		
07		03		
० १		03		
		03		
/3		OY		
		04		
/ 12		/ 04		
13		/ US		* *
17		05		
2070-5015	Qu (BS	2070-5005		
2071- 62101	20 CBS	2070-5005	Pit 6	7-1492 Staberget
02		01		
03		0/		
04		02		
<u> </u>				
00		02		
2071-60 07	Du CBS	2071-5003		<u>/·</u>
2077- 2001	18 (BS	2077-5001	Pix 6	3-17-52 tenteggil
2078 - EOI	20135	2078-5001	PIT 8	3-19-72 Scaligger
62		01		
03		01		
04		02		
05		02		
) 06		02		
	•			

BAG NUMBER	EXPLOSIVE WEIGHT	SERIALIZED PAIL #	EXCAVATED AT:	DISPOSITION AND DATE
2078-6007 08 09 10 11 12 13 14 15 16 2078-6018		2078-5003 03 04 04 04 05 05 06 06 2078-50 06		3-17-92 Jenty
2079 - CX1.	20 (35 20 5 31	2079-Suo1	PIT 8	3-19-92 Hatizzol
2080- (200) 2080-(2002	90 CBS	2080-5001 2080-5002	PIT Y	3-60-92 frentegges to llemo stress
	12,360,5	LBS TOTAL 14	= RESIÒU	
	10.			Not see .



EOD TECHNOLOGY, INC. EXPLOSIVE STORAGE LOG FOR SITE 4

SERIALIZED PAIL #	EXPLOSIVE WEIGHT	BAG <u>NUMBER</u>	EXCAVATED AT:	DISPOSITION AND DATE
1312-5001	5.5185	1312-6001	PITS 1-THEU 5	11-7-91 (C)
-	/o. O (85	1312-E002	PIT 6	~
7	9.0 LBS	1312-6003	PIT 6) and
1317-5002	5.0 (BS	1317- 6004	PIT G	11-12-91 (ce)
	6.0 (85	1317 = E005	DIL COENEY	S
L1318-5003	5.0CBS	1318 - 6006	PITG	10 Desas/Storase
	5.0 CBS	1318-6007	7	1 2
	6.0 65	1318- 6008	<u> </u>	
1318-5001	6.5 (35	L1318 - E001	PIT 6	TO DESTO/STOCKE
,	5,048	L1318- E002	S	5 5
1319-5001	5.0 (85	1319-6001		70 Dems / from a-
	5.0 (<u> (6302</u>		
	50	5003		
	3.5	J 6304		
1322-5001	10, LBS	1322- 5001	SECTION 19 PIT L	TU DEMOS STURBLE
-	10,	E002		
		€003		
	10.	(=00×		
	10.	E005		
1322-5002	jυ.	E006		
	10.	E007		
		(5003)
	11. LBS	1322 2009	7	***
1323-5001	10. LBS	1323 - E001	PITG	70 Demo/STORAGE
(10.	1 - E002		
	10.	- 6003		
<u> </u>		- GOVY		
		- 6005		
Į.	1			

7722.5

EOD TECHNOLOGY, INC. EXPLOSIVE STORAGE LOG FOR SITE 4

SERIALIZED PAIL #	EXPLOSIVE WEIGHT	BAG NUMBER	EXCAVATED AT:	DISPOSITION AND DATE
1323-5002	10. LBS	1323- 6006	PIT 6	TU DEMOSTURACE
	10.65	(E007		
	10. CBS	COO 8		
	7. CBS	1 6009	7	
1324-5001	10 LBS	1324-E001	pr 6	70 0000/STORAGE
	10 LBS	(- E002		
	10 LBS	- E003		
	10 UBS	- E00 Y		
	10 (85	J -E005		
1324-5002	10 65	1324 - EUG6		
	10 LBS			
	10 LBS	_\\\		
		Ew9		
	10 LBS	1 6010	J	J. /
1325-5001	10 CBS	1325 - E001	PITE	10 DCM6/STORAL.
(Cappe	10 LBS	(EZW2		
	10 05	(EX13		
	10 08	Early		
	10 185			
1325-5002	10 USS	1325- 6006		
	13 05	E007		
)	14 USS	<u> </u>		
1325-5003	31 LBS	1325- 6009		
5 5	21 UBS	S EUIO		
1326-5001	10 CBS	1326 - 6001	PITC	70 DGMO/STSARGE
		(2002		
		<i>E</i> 7003		
J		COOV		
1326- 801	70 (85	1324 EOUS	2116	

326 08

EOD TECHNOLOGY, INC. EXPLOSIVE STORAGE LOG FOR SITE 4

SERIALIZED PAIL #	EXPLOSIVE WEIGHT	BAG NUMBER	EXCAVATED AT:	DISPOSITION AND DATE
1326-5002	10 685	1326-6006	DIT 6	11-22-41 fa
	10 (85			C
1	<u>/0 (BS</u>	E008		
	10 (85	E00 9		
1326-5002	10 CBS	6010	PITL	
1329-5001	10 CB5	1329- 5001	PT6	11-25-91 fec
	10 (85	E602		
	/0 LBS	E003		
	10 (B)	Cooy		
1329-5001	1 9 LB	E005		ý -:
1329-5002	11 LBS	- COO(
	10 cas	cou?		
	_/O USS	E008		
	17 005	<u>-</u> 009	,	\$1. \$2.
1329-5002	14 CBS	1329- EUS	Pira	1
/330-500/	10 LBS	1330-5001		11-26-91 for
-	/0	_ (&		
	/0	\ EZU3		1
	/0) E004		
/330-500/	/0	1330 - 6005		
1330-5002	/0	1330 - 5006		
-		(6007		
	/0			
	_/0	(5009		
1330-5002	/٥	1330-6010		
330-2003		1330-6011		
1	/0	(5012		
J J	/0	6013		
1330 - 5003	10 LB5	1334 - 6015		11-26-91 Jec

312 035

EOD TECHNOLOGY, INC. EXPLOSIVE STORAGE LOG FOR SITE 4

and the second

SERIALIZED PAIL #	EXPLOSIVE WEIGHT	BAG <u>NUMBER</u>	EXCAVATED AT:	DISPOSITION AND DATE
1331-5001	10 (85	1331-6001	PIT 6	11-27-91 for
		(5002	\mathcal{L}	
		<u>-</u> 003		
		े हरळ५		
1331-5001		1331- 5005		
1331-5003		1331- Eugl		
		(6007		
		E008		
		J E209		
1331-5002	10 CBS	1331- 500	PIT 6	11-27-91 Jec
1337-5001	13 USS	1337-6001		12-8-98 Je
	10 CBS			
	12 435	<u> </u>		
1222 5	32 CBS	J 6004		17-3-91fa
/337-500/	12 (185	1337 005		1233000
1338-5001	10 685	1338 - EDU/	PITC	12-4-91 fcc
(Soo/		(Etv)		
500/	 	<u> 6003</u>		
<u></u>	-			
5001	l -1 '-	5005		
1338 - 5002				
1		<u> </u>		
		<u> </u>		
1300 5.02				
1338 5002	10 LBS	1338 - 600	PITG	12-4-91 foc
139-5001	10 (B)	1339- 6001		10 Demu/Stonage
1339-5001	105	(3002		See
1301-2001	23 CBS) (2003		S for

299 (8)

EOD TECHNOLOGY, INC. EXPLOSIVE STORAGE LOG FOR SITE 4

SERIALIZED PAIL #	EXPLOSIVE WEIGHT	BAG NUMBER	EXCAVATED AT:	DISPOSITION AND DATE
1340-5001	10 (BS	1340- (=001	PIT 6	12-6-91 LCC
SS	10 LBS	٢ ڪرهي	5 5	5
1343-5001	10 (85	1843-6001	PIT 6	70 Dans STORAGE
		(-2002	((1
		E003		
		G00 Y		
1343-5001		1705		4
1343-Soul		2015		
	10 /	(707		
	7 (85	Evol	./	
1344-5001	10 LBS	1344-6001	PIT 6	10 DEMO/STORAGE
50031	<u></u>	E602		
500\$1		£003		
50041		C704		
Soot		Evos		
1344-5002		6306		
_ (Sou2		6807		9
		E008		
	10 (B)	(=309		
13-45-5001	10 (BS	1345- (5001	Pi-Te	10 Demo/STOADGE
	<u> </u>	(20)		
		(=(03		
		(-7:04		
3001		(=7:05		
5002		(=Cro 6		
5002	10 (.8)	(707		
1346-5001	10 (BS	1346-6001	PITC	TO Dems/STORAGE
				12-12-61
	262 (8)			

267 Les

EOD TECHNOLOGY, INC. EXPLOSIVE STORAGE LOG FOR SITE 4

				:
SERIALIZED PAIL #	EXPLOSIVE WEIGHT	BAG NUMBER	EXCAVATED AT:	DISPOSITION AND DATE
1352-5001	10 (85	1352- EOO/	proc	70 Dems/Stocker
		(Zv.)		
		<i>(-7</i> 203		
		EZUY		
1352- Just		(- 705		
_ (Sao)		C70(.		
		(2007		
1 5002	10 CBS	508		
1353-5001	((1353-6001	C	12-19-91 to pomo for socret
_ ((5007		((
)	10 CBS	(-Zv) 3		
5 200	8 181	£004/		
509-5001	10 CBS	2009-6001	PIT (1-9-92 fec TO POMO/STORAGE
		((2		- PONS/PIONAGE
		3		
		4		
5001		5		
5002				
		7		
		1 8		
	10 685	9		
2009-5002	12.5 (BS	010		
2010 -5001	50 (BS	2010-6701		1-10-92 JCC TU DEMO /STUDDES
5002	40 (85	(602		- C
5003	46.5 CBS	003		
5004	50 (85	004		
				1.
	299 (B)	+119= 407 (B)		
		111 - 401 (B)		

EOD TECHNOLOGY, INC. EXPLOSIVE STORAGE LOG FOR SITE 4

SERIALIZED PAIL #	EXPLOSIVE WEIGHT	BAG NUMBER	EXCAVATED AT:	DISPOSITION AND DATE
2014-5001	10 (BS	2014-6001	pir (1-14-92 SCC TO DEMO/STORAGE
		C 6002		
		(7003		
		C00 Y		
5001		C7:05		
2002		206		440
		60.7		*
		008		
.)		009		
5002	10 (85	0/0		
5003	यम (BZ	0//		
	10 (B5	012		:
		013		-
		614		•
5003		015		
5004		0/6		
		017		(**
		618		
		(15)		
5004		020		
5005		02/		
		622		
		023		
		<u> </u>		:
500\$		025		
5006		626		
7		627		*/
		021		
5006	302 CBS	2014-029	BITG	

EOD TECHNOLOGY, INC. EXPLOSIVE STORAGE LOG FOR SITE 4

\$\lims\$\frac{1}{5}\cdot \frac{1}{5}\cdot	SE SE	RIALIZED PAIL #	EXPLOSIVE WEIGHT	BAG NUMBER	EXCAVATED AT:	DISPOSITION AND DATE
Soot S Soot S Soot	20	15-5001	10 CBS	2015- 6001	Bitte	
Soot S Soot S Soot S Soot S Soot S Soot S Soot S Soot S Soot S Soot S S S S S S S S S						10 Semoj Stratur
Soo1 S Soo2 Cool S Soo3 Cool S Soo4 Soo5 Soo5 Soo6 So				1 / -	1	
\$\sigma_{\chingle}}}}}}} \end{caligned}}}}}}}}}}\rightgraphilder \tag{\fighta_{\sigma_{\sigma_{\sigma_{\sigma_{\sigma_{\sigma_{\sigma_{\sigma_{\sigma_{\sigma_{\chingle}}}}}}} \righta_{\sigma_{\sigma_{\sigma_{\sigma_{\sigma_{\sigma_{\chingle}}}}}} \righta_{\sigma_{\sigma_{\sigma_{\sigma_{\sigma_{\chingle}}}}}}} \righta_{\sigma_{\sigma_{\sigma_{\sigma_{\sigma_{\sigma_{\chingle}}}}}}} \righta_{\sigma_{\sigma_{\sigma_{\sigma_{\sigma_{\sigma_{\sigma_{\sigma_{\sigma_{\sigma_{\sigma_{\chingle}}}}}} \righta_{\sigma_{\si\sigma_{\sigma_{\sigma_{\sigma_{\sindle\con\con\con\con\con\con\c						
\$\sigma_{\sigma} \frac{1}{2} \\ \fra		500/				
1		5002				
\$\frac{8}{5\cdot 2} \\ \frac{5\cdot 2}{5\cdot						
\$\frac{5}{5\cdot 2} \\ \frac{5}{5\cdot 2} \\						
\$002 \$003 \$003 \$13 \$14 \$15 \$2004 \$15 \$16 \$17 \$18 \$2004 \$20 \$20 \$20 \$20 \$20 \$20 \$20 \$20						
\$003 \$001 \$2 \$3 \$3 \$3 \$3 \$3 \$3 \$3		5002				*
12 13 14 15 15 15 15 15 15 16 16					3 ··.	,
3003 3004 3004 3004 3004 3005 3005 3006 3005 3006 3006 3006 3006		300,				
\$\int 3\infty\$ \$\sqrt{3\infty}\$ \$\sqrt{3\infty}\$ \$\sqrt{1\infty}\$ \$1						
\$\sigma_{\chingle}}}}}}}} \end{\limeto_{\sigma_{\sigma_{\sigma_{\sigma_{\sigma_{\sigma_{\chingle}}}}}}} \end{\limeto_{\sigma_{\sigma_{\sigma_{\sigma_{\sigma_{\sigma_{\sigma_{\chingle}}}}}}}} \end{\limeto_{\sigma_{\sigma_{\sigma_{\sigma_{\sigma_{\chingle}}}}}}} \end{\limeto_{\sigma_{\sigma_{\sigma_{\sigma_{\sigma_{\chingle}}}}}}}} \end{\limeto_{\sigma_{\sigma_{\sigma_{\sigma_{\sigma_{\sigma_{\sigma_{\chingle}}}}}}}}} \end{\limeto_{\sigma_{\sigma_{\sigma_{\sigma_{\sigma_{\sigma_{\sigma_{\chingle}}}}}}}} \end{\limeto_{\sigma_{\sigma_{\sigma_{\sigma_{\sigma_{\sigma_{\sigma_{\sigma_{\sigma_{\sigma_{\sigma_{\sigma_{\sigma_{\sigma_{\sigma_{\sigma_{\chingle}}}}}}} \end{\limeto_{\sigma_{\sigma_{\sigma_{\sigma_{\sigma_{\sigma_{\sigma_{\sigma_{\chingle}}}}}}}} \end{\limeto_{\sigma_{\chingle}}}}}}} \end{\limeto_{\sigma_{\sigma_{\sigma_{\sigma_{\sigma_{\sigma_{\sigma_{\sigma_{\sigma_{\sigma_{\sigma_{\sigma_{\sigma_{\sigma_{\sigma_{\sigma_{\chingle}}}}}} \limeto_{\sigma_{\sigma_{\sigma_{\sigma_{\sigm	1					
\$00\forall 1(5003				
17	1					<u>~</u>
11		300/				
\$\lims\{\frac{14}{5\infty}\} \\ \frac{5\infty}{5\infty}\} \\ \frac{20}{5\infty}\} \\ \frac{20}{5\infty						
\$\frac{3004}{5005}				1		
Sous 21 22 3005 Sous 25 21 22 32 32 32 32 32 32 32 32		80016				
22 23 2005 5006 25 21	-					
3005 Sou6 25 27		2003				
Sou(25) 27) 27) 27) 27) 27) 27) 27)						
Sou6 25 25 27 27 27 27 27 27 27 27 27 27 27 27 27		1				
21			<i> </i>	7		
22		3006	/			
5006 10 CBS 2015- E028 PIT 6	-	/			i	
10 CB 2015 - E028 PT 6				27		//
· · · · · · · · · · · · · · · · · · ·		2001	10 CBS	2015 - 5028	PT 6	

EOD TECHNOLOGY, INC. EXPLOSIVE STORAGE LOG FOR SITE 4

SERIALIZED	EXPLOSIVE	BAG	EXCAVATED	DIŠPOSITION
PAIL #	WEIGHT	NUMBER	AT:	AND DATE
0015-5007	10 CBS	2015- 5029	PIT C	1-15-92 for to Semo/storal
		30		
		31		
5007		32		
5008		33		- A.
		34		
		35		
5008		36		
5004	10 (85	37		
5009	34 LBS	38		
2010	27 CBS	39		
2011	9 (85	040		
15-5012	27 (85		n- 1	
2017-5001		2015-6041	PITC	1-17-92 dec
	10 (BS	2017- 6001		TO Demo/STURAGE
		02.	/	
		<u>c3</u>		
	.)	04		
5001	10 (BS	05		
5002	15 (85	06		
	10	07		
Son 2	70	<u> 01</u>		
<u> 5003</u>	37 LBS	2017-09		
2021 5		4		
2021-2001	10 (BS	2021-6001	PITG	1-21-92 for to Domo / STOR.
		()		
		(3	· \	
	<u> </u>	04		÷-
	10 (BS	1) OS		
·	362 CBS			:

EOD TECHNOLOGY, INC. EXPLOSIVE STORAGE LOG FOR SITE 4

SERIALIZED PAIL #	EXPLOSIVE WEIGHT	BAG NUMBER	EXCAVATED AT:	DISPOSITION AND DATE
2021-5002	10 CBS	2021-6006	PITG	1º21-92 JCE TO DEMOISTURATE
		67		
		65		
		09		
5002		/0		
5003	10 CBS	//		**************************************
	11	12		
	//	/ 3		***
5003	12	14		
5004	21	15		
5005	22	16		- 1
	26		<i></i> _	
5007	9	2021-5018		
0.000			· · · · · · · · · · · · · · · · · · ·	1-22-92 dec
2022-5001	10 (BS	2022 - 5001	PIT 6	TO DEMOSTURAGE
		6.2		
		03		
	 	<u> </u>		
		05		
: 5000		06		
				
		- ०४		
		09		
5003		/0		
1 2003		/1		
		12		
				
5003		14		
	3220	/- /-		- -

EOD TECHNOLOGY, INC. EXPLOSIVE STORAGE LOG FOR SITE 4

SERIALIZED PAIL #	EXPLOSIVE WEIGHT	BAG NUMBER	EXCAVATED AT:	DISPOSITION AND DATE
2022-5004	10 CBS	2022 - 6016	PITG	1-22-92 fce to DEMOSTORE
		(1)		
		18		
		19		
2004		20		
2005		21		
		22.		
		.23		
		24		
2005	10 CBS	25		
5000	20	26		
	20	27		
\$00 °	20	28		
5007	15	29		
	20	30		
5007	40	1 31		
				÷
2023-5001	20 (BS	2023- (-00/	PIT 6	1-27-52 yee to somo /5 rocose
-		62		
5001		63		
5002		69		
		65		
5002		- 66		
2003		67		
5 5		<u> </u>		
5003	20 (85	69		
7 5004	24 CBS	/ E010		
ı	1600.00	. 1		

439 00

EOD TECHNOLOGY, INC. EXPLOSIVE STORAGE LOG FOR SITE 4

SERIALIZED PAIL #	EXPLOSIVE WEIGHT	BAG NUMBER	EXCAVATED AT:	DISPOSITION AND DATE
2024-500/	20 (BS	2024- (-00)	PT 6	1-24-92 for TO DEMOBROADES
5				
01		03		
5002		6204		
()		02		
02		06		
<u>Soo 3</u>		07		
		CX		
63		09		
		10		
_/ 04		FO11		
2027-500/	20 (BS	2027 - (-701	PIT 6	10 Demolstope
0/		52		70 Demo/3/0-20
		03		•
5002		04		
02		05		
02		06		
\$∞3		07		
03	20 (B)	08		
	15 (85	07		
2028-3001	20 685	2028-6001	pr 6	1-21/12 000
		((2	<i>F1 G</i>	TO boss/stokage
		3		1
5002		1 4		
1 (2		15		*
12		1	- / -	

EOD TECHNOLOGY, INC. EXPLOSIVE STORAGE LOG FOR SITE 4

SERIALIZED PAIL #	EXPLOSIVE WEIGHT	BAG NUMBER	EXCAVATED AT:	DISPOSITION AND DATE
2028-5003	20 LBS	2028-6007	Pri 6	1-28-92 JCC
		C (8		
) 3				
5004		10		V V
	<u> </u>		\	1
Sov 4		12		
2029-5001	20 (BS	2029- (=001	PFT 6	1-24-92 JCC TO DOMO/STOKE
		7 / 3		
2		4		
			. (
2		6		
3		7		
3		8		
1 3				
1 4	\	9		
) \ \ \ \ \		/0		
4		//		
2030-5001	2/05	12		1-30-92 Selator
	20 (85	2030- 600/	PITE	TO Demo /STORPET
6)		62		
•/		63		
62		64		
02		05		
02		0(
03		67		
0.3		69		
03				
				
'		ı		

EOD TECHNOLOGY, INC. EXPLOSIVE STORAGE LOG FOR SITE 4

				4
SERIALIZED PAIL #	EXPLOSIVE WEIGHT	BAG <u>NUMBER</u>	EXCAVATED AT:	DISPOSITION AND DATE
2035-5001	20 CBS	2035- 6001	Pit (2-4-92 Contegy
01		02		
6/		63		
02		04		
02		05		4.1
02		20	÷	
03		67		
O3		01		
03		09		
		6/0		
	20 (85	011		
2036-5001	20 45	2036-6001	pit 6	70 Demo/STURPE
01		(02		
01		03		
02		04		# W + + + + + + + + + + + + + + + + + +
62		05		4.
02		06		No.
03		07		
03		08		
03		09		
<u> </u>		/		
04	20CBS			
04	16 CBS	1 12		
2037-5001	20185	2037-6001	PIT 6	TO J-6-92 Jesty
01		02		
01		OB		
02		0.24		•
		03		
02	1	0 16		
	576 LBS			

NUMBER SERIALIZED SECAVATED DISPOSITION	mi				
03 03 04 09 09 09 09 09 09 09 09 09 09 09 09 09	NUMBER		PAI L #		AND DATE
03 03 04 09 09 09 09 09 09 09 09 09 09 09 09 09	2037-5003	20 CBS	2037-6207	Pi+ 6	2-6-52 Scales
0 0 0 0 0 0 0 0 0 0	03				
04			7		
64 05 05 05 06 06 06 06 07 07 07 08 09 09 09 09 09 09 09 09 09 09 09 09 09			/0		
64 05 19 19 10 10 10 10 10 10 10 10 10 10 10 10 10	04		11		
05	64		12		
05 06 06 06 07 01 01 02 02 02 02 02 03 03 07 03 03 07 06 07 07 09 07 09 07 07 07 07 07 07 07 07 07 07 07 07 07	05		13		
06 06 01 01 02 02 02 02 02 03 07 03 03 07 03 07 09 09 09 09 09 09 09 09 09 09 09 09 09	05		14		
	05	\ \	15		
01 21 2038-8001 20183 2038-8001 21 21 21 21 21 21 21 21 21 21 21 21 21	06		16		
01	66		17	1,	·:
01 01 02 02 02 02 03 07 02 06 03 07 07 07 07 09 09 11 19 19 17 19 19 19 11 11 11 11 11 11 11 11 11 11			18		
01 01 03 02 09 07 02 06 03 07 03 07 08 09 09 11 11 19 19 12 07 13 05 16 06 16 06 17	38-8001	ou CBS	2038- 001	Pirc	2-7-57 Scenter
02 07 05 07 07 06 07 07 07 07 07 07 07 07 07 07 07 07 07	01		02		
02 04 05 05 05 05 05 05 05 05 05 05 05 05 05	01		03		
02 03 07 07 07 09 09 11 11 11 11 12 05 13 05 16 17 18 19 19 10 11 11 11 11 11 11 11 11 11	02		04		
03 03 07 03 07 09 09 10 11 12 13 13 15 16 16 17 18 19 19 10 11 11 12 13 14 15 16 16 17 17 18 18 19 19 19 10 10 10 10 10 10 10 10 10 10	62		05		
03 03 04 04 11 12 05 05 13 05 14 06 06	02		06		
03 64 10 04 11 12 05 05 13 05 16 06 16	63		07		
64 64 11 12 05 05 13 05 15 06 16	- 03		or		
9y 12 13 15 15 16 16 16 16 16 16 16 16 16 16 16 16 16	03		0 9		
9y	64		10		
05 13 17 15 16 16 16 16 16 16 16 16 16 16 16 16 16	04				
05 14 15 16	94		12		
05 /15					÷
06 / 14	05		14		
06 / 14	05		15		
/ 06 /			16		
600 CBS	06	20 CBS		7	
		600 (8)	/8	/	·

Mic				
NUMBER	EXPLOSIVE WEIGHT	SERIALIZED -PAIL # BAC	EXCAVATED AT:	DISPOSITION AND DATE
2042-5001	20 (85	2042- FOO!	PIT (2-12-92 Maly
01		62		70 ams/striv
		03		
02		OY		
02		or		
02		06		
03		07		
03		01		4
03	20 (85	09		
2043-5001	20 CBS	2043-6001	PITC	2-18-52 faculty
(01		(02	77,6	10 Dime/street
0)				
		03		
02	l	04		
OZ		05		
03		06		
		07		
63	-	01		(E.)
03		09		\$
04		/0		
04	- (00	//		Total Park
7 64	20 CBS	1 2		
2044-3001	20 CBS	2044-6001	PITG	2-14-12 Jay
01		03		
62	-	OY		
02		05		:
02	2665			
				v.
	1			

PAIC PAR NUMBER	EXPLOSIVE WEIGHT	SERIALIZED PATL # BAG-	EXCAVATED AT:	DISPOSITION AND DATE
2044-2003	20 CBS	2044-6007	P1 6	10 pms / street
		01		
03		09		E#
04		/0		
04				
04	20(8)	12		
2045-5001	20 LBS	2045-€001	9156	2-14-92 gcolog
01		02		
01		63		
		04		
02_		05		
02		06		
03		07		
03		08		
03		09		
04		10		3 *
04		//		8
oy		B		**. **. **. ·
05		13		
05		14		
05		15		e en en en en en en en en en en en en en
		16		
	20 CBS	18		
2049- 5001	20 LBS	2049-6001	PIT 6	2-18-92-90-976
		(02		-9
0/		03		
02		04		
) 02		05		
02	(A)	06		

BAG NUMBER	EXPLOSIVE WEIGHT	SERIALIZED	EXCAVATED AT:	DISPOSITION AND DATE
2049- Sus 3	20 LBS	2044-6007	Dot 6	2-11-42 Keleps
09		01		To profession
03		09		
04		10		
04		11		
04	20180) n		
2050-5001	20 (BS	2050-6001	PMG	2-19-92 Lookyn
01		02		To promy floring.
01		03		
		04		
02		05		
02		06		**
03		07		
03		CY		
03		09		2 12
04		10		
04				
04		12		
01		13		
05	/			
	20 LBS	15		
20/51-5001	20 CBS	2051-6001	Pri 6	10 Dans/ source
61		02_		
01		03		
02		04		
02		05		
02		06		
03		07		1
03		09		
/ 03	LOO CBS	09		
	, AT 10 C.D.			

NUMBER WEIGHT PATE # AT: AND I	- Vig
04	
2052-Seo1 20CBS 2052-COO) PFT 6 2.21-92 80 01 02 03 05 02 05 05 03 07 07 03 07 07 03 07 07 03 07 07 03 07 07 03 07 07 04 07 07 05 07 07 07 07 07 08 07 07 07 07 07 07 07 07 07 07 07 07 07	
2052-5001 20CB) 2053-600/ P/1 G 10 pamo /2 01 02 03 03 03 03 03 03 03 03 03	
01 02 02 03 05 05 06 07 03 07 03 00 00 00 00 00 00 00 00 00	
02 02 03 03 03 03 00 01 00 01 02 03 00 01 01 02 01 02 03 04 05 05 07 01 01 02 04 05 05 06 07 06 07 07 07 07 07 07 07 07 07 07	
02 02 03 03 03 01 2055-5001 2055-6001 2055-6001 2055-6001 2055-6001	
02 03 03 00 00 00 00 00 00 00 00	
2055- Soo1 2065 2055-COO1 Pir 6 2-24-52-05	
2055-5001 20 CBS 2055-COO1 Pit 6 2-24-52-06	
2055-5001 20 CBS 2055-6001 Pit 6 2-24-52 de	
2035 3061 2055 - 2057 PAT 6 to print 186	
01 (02	25°
02 03 .	
02 04	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
02 05	3
02 06	3 No. 1
03 67	40 545 1 - \$
03 Or	*
. 07	
2055-2004 //	
· 5 Svo 4 L / 12 / 12	1
2056- Soul 20181 2056-1-001 PII 6 2-25-52 18	UKA6
$\begin{array}{c c} \hline & 01 \\ \hline & \end{array}$	
0)	
02	
05	
02 / 06	

PAIC BAG NUMBER	EXPLOSIVE WEIGHT	SERIALIZED PATE # BAG	EXCAVATED <u>AT:</u>	DISPOSITION AND DATE
2056-2003	20 CBS	2056- 6007	PIT 6	to Bons /stone
03		08		
03		09		1844 A. S.
04		70		
- ov				
1 04		12		
2057 - 2001	<u>20185</u>	2057-6001	PIT 6	TU DONO / 4 TO CANCE
01				
01		03		
02		<u> </u>		
02		05		de la companya de la
02		06		
<u>03</u>		07		
03		OY		•
03		09		
04				
04				
04		/ 12		
2058-5001	20 CBS	2058- (-001	PM 6	TO DEMO/STORAGE
01		03		
62		04		
02		05		
02		06		
03		07		
03		08		
63		09		A Property Control
04		/0		
04				
	LANCRI	12	/	

PAIC BAC NUMBER	EXPLOSIVE WEIGHT	SERIALIZED PATE # BAG	EXCAVATED AT:	DISPOSITION AND DATE
2057-5005	20 CBS	2051-E013	PITC	2-27-92 Hortogy
		14		
05		15		
66		16		
06)	17		
06	20 (B)	//		
	826 CBS			
07	96 CBS	20		
2063-5001	20 (BS	2063-6201	PK6	3-3-92 Herby
01_				
01		03		
02_		64		A Section of the sect
62_		ór		一个
02		06		
03	-	07		
63		01		
63		09		ž.
		/0		AF D
				ud,
. 04		12		
84				
		14		
		15		
				.4)
		17		
06		2063-6018		77
2063-E0 C	Determinent.			

				<u></u>
	11/00	00		

1402 685

NUMBER	EXPLOSIVE WEIGHT	SERIALIZED PATE # BAG	EXCAVATED AT:	DISPOSITION AND DATE
2064-5001	20 (85		PIT 6	
		02		97. 14. 18.7
01		23		
	-	04		No.
02		05		
02	· · · · · · · · · · · · · · · · · · ·	06		
03		07		
03	-	21		
03		15		†. •
04	:			
<u> </u>				
04		12		A
05	h	/3		
05	# ! !			
		15		
		16		**
06				### ** ** ** ** ** ** ** ** ** ** ** **
	20 (B)	2064-6018		
	20 (B)	2065-6001	P1-6	
- 0/		02		
- 0/		<u> </u>	 -	
02		04		
02		05		
02		06		1.1
03		07		
03		01		
03		09		
04		/ / //	 -	
2061- 50 04	20CBS	CODIRE D		

EXPLOSIVE RECOVERY LOG FOR SITE 4


PAIC BAC NUMBER	EXPLOSIVE WEIGHT	SERIALIZED PATE # BAG	EXCAVATED AT:	DISPOSITION AND DATE
2065-5005	20 (85	2065-E013	Pr (to Demoston
05		15		
06		16		
		D		
2065-10 06	20 CBS) 18		
2066-5001	20 (8)	2066-6301	PTIG	3-6-97 Jeorly
0/		02		
01.		_/ oB		**************************************
		04		
02		05		
02		06		
03		07		
03		08		
03		. 09		
		10		
04				
04		12		
		/3		
				1
05				
06		16		-
06				
2066-5006	20 (BS	2066-6018		
07		019		
07		020		
07		2/		
08		22	7	
1 38		23		
AS OF 3-64 52	(225) 6	ooles 24		<u>1 1984</u>

EXPLOSIVE RECOVERY LOG FOR SITE 4


PAIC -BAG NUMBER	EXPLOSIVE WEIGHT	SERIALIZED PAID #	EXCAVATED AT:	DISPOSITION AND DATE
2070-5001	20 CBS	2070-6-201	Pr 6	3-13-92 frailegy
01		02		
		03		
62		04		
02		05		
62		06		
03		07		
03		08		
03		09		
04		10		1
04		//		
04		12		
05		/ /3		
05		/ 14		
	20 CBS	2070-6015		20.3
2071-5001	20 CBS	2071- 6-601	PH 6	TO Deseletes
01		02		
01		03		
02		04		
02	- J	05		
02		06		
2071-5003		2071-6007		a constant
2077-5001	18 CBS	2077-6001	P/ 8	to Remo/Strap
	20 CBS	2078- EOU	2118	to Benef stand
61		02		
01		03		
02		04		
02		05		
	<u> </u>) 06		

PAIC BAG NUMBER	EXPLOSIVE WEIGHT	SERIALIZED PATT # BAG	EXCAVATED AT:	DISPOSITION AND DATE
2078-5003	20 (85	2071-1507	PM 8	to send story
03		* 8		
		79		
64				
- OY		<u> </u>		
00		2-		
05		***		
05		<u> </u>		
	j.			
06				
2071-5006	20 (85	2011		
979 - Sool	20 (85	2079- 6001	PIT 8	3-19-92 destay
(0/	20	02		. (
	31)) 03)	
	M			
	12,180.5	TOTAL WITH	Pesion	وح.
20.80-5001	90 (6)	2080-601	PH 8	3-20-92 Scalegge
2080-5002	90(8)	2080- 6-002	_ 5	5
	12,360.5	total wit	HE RESI	DUE REMOVED
	=			
			:	
				•.










- D-30' ALONG ROADWHY-SATURATED WITH ROCKS, HAS NOT BEEN DONE.
- 2 AREA Q.C EOD-T 01/14/92 (PASS) AREAS 3,4,5,6
- 3 AREA QC EODT 03/17/92 PASS AREAS 18, 25, 26,7
- SITE 10 HAS 27 AREAS 105' X 115 (APPX)
- PARKING LOT IS SITUATED IN HPPX 9 AREAS OR 30% WHICH
- PREVENTS MAGGING AND HAND DIGGING.
- OF THE REMAINING 70% OF SITE 10 3, 75 AREAS OR 22% HAVE BEEN
- QC COVERED 180 OF MACHS 3,45,76.
 - x UXO
 - 0 new



Date	Subject S/JE	Sheet No of
Chkd. ByDate		Proj. No
••		À / _>

AREA 10

CANE 3221 2019 18 17 16 15 14 13 12 11 10 9 8 7 6 5 4 3 2 1



115'110' 105' 100' 95' 90' 75' 80' 75' 70' 65' 60' 55' 50' 45' 40' 35' 30' 25' 20' 15' 10' 5' 0

PIT - 12'X 14'X 3 YIELDED MAPK 350 lbs SCRAP METAL, PARTS 4CONCRETE.

- RR TRACKS

- APPEARS THE THEE BUNGER


14 = 5'



Date	Subject SITE 10	Sheet No of
Chkd. ByDate	AREA 4	Proj. No

AREA 9

23 22 21 20 19 18 17 16 15 14 13 12 11 10 9 8 7 6 5 4 3 2 LANE



RCADWAY

00 INDICATES AREA THAT WAS MAGGED AND PLOTTED - NO DIEGING DONE

AREA


	TERNATIONAL SCHNOLOGY DREPORATION AREA 4 Date Subject	
У	_ Date Subject	Sheet No.
Chkd. By	Date	Proj. No
	HICH BACKGROUND R	EADINGS
	HIOT DIEAGAONE A	
	.1	
	HIGHEST BG.	
AREA	AREA 4.	
	1	
5		
	← 30'→	
1-1-6		
	ROADWAY	
	DUG, HIT WATER TABLE ITEM NOT FO	
	WITTER NOT FO	
		108-10-85



	NTERNATIONAL ECHNOLOGY ORPORATION	- LTF LD	
Chief B.	Date Su	bject <u>SITE 10</u> AREA 5	Sheet No G
CNKO. BY	Date	11110113	Proj. No
LANE	23 22 21 20 19 18	AREA 8 17 16 15 14 13 12 11 10 9 8 7	6 5 4 3 2 i
		86 75' 10' 66' 60' 55' 50' 45' 40' 35' ROADWAY	
	DODEN WIRE RAPPED SEWAR FIRE		
W	KNPPEDSEWNX FIFE	***	
		· · · · · · · · · · · · · · · · · · ·	
			1/4 75
Lange	and and the paper of		108-10-85



y Chkd: By.	Date Date	Subject _	SIT AREA	E 1	D				•				of_	
LANE	DITCH HREH	20 19 18 11 16	<u>A</u>	REA 7		8	7 6		:					
ROADWAY		15- 20 20 27 25-	28 30 29	25 23	18-26	76	E SE	74 2	6 28 	29		35 30 35 30 35 AV AV AV AV AV AV AV AV AV AV AV AV AV		ARE
	,	00' 95' 90' 85' 80' 7	15' 70' 65'	60' 55' 50	9'45"	40' S	s'.30' 2	5'20'	15'	10' =	٠,	' O		
		P	onDu	JAY						-				
	K AREA 6	= HAS ONLY	20 LAN	JE'S	100	ω×	(10:	5'1		1				
								• .						3



DITCH

AREA 6



By Chkd. By	Date Date	Subject <u>S/TE/()</u> 	Sheet No of Proj. No
		AREA 17 18 17 16 15 14 13 12 11 10 9 8 PARILLE	
115	100'105 100' 95'	10 85 80 15 70 65 60 55 50 45 40 3	35' 30' 25' 20' 15' 10' 5' 0

108-10-85



y——— hkd. By_	Date	Subject _	SITE	10		Sheet No Proj. No	
		-	101'->		*		
E	2019 18 /7 1	6 15 14 13	1211 109	8765	432	/ 	
					RK N.	115 110' 106' 95' 90' 85 80' 75' 65' 60' 55' 40' 35' 30' 25' 20' 8'	AKEA-
	100 95 90 85 80			40° 35′ 30° 25′ 2	o' 15' 10' 5	' 0	
		- 1	100-				



MAC_ Date Fel 92 Subject SITE 10

cd. By___ Date_____ AREA - 25 __ Sheet No.__/_ of_ Proj. No. TAE. PARK ROADWAY 26 24 23 22 21 20 19 18 17 16 15 14 13 12 11 10 9 8 7 6 - MK & GRENADE Firse Expenses # OEW - 2055 +1 AREA - 24 X=PIPELINE/SIDEWALK



	Date	AREA 26	Sheet No of Proj. No
:		energy of the second of the se	
			ROAD
113		PARKING LO	
12	6'		23 27->



EOD TECHNOLOGY, INC. FORMER RARITAN ARSENAL PROJECT

ORDNANCE ACCOUNTABILITY LOG ()

DATE	SITE	ORDNANCE RECOVERED	STORAGE LOCATION	DATE DEST.	REMARKS
10/17/91	10 AREA 3 LANE 2	PRACTICE BOMB	SITE 16	11/07/91	0EW 1290-1
10/18/91	AREA 5 LANE 1	IEA FRENCH RIFLE GRENADE	SITE 16	11/07/91	·UXO /29/-1
10/21/91	ID HREAS IANES	JEH FRETVLH RIFLE GREWADE	SIJE 16	11/07/91	UXO 1294-1
11/05/91	10	MEA EXPENDED MEZ GRENHDE EUZE	SITE IL. (BOX 14)	12/05/91	0EW 1309-1
11/05/91	AREA 18 S.W. COR.	IEA FRENCH BIFLE GRENADE	SITE 16	11/07/41	UXO 1309-1
11/07/91	10 AREA 4 LANE 15	MKZ GREWADE EVZE	517E 16. (BOX 14)	12/05/91	0EW 1311-1
11/19/91	10 AREA 4 LIANE 1	IEA EXPENDED MKZ GRENADE FL'ZE	51TE 10	12/05/91	0EW 1323-1
11/20/91	AREA 4 LANE	IEA EXPENDED MKZ GRENADE FUZE	SITE 16 (BOX 14).	12/05/91	DEW 1324-1
11/20/91	10 HREA4 CANEL	IEA EXPENDED MK 1 GRENADE FV2E	51 TE 16. (BDX 14)	12/05/91	0EU 1324-2
11/21/91	AREA 3 LANE 20	IEH FRENCH KIFLE GRENADE	SITE 16	12/05/91	UXO 10-1325-1
11/22/91	AREA 3 LANE 17	ILA EXPENUED INK 2 GUENHOE FUZE	SITE 16	12/05/91	0EW 10-1326-1
11/22/91	AREH 3 LANE 16	RIPLE WENAUL	SITE 16	12/05/91	UXD 10-1326-1
11/22/91	AREA 3 LANE 17	MKZ GLENADE PUZE	SITE 16	12/05/91	0EW 10-1326-2
11/25/91	HREA 3 LANEIL	IEH EXPENDED MK2 GRETVHOE FUZE	SITE 16	12/05/91	0EW 10-1329-1
11/26/9	ID ARGA 3 LANE 13	TBD DETERMINED TO BE A NICH OND ITEM	SITE 16	12/05/91	0EW 10-1330 - /
	"	12/05/9/		н ' '	Н

EOD TECHNOLOGY, INC. FORMER RARITAN ARSENAL PROJECT

ORDNANCE ACCOUNTABILITY LOG

1	ı	Ĥ	ti	H	
DATE	SITE	ORDNANCE RECOVERED	STORAGE LOCATION	DATE DEST.	REMARKS
11/26/91	10 AREA 3 LANE12	IEH EXPONDED MKZ GRENADE FUZE	SITE 16	12/05/91	0EW 10-1330-2
11/27/91	ID AREA 3 IANE ID	IEA FRENCH RIFLE GRENADE	SITE 16	12/05/91	·U×0
12/04/91	AREA 6 LANE 6	IEA FRENCH RIFLE GRENAUE	SITE 16	12/05/91	UXO 10-1338-1
12/12/91	10 AREA T LANE /	I EA FRENCH RIFLE GRENADE	SITE 16	12/19/91	UXO 10 - 1347-1
02/19/92	AREA 18	IEA FRENCH RIFIE GRENDE	SITE 16		UXO 10-2050-1
1130	IDD 60 AREA 36	IEA FRENCH RIFLE GRENADE			UXO
1600	AREA 25	I EA EXPLUDED MR 2 GRENADE	SITE 16	13/06/92	10-2052-1
1255	LANEZL 10 DEGO AREAZE		SITE IL	03/06/92	10-2055-1 UXO.
0945	LANES 10 prep 27	RIFLE GRENADE	SITE 16	03/06/92	10 2056-1 UXO
0825	L11@9'	RIFLE GRENADE. 1 RA FRENCH		03/06/22	UKO
3/17/93	4802514	RIPLE CREMPOR	SITE 16	03/20/92	10-2077-1
• • • • • • • • • • • • • • • • • • •					



WORK PLAN THOMAS EDISON PARK (AREA 10) FILL PILE # 1

This area is located on the campus of Middlesex County College. The area is approximately 115' X 65' and contains a fill pile 25' at the base and 9' high. The site is moderate to heavily vegitated. As per meeting on site with Robert Nore, CE, Huntsville, George Spencer, CE, Huntsville and Dr. L. Chan, IT, this area is required to be "Checked and cleared".

We (EODT) will start by laying sweep lines and then checking the entire area with a magnatom ter. All hits will be recorded and dug by hand to a depth of 10". Items deeper than that will be excavated using a Case 580 loader/backhoe. Each bucket of excavated soil will and the exposed ground surface will be examined for any munitions or related hazards. All excavated areas will be backfilled.



Date 21 Aug 9/ Subject AREA Checked 21 Aug 9/ Sheet No. of. Map not to scale Chkd. By___ Proj. No. _Date_ Deved Park Paved -2300 x X Mound to be O checked by hand. Χ Mound to be X χ X **(2)** X X X × X 🗞 🗞 K O OX X χ 8- Fire hydra primary reterance point ON All MEASUREMENT AND compass readings X - Mag hit nothing found & - Mag hits backher needed. Or ordnance found